Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Asset:	P.S. 4 - STATEN ISLAND, 200 NEDRA LANE, STATEN ISLAND, N	VY, 10312	
Inspection Id	Inspection Type	Time In	Last Edited
4349	MECHANICAL	2024-03-29 08:23AM	2024-05-15 03:48PM
sset Data			
Question	Α	nswer	

Have any Systems/Major Building Components been upgraded?	Systems: Drinking Fountains
	Years: 2022
	Systems: Kitchen - Hood Exhaust Fan; Electric Domestic Water
	Heaters in Boiler Room (2 of 3)
	Years: 2019
	Systems: Fixtures - Toilets, Urinals
	Years: 2018
	Systems: Kitchen - Grease Traps; Electric Domestic Water
	Heater for Kitchen (1 of 3)
	Years: 2015
Are there fuel tanks?	No
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	MER C10, Attic Fan Rooms
Are there any spaces with Missing or Defective CO Detectors?	Yes
Location(s)	Kitchen
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Basement - Room C15, Corridor near Room C20 (painted, 4)
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Defective Sprinkler/Standpipe System	Sprinkler Head Covered with Foil	Sprinkler Head	Room C9	Mike Galant	Fireman	L. C

Inspection

Question	Response	
Mechanical		
AIR CONDITIONING	Inspected	
Chilled Water System	Inspected	
Absorption Chiller	Does not exist	
Air Cooled Chiller	Does not exist	
Air Cooled Condenser	Does not exist	
Chilled Water Distribution: Piping, Pumps and Auxiliaries	Under construction	
Backflow Preventer	Does not exist	
Central Station Air Handler	Inspected	
Instance	MER C10	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	AC-1	
Capacity/Size Quantity	5	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Documented	
Installation Year	1984	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

stion	Response	
R CONDITIONING		
Chilled Water System		
Central Station Air Handler		
Deficiency Location/Instance	MER C10	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	MER C10	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	AC-2	
Capacity/Size Quantity	3	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Documented	
Installation Year	1984	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	MER C10	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1 LEVEL 2	
Purpose of Action Violations		
	No violations recorded	
Instance	MER C10 3- Fair	
Instance Condition		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	AC-3	
Capacity/Size Quantity	10	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Documented	
Installation Year	1984	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	MER C10	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fan Coil Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Packaged Air Cooled Chiller	Does not exist	
Water Cooled Chiller	Does not exist	
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist	
Cooling Coil in Ductwork	Does not exist	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

nunical Inspection	K004
Question	Response
AIR CONDITIONING	
DX Split System	Does not exist
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Does not exist
Return Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Under construction
COMPACTOR	Does not exist
CONVEYING	Inspected
Dumbwaiter	Does not exist
Elevator	Inspected
Condition	2- Between Good and Fair
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Gas/Water/Sprinkler Meter Room C22
Instance Condition	3- Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Deficiency	WATER MAIN: MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Gas/Water/Sprinkler Meter Room C22
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Gas/Water/Sprinkler Meter Room C22
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Gas/Water/Sprinkler Meter Room C22
Deficiency Quantity	1
Lenerery Country	1
Quantity Uom	EACH
Quantity Uom Potential Action	EACH INSTALL
Potential Action	INSTALL
-	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

r	
estion	Response
OMESTIC WATER SYSTEM	
Domestic Cold Water System	
Water Service	
Deficiency	WATER MAIN: DEFECTIVE VALVE
Deficiency Location/Instance	Gas/Water/Sprinkler Meter Room C22
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Kitchen (1 of 3)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE BACKFLOW PREVENTER
Deficiency Location/Instance	Gas/Water/Sprinkler Meter Room C22
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
RAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	Rooms C12, C16, C18
Deficiency Quantity	30
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	Does not exist
	Does not exist Inspected 3- Fair

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
TXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Locker Room Shower	
Sink And Fountain Combo Unit	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
AS FIRED FURNACE	Does not exist
AS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Does not exist
IEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	RADIATOR/CONVECTOR:DEFECTIVE/DETERIORATED
Deficiency Location/Instance Deficiency Quantity	Room C5 1

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	K
iestion	Response
HEATING	
Radiator/Convector/Fin Tube	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Room C11
Deficiency Quantity	40
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Pumping System	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE PUMP
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Terminal Unit Thermostatic Trap	
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Room C19
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
IEATING PLANT	Inspected
	Under construction
Instance on Basement	Chaef construction
Instance on Basement Enclosed IDF Room	Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	Inspection		IX00
uestion		Response	
Enclosed	IDF Room		
Dedicat	ted A/C Equipment		
	Instance on Room 208A	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
KITCHE		Inspected	
	Instance on 1st Floor	Inspected	
CO Det		mspected	
00 00	Instance on 1st Floor	Inspected	
	Instance Condition	4- Between Fair and Poor	
	Deficiency	DEFECTIVE/MISSING	
	Deficiency Location/Instance	Kitchen	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	MAINTENANCE	
	Urgency of Action	PRIORITY 5	
	Purpose of Action	LEVEL 6	
	Violations	No violations recorded	
Gas Sy			
Jasby	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
<u> </u>			
Grease	Instance on 1st Floor	Insurantad	
		Inspected 2- Between Good and Fair	
	Instance Condition		
	Deficiency	No deficiencies recorded	
Hood			
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood E	Cxhaust Ductwork		
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood E	Cxhaust Fan		
	Instance on 1st Floor	Inspected	
	Instance Condition	1- Good	
	Deficiency	No deficiencies recorded	
Hood F	ire Suppression System		
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hot Wa	ater Temperature Booster		
	Instance on 1st Floor	Does not exist	
Kitchei			
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
(DE P			
ADF Ro		Inspected	
	Instance on Room 205	Inspected	
Dedicat	ted A/C Equipment		
	Instance on Room 205	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

*	
uestion	Response
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Inspected
Condition	3- Fair
Deficiency	MISSING CAPS
Deficiency Location/Instance	Exterior Building Exist 4
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Basement - Room C15, Corridor near Room C20 (painted, 4)
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Room C9
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Inspected
Hose Valve Assembly	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Partial
Exhaust Fan	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

1		
uestion	Response	
VENTILATION		
Exhaust Fan		
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	Yes	
Deficiency	DEFECTIVE REGISTER/DIFFUSER	
Deficiency Location/Instance	Rooms C18, C19	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Does not exist	
Unit Ventilator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	