Building Condition Assessment Survey 2023-2024

| | | EI (ISEII (D, SU VEI I EI SC | N STREET, STA | TEN ISLAND, | NY, 10304 | |
|---|--|---------------------------------|---------------|--|--|--------------------|
| Inspection | | | | | Time In | Last Edited |
| | 4102 MECHANICAL | | | | 2024-03-20 11:59AM | 2024-05-02 09:01AM |
| set Data | | | | | | |
| Question | | | | Answer | | |
| Have any | Systems/Major Buildin | ng Components been upgraded? | | Systems: | Electric Domestic Water Heater | • |
| | | | | Years: | 2023 | |
| | | | | Systems: | Sump Pump (1 of 2) | |
| | | | | Years: | 2022 | |
| | | | | Systems: | Kitchen - Grease Trap | |
| | | | | Years: | 2020 | |
| | | | | Systems: | Toilet Room Fixtures (~90%) | |
| | | | | Years: | 2019 | |
| | | | | Systems: | MDF Room - Dedicated A/C Ed | quipment (DX Split |
| | | | | V | System) 2018 | |
| Ara thara | fuel tanks? | | | Years: Yes | 2018 | |
| | # of above ground tanks | c | | 1 | | |
| | capacity of all above gr | | | 7,500 | | |
| | # of below ground tank | | | 0 | | |
| | capacity of all below gr | | | 0 | | |
| | f water main service ent | | | 2 | | |
| MERs/Fa | n Rooms Locations | | | Boiler Ro | om Mechanical Area, Penthouse I | Fan Room |
| Are there | any spaces with Missin | ng or Defective CO Detectors? | | No | | |
| | any Painted/Obstructed | | | No | | |
| Are there | any Emergency Stop S | witches with Missing Hammers? | | No compo | onents | |
| iority Co | ndition | | | | | |
| xist | Priority | Condition | Component | Location | | Photo |
| ast Year? | Category | Description | Affected | Description | Notified Title | Image |
| No condit | tion recorded | | | | | |
| spection | 1 | | | | | |
| | | | | | | |
| Question | | | | Response | | |
| Question Mechanic | l | | | Response | <u> </u> | |
| Mechani | cal | | | Response | | |
| Mechanic AIR CO | cal ONDITIONING | | | • | | |
| Mechanic AIR CO | cal ONDITIONING ed Water System | ion: Piping, Pumps and Auxiliar | ies | Inspected | exist | |
| Mechanic AIR CC Chille Cond | cal ONDITIONING ed Water System lenser Water Distributi | ion: Piping, Pumps and Auxiliar | ies | Inspected Does not | exist exist | |
| Mechanic AIR CO Chille Cond Cooli | cal ONDITIONING ed Water System | ion: Piping, Pumps and Auxiliar | ies | Inspected Does not | exist exist exist | |
| Mechanic AIR CO Chille Cond Cooli Cooli | cal ONDITIONING ed Water System lenser Water Distributi ing Coil in Ductwork | ion: Piping, Pumps and Auxiliar | ies | Inspected Does not of Does not Does no | exist exist exist exist | |
| AIR CO Chille Cond Cooli Cooli DX S | cal ONDITIONING ed Water System lenser Water Distributi ing Coil in Ductwork ing Tower | ion: Piping, Pumps and Auxiliar | ies | Inspected Does not of Does not Does no | exist exist exist exist | |
| Mechanic AIR CC Chille Cond Cooli Cooli DX S Ind | cal ONDITIONING ed Water System lenser Water Distributi ing Coil in Ductwork ing Tower plit System | ion: Piping, Pumps and Auxiliar | ies | Inspected Does not of Does not of Does not of Inspected Inspected | exist exist exist exist | |
| Mechanic AIR CC Chille Cond Cooli Cooli DX S Ind | cal ONDITIONING ed Water System lenser Water Distributi ing Coil in Ductwork ing Tower plit System oor Unit | ion: Piping, Pumps and Auxiliar | ies | Inspected Does not of Inspected Inspected 2- Between | exist exist exist exist | |
| Mechanic AIR CC Chille Cond Cooli Cooli DX S Ind | cal ONDITIONING ed Water System lenser Water Distributi ing Coil in Ductwork ing Tower plit System oor Unit | | ies | Inspected Does not of Does not of Does not of Inspected Inspected Inspected UP TO 5 | exist exist exist exist exist exist | |
| Mechanic AIR CC Chille Cond Cooli Cooli DX S Ind | cal ONDITIONING ed Water System lenser Water Distribution In Ductwork ing Tower plit System oor Unit Ondition Deficiency | ion/Instance | ies | Inspected Does not of Does not of Does not of Inspected Inspected Inspected UP TO 5 | exist exist exist exist exist en Good and Fair TONS:DEFECTIVE | |
| Mechanic AIR CC Chille Cond Cooli Cooli DX S Ind | cal ONDITIONING ed Water System lenser Water Distribution ing Coil in Ductwork ing Tower plit System oor Unit ondition Deficiency Deficiency Location Deficiency Quantion Quantity Uom | ion/Instance | ies | Inspected Does not of Does no | exist exist exist exist exist en Good and Fair TONS:DEFECTIVE | |
| Mechanic AIR CC Chille Cond Cooli Cooli DX S Ind | cal ONDITIONING ed Water System lenser Water Distribution ing Coil in Ductwork ing Tower plit System oor Unit ondition Deficiency Deficiency Location Deficiency Quantity Uom Potential Action | ion/Instance tity | ies | Inspected Does not of Does not Does not of Does not of Does not Does not of Does not | exist exist exist exist exist en Good and Fair TONS:DEFECTIVE 06 (1 of 2) | |
| Mechanic AIR CC Chille Cond Cooli Cooli DX S Ind | cal ONDITIONING ed Water System lenser Water Distribution ing Coil in Ductwork ing Tower plit System oor Unit ondition Deficiency Deficiency Location Deficiency Quantity Uom Potential Action Urgency of Action | ion/Instance tity | ies | Inspected Does not of Does not | exist exist exist exist exist en Good and Fair TONS:DEFECTIVE 06 (1 of 2) | |
| Mechanic AIR CC Chille Cond Cooli Cooli DX S Ind | cal ONDITIONING ed Water System lenser Water Distribution Coil in Ductwork ing Tower plit System oor Unit ondition Deficiency Deficiency Location Deficiency Quantity Uom Potential Action Urgency of Action Purpose of Action | ion/Instance tity | ies | Inspected Does not of Does not of Does not of Does not of Inspected Inspected 2- Between UP TO 5 ' Library 30 1 EACH REPAIR PRIORIT LEVEL 2 | exist exist exist exist exist en Good and Fair TONS:DEFECTIVE 06 (1 of 2) | |
| Mechanic AIR CC Chille Cond Cooli Cooli DX S Ind | cal ONDITIONING ed Water System lenser Water Distribution ing Coil in Ductwork ing Tower plit System oor Unit ondition Deficiency Deficiency Location Deficiency Quant Quantity Uom Potential Action Urgency of Action Purpose of Action Violations | ion/Instance tity | ies | Inspected Does not of Does not Does | exist exist exist exist exist exist en Good and Fair TONS:DEFECTIVE 06 (1 of 2) Y 3 | |
| Mechanic AIR CC Chille Cond Cooli Cooli DX S Ind | cal ONDITIONING ed Water System lenser Water Distribution ing Coil in Ductwork ing Tower plit System oor Unit ondition Deficiency Deficiency Location Deficiency Quantity Uom Potential Action Urgency of Action Purpose of Action Violations tdoor Unit | ion/Instance tity | ies | Inspected Does not of Does not Does | exist exist exist exist exist exist en Good and Fair TONS:DEFECTIVE 06 (1 of 2) Y 3 ions recorded | |
| Mechanic AIR CC Chille Cond Cooli Cooli DX S Ind | cal ONDITIONING ed Water System lenser Water Distribution ing Coil in Ductwork ing Tower plit System oor Unit ondition Deficiency Deficiency Location Deficiency Quant Quantity Uom Potential Action Urgency of Action Purpose of Action Violations | ion/Instance tity | ies | Inspected Does not of Does not Does | exist exist exist exist exist exist en Good and Fair TONS:DEFECTIVE 06 (1 of 2) Y 3 | |
| Mechanic AIR CC Chille Cond Cooli Cooli DX S Ind | cal ONDITIONING ed Water System lenser Water Distribution ing Coil in Ductwork ing Tower plit System oor Unit ondition Deficiency Deficiency Location Deficiency Quantity Uom Potential Action Urgency of Action Purpose of Action Violations tdoor Unit | ion/Instance tity | ies | Inspected Does not of Does not Does not Does not Does not Does not | exist exist exist exist exist exist en Good and Fair TONS:DEFECTIVE 06 (1 of 2) Y 3 ions recorded | |
| Mechanic AIR CC Chille Cond Cooli DX S Ind Co | cal ONDITIONING ed Water System lenser Water Distribution ing Coil in Ductwork ing Tower plit System oor Unit ondition Deficiency Deficiency Location Deficiency Quantity Uom Potential Action Urgency of Action Purpose of Action Violations tdoor Unit ondition | ion/Instance tity | ies | Inspected Does not of Does not Does not Does not Does not Does not | exist exist exist exist exist exist en Good and Fair TONS:DEFECTIVE 06 (1 of 2) Y 3 ions recorded en Good and Fair encies recorded exist | |

Building Condition Assessment Survey 2023-2024

| Mechanical Inspection | R011 |
|-----------------------|------|
|-----------------------|------|

| апісаі Інѕресион | K |
|---|---|
| nestion | Response |
| AIR CONDITIONING | |
| Refrigerant Leak Detection System | Does not exist |
| Refrigerant Piping | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Return Fan | Does not exist |
| CENTRAL ACID WASTE NEUTRALIZING TANK | Does not exist |
| CLIMATE CONTROL SYSTEM | Inspected |
| BMS | Does not exist |
| Pneumatic System | Inspected |
| Instance | Throughout |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Building Area Covered by Operational System | 41-60% |
| Deficiency | DEFECTIVE TEMPERATURE CONTROL THERMOSTAT |
| Deficiency Location/Instance | Rooms 301, 303, 309 |
| Deficiency Quantity | 15 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | DEFECTIVE TERMINAL UNIT CONTROL VALVE |
| Deficiency Location/Instance | Rooms 301, 308, 309 |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | DEFECTIVE TEMPERATURE CONTROL ZONE VALVE |
| Deficiency Location/Instance | Boiler Room Mechanical Area @ Auditorium Bl |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Hybrid System | Does not exist |
| Electric System | Does not exist |
| COMPACTOR | Does not exist |
| CONVEYING | Does not exist |
| DOMESTIC WATER SYSTEM | Inspected |
| Domestic Cold Water System | Inspected |
| Gravity System | Does not exist |
| | Does not exist |
| Pressure Booster System Water Service | Inspected |
| | |
| Instance | Building Exterior – Water Meter Room; 1st Floor – Water Meter Room 152 |
| Instance Condition | 3- Fair |
| Instance Quantity | 2 |
| Instance Quantity Uom | EACH |
| Deficiency | WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE |

Building Condition Assessment Survey 2023-2024

| Question | Response |
|--|--|
| DOMESTIC WATER SYSTEM | |
| Domestic Cold Water System | |
| Water Service | |
| Deficiency Location/Instance | Building Exterior – Water Meter Room; 1st Floor – Water Meter Room 152 |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | INSTALL |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | WATER MAIN:DEFECTIVE VALVE |
| Deficiency Location/Instance | Building Exterior – Water Meter Room; 1st Floor – Water Meter Room 152 (Pressure Regulator) |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action Violations | LEVEL 2 |
| | No violations recorded |
| Domestic Hot Water System | Inspected Does not exist |
| Domestic Hot Water Remote Storage Tank | |
| Domestic Water Heat Exchanger | Does not exist |
| Electric Domestic Water Heater | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Gas Fired Domestic Water Heater | Under construction |
| Oil Fired Domestic Water Heater | Does not exist |
| Heat Pump Domestic Water Heater | Does not exist |
| Domestic Water Distribution Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | DEFECTIVE DOMESTIC HOT WATER CIRCULATING PUMP |
| Deficiency Location/Instance Deficiency Quantity | Boiler Room 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| DRAIN/WASTE/VENT AND STORM SYSTEM | Inspected |
| Interior Storm Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Sewage/Waste/Vent Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Sewage Ejector Pump | Does not exist |
| Sump Pump | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER) | Does not exist |
| FIXTURES | Inspected |
| Staff And Other | Inspected |
| Janitor Sink | Inspected |

Building Condition Assessment Survey 2023-2024

| апісаі Іпѕресиоп | KUI |
|---|---|
| uestion | Response |
| FIXTURES | |
| Staff And Other | |
| Janitor Sink | |
| Deficiency | No deficiencies recorded |
| Lavatory/Sink | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Toilet | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Urinal | Does not exist |
| Student | Inspected |
| Drinking Fountain | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lavatory/Sink | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Locker Room Shower | Does not exist |
| Sink And Fountain Combo Unit | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Toilet | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Urinal | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| • | Does not exist |
| GAS FIRED FURNACE | |
| GAS SERVICE | Inspected |
| Gas Distribution Piping | Inspected 3- Fair |
| Condition | |
| Deficiency | No deficiencies recorded |
| Gas Meter Room Exhaust Fan | Inspected 3- Fair |
| Condition | |
| Deficiency | No deficiencies recorded |
| Gas Meter Room Vent | Inspected 3- Fair |
| Condition | No deficiencies recorded |
| Deficiency P | Does not exist |
| Gas Pressure Booster | Inspected |
| CO/Gas Leak Detection Instance | 1st Floor - Boiler Room; Building Exterior Gas Meter Room |
| Instance Condition | 3- Fair |
| | |
| Instance Quantity | 1 EACH |
| Instance Quantity Uom | 2012 |
| Installation Year Source of Installation Year | 2012 Custodial Staff |
| Deficiency | No deficiencies recorded |
| | |
| HEATING | Inspected |
| Heating Coil In Ductwork Condition | Inspected 3- Fair |
| | |
| Deficiency | No deficiencies recorded |

Building Condition Assessment Survey 2023-2024

| estion | Response |
|--|---|
| EATING | |
| Radiator/Convector/Fin Tube | Inspected |
| Condition | 3- Fair |
| Deficiency | AUXILIARY (VALVE, VENT): DEFECTIVE |
| Deficiency Location/Instance | 2nd Floor near Stair C, Stair "G/3 |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Steam Heating | Inspected |
| F&T/Steam Drip Trap | Inspected |
| Condition | 4- Between Fair and Poor |
| | |
| Deficiency | DEFECTIVE/DETERIORATED |
| Deficiency Location/Instance | Boiler Room, Cafeteria, 1st Floor Exits |
| Deficiency Quantity | 15 FACH |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| MER Steam and Condensate Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Steam Condensate Return Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Steam Condensate Return Pumping System | Inspected |
| Condition | 3- Fair |
| Deficiency | DEFECTIVE PUMP |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | J |
| Quantity Uom | EACH |
| Potential Action | |
| Urgency of Action | MAINTENANCE PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| | |
| Steam Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Terminal Unit Thermostatic Trap | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Steam supplied by External Sources | Does not exist |
| Unit Heater/Cabinet Heater | Inspected |
| Condition | 3- Fair |
| Deficiency | DEFECTIVE |
| Deficiency Location/Instance | Corridor near Exist 6 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |

Building Condition Assessment Survey 2023-2024

| Mechanical Inspection | | R011 | |
|-----------------------|----------|------|--|
| | ~ | • | |

| * | |
|--|---|
| estion | Response |
| EATING PLANT | Inspected |
| Instance on 1st Floor | Inspected |
| Is there a water meter on the boiler make-up water piping? | No |
| Burner Manufacturer | Gordon-Piatt |
| Burner Model | AF147992 |
| Burner Type | Dual Fuel (Gas/Oil) |
| Heating Plant Oil Number | 2 |
| Boiler Auxiliaries | |
| Instance on 1st Floor | Inspected |
| Boiler Auxiliary Piping | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | DEFECTIVE BOILER AUTOMATIC FEEDWATER VALVE |
| Deficiency Location/Instance | Boiler Room @ Boiler #1 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Boiler Emergency Stop Switch | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Boiler Feedwater System | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | FEEDWATER PUMP:DEFECTIVE |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Boiler Feedwater Treatment(Automatic) | |
| Instance on 1st Floor | Does not exist |
| Boiler Flue Exhaust | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Boiler Make-up Water Backflow Preventer | 1.0 40.10.10.10.10.10.10.10.10.10.10.10.10.10 |
| Instance on 1st Floor | Inspected |
| | 3- Fair |
| Instance Condition | |
| Deficiency | No deficiencies recorded |
| Boiler Room Steam And Condensate Piping | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Boiler Safety Valve | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Boiler System | |
| Instance on 1st Floor | Inspected |

Building Condition Assessment Survey 2023-2024

| uestion | Response |
|--|---|
| HEATING PLANT | |
| Boiler System | |
| Coal-fired Boiler | |
| Instance on 1st Floor | Does not exist |
| Hot Water Boiler | |
| Instance on 1st Floor | Does not exist |
| Modular Boiler | |
| Instance on 1st Floor | Does not exist |
| Steam Boiler | |
| Instance on 1st Floor | Inspected |
| Instance on 1st Floor | Inspected |
| Instance | Boiler Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 4,299 |
| Instance Quantity Uom | MBH NET |
| Cast Iron Boiler? | No |
| Manufacturer | Burnham |
| EquipmentId | 7389-1 |
| Capacity/Size Quantity | 5537 |
| Capacity/Size UOM | MBH Gross |
| Source of Capacity/Size | Documented |
| Installation Year | 1994 |
| Source of Installation Year | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Instance | Boiler Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 4,299 |
| Instance Quantity Uom | MBH NET |
| Cast Iron Boiler? | No |
| Manufacturer | Burnham |
| EquipmentId | 7389-2 |
| Capacity/Size Quantity | 5537 |
| Capacity/Size UOM | MBH Gross |
| Source of Capacity/Size | Documented |
| Installation Year | 1994 |
| Source of Installation Year | Custodial Staff No deficiencies recorded |
| Deficiency | No deficiencies recorded |
| Fuel System | Inquested |
| Instance on 1st Floor | Inspected |
| Boiler Fresh Air Louver/Damper | |
| Instance on 1st Floor | Inspected 4- Between Fair and Poor |
| Instance Condition | |
| Type | Automatic DEFECTIVE ACTUATOR |
| Deficiency | DEFECTIVE ACTUATOR |
| Deficiency Location/Instance Deficiency Quantity | Boiler Room 2 |
| Quantity Uom | EACH |
| Potential Action | EACH MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Burner/Burner Control Panel | To Homous recorded |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| | |
| Deficiency Deficiency Location/Instance | BURNER CONTROL PANEL:DEFECTIVE Boiler Room (lead lag) |

Building Condition Assessment Survey 2023-2024

| Question | Response | |
|-----------------------------------|--------------------------|--|
| HEATING PLANT | | |
| Fuel System | | |
| Burner/Burner Control Panel | | |
| Deficiency Quantity | 1 | |
| Quantity Uom | EACH | |
| Potential Action | MAINTENANCE | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| Fuel Oil Storage/Supply System | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Gas Trains And Vent At The Boiler | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Enclosed IDF Room | Does not exist | |
| KITCHEN | Inspected | |
| Instance on 1st Floor | Inspected | |
| CO Detector | • | |
| Instance on 1st Floor | Not required | |
| Gas System | • | |
| Instance on 1st Floor | Does not exist | |
| Grease Trap | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| Hood | | |
| Instance on 1st Floor | Does not exist | |
| Hood Exhaust Ductwork | | |
| Instance on 1st Floor | Does not exist | |
| Hood Exhaust Fan | | |

Does not exist

Does not exist

VALVE,ETC.) kitchen

MAINTENANCE PRIORITY 3

No violations recorded

DEFECTIVE AUXILIARY (FAUCET, SHUT OFF

Inspected

3- Fair

1

EACH

LEVEL 2

Hood Fire Suppression System
Instance on 1st Floor

Hot Water Temperature Booster

Kitchen Sink

Instance on 1st Floor

Instance on 1st Floor

Deficiency Location/Instance Deficiency Quantity

Instance Condition

Quantity Uom

Violations

Potential Action

Urgency of Action Purpose of Action

Deficiency

Building Condition Assessment Survey 2023-2024

| | KU1. |
|--|---|
| Response | |
| | |
| | |
| No deficiencies recorded | |
| Does not exist | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| - | |
| | |
| | |
| | |
| | |
| Does not exist | |
| Inspected | |
| Yes | |
| | |
| 3- Fair | |
| 1-25 | |
| DEFECTIVE | |
| Penthouse Fan Room / Toilet Exhaust 2A (bearing) | |
| 1 | |
| EACH | |
| | |
| PRIORITY 3 | |
| LEVEL 2 | |
| No violations recorded | |
| Does not exist | |
| | |
| | |
| | |
| | |
| | |
| | |
| 2 | |
| EACH | |
| | |
| | |
| | |
| No violations recorded | |
| | |
| | |
| 1-5 | |
| No deficiencies recorded | |
| Inspected | |
| 3- Fair | <u></u> |
| No deficiencies recorded | |
| | No deficiencies recorded Does not exist Inspected 3- Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded Does not exist Inspected 3- Fair 1-25 DEFECTIVE Penthouse Fan Room / Toilet Exhaust 2A (bearing) 1 EACH MAINTENANCE PRIORITY 3 LEVEL 2 No violations recorded Does not exist Inspected 3- Fair No No DAMAGED FLEXIBLE CONNECTION Boiler Room Mechanical Area @ Auditorium BI 2 EACH MAINTENANCE PRIORITY 3 LEVEL 2 No violations recorded Does not exist Inspected 3- Fair No No DAMAGED FLEXIBLE CONNECTION Boiler Room Mechanical Area @ Auditorium BI 2 EACH MAINTENANCE PRIORITY 3 LEVEL 2 No violations recorded Inspected 3- Fair 1-5 No deficiencies recorded Inspected 3- Fair |