Building Condition Assessment Survey 2023-2024

Asset:	P.S. 23 - STATEN	ISLAND, 30 NATIC	K STREET, STATEN	ISLAND, NY,	10306	
Inspection Id	Inspection Type				Time In	Last Edited
	5 ELECTRICAL				2024-02-28 07:30AM	2024-03-19 10:01AN
set Data	<u> </u>					
Question				Answer		
	tama/Maian Duildina Ca		40	Systems:	IPDVS/CCTV System, LAN,	Auditorium (Projection
Have any Syst	tems/Major Building Co	omponents been upgrade	u:	bystems.	System)	ruditorium (1 rojection
				Years:	2022	
				Systems:	Telephone System	
				Years:	2017	
				Systems:	Interior Lighting (Except Libra	ary)
				Years:	2015	
				Systems:	Partial Molded Case Circuit B	reaker Panel Board
				Years:	2013, 2008, 2004	
				Systems:	Partial Fused Disconnect Swite	ch Type Panel Board
				Years:	2010, 2001	
				Systems:	Public Address System, Local	Sound System
				Years:	2010	
				Systems:	• ,	
					Annunciator Panel, Duct Smol	
					Shutdown Controls, Fused Cut Service Switch, Partial Switch	
				Years:	2008	board
				Systems:		
				Years:	2005	
				Systems:		urity
				Years:	2004	·
				Systems:	Emergency Light/Exit Light P	anel
				Years:	2001	
Type of Service	ce			Below G	round	
	ve Whiteboard (IWB) E	Exist?		Yes		
Water Penetra	tion In Electrical Room	?		No		
DEDICATE	D INTERCOMS IN	FIRE RESCUE ARI	EAS			
Question					Response	
	•	ce Areas, Fire Rescue Ar	eas, and/or Holding Roor	ns in	No	
your buildin						
riority Condi	tion					
	iority	Condition	Component	Location	Person(s) Person(s)	Photo
Last Year? Ca	tegory	Description	Affected	Description	Notified Title	Image
No condition i	recorded					
nspection						
Question				Response	ρ	
Electrical				response		
	2 PVPV P			D	• ,	
ATHLETIC FIELD			Does not			
AUDITORIUM			Inspected			
	nstance on 1st Floor			Inspected	l	
House Lig						
	nstance on 1st Floor	9		Inspected	I	
	Does a Chandelier Exist			No		
	g Fixture - Fluorescent	<u> </u>		τ . •	1	
	nstance on 1st Floor			Inspected	<u> </u>	
_	nt Mounted			<u> </u>		
_	nstance on 1st Floor			Inspected		
Instance Condition			2- Betwee	en Good and Fair		

No deficiencies recorded

Deficiency

Building Condition Assessment Survey 2023-2024

Electrical InspectionR023QuestionResponse

Response	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
1.0 0011011010110101	
Inspected	
•	
-	
ivo violations recorded	
D	
Does not exist	
Does not exist	
Inspected	
Does not exist	
Does not exist	
Inspected	
-	
No violations recorded	
No deficiencies recorded	
1- Good	
Ceiling	
No deficiencies recorded	
Inspected	
Does not exist	
Inspected	
	Inspected Does not exist Inspected 2- Between Good and Fair LIGHTING FIXTURE BALLAST DEFECTIVE 4 EACH REPLACE BALLAST PRIORITY 3 LEVEL 2 No violations recorded Inspected 3- Fair 2010 Documented No deficiencies recorded Inspected 1- Good Ceiling No deficiencies recorded

Building Condition Assessment Survey 2023-2024

icai inspection		KU23
uestion	Response	
AUDITORIUM		
Theater Lighting System		
Theater Lighting		
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	32	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
CAFETERIA	Inspected	
Instance on 1st Floor	Inspected	
Lighting_		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	_
COMPUTER LAB	Inspected	
Instance on Room 308	Inspected	
Power Panel?	Yes	
Lighting		
Instance on Room 308	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 308	Inspected	
Pendant Mounted		
Instance on Room 308	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 308	Does not exist	
Recessed Mounted		
Instance on Room 308	Does not exist	
Lighting Fixture - HID		
Instance on Room 308	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 308	Does not exist	
Lighting Fixture - LED		
Instance on Room 308	Does not exist	
Raceway With Receptacles		
Instance on Room 308	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID	D	
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED Instance on 1st Floor	Inspected	
Pendant Mounted	inspected	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Tro deficiencies recorded	
Instance on 1st Floor	Does not exist	
Recessed Mounted	Does not exist	
Instance on 1st Floor	Does not exist	
mountee on 15t 1 1001	Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection	R023

a com inspection		
Question	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - LED		
Recessed Mounted		
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 204	Inspected	
Lighting		
Instance on Room 204	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 204	Inspected	
Pendant Mounted	1	
Instance on Room 204	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	1 to deficiences foodiaca	
Instance on Room 204	Does not exist	
Recessed Mounted	DOGS HOL CAISE	
Instance on Room 204	Inspected	
Instance on Room 204 Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

circui Inspection		1025
Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - HID		
Instance on Room 204	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 204	Inspected	
Pendant Mounted		
Instance on Room 204	Does not exist	
Surface Mounted		
Instance on Room 204	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 204	Does not exist	
Lighting Fixture - LED		
Instance on Room 204	Does not exist	
Raceway With Receptacles		
Instance on Room 204	Does not exist	
Projection System		
Instance on Room 204	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
	Does not exist	
SCIENCE DEMO ROOM		
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - Incandescent Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition Condition	3- Fair	
Condition Deficiency	No deficiencies recorded	
Deficiency	140 deficiencies recorded	

Building Condition Assessment Survey 2023-2024

trical Inspection		R023
Question	Response	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Does not exist	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Does not exist	
CO Detector	Does not exist	
Heat Detector	Does not exist	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards	

Building Condition Assessment Survey 2023-2024

······································	
Question Response	

nestion	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Standard)	
EquipmentId	Fire Alarm Control Panel
Installation Year	1964
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	66,000 S.F.
Quantity Uom Potential Action	s.r. REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Fire Alarm Control Panel (Electronic) Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1 EACH
Instance Quantity Uom	
Manufacturer Model	General Electric EST 2
	ES1 2 Fire Alarm Control
EquipmentId Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards
EquipmentId	Sprinkler Alarm Control Board
Installation Year	1964
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	66,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Does not exist
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected

Building Condition Assessment Survey 2023-2024

Question	Response
FIRE ALARM SYSTEM	
Sprinkler Flow/Air Pressure Switch	
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROLLER MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement - Fan And Boiler Rooms
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations Make a Committee Brooker Trans	No violations recorded
Molded Case Circuit Breaker Type	Inspected 3- Fair
	J- 1'all
Condition	DANEL DOADD DEVOND LIGEETH TEE
Condition Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Condition Deficiency Deficiency Location/Instance	Throughout the Building
Condition Deficiency	

Building Condition Assessment Survey 2023-2024

nestion	Response
ANEL BOARD	
Molded Case Circuit Breaker Type	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Main Office - Room 117
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2010
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	17
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
EECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2022
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 117
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom Model	Vista - 128B
	2005
Installation Year Source of Installation Year	Documented
Deficiency	No deficiencies recorded
	Inspected
Infrared Sensor	<u> </u>
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Building Perimeter
Deficiency Quantity	Building I Crimical

Building Condition Assessment Survey 2023-2024

icai Inspection		KU2
uestion	Response	
SECURITY		
Lighting - Security		
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 3	
Violations	No violations recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Electric Panel	
EquipmentId	Heating Equipment Service	
Capacity/Size Quantity	400	
Capacity/Size Quality Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1964	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Manufacturer	Lexington	
EquipmentId	Lighting Switch	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate 1964	
Installation Year Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance		
	Electrical Room 2- Between Good and Fair	
Instance Condition		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Cutler Hammer	
EquipmentId	MDB Main SW.	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2008	

Building Condition Assessment Survey 2023-2024

cirical Inspection		KU23
Question	Response	
SERVICE SWITCH		
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
	Lexington	
Manufacturer	Power Switch	
EquipmentId Capacity/Size Quantity	800	
Capacity/Size Quantity Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1964	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1 FACH	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	Roof AC	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	2	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Cutler Hammer	
EquipmentId	ACDP	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Lexington	
Manufacturet	Leanington	

Building Condition Assessment Survey 2023-2024

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1964
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist