#### **Building Condition Assessment Survey 2023-2024**

Electrical Inspection R027

Asset:	I.S. 27 - STATEN ISLAND, 11 CLOVE LAKE PLACE, STATEN ISLAND, NY, 10310			
Inspection Id	d Inspection Type Time In Last Edited			
3624	ELECTRICAL	2024-02-29 07:10AM	2024-06-18 09:56AM	

#### Asset Data

Question	Answer	
Have any Systems/Major Building Components been upgraded?	Systems:	Retrofitted LED Lights (Except Gymnasium and 9
		Incandescent Recessed Fixtures in Auditorium).

Years: 2023 Systems: LAN Years: 2022

Systems: Partial Molded Case Circuit Breaker Panel Board

Years: 2021, 2009, 1996 Systems: Gymnasium (Scor

ss: Gymnasium (Scoreboard), Partial Service Switch, Partial Switchboard

. 2021

Years: 2021

Systems: Lighting - Security

Years: 2020

Systems: Gymnasium (Retrofitted LED Lighting)

Years: 2018

Systems: Most Exit Lights (Battery Pack)

Years: 2013

Systems: Intrusion Alarm System (Except Siren/Strobe)

Years: 2012

Systems:

IPDVS/CCTV System, Telephone System

Years: 2010

Systems: Public Address System, Local Sound System, Fire

Alarm System

Years: 2007

Systems: Emergency Light/Exit Light Panel

Years: 1996 Below Ground

Yes No

#### DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Does Interactive Whiteboard (IWB) Exist?

Water Penetration In Electrical Room?

DEDICHTED INTERIOR IN TIME TESTOR INTERIOR		
Question	Response	
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No	
your building?		

#### **Priority Condition**

Type of Service

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Water Leaks onto Electrical Equipment	Water penetrates trough ceiling onto light fixture.	Lighting Fixture	Inside Room 331	Francisco Gonzalez	Fireman	16

#### Inspection

Question	Response	Response	
Electrical			
ATHLETIC FIELD	Does not exist		
AUDITORIUM	Inspected		
Instance on 1st Floor	Inspected		
House Lighting			
Instance on 1st Floor	Inspected		
Does a Chandelier Exist?	No		

Electrical Inspection	KU2 /

estion	Response
UDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Cart
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	DIMMING RACK/LIGHT CONSOLE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

Electrical Inspection	R027

*	
nestion	Response
AUDITORIUM	
Theater Lighting System	
Dimming System	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	126
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Inspected
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Lighting	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Pendant Mounted	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Surface Mounted	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Recessed Mounted	2000 100 01100
Instance on 1st Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	No deficiencies recorded
Local Sound System  Instance on 1st Floor - Students	Inspected
	3- Fair
Installation Year	2007
Source of Installation Year	2007 Documented
Deficiency	No deficiencies recorded
Deficiency	Does not exist

## **Building Condition Assessment Survey 2023-2024**

icui Inspection		1027
uestion	Response	
CAFETERIA		
Projection System		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
Theater Lighting System		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	mspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	mspected	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	100 deficiencies recorded	
Instance on 1st Floor	Does not exist	
Recessed Mounted	DOCS HOT CAIST	
Instance on 1st Floor	Does not exist	
Local Sound System	Does not exist	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Inspected	

## **Building Condition Assessment Survey 2023-2024**

Electrical InspectionR027QuestionResponse

iricui Inspection		1027
Question	Response	
GYMNASIUM		
Scoreboard		
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	nispected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Instance on 1st Floor	Inspected	
Pendant Mounted	nispected	
Instance on 1st Floor	Does not exist	
	Does not exist	
Surface Mounted Instance on 1st Floor	Does not exist	
	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Inspected	
Instance on Room 229	Inspected	
Lighting	•	
Instance on Room 229	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 229	Does not exist	
Lighting Fixture - HID		
Instance on Room 229	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 229	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Room 229	Inspected	
Pendant Mounted	пърсски	
Instance on Room 229	Does not exist	
	DOCS HOT CAIST	
Surface Mounted	December and aniet	
Instance on Room 229	Does not exist	
Recessed Mounted		
Instance on Room 229	Inspected	
Instance Condition	2- Between Good and Fair	

Electrical Inspection	R027

uestion	Response	
LIBRARY		
Lighting		
Lighting Fixture - LED		
Recessed Mounted		
Deficiency	No deficiencies recorded	
Raceway With Receptacles		
Instance on Room 229	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 229	Does not exist	
LOCKER ROOM	Inspected	
Instance on Basement - Boys	Inspected	
Alternative Use	No	
Instance on Basement - Girls	Inspected	
Alternative Use	Yes	
Lighting	105	
Instance on Basement - Boys	Inspected	
Instance on Basement - Girls	Inspected	
Lighting Fixture - Fluorescent	inspected	
Instance on Basement - Boys	Inspected	
Instance on Basement - Girls	Does not exist	
Pendant Mounted	Does not exist	
Instance on Basement - Boys	Does not exist	
Surface Mounted	Does not exist	
Instance on Basement - Boys	Does not exist	
Recessed Mounted	Does not exist	
	Does not exist	
Instance on Basement - Boys	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on Basement - Boys		
Instance on Basement - Girls	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement - Boys	Does not exist	
Instance on Basement - Girls	Does not exist	
Lighting Fixture - LED		
Instance on Basement - Boys	Inspected	
Instance on Basement - Girls	Inspected	
Pendant Mounted		
Instance on Basement - Boys	Does not exist	
Instance on Basement - Girls	Does not exist	
Surface Mounted		
Instance on Basement - Boys	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Basement - Girls	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement - Boys	Does not exist	
Instance on Basement - Girls	Does not exist	
MULTIPURPOSE ROOM	Does not exist	

Electrical Inspection	K02 /

eui mspeenon		
estion	Response	
CIENCE DEMO ROOM		
Power Panel?	No	
Alternative Use	Yes	
Instance on Room 353	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting	INO	
Instance on Rooms: 339, 343, 347, 350	Inspected	
Instance on Room 353	Inspected	
Lighting Fixture - Fluorescent	nispected	
	Does not exist	
Instance on Rooms: 339, 343, 347, 350		
Instance on Room 353	Does not exist	
Lighting Fixture - HID		
Instance on Rooms: 339, 343, 347, 350	Does not exist	
Instance on Room 353	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms: 339, 343, 347, 350	Does not exist	
Instance on Room 353	Does not exist	
Lighting Fixture - LED		
Instance on Rooms: 339, 343, 347, 350	Inspected	
Instance on Room 353	Inspected	
Pendant Mounted		
Instance on Rooms: 339, 343, 347, 350	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 353	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Rooms: 339, 343, 347, 350	Does not exist	
Instance on Room 353	Does not exist	
Recessed Mounted		
Instance on Rooms: 339, 343, 347, 350	Does not exist	
Instance on Room 353	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Rooms: 339, 343, 347, 350	Does not exist	
Instance on Room 353	Does not exist	
Emergency Shut-Off Power		
Instance on Rooms: 339, 343, 347, 350	Does not exist	
Instance on Room 353	Does not exist	
Power Supply		
Instance on Rooms: 339, 343, 347, 350	Does not exist	
Instance on Room 353	Does not exist	
Projection System		
Instance on Rooms: 339, 343, 347, 350	Does not exist	
Instance on Room 353	Does not exist	
CIENCE LAB	Inspected	
Instance on Room 357A	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting	110	

## **Building Condition Assessment Survey 2023-2024**

rical Inspection		I
uestion	Response	
SCIENCE LAB		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Room 357A	Does not exist	
Lighting Fixture - HID		
Instance on Room 357A	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 357A	Does not exist	
Lighting Fixture - LED		
Instance on Room 357A	Inspected	
Pendant Mounted		
Instance on Room 357A	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 357A	Does not exist	
Recessed Mounted		
Instance on Room 357A	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 357A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
<b>Emergency Shut-Off Power</b>		
Instance on Room 357A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 357A	Inspected	
Instructor Unit		
Instance on Room 357A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 357A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Student Unit	The deficiences recorded	
Instance on Room 357A	Does not exist	
Projection System	Does not exist	
Instance on Room 357A	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Rooms: 341, 349	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Instance on Room 355	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Rooms: 341, 349	Inspected	
Instance on Room 355	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms: 341, 349	Does not exist	

Does not exist

Instance on Room 355

**Lighting Fixture - HID** 

Electrical Inspection		
Ouestion	Response	_

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - HID	
Instance on Rooms: 341, 349	Does not exist
Instance on Room 355	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms: 341, 349	Does not exist
Instance on Room 355	Does not exist
Lighting Fixture - LED	
Instance on Rooms: 341, 349	Inspected
Instance on Room 355	Inspected
Pendant Mounted	
Instance on Rooms: 341, 349	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 355	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms: 341, 349	Does not exist
Instance on Room 355	Does not exist
Recessed Mounted	
Instance on Rooms: 341, 349	Does not exist
Instance on Room 355	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Rooms: 341, 349	Does not exist
Instance on Room 355	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Rooms: 341, 349	Does not exist
Instance on Room 355	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Rooms: 341, 349	Does not exist
Instance on Room 355	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist

## **Building Condition Assessment Survey 2023-2024**

ricai Inspection		KU2/
Question	Response	
TOILET ROOM - STUDENT		
Lighting		
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected Inspected	
Battery Pack Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Non Battery Pack Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
EXIT/EMERGENCY LIGHT		
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected  2- Between Good and Fair	
Condition	2 Detriven Social and Lan	
Deficiency	No deficiencies recorded	
Strobe	Inspected 2- Between Good and Fair	
Condition	No deficiencies recorded	
Deficiency		
Manual Pull Station  Condition	Inspected  2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Fan Shutdown Control Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	

## **Building Condition Assessment Survey 2023-2024**

uestion	Response	
FIRE ALARM SYSTEM		
Heat Detector		
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
	Edwards System Technology	
Manufacturer Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch Condition	Inspected 2- Between Good and Fair	
	No deficiencies recorded	
Deficiency		
Tamper Flow Switch/Chain Condition	Inspected 2- Between Good and Fair	
	No deficiencies recorded	
Deficiency		
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROLLER		

Question	Response
MOTOR CONTROLLER	
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Fan Rooms: 116 and 254, Boiler Room
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room 139
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	38
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Main Office
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom Model	Rauland TC2100
	2007
Installation Year Source of Installation Year	Documented
	CLOCK NOT OPERATIONAL
Deficiency	
Deficiency Location/Instance Deficiency Quantity	Throughout the Building 21
	EACH
Quantity Uom	
Potential Action	REPLACE DRIGHTY 2
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected

Electrical Inspection		KU2/
Ouestion	Response	

Question	Response	
SECURITY		
IPDVS/CCTV System		
Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office - Room 145	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista - 250BP	
Installation Year	2012	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Inspected	
SERVICE SWITCH	*	
Instance	Electrical Room 139 3- Fair	
Instance Condition		
Instance Quantity	I FACIL	
Instance Quantity Uom	EACH	
Manufacturer	General Electric	
EquipmentId	Heating Equipment Disc SW	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate 1963	
Installation Year Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room 139	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room 139	
Instance Condition	1- Good	
Instance Condition	1 0000	

## **Building Condition Assessment Survey 2023-2024**

circui Inspection	102
Question	Response
SERVICE SWITCH	
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	Main Switch
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2021
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 139
Instance Condition	3- Fair
Instance Quantity	1 EACH
Instance Quantity Uom	EACH
Manufacturer	Lexington
EquipmentId	Switchboard Section "A" Lighting
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1963
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room 139
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room 139
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	Lexington
EquipmentId	Switchboard Section "B" Power
Capacity/Size Quantity	1500
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1963
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room 139
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	2
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room 139
Instance Condition	1- Good
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	All City Switchboard

## **Building Condition Assessment Survey 2023-2024**

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
EquipmentId	Distribution Panel ACDP
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2021
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 139
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington
EquipmentId	Main Dist Center
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	4
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1963
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room 139
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist