### **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection R027

Asset:	I.S. 27 - STATEN ISLAND, 11 CLOVE LAKE PLACE, STATEN ISLAND, NY, 10310		
Inspection Id	Inspection Type	Time In	Last Edited
3645	MECHANICAL	2024-02-29 09:14AM	2024-03-31 11:22AM

#### Asset Data Question Answer Systems: Heat Pump Domestic Water Heaters; Kitchen - Hot Have any Systems/Major Building Components been upgraded? Water Temperature Booster; Drinking Fountains Years: Systems: F&T/Steam Drip Traps; Terminal Unit Thermostatic Traps 2020 Years: Fixtures - Toilets; Water Service refurbished (2 of 3) Systems: Years: Systems: Kitchen - Grease Trap Years: 2015 Are there fuel tanks? Yes Total # of above ground tanks Total capacity of all above ground tanks in gal. 20,000 0 Total # of below ground tanks Total capacity of all below ground tanks in gal. 0 Total # of water main service entries to the asset MERs/Fan Rooms Locations MERs 116, 254; Room 201 - Fan Room; Fan Room 204 Are there any spaces with Missing or Defective CO Detectors? Science Demo Room 353, Science Prep Room 355 Location(s) Yes Are there any Painted/Obstructed Sprinkler Heads? Location(s) Rooms 106A, 106B, 134, 137, 138, 140A, 156A, 208, 252,

### **Priority Condition**

Are there any Emergency Stop Switches with Missing Hammers?

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Defective Boiler Safety Auxiliary	Boiler #2: Water Column's try cocks handle is missing. Boiler #3: Primary Low Water Cut-off and its piping are defective.	Steam Boiler	Boiler Room	Francisco Gonzalez	Fireman	

253, 365, 367 (painted, 68)

No components

### Inspection

Question	Response	
Mechanical		
AIR CONDITIONING	Does not exist	
CENTRAL ACID WASTE NEUTRALIZING TANK	Inspected	
Condition	3- Fair	
Deficiency	NOT IN USE	
Deficiency Location/Instance	Girls Locker Room - Crawlspace	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	NO ACTION	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 1	
Violations	No violations recorded	
CLIMATE CONTROL SYSTEM	Inspected	
BMS	Does not exist	
Pneumatic System	Inspected	
Instance	Throughout	
Instance Condition	3- Fair	
Dt V	D1-£15	Duint Data: 9/9/2024

### **Building Condition Assessment Survey 2023-2024**

1
1
EACH
81-100%
DEFECTIVE TEMPERATURE CONTROL ZONE VALVE
MER 116 @ Kitchen Blower
1
EACH
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded
Does not exist
Inspected
Inspected
Does not exist
Does not exist
Inspected
Sprinkler/Water/Gas Meter Room 131
3- Fair
1 EACH
WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Sprinkler/Water/Gas Meter Room 131
1
EACH
INSTALL
PRIORITY 3
LEVEL 2
No violations recorded
Boys Locker Room - Crawlspace; Sprinkler/Water/Gas Meter Room 131
2- Between Good and Fair
2
EACH
WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Boys Locker Room - Crawlspace; Sprinkler/Water/Gas Meter Room 131
2
EACH
INSTALL
PRIORITY 3
LEVEL 2
No violations recorded
Inspected
Does not exist
Inspected
3- Fair

### **Building Condition Assessment Survey 2023-2024**

estion	Response
OMESTIC WATER SYSTEM	
Domestic Hot Water System	
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	1- Good
Instance Quantity	2
Instance Quantity Uom	EACH
Manufacturer	A.O. Smith
EquipmentId	N/A
Capacity/Size Quantity	5
Capacity/Size UOM	KW Input
Capacity/Size 2 Quantity	119
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2022
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Boys Locker Room
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room, Boys Locker Room
Deficiency Quantity	30
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
RAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
IXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair

### **Building Condition Assessment Survey 2023-2024**

stion	Response
XTURES	
Staff And Other	
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE FLUSHOMETER VALVE
Deficiency Location/Instance	Toilet Room 344
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Boys Locker Room - Toilets Room; Auditorium Dressing Room; Toilet Room 316
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Locker Room Shower	Inspected
Instance on Basement - Boys	Inspected
Instance Condition	3- Fair
Alternative Use	Yes
Deficiency	No deficiencies recorded
Instance on Basement - Girls	Inspected
Instance Condition	3- Fair
Alternative Use	Yes
Deficiency	No deficiencies recorded
Sink And Fountain Combo Unit	Inspected
Condition Combo Citi	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Boys Locker Room - Toilets Room

### **Building Condition Assessment Survey 2023-2024**

KUZ
Response
EACH
REPLACE
PRIORITY 3
LEVEL 2
No violations recorded
Does not exist
Inspected
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
3- Fair
No deficiencies recorded
Does not exist
Does not exist
Inspected
Inspected
3- Fair
DEFECTIVE/DETERIORATED
MER 254 @ Gym Blower 4
1
EACH
REPLACE
PRIORITY 3
LEVEL 2
No violations recorded
Does not exist
Inspected 3- Fair
RADIATOR/CONVECTOR: DAMAGED GUARD/SHIELD
Toilet Room 117
1
EACH
REPLACE
PRIORITY 3
LEVEL 2
No violations recorded
Inspected
Inspected
1- Good
No deficiencies recorded
Inspected
3- Fair
DEFECTIVE/LEAKS
MER 116 @ Kitchen Blower
10
L.F.
REPLACE
REPLACE PRIORITY 3 LEVEL 2

Mechanical Inspection	KU2 /

eur =sp eerre.r		1102
nestion	Response	
HEATING		
Steam Heating		
MER Steam and Condensate Piping		
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	MERs 116, 254	
Deficiency Quantity	60	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam Condensate Return Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Pumping System	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Steam Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Terminal Unit Thermostatic Trap	<del>-</del>	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Locker Rooms	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
HEATING PLANT	Inspected	
Instance on Basement	Inspected	
Is there a water meter on the boiler make-up water piping?	No	
Burner Manufacturer	Preferred Utilities	
Burner Model	BHE6V3A4	
Burner Type	Oil	
Heating Plant Oil Number	2	
Boiler Auxiliaries		
Instance on Basement	Inspected	
Boiler Auxiliary Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on Basement	Does not exist	
motanice on Dascinent	Does not exist	
Boiler Feedwater Treatment(Automatic)		

	_
uestion	Response
HEATING PLANT	
Boiler Auxiliaries	
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	BOILER BREECHING: DEFECTIVE
Deficiency Location/Instance	Boiler Room @ Boiler #1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Does not exist
Boiler Room Steam And Condensate Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE ISOLATION VALVE
Deficiency Location/Instance	Boiler Room @ Boiler #2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler System	
Instance on Basement	Inspected
Coal-fired Boiler	
Instance on Basement	Does not exist
Hot Water Boiler	DOGS HOT CAIST
Instance on Basement	Does not exist
	Does not exist
Modular Boiler	D
Instance on Basement	Does not exist
Steam Boiler	Y 1
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,725
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	National Radiator Corp. (NRC)
EquipmentId	50202-1
Capacity/Size Quantity	4725
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Documented
Installation Year	1963
Source of Installation Year	Documented
Deficiency	DEFECTIVE AUXILIARY (GAUGES, GASKETS ETC.)

### **Building Condition Assessment Survey 2023-2024**

R027

**Mechanical Inspection** 

Source of Installation Year

Deficiency Quantity

Deficiency

Violations

Deficiency

Question	Response	
HEATING PLANT		
Boiler System		
Steam Boiler		
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	DAMAGED REFRACTORY	
Deficiency Quantity	20	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	4,725	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	National Radiator Corp. (NRC)	
EquipmentId	50202-2	
Capacity/Size Quantity	4725	
Capacity/Size UOM	MBH Net	
Source of Capacity/Size	Documented	
Installation Year	1963	

Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE AUXILIARY (GAUGES, GASKETS ETC.)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

Documented

20

DAMAGED REFRACTORY

No violations recorded

DEFECTIVE SAFETY AUXILIARY: LOW-WATER CUT-OFF,

	WATER COLUMN ASSEMBLY
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5

Purpose of Action LEVEL 6
Violations No violations recorded

Instance Boiler Room
Instance Condition 3- Fair
Instance Quantity 4.725

 Instance Quantity
 4,725

 Instance Quantity Uom
 MBH NET

 Cast Iron Boiler?
 No

Manufacturer
National Radiator Corp. (NRC)
EquipmentId
50202-3

Mechanical Inspection	R027
-----------------------	------

stion	Response
EATING PLANT	
Boiler System	
Steam Boiler	4725
Capacity/Size Quantity	4725
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Documented 1963
Installation Year Source of Installation Year	
	Documented DAMA GEO REFER A GEORY
Deficiency Deficiency Quantity	DAMAGED REFRACTORY
	20 G.F.
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE AUXILIARY (GAUGES, GASKETS ETC.)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE SAFETY AUXILIARY: LOW-WATER CUT-OFF, WATER COLUMN ASSEMBLY
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Fuel System	
Instance on Basement	Inspected
Boiler Fresh Air Louver/Damper	
Instance on Basement	Inspected
Instance Condition	3- Fair
Туре	Automatic
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Basement	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	OIL BURNER:DEFECTIVE
Deficiency Location/Instance	Boiler Room @ Boilers #1, #2
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	OIL BURNER:DEFECTIVE

Mechanical Inspection	RU.	<i>2</i> /
Question	Response	

Question	Response
HEATING PLANT	
Fuel System	
Burner/Burner Control Panel	
Deficiency Location/Instance	Boiler Room @ Boiler #3
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fuel Oil Storage/Supply System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	FUEL OIL LEVEL GAUGE:DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Gas Trains And Vent At The Boiler	
Instance on Basement	Does not exist
Enclosed IDF Room	Inspected
Instance on Rooms 142A, 218A, 342A	Inspected
Dedicated A/C Equipment	
Instance on Rooms 142A, 218A, 342A	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DOES NOT EXIST
Deficiency Location/Instance	Rooms 142A, 218A, 342A
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
KITCHEN	Inspected
Instance on 1st Floor	Inspected
CO Detector	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Gas System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Grease Trap	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE/CLOGGED
Deficiency Location/Instance	Kitchen
Deficiency Location/instance Deficiency Quantity	l
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3

Mechanical Inspection	R027
Question	Response

2		
Question	Response	
KITCHEN		
Grease Trap		
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Hood		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hot Water Temperature Booster		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	MISSING INDIRECT WASTE	
Deficiency Location/Instance	Kitchen (1 of 4)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
MDF Room	Inspected	
Instance on Room 258	Inspected	
Dedicated A/C Equipment		
Instance on Room 258	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Inspected	
Instance on Room 353	Inspected	
Alternative Use	No	
Instance on Rooms 339, 343, 347, 350	Inspected	
Alternative Use	Yes	
	ics	
Acid Waste Neutralizing Tank Instance on Room 353	Does not exist	
	Does not exist	
Instance on Rooms 339, 343, 347, 350  CO Detector	Does not exist	
Instance on Room 353	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE/MISSING	

Mechanical Inspection	R027

estion	Response	
CIENCE DEMO ROOM		
CO Detector		
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Instance on Rooms 339, 343, 347, 350	Not required	
Emergency Shower		
Instance on Room 353	Does not exist	
Instance on Rooms 339, 343, 347, 350	Does not exist	
Eye Wash		
Instance on Room 353	Does not exist	
Instance on Rooms 339, 343, 347, 350	Does not exist	
Hood Exhaust Ductwork		
Instance on Room 353	Does not exist	
Instance on Rooms 339, 343, 347, 350	Does not exist	
Hood Exhaust Fan		
Instance on Room 353	Does not exist	
Instance on Rooms 339, 343, 347, 350	Does not exist	
Fixed Laboratory Hood		
Instance on Room 353	Does not exist	
Instance on Rooms 339, 343, 347, 350	Does not exist	
Laboratory Sink		
Instance on Room 353	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 339, 343, 347, 350	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit		
Instance on Room 353	Does not exist	
Instance on Rooms 339, 343, 347, 350	Does not exist	
CIENCE LAB	Inspected	
Instance on Room 357A	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank		
Instance on Room 357A	Does not exist	
CO Detector		
Instance on Room 357A	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Emergency Shower		
Instance on Room 357A	Does not exist	
Eye Wash		
Instance on Room 357A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on Room 357A	Does not exist	
Hood Exhaust Fan		
Instance on Room 357A	Does not exist	

Mechanical Inspection	R027

nestion	Response	
SCIENCE LAB		
Fixed Laboratory Hood		
Instance on Room 357A	Does not exist	
Laboratory Sink		
Instance on Room 357A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit		
Instance on Room 357A	Does not exist	
CIENCE PREP ROOM	Inspected	
Instance on Room 355	Inspected	
Alternative Use	No	
Instance on Rooms 341, 349	Inspected	
Alternative Use	Yes	
Acid Waste Neutralizing Tank		
Instance on Room 355	Does not exist	
Instance on Rooms 341, 349	Does not exist	
CO Detector		
Instance on Room 355	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE/MISSING	
Deficiency Location/Instance	Room 355	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Instance on Rooms 341, 349	Not required	
Emergency Shower		
Instance on Room 355	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 341, 349	Does not exist	
Eye Wash		
Instance on Room 355	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 341, 349	Does not exist	
Hood Exhaust Ductwork		
Instance on Room 355	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 341, 349	Does not exist	
Hood Exhaust Fan		
Instance on Room 355	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 341, 349	Does not exist	
Fixed Laboratory Hood		
Instance on Room 355	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 341, 349	Does not exist	

### **Building Condition Assessment Survey 2023-2024**

inical Inspection	KU
uestion	Response
SCIENCE PREP ROOM	
Laboratory Sink	
Instance on Room 355	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 341, 349	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Room 355	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 341, 349	Does not exist
<u> </u>	
PRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Head	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Rooms 106A, 106B, 134, 137, 138, 140A, 156A, 208, 252, 253, 365, 367 (painted, 68)
Deficiency Quantity	68
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	DEFECTIVE
Deficiency Location/Instance	Room 201 - Fan Room / Band Practice Room Exhaust Fan
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected

### **Building Condition Assessment Survey 2023-2024**

uestion	Response
VENTILATION	
Metal Ductwork	
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	Yes
Deficiency	DEFECTIVE REGISTER/DIFFUSER
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Supply Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-5
Deficiency	No deficiencies recorded
Unit Ventilator	Does not exist