#### **Building Condition Assessment Survey 2023-2024**

**Electrical Inspection** R031

Asset:	P.S. 31 - STATEN ISLAND, 55 LAYTON AVENUE, STATEN ISLAND, NY, 10301			
Inspection Id	on Id Inspection Type Time In Last Edited			
4306	ELECTRICAL	2024-03-28 07:25AM	2024-04-16 02:35PM	

1	sset	Data	

et Data	
Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Partial Molded Case Circuit Breaker Panel Board
	Years: 2024, 2017, 2010, 1990
	Systems: Lightning Protection System, Gymnasium LED Lighting, Partial Motor Starters
	Years: 2024
	Systems: IPDVS/CCTV System
	Years: 2022
	Systems: Partial Switchboard
	Years: 2020
	Systems: Interior Lighting (Except Library, Science Lab Room 202/204) Emergency Lighting (Non Battery Pack), Auditorium (Projection System), Partial Exit Lights (Battery Pack)
	Years: 2016
	Systems: Partial Security Lighting
	Years: 2010, 2000
	Systems: Science Lab Room 202/204
	Years: 2010
	Systems: Library
	Years: 2008
	Systems: Intrusion Alarm System
	Years: 2002
	Systems: Public Address System, Local Sound System, Emergency Light/Exit Light Panel, Fire Alarm System (Except Fused Cutout Panel, Tamper Flow Switch/Chain)
	Years: 2001
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes

#### DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Water Penetration In Electrical Room?

DEDICATED INTERCOMO INTIRE RESCUETAREMO	
Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No
your huilding?	

Yes

#### **Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Fire Alarm System - Components Not Operational	Fire Alarm Digital Communicator is out of order.	Fire Alarm System - Digital Communicato r	Electrical Room	Edwin Acosta	Fireman	
Yes	Fire Alarm System - Components Not Operational	Fire Alarm Magnetic Door holders are out of order	Fire Alarm System - Magnetic Door Holder/Contac tor	Corridor by Rooms: 106 and 308	Edwin Acosta	Fireman	No Photo Taken

## **Building Condition Assessment Survey 2023-2024**

	Inspection						R031
Yes	Water Leaks onto Electrical Equipment	Water penetrates through ceiling	FDNY box	Basement corridor by Boiler Room	Edwin Acosta	Fireman	
No	Water Penetration in Electrical Room	Water penetrates through CT Cabinet	Electrical Equipment	Basement - Electrical Room	Edwin Acosta	Fireman	
Inspectio	n						
Questio	n			Response	2		
Electric	al						
ATHI	LETIC FIELD			Does not	exist		
AUDI	TORIUM			Inspected			
	Instance on 2nd Floor			Inspected			
Hou	se Lighting						

uestion	Response
lectrical	-
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 2nd Floor	Inspected
House Lighting	
Instance on 2nd Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Installation Year	2001
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE

## **Building Condition Assessment Survey 2023-2024**

iricai Inspection	KUJ
Question	Response
AUDITORIUM	
Local Sound System	
Deficiency Location/Instance	Auditorium-2nd Floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 2nd Floor	Inspected
Dimming System	
Instance on 2nd Floor	Does not exist
Theater Lighting	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	34
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	2001
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1

## **Building Condition Assessment Survey 2023-2024**

intent Inspection		1051
Question	Response	
CAFETERIA		
Local Sound System		
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 2nd Floor	Inspected	
Lighting	1	
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted	Does not exist	
Instance on 2nd Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Recessed Mounted	110 deficiences recorded	
Instance on 2nd Floor	Does not exist	
	DOCS HOL CYIST	
Local Sound System  Instance on 2nd Floor	Inspected	
	Inspected 5- Poor	
Installation Year	5- Poor 2001	
Source of Installation Year	Documented	
Deficiency	Documented	

## **Building Condition Assessment Survey 2023-2024**

nestion	Response	
GYMNASIUM		
Local Sound System		
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 2nd Floor	Does not exist	
Scoreboard		
Instance on 2nd Floor	Does not exist	
Theater Lighting System		
Instance on 2nd Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	2000 1000 0.1100	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 1st Floor	Does not exist	
LIBRARY 2 151	Inspected	
Instance on 2nd Floor	Inspected	
Lighting	Incurated	
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent	T 1	
Instance on 2nd Floor	Inspected	
Pendant Mounted	Y 1	
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	

# **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	KUSI

icui Inspection		
uestion	Response	
LIBRARY		
Lighting		
Lighting Fixture - LED		
Instance on 2nd Floor	Does not exist	
Raceway With Receptacles		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 2nd Floor	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 202/204	Inspected	
Power Panel?	Yes	
Alternative Use	No	
	INO	
Lighting Instance on Room 202/204	Inspected	
Lighting Fixture - Fluorescent	nispected	
Instance on Room 202/204	Inspected	
Pendant Mounted	inspected	
Instance on Room 202/204	Inspected	
Instance Condition	3- Fair	
	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Surface Mounted	D	
Instance on Room 202/204	Does not exist	
Recessed Mounted		
Instance on Room 202/204	Does not exist	
Lighting Fixture - HID	T 1	
Instance on Room 202/204	Inspected	
Pendant Mounted		
Instance on Room 202/204	Does not exist	
Surface Mounted		
Instance on Room 202/204	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 202/204	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 202/204	Does not exist	
Lighting Fixture - LED		
Instance on Room 202/204	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 202/204	Does not exist	
Emergency Shut-Off Power		
Instance on Room 202/204	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 202/204  Instructor Unit	Inspected	
Instance on Room 202/204	Inspected	

## **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	RUSI

Question	Response
SCIENCE LAB	
Power Supply	
Instructor Unit	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 202/204	Does not exist
Student Unit	
Instance on Room 202/204	Does not exist
Projection System	
Instance on Room 202/204	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	5- Poor
Deficiency	BELL TRANSFORMER PANEL NOT OPERATIONAL
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
	3- Fair No deficiencies recorded

## **Building Condition Assessment Survey 2023-2024**

nestion	Response	
EMERGENCY LIGHTING	K** ***	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	7	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 4	
Violations	35672811N	
Non Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Does not exist	
<b>Duct Smoke Detector</b>	Does not exist	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Inspected	
Condition	3- Fair	
Deficiency	CONTACTOR NOT OPERATIONAL	
Deficiency Location/Instance	Corridor by Rooms 106 and 308	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
•		
Fire Alarm Digital Communicator	Inspected	

## **Building Condition Assessment Survey 2023-2024**

uestion	Response	
FIRE ALARM SYSTEM	Tessponse .	
Fire Alarm Digital Communicator		
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Ademco	
EquipmentId	Fire Alarm Communicator	
Installation Year	2001	
Source of Installation Year	Documented	
Deficiency	COMMUNICATOR NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Notifier	
Model	AFP - 400	
EquipmentId	Fire Alarm Panel	
Installation Year	2001	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Does not exist	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Does not exist	
Main Equipment Rack (MDF)	Inspected	

## **Building Condition Assessment Survey 2023-2024**

incui Inspection		11051
Question	Response	
LAN		
Main Equipment Rack (MDF)		
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Inspected	
Condition	3- Fair	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance	Fan Room by Kitchen, Boiler Room	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Inspected	
Condition	3- Fair	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	12	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Main Office - Room 127	
Instance Condition	3- Fair	
Instance Quantity	1 EACH	
Instance Quantity Uom	EACH	
Model	Telecor 250	
Installation Year	2001	
Source of Installation Year	Documented	
Deficiency	CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	20	

## **Building Condition Assessment Survey 2023-2024**

KUSI
rded
corded
corded
corded
corded
corded
corded
NOT OPERATIONAL
ll .
rded
corded
ectric
nt. Main Panel

## **Building Condition Assessment Survey 2023-2024**

nicui inspection	N.
Question	Response
SERVICE SWITCH	
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	LGT SERV. SW
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Empire Switchboard
Manufacturer	PWR SERV. SW
EquipmentId	
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Nameplate
Source of Capacity/Size	Namepiate 1965
Installation Year Source of Installation Year	Documented
	BEYOND USEFUL LIFE
Deficiency	
Deficiency Location/Instance Deficiency Quantity	Electrical Room
	1 EAGH
Quantity Uom	EACH PER A CE
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electric Switchboard

## **Building Condition Assessment Survey 2023-2024**

cirical Inspection	KUJ
Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
EquipmentId	PWR Distribution
Capacity/Size Quantity	938
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	LTG Distribution
Capacity/Size Quantity	1200
Capacity/Size Quantity  Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	l
Quantity Uom	EACH DEDY A CE
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Capacity/Size Quantity	400
Capacity/Size Quantity  Capacity/Size UOM	
Capacity/Size 2 Quantity	Amps Total 1
Capacity/Size 2 Quantity Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
	2020
Installation Year Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected

# **Building Condition Assessment Survey 2023-2024**

uestion	Response	
TELEPHONE SYSTEM		
PBX/Intercom		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	