Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Asset:	P.S. 32 - STATEN ISLAND, 232 BARLOW AVENUE, STATEN ISLAND, NY, 10308			
Inspection Id	Inspection Type	ſ	fime In	Last Edited
4534	MECHANICAL	2	2024-04-05 07:20AM	2024-06-20 01:19PM
Asset Data				
Question		Answer		

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Boiler Feedwater System; Steam Condensate Return
	Pumping System
	Years: 2023
	Systems: F&T/Steam Drip Traps; Terminal Unit Thermostatic
	Traps; Boiler Feedwater Treatment (Automatic)
	Years: 2022
	Systems: Climate Control System - BMS
	Years: 2021
	Systems: Kitchen - Grease Trap; Electric Domestic Water Heater
	for Kitchen; MDF Room - Dedicated A/C Equipment
	(DX Split System)
	Years: 2018
	Systems: Fixtures - Toilets, Urinals
	Years: 2015
Are there fuel tanks?	Yes
Total # of above ground tanks	2
Total capacity of all above ground tanks in gal.	15,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	MER B14
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Boiler Room - Paint Room; Rooms B6, B8, B11, 151, 227, 329
	(painted, 17)
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No condi	tion recorded						
nspection	1						
Question	I			Response	;		
Mechani	cal						
AIR C	ONDITIONING			Inspected			
Chill	ed Water System			Does not	exist		
Cond	Condenser Water Distribution: Piping, Pumps and Auxiliaries Does not exist						
Cooli	ing Coil in Ductwor	k	Does not exist				
Cooli	ing Tower			Does not	exist		
DX S	plit System			Inspected			
Ind	loor Unit			Inspected			
С	ondition		2- Between Good and Fair				
	Deficiency		No deficiencies recorded				
Ou	tdoor Unit			Inspected			
C	ondition			2- Betwee	en Good and Fa	ir	
Deficiency				No defici	encies recorded		
Dry Cooler			Does not	exist			
Pack	aged / Rooftop Unit			Does not	exist		
	aged Terminal A/C			Does not	exist		
	gerant Leak Detecti	ion System		Does not	exist		
Refri	gerant Piping			Inspected			
Cor	ndition	ition 2- Between Good and Fair					

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

uestion		Response
AIR CON	NDITIONING	
	erant Piping	
0	Deficiency	No deficiencies recorded
Return	Fan	Does not exist
CENTRA	AL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMAT	TE CONTROL SYSTEM	Inspected
BMS		Inspected
Dillo	Instance	Throughout except Auditorium, Cafeteria, Gymnasium (WPT System)
	Instance Condition	1- Good
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Building Area Covered by Operational System	81-100%
	Installation Year	2021
	Source of Installation Year	Documented
	Deficiency	DEFECTIVE LOCAL CONTROL PANEL
	Deficiency Location/Instance	Custodian's Office (BMS Computer)
	Deficiency Quantity	1
	Quantity Uom	EACH
	Potential Action	MAINTENANCE
	Urgency of Action	PRIORITY 3
	Purpose of Action	LEVEL 2
	Violations	No violations recorded
Pneum	atic System	Inspected
	Instance	Auditorium, Cafeteria, Gymnasium
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Building Area Covered by Operational System	81-100%
	Deficiency	No deficiencies recorded
	System	Does not exist
	c System	Does not exist
COMPA	CTOR	Does not exist
CONVEY	YING	Does not exist
DOMES	TIC WATER SYSTEM	Inspected
Domest	tic Cold Water System	Inspected
Gravi	ity System	Does not exist
Press	ure Booster System	Does not exist
Wate	r Service	Inspected
	Instance	1st Floor - Gas/Sprinkler/Water Meter Room, Crawlspace
	Instance Condition	3- Fair
	Instance Quantity	3
	Instance Quantity Uom	EACH
	Deficiency	WATER MAIN: MISSING BACKFLOW PREVENTION DEVICE
	Deficiency Location/Instance Deficiency Quantity	1st Floor - Gas/Sprinkler/Water Meter Room, Crawlspace 3
	Quantity Uom	EACH
	Potential Action	INSTALL
	Urgency of Action	PRIORITY 3
	Purpose of Action	LEVEL 2
	Violations	No violations recorded
Domest	tic Hot Water System	Inspected
	estic Hot Water Remote Storage Tank	Does not exist
Dome	estic Water Heat Exchanger	Inspected

Building Condition Assessment Survey 2023-2024

estion	Response	
OOMESTIC WATER SYSTEM	- I	
Domestic Hot Water System		
Domestic Water Heat Exchanger		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Electric Domestic Water Heater	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas Fired Domestic Water Heater	Inspected	
Instance	Boiler Room	
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1 EACH	
Instance Quantity Uom		
Manufacturer	Laars	
EquipmentId	N/A	
Capacity/Size Quantity Capacity/Size UOM	715 MBH Input	
Capacity/Size 2 Quantity	0	
Capacity/Size 2 UOM	Gallons	
Source of Capacity/Size	Documented	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	TANK RUSTY/LEAKS	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater	Does not exist	
Domestic Water Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
RAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	3- Fair	
Deficiency	INTERIOR FLOOR DRAIN: DEFECTIVE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	

NYC Department of Education Building Condition Assessment Survey 2023-2024

п	n	2	1
к		1	1

anical Inspection	R03
uestion	Response
FIXTURES	
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	CLOGGED/LEAKING
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lavatory/Sink	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Boys Toilet Room 331
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
SAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

-	RUS
estion	Response
AS SERVICE	
Gas Meter Room Vent	
Deficiency	No deficiencies recorded
Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Does not exist
EATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	RADIATOR/CONVECTOR:MISSING GUARD/SHIELD
Deficiency Location/Instance	Toilet Room 135
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
	Inspected
MER Steam and Condensate Piping	-
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	MER B14
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Crawlspace
Deficiency Quantity	40
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Pumping System	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE VALVE
Deficiency Location/Instance	Crawlspace
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

		K0.
lestion	Response	
IEATING		
Steam Heating		
Steam Piping		
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Terminal Unit Thermostatic Trap	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Does not exist	
IEATING PLANT	Inspected	
Instance on 1st Floor	Inspected	
Is there a water meter on the boiler make-up water piping?	No	
Burner Manufacturer	Preferred Utilities	
Burner Model	N/A	
Burner Type	Oil	
Heating Plant Oil Number	4	
Boiler Auxiliaries		
Instance on 1st Floor	Inspected	
Boiler Auxiliary Piping		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Feedwater Treatment(Automatic)		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Flue Exhaust		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on 1st Floor	Does not exist	
Boiler Room Steam And Condensate Piping		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Safety Valve		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler System	The deficiencies recorded	
Instance on 1st Floor	Inspected	
Coal-fired Boiler	inspected	
Instance on 1st Floor	Does not exist	
Hot Water Boiler		

Building Condition Assessment Survey 2023-2024

tion	Response
ATING PLANT	
oiler System	
Hot Water Boiler	
Instance on 1st Floor	Does not exist
Modular Boiler	
Instance on 1st Floor	Does not exist
Steam Boiler	
Instance on 1st Floor	Inspected
Instance on 1st Floor	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,720
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Pacific Steel Boiler Corporation
EquipmentId	53422-1
Capacity/Size Quantity	4720 MDU N.4
Capacity/Size UOM Source of Capacity/Size	MBH Net Documented
Installation Year	1968
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,720
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Pacific Steel Boiler Corporation
EquipmentId	53422- 2
Capacity/Size Quantity	4720
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Documented
Installation Year	1968
Source of Installation Year	Documented
Deficiency	DEFECTIVE AUXILIARY (GAUGES, GASKETS ETC.)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action Urgency of Action	MAINTENANCE PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
uel System	
Instance on 1st Floor	Inspected
Boiler Fresh Air Louver/Damper	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Туре	Automatic
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	OIL BURNER:DEFECTIVE
Deficiency Location/Instance	Boiler Room@ Boiler #2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

unicui Inspection		KU3.
uestion	Response	
HEATING PLANT		
Fuel System		
Burner/Burner Control Panel		
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fuel Oil Storage/Supply System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	FUEL OIL LEVEL GAUGE: DEFECTIVE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Gas Trains And Vent At The Boiler		
Instance on 1st Floor	Does not exist	
Enclosed IDF Room	Inspected	
Instance on Room 151	Inspected	
Dedicated A/C Equipment		
Instance on Room 151	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DOES NOT EXIST	
Deficiency Location/Instance	Room 151	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector		
Instance on 1st Floor	Not required	
Gas System		
Instance on 1st Floor	Does not exist	
Grease Trap	T (1	
Instance on 1st Floor	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Hood	Turnerated	
Instance on 1st Floor	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork	Turner of J	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan	T / 1	
Instance on 1st Floor	Inspected	
	Inspected 3- Fair No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

uestion	Response
KITCHEN	•
Hood Fire Suppression System	
Instance on 1st Floor	Does not exist
Hot Water Temperature Booster	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Kitchen Sink	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
MDF Room	Inspected
Instance on Room 329	Inspected
	Inspected
Dedicated A/C Equipment	Increated
Instance on Room 329	Inspected 2- Between Good and Fair
Instance Condition	
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Boiler Room - Paint Room; Rooms B6, B8, B11, 151, 227, 329
Denetenely Docurons instance	(painted, 17)
Deficiency Quantity	17
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Partial
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
	Does not exist
Heating And Ventilating Unit Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	5- rair Yes

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

lestion	Response
/ENTILATION	
Metal Ductwork	
Are there chain operated dampers?	No
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	MER B14
Deficiency Quantity	40
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Supply Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-5
Deficiency	No deficiencies recorded
Unit Ventilator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded