Building Condition Assessment Survey 2023-2024

Mechanical Inspection

| Asset: P.S. 38 - STATEN ISLAND, 421 LINCOLN AVENUE, STATEN ISLAND, NY, 10306 | | | |
|--|-----------------|--------------------|--------------------|
| Inspection Id | Inspection Type | Time In | Last Edited |
| 4170 | MECHANICAL | 2024-03-22 08:49AM | 2024-05-03 11:08AM |
| set Data | | | |

| Question | Answer |
|--|---|
| Have any Systems/Major Building Components been upgraded? | Systems: Boiler refractory |
| | Years: 2023 |
| | Systems: F&T/Steam Drip Traps; Terminal Unit Thermostatic |
| | Traps; Steam Condensate Return Pumping System |
| | Years: 2022 |
| | Systems: Toilet Room Fixtures (~50%); Gas Fired Furnace |
| | Years: 2021 |
| | Systems: Kitchen - Grease Trap |
| | Years: 2018 |
| | Systems: Electric Domestic Water Heaters |
| | Years: 2017 |
| | Systems: MDF Room - Dedicated A/C Equipment (DX Split |
| | System); Kitchen - Hood Fire Suppression System |
| | Years: 2015 |
| Are there fuel tanks? | Yes |
| Total # of above ground tanks | 1 |
| Total capacity of all above ground tanks in gal. | 5,000 |
| Total # of below ground tanks | 0 |
| Total capacity of all below ground tanks in gal. | 2 |
| Total # of water main service entries to the asset | 2 |
| MERs/Fan Rooms Locations | MER 28 |
| Are there any spaces with Missing or Defective CO Detectors? | Yes |
| Location(s) | Kitchen |
| Are there any Painted/Obstructed Sprinkler Heads? | No |
| Are there any Emergency Stop Switches with Missing Hammers? | No components |

Priority Condition

| Exist | Priority | Condition | Component | Location | Person(s) | Person(s) | Photo |
|------------|--------------------------------------|-------------|------------------------|-------------|----------------|-----------|-------|
| Last Year? | Category | Description | Affected | Description | Notified | Title | Image |
| Yes | Defective Boiler Safety Auxiliary | (1) | Boiler Safety Valve | Boiler Room | Peter Cowan | Fireman | |

Inspection

| Question | Response | | | |
|---|---------------------------|--|--|--|
| Mechanical | | | | |
| AIR CONDITIONING | Inspected | | | |
| Chilled Water System | Does not exist | | | |
| Condenser Water Distribution: Piping, Pumps and Auxiliaries | Does not exist | | | |
| Cooling Coil in Ductwork | Does not exist | | | |
| Cooling Tower | Does not exist | | | |
| DX Split System | Inspected | | | |
| Indoor Unit | Inspected | | | |
| Condition | 3- Fair | | | |
| Deficiency | OVER 5 TONS:DEFECTIVE FAN | | | |
| Deficiency Location/Instance | MER 28 | | | |
| Deficiency Quantity | 1 | | | |
| Quantity Uom | EACH | | | |
| Potential Action | MAINTENANCE | | | |
| Urgency of Action | PRIORITY 3 | | | |

1

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

| unicui Inspection | KU |
|---|---------------------------------------|
| uestion | Response |
| AIR CONDITIONING | |
| DX Split System | |
| Indoor Unit | |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Outdoor Unit | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Dry Cooler | Does not exist |
| Packaged / Rooftop Unit | Does not exist |
| Packaged Terminal A/C | Does not exist |
| Refrigerant Leak Detection System | Does not exist |
| Refrigerant Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | DEFECTIVE |
| Deficiency Location/Instance | MER 28 @ HVAC-2 |
| Deficiency Quantity | 10 |
| Quantity Uom | L.F. |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Return Fan | Does not exist |
| CENTRAL ACID WASTE NEUTRALIZING TANK | Does not exist |
| CLIMATE CONTROL SYSTEM | Inspected |
| BMS | Does not exist |
| Pneumatic System | Inspected |
| Instance | Original Building - Throughout |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Building Area Covered by Operational System | 41-60% |
| Deficiency | PNEUMATIC TUBING: DEFECTIVE/LEAKS AIR |
| Deficiency Location/Instance | Various Locations |
| Deficiency Quantity | 100 |
| Quantity Uom | L.F. |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Hybrid System | Does not exist |
| Electric System | Does not exist |
| COMPACTOR | Does not exist |
| CONVEYING | Does not exist |
| | |
| DOMESTIC WATER SYSTEM | Inspected |
| Domestic Cold Water System | Inspected Does not exist |
| Gravity System | |
| Pressure Booster System | Does not exist |
| Water Service | Inspected |
| Instance | Boiler Room, MER 28 |
| Instance Condition | 3- Fair |
| | 2 |
| Instance Quantity | |
| Instance Quantity Instance Quantity Uom | EACH |

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

| Question | Response |
|---|---------------------------|
| DOMESTIC WATER SYSTEM | |
| Domestic Cold Water System | |
| Water Service | |
| Deficiency Location/Instance | Boiler Room, MER 28 |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | INSTALL |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Domestic Hot Water System | Inspected Does not exist |
| Domestic Hot Water Remote Storage Tank | Inspected |
| Domestic Water Heat Exchanger | - |
| Condition | 3- Fair |
| Deficiency | NOT IN USE |
| Deficiency Location/Instance Deficiency Quantity | Boiler Room (1 of 1) 1 |
| Quantity Uom | I EACH |
| Potential Action | NO ACTION |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 1 |
| Violations | No violations recorded |
| Electric Domestic Water Heater | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Gas Fired Domestic Water Heater | Does not exist |
| Oil Fired Domestic Water Heater | Does not exist |
| Heat Pump Domestic Water Heater | Does not exist |
| Domestic Water Distribution Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| DRAIN/WASTE/VENT AND STORM SYSTEM | Inspected |
| Interior Storm Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Sewage/Waste/Vent Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Sewage Ejector Pump | Does not exist |
| Sump Pump | Does not exist |
| DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER) | Does not exist |
| FIXTURES | Inspected |
| Staff And Other | Inspected |
| Janitor Sink | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lavatory/Sink | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Toilet | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Urinal | Does not exist |
| Student | Inspected |

NYC Department of Education Building Condition Assessment Survey 2023-2024

Mechanical Inspection

| unicui Inspeciion | | KU3 |
|--|--------------------------|-----|
| uestion | Response | |
| FIXTURES | | |
| Student | | |
| Drinking Fountain | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Lavatory/Sink | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Locker Room Shower | Does not exist | |
| Sink And Fountain Combo Unit | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Toilet | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Urinal | Inspected | |
| Condition | 2- Between Good and Fair | |
| | | |
| Deficiency | No deficiencies recorded | |
| GAS FIRED FURNACE | Inspected | |
| Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| GAS SERVICE | Inspected | |
| Gas Distribution Piping | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Gas Meter Room Exhaust Fan | Does not exist | |
| Gas Meter Room Vent | Does not exist | |
| Gas Pressure Booster | Does not exist | |
| CO/Gas Leak Detection | Does not exist | |
| HEATING | Inspected | |
| Heating Coil In Ductwork | Does not exist | |
| Hydronic Heating | Does not exist | |
| Radiator/Convector/Fin Tube | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Steam Heating | Inspected | |
| F&T/Steam Drip Trap | Inspected | |
| Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| MER Steam and Condensate Piping | Does not exist | |
| Steam Condensate Return Piping | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Steam Condensate Return Pumping System | Inspected | |
| Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| Steam Piping | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Terminal Unit Thermostatic Trap | Inspected | |
| Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| Steam supplied by External Sources | Does not exist | |

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

| nicul Inspection | KU |
|--|---------------------------------------|
| estion | Response |
| EATING | |
| Unit Heater/Cabinet Heater | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| EATING PLANT | Inspected |
| Instance on 1st Floor | Inspected |
| Is there a water meter on the boiler make-up water piping? | No |
| Burner Manufacturer | Carlin |
| Burner Model | N/A |
| Burner Type | Oil |
| Heating Plant Oil Number | 2 |
| Boiler Auxiliaries | |
| Instance on 1st Floor | Inspected |
| Boiler Auxiliary Piping | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | DEFECTIVE BOILER MAKE-UP WATER PIPING |
| Deficiency Location/Instance Deficiency Quantity | Boiler Room |
| | |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Boiler Emergency Stop Switch | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Boiler Feedwater System | |
| Instance on 1st Floor | Does not exist |
| Boiler Feedwater Treatment(Automatic) | |
| Instance on 1st Floor | Does not exist |
| Boiler Flue Exhaust | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | BOILER BREECHING:DEFECTIVE |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Boiler Make-up Water Backflow Preventer | |
| Instance on 1st Floor | Does not exist |
| Boiler Room Steam And Condensate Piping | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Boiler Safety Valve | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 5- Poor |
| Deficiency | DEFECTIVE |
| Deficiency Location/Instance | Boiler Room (1 of 1) |
| Deficiency Quantity | 1 |

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

| stion | Response |
|-----------------------------------|----------------------------|
| CATING PLANT | |
| Boiler Auxiliaries | |
| Boiler Safety Valve | |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| Boiler System | |
| Instance on 1st Floor | Inspected |
| Coal-fired Boiler | |
| Instance on 1st Floor | Does not exist |
| Hot Water Boiler | |
| Instance on 1st Floor | Does not exist |
| Modular Boiler | |
| Instance on 1st Floor | Does not exist |
| Steam Boiler | |
| Instance on 1st Floor | Inspected |
| Instance on 1st Floor | Inspected |
| Instance | Boiler Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1,744 |
| Instance Quantity Uom | MBH NET |
| Cast Iron Boiler? | Yes |
| Manufacturer | H. B. Smith Co., Inc. |
| EquipmentId | 44547-1 |
| Capacity/Size Quantity | 2316 |
| Capacity/Size UOM | Lbs/Hr steam |
| Source of Capacity/Size | Documented |
| Installation Year | 1956 |
| | |
| Source of Installation Year | Documented |
| Deficiency Deficiency Quantity | DAMAGED/MISSING INSULATION |
| | 50 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| uel System | |
| Instance on 1st Floor | Inspected |
| Boiler Fresh Air Louver/Damper | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Туре | Automatic |
| Deficiency | No deficiencies recorded |
| Burner/Burner Control Panel | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Fuel Oil Storage/Supply System | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Dentency | no deficiencies recorded |

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

| uestion | | Response | |
|----------------|------------------------------------|-----------------------------|--|
| Enclosed IDF R | oom | Inspected | |
| Insta | nce on Original Building - Room 14 | Inspected | |
| Dedicated A/C | C Equipment | | |
| | nce on Original Building - Room 14 | Inspected | |
| Insta | nce Condition | 4- Between Fair and Poor | |
| Defic | viency | DOES NOT EXIST | |
| | ficiency Location/Instance | Original Building - Room 14 | |
| De | ficiency Quantity | 1 | |
| Qu | antity Uom | EACH | |
| | tential Action | INSTALL | |
| | gency of Action | PRIORITY 3 | |
| | pose of Action | LEVEL 2 | |
| Vic | olations | No violations recorded | |
| ITCHEN | | Inspected | |
| Insta | nce on 1st Floor | Inspected | |
| CO Detector | | | |
| | nce on 1st Floor | Inspected | |
| | nce Condition | 4- Between Fair and Poor | |
| | viency | DEFECTIVE/MISSING | |
| | ficiency Location/Instance | Kitchen | |
| | ficiency Quantity | 1 | |
| | antity Uom | EACH | |
| | tential Action | MAINTENANCE | |
| | gency of Action | PRIORITY 5 | |
| | pose of Action plations | LEVEL 6 | |
| - | Dations | No violations recorded | |
| Gas System | nce on 1st Floor | Does not exist | |
| Grease Trap | | | |
| | nce on 1st Floor | Inspected | |
| | nce Condition | 2- Between Good and Fair | |
| Defic | | No deficiencies recorded | |
| Hood | | | |
| | nce on 1st Floor | Inspected | |
| Insta | nce Condition | 3- Fair | |
| Defic | viency | No deficiencies recorded | |
| Hood Exhaust | | | |
| Insta | nce on 1st Floor | Inspected | |
| Insta | nce Condition | 3- Fair | |
| Defic | viency | No deficiencies recorded | |
| Hood Exhaust | t Fan | | |
| Insta | nce on 1st Floor | Inspected | |
| Insta | nce Condition | 3- Fair | |
| Defic | viency | No deficiencies recorded | |
| Hood Fire Su | ppression System | | |
| Insta | nce on 1st Floor | Inspected | |
| Insta | nce Condition | 2- Between Good and Fair | |
| Defic | iency | No deficiencies recorded | |
| Hot Water Ter | mperature Booster | | |
| | nce on 1st Floor | Does not exist | |
| Kitchen Sink | | | |
| Insta | nce on 1st Floor | Inspected | |
| Insta | nce Condition | 3- Fair | |
| Defic | iency | No deficiencies recorded | |
| MDF Room | | Inspected | |

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

| anicai Inspection | | KUJO |
|---|-----------------------------|------|
| uestion | Response | |
| MDF Room | | |
| Instance on Building Addition - Room 30 | Inspected | |
| Dedicated A/C Equipment | | |
| Instance on Building Addition - Room 30 | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| SCIENCE DEMO ROOM | Does not exist | |
| SCIENCE LAB | Does not exist | |
| SCIENCE PREP ROOM | Does not exist | |
| SPRINKLERS, STANDPIPE, FIRE SYSTEM | Does not exist | |
| SWIMMING POOL | Does not exist | |
| VENTILATION | Inspected | |
| Is the building Mechanically ventilated? | Yes | |
| Exhaust Fan | Inspected | |
| Condition | 3- Fair | |
| Approximate Total # of Fans | 1-25 | |
| Deficiency | No deficiencies recorded | |
| Heating And Ventilating Unit | Does not exist | |
| Metal Ductwork | Inspected | |
| Condition | 3- Fair | |
| Are there any uninsulated ductwork by design in Mechanical rooms? | No | |
| Are there chain operated dampers? | No | |
| Deficiency | DAMAGED/MISSING INSULATION | |
| Deficiency Location/Instance | MER 28 | |
| Deficiency Quantity | 40 | |
| Quantity Uom | L.F. | |
| Potential Action | MAINTENANCE | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| Deficiency | DEFECTIVE REGISTER/DIFFUSER | |
| Deficiency Location/Instance | Room 35 | |
| Deficiency Quantity | 1 | |
| Quantity Uom | EACH | |
| Potential Action | MAINTENANCE | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| Supply Fan | Does not exist | |
| Unit Ventilator | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |

Deficiency

No deficiencies recorded