Building Condition Assessment Survey 2023-2024

Mechanical Inspection R039

Asset:	P.S. 39 - STATEN ISLAND, 71 SAND LANE, STATEN ISLAND, NY, 10305		
Inspection Id	Inspection Type	Time In	Last Edited
3793	MECHANICAL	2024-03-07 11:24AM	2024-04-24 11:02AM
ssat Data			

inspection is inspection type			Eust Eureta
3793 MECHANICAL		2024-03-07 11:24AM	2024-04-24 11:02AM
et Data			
Question	Answer		
Have any Systems/Major Building Components been upgraded?	Systems:	Staff Fixtures - Toilets, Urinal; S Toilets	tudent Fixtures -
	Years:	2021	
	Systems:	Steam Condensate Return Pumpi	ing System (1 of 2)
	Years:	2020	
	Systems: Years: Systems:	Climate Control System - BMS; Traps; Terminal Unit Thermostat Climate Control System - Pneum Refrigerated Air Dryer, Pneumat Kitchen - Grease Trap 2019 Gas Fired Domestic Water Heate	ic Traps (~90%); tatic System: ic PRV Station;
	Years:	2016	
Are there fuel tanks?	Yes		
Total # of above ground tanks	1		
Total capacity of all above ground tanks in gal.	5,000		
Total # of below ground tanks	0		
Total capacity of all below ground tanks in gal.	0		
Total # of water main service entries to the asset	1		
MERs/Fan Rooms Locations	1st Floor	MER	
Are there any spaces with Missing or Defective CO Detectors?	No		
Are there any Painted/Obstructed Sprinkler Heads?	Yes		
Location(s)	Basement (painted, o	- Paint Room; Stairway close to R	ooms 263, 357

Priority Condition

Are there any Emergency Stop Switches with Missing Hammers?

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Other	Defective Flue Exhaust (temporarily repaired with duct tape)	Gas Fired Domestic Water Heater	Boiler Room	Tommy Donoghue	Fireman	

No components

Inspection

uestion	Response
[echanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Outdoor Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist

Building Condition Assessment Survey 2023-2024

anicai Inspection	KUS
uestion	Response
AIR CONDITIONING	
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Return Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Inspected
Instance	Building Addition - Throughout
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Building Area Covered by Operational System	0-20% 2019
Installation Year Source of Installation Year	Custodial Staff
	DEFECTIVE SYSTEM
Deficiency Deficiency	
Deficiency Location/Instance Deficiency Quantity	Building Addition - Throughout
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Inspected
Pneumatic System Instance	Original Building - Throughout
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Building Area Covered by Operational System	61-80%
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance Deficiency Quantity	Rooms 310, 313, 314 and other locations
• • •	10 FACH
Quantity Uom Potential Action	EACH MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Does not exist
Hybrid System Floridi System	Does not exist Does not exist
Electric System	Does not exist
COMPACTOR	
CONVEYING	Inspected
Dumbwaiter	Does not exist
Elevator	Does not exist
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Inspected
Condition	3- Fair
Are all the existing non-auditorium vertical handicap lifts operable?	Yes
Deficiency	No deficiencies recorded
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Does not exist

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	R039
-----------------------	------

estion	Response
OMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	A.O. Smith
Manuracturer EquipmentId	N/A
Capacity/Size Quantity	390
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	100
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2016
Source of Installation Year	Documented
Deficiency	DEFECTIVE FLUE EXHAUST
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	60
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
RAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping Condition	Inspected 3- Fair
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS

Building Condition Assessment Survey 2023-2024

Question	Response
DRAIN/WASTE/VENT AND STORM SYSTEM	
Sewage/Waste/Vent Piping	
Deficiency Location/Instance	Boiler Room, Basement near Gas Meter Room
Deficiency Quantity	40
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<u></u>	
Urinal	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	2- Between Good and Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	
Deficiency Location instance Deficiency Quantity	Boy's Toilet Room 106
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected

Building Condition Assessment Survey 2023-2024

anicai Inspection	KUSY
uestion	Response
GAS SERVICE	
Gas Distribution Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Vent	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Inspected
Instance	Basement - Boiler Room, Gas Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	1999
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
HEATING	Inspected
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	AUXILIARY (VALVE, VENT): DEFECTIVE
Deficiency Location/Instance	Main Entrance, Corridors near Stair "F/1", Room 310
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	RADIATOR/CONVECTOR:MISSING GUARD/SHIELD
Deficiency Location/Instance	Rooms 256, 263
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE PUMP
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1

Building Condition Assessment Survey 2023-2024

estion	Response
EATING	
Steam Heating	
Steam Condensate Return Pumping System	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Basement near Oil Tank Room, East Multipurpose Room, Rooms 205, 208
Deficiency Quantity	40
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<u> </u>	
IEATING PLANT	Inspected
Instance on Basement	Inspected
Is there a water meter on the boiler make-up water piping?	Yes
Observed Operational?	Yes
Burner Manufacturer	Industrial Combustion
Burner Model	N/A
Burner Type	Dual Fuel (Gas/Oil)
Heating Plant Oil Number	2
Boiler Auxiliaries	
Instance on Basement	Inspected
Boiler Auxiliary Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE BOILER MAKE-UP WATER PIPING
Deficiency Location/Instance	Boiler Room @ Boiler #2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Roiler Feedwater System	
Boiler Feedwater System Instance on Resement	Increated
Instance on Basement	Inspected
	Inspected 3- Fair FEEDWATER PUMP:DEFECTIVE

Building Condition Assessment Survey 2023-2024

iestion	Response	
HEATING PLANT	response	
Boiler Auxiliaries		
Boiler Feedwater System		
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Feedwater Treatment(Automatic)		
Instance on Basement	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Flue Exhaust		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer	1 to deficiences recorded	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Safety Valve		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler System		
Instance on Basement	Inspected	
Coal-fired Boiler		
Instance on Basement	Does not exist	
Hot Water Boiler		
Instance on Basement	Does not exist	
Modular Boiler		
Instance on Basement	Does not exist	
Steam Boiler		
Instance on Basement	Inspected	
Instance on Basement	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	2,926	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	A. L. Eastmond & Sons Inc.	
EquipmentId	7340-01	
Capacity/Size Quantity	2926	

Building Condition Assessment Survey 2023-2024

uestion	Response	
HEATING PLANT	тегропос	
Boiler System		
Steam Boiler		
Capacity/Size UOM	MBH Net	
Source of Capacity/Size	Documented	
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	2,926	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	A. L. Eastmond & Sons Inc.	
EquipmentId	7340-02	
Capacity/Size Quantity	2926	
Capacity/Size UOM	MBH Net	
Source of Capacity/Size	Documented 1999	
Installation Year Source of Installation Year	Documented	
	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Fuel System		
Instance on Basement	Inspected	
Boiler Fresh Air Louver/Damper		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Туре	Automatic	
Deficiency	No deficiencies recorded	
Burner/Burner Control Panel		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fuel Oil Storage/Supply System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
	No deficiencies recorded	-
Deficiency	No deficiencies recorded	
Gas Trains And Vent At The Boiler	T 1	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Enclosed IDF Room	Inspected	
Instance on Building Addition - Room 122	Inspected	
Dedicated A/C Equipment		
Instance on Building Addition - Room 122	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DOES NOT EXIST	
Deficiency Location/Instance	Building Addition - Room 122	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
KITCHEN	Inspected	

Building Condition Assessment Survey 2023-2024

ianicai Inspection	KU3
Question	Response
KITCHEN	
CO Detector	
Instance on 1st Floor	Not required
Gas System	
Instance on 1st Floor	Does not exist
Grease Trap	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Hood	
Instance on 1st Floor	Does not exist
Hood Exhaust Ductwork	
Instance on 1st Floor	Does not exist
Hood Exhaust Fan	
Instance on 1st Floor	Does not exist
Hood Fire Suppression System	
Instance on 1st Floor	Does not exist
Hot Water Temperature Booster	
Instance on 1st Floor	Does not exist
Kitchen Sink	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
MDF Room	Inspected
Instance on Original Building - Room 254	Inspected
Dedicated A/C Equipment	1
Instance on Original Building - Room 254	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
	Does not exist
SCIENCE LAB	
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head Condition	Inspected 4- Between Fair and Poor
Deficiency	DEFECTIVE/DETERIORATED
•	Basement - Paint Room; Stairway close to Rooms 263, 357
Deficiency Location/Instance	(painted, 6)
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
Water Gong	Does not exist
SWIMMING POOL	Does not exist

Building Condition Assessment Survey 2023-2024

uestion	Response
VENTILATION	Inspected
Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	No
Are there chain operated dampers?	No
Deficiency	No deficiencies recorded
Supply Fan	Does not exist
Unit Ventilator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded