lectrical Inspe							R0
Asset:		ISLAND, 216 CLAWS	SON STREET, STA	TEN ISLAND, I			
Inspection Id	Inspection Type				Time In		Last Edited
	ELECTRICAL				2024-03-20	08:58AM	2024-04-09 09:39AN
set Data							
Question				Answer			
Have any Syste	ms/Major Building Co	omponents been upgraded?		Systems:	Exit/Emergency Ligh	t	
				Years:	2023		
				Systems:		_	ing, Lighting - Security,
				Years:	Auditorium (Projection 2022	on Systen	n, Local Sound System)
						- alr)	
				Systems:	Exit Light (Battery Pa	ick)	
				Years:	2021	-1-4: (D	1-44 D1-)
				Systems:	Partial Emergency Li	gnung (B	attery Pack)
				Years:	2020		
				Systems:	IPDVS/CCTV System	n	
				Years:	2019	::4 D	-1 D1 D1
				Systems:	Most Molded Case C	ncuit Bre	aker panel board
				Years:	2018, 2007	A 1	System Semile S 11
				Systems:	Switchboard	ire Alarm	System, Service Switch,
				Years:	2018	L.: OT	D (
				Systems:	Most Emergency Light	hting (No	on Battery Pack)
				Years:	2013	r 1	G 1G 4
				Systems:	Public Address System	m, Local	Sound System
				Years:	2011	r · · · ·	<b>G</b> ( )
				Systems:	Auditorium (Theater	Lighting	System)
				Years:	2007		
				Systems:	Intrusion Alarm Syste	m	
m 60 :				Years: Below Gr	2004		
Type of Service		7:-49			ound		
	e Whiteboard (IWB) I on In Electrical Room			Yes No			
		FIRE RESCUE AREA	· S	NO			
Question	INTERCOMS	FIRE RESCUE AREA	1.5	]	Response		
	Life Rescue Assistan	ce Areas, Fire Rescue Area	s, and/or Holding Rooi		No		
your building	?						
riority Conditi	ion						
Exist Prio Last Year? Cate	•	Condition Description	Component Affected	Location Description	Person(s) Person Notified Title	` '	Photo
No condition re	egory	Description	Affected	Description	Notified Title		Image
nspection	corded						
Question				Response	<u> </u>		
Electrical							
ATHLETIC	FIELD			Does not	exist		
AUDITORIU	J <b>M</b>			Inspected			
-	stance on 1st Floor			Inspected			
House Ligh							
	stance on 1st Floor			Inspected			
-	oes a Chandelier Exist			No			
-	Fixture - Fluorescen	t					
-	stance on 1st Floor			Does not	exist		
	Fixture - HID				• .		
	stance on 1st Floor			Does not	exist		
	Fixture - Incandesce	nt					
In	stance on 1st Floor			Does not	exist		

Duestion	Response	
	Response	
AUDITORIUM		
House Lighting		
Lighting Fixture - LED	Y 1	
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Installation Year	2022	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		-
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor	Inspected	
	Inspected	
Lighting Instance on 1st Floor	Inspected	
	nispected	
Lighting Fixture - Fluorescent Instance on 1st Floor	Does not exist	
	Does not exist	
Lighting Fixture - HID	B	
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	B	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	

iestion	Response	
CAFETERIA		
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting Does a Chandelier Exist?	Inspected No	
	Does not exist	
Lighting Fixture - Fluorescent		
Lighting Fixture - HID	Does not exist  Does not exist	
Lighting Fixture - Incandescent		
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 3rd Floor	Inspected	
Lighting	nispected	
Instance on 3rd Floor	Inspected	
Lighting Fixture - Fluorescent	nispected	
Instance on 3rd Floor	Does not exist	
	Does not exist	
Lighting Fixture - HID		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 3rd Floor	Inspected	
Pendant Mounted		
Instance on 3rd Floor	Does not exist	
Surface Mounted		
Instance on 3rd Floor	Does not exist	
Recessed Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
	110 violations recorded	
Local Sound System Instance on 3rd Floor	Inspected	

Electrical Inspection	K04	
Question	Response	

incui inspection		1041
Question	Response	
GYMNASIUM		
Local Sound System		
Instance Condition	3- Fair	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 3rd Floor	Does not exist	
Scoreboard		
Instance on 3rd Floor	Does not exist	
Theater Lighting System		
Instance on 3rd Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
<b>Lighting Fixture - Incandescent</b>		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Inspected	
Instance on Room 314	Inspected	
Lighting		
Instance on Room 314	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Room 314	Does not exist	
Lighting Fixture - HID		
Instance on Room 314	Does not exist	
Lighting Fixture - Incandescent	2 545 100 6.1100	
Instance on Room 314	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Room 314	Inspected	
Pendant Mounted	nispected	
Instance on Room 314	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Surface Mounted		
Instance on Room 314	Does not exist	
Recessed Mounted	<u> </u>	
Instance on Room 314	Does not exist	
Raceway With Receptacles		
Instance on Room 314	Inspected	

## **Building Condition Assessment Survey 2023-2024**

iteui Inspection	IVI-
Question	Response
LIBRARY	
Raceway With Receptacles	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 314	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected  Does not exist
Lighting Fixture - Fluorescent	Does not exist  Does not exist
Lighting Fixture - HID	Does not exist  Does not exist
Lighting Fixture - Incandescent	Inspected
Lighting Fixture - LED Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Inspected
Surface Mounted	2- Between Good and Fair
Condition	No deficiencies recorded
Deficiency	
Recessed Mounted	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected  Does not exist
Lighting Fixture - Fluorescent	Does not exist  Does not exist
Lighting Fixture - HID	Does not exist  Does not exist
Lighting Fixture - Incandescent Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected  2- Between Good and Fair
Condition Deficiency	No deficiencies recorded
	Does not exist
Recessed Mounted	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance Deficiency Quantity	Boiler Room 1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded

## **Building Condition Assessment Survey 2023-2024**

icui inspection		KU41
uestion	Response	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Vestibule	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer		

## **Building Condition Assessment Survey 2023-2024**

nicui inspection	NV41
Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Model	EST
EquipmentId	Fire Alarm Control Panel
Installation Year	2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
•	Does not exist
INTERCOM SYSTEM	
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, 3rd Floor Mechanical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

Electrical Inspection	R04
Question	Response
PANEL BOARD	

Question	Response
PANEL BOARD	
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Deficiency Location/Instance	
Deficiency Quantity	Throughout the Building 8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance Deficiency Quantity	Kitchen, Cafeteria 2
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 209
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2011
Source of Installation Year	Documented
Deficiency	MICROPHONE / JACK NOT OPERATIONAL
Deficiency Location/Instance	General Office - Room 209
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 101A
Instance Condition	3- Fair

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2004
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Siren/Strobe	
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inaccessible
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Service Disconnect
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size  Installation Year	Nameplate 2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD Number of Spares	Inspected 9
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Siemens
Manufacturer	N/A
EquipmentId Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 Quantity	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
	1

## **Building Condition Assessment Survey 2023-2024**

uestion	Response	
TELEPHONE SYSTEM		
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	