## **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

Asset:	P.S. 48 - STA	TEN ISLAND, 1055 TARGEE	STREET, STAT	TEN ISLAND, N	Y, 10304		
Inspection Id	Inspection Typ	e			Time	In	Last Edited
429	9 MECHANICAI	L			2024-	-03-28 12:16PM	2024-04-11 02:25PM
Isset Data							
Question				Answer			
Have any Systems/Major Building Components been upgraded?				Systems: Years:			raps; F&T/Steam Drip ensate Piping (~50%)
				Systems:		Dedicated A/C 1	Equipment (DX Split
				Systems.		tric Domestic W	
				Years:	2021		
				Systems:	Kitchen - Gre	ase Trap	
				Years:	2018		
Are there fuel	l tanks?			No			
Total # of wat	ter main service en	tries to the asset		2			
MERs/Fan Ro	ooms Locations			Boiler Ro	om Mechanical	Area	
Are there any	spaces with Missi	ng or Defective CO Detectors?		Yes			
Location(s)				Kitchen			
	/ Painted/Obstructe	d Sprinkler Heads?		Yes			
Location(s)				Room 103	3 (painted, 2)		
Are there any	Emergency Stop S	Switches with Missing Hammers?		No compo	onents		
Priority Cond	ition						
Exist Pr	riority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year? Ca	ategory	Description	Affected	Description	Notified	Title	Image
No condition	recorded						
Inspection							
Question				Response	•		
Mechanical							
AIR CONI	DITIONING			Does not	exist		
CENTRAL	LACID WASTE N	EUTRALIZING TANK		Does not	exist		
CLIMATE	CONTROL SYS	ТЕМ		Inspected			
BMS				Under cor			
Pneumati	ic System			Does not	exist		
Hybrid S				Does not	exist		
Electric S	System			Does not	exist		
COMPAC	TOR			Does not	exist		
CONVEYI	ING			Does not	exist		
DOMESTI	IC WATER SYST	EM		Inspected			
	c Cold Water Syste			Inspected			
Gravity	y System			Does not	exist		
Pressur	re Booster System			Does not	exist		
Water S				Inspected			
indeer a	Service						
-	Service Instance			Boiler Ro	om Mechanical	Area	
]				Boiler Ro 3- Fair	om Mechanical	Area	
]	Instance				om Mechanical	Area	
	Instance Instance Condition			3- Fair	om Mechanical	Area	
	Instance Instance Condition Instance Quantity			3- Fair 1 EACH WATER M		Area G BACKFLOW	PREVENTION
	Instance Instance Condition Instance Quantity Instance Quantity U Deficiency	Jom		3- Fair 1 EACH WATER M DEVICE	MAIN:MISSING	G BACKFLOW	PREVENTION
	Instance Instance Condition Instance Quantity Instance Quantity U Deficiency Deficiency Locat	Jom tion/Instance		3- Fair 1 EACH WATER M DEVICE Boiler Ro		G BACKFLOW	PREVENTION
	Instance Instance Condition Instance Quantity Instance Quantity I Deficiency Deficiency Locat Deficiency Quan	Jom tion/Instance		3- Fair 1 EACH WATER M DEVICE Boiler Ro 1	MAIN:MISSING	G BACKFLOW	PREVENTION
	Instance Instance Condition Instance Quantity Instance Quantity I Deficiency Deficiency Locat Deficiency Quan Quantity Uom	Jom tion/Instance		3- Fair 1 EACH WATER M DEVICE Boiler Ro 1 EACH	MAIN:MISSIN( om Mechanical	G BACKFLOW	PREVENTION
	Instance Instance Condition Instance Quantity Instance Quantity U Deficiency Deficiency Locat Deficiency Quan Quantity Uom Potential Action	Jom tion/Instance tity		3- Fair 1 EACH WATER M DEVICE Boiler Ro 1 EACH INSTALL	MAIN:MISSING om Mechanical	G BACKFLOW	PREVENTION
	Instance Instance Condition Instance Quantity Instance Quantity I Deficiency Deficiency Locat Deficiency Quan Quantity Uom	Jom tion/Instance tity		3- Fair 1 EACH WATER M DEVICE Boiler Ro 1 EACH	MAIN:MISSING om Mechanical , Y 3	G BACKFLOW	PREVENTION

R048

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

unicui Inspeciion	IX0'		
uestion	Response		
DOMESTIC WATER SYSTEM			
Domestic Cold Water System			
Water Service			
Instance	Boiler Room		
Instance Condition	4- Between Fair and Poor		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE		
Deficiency Location/Instance	Boiler Room		
Deficiency Quantity	1		
Quantity Uom	EACH		
Potential Action	INSTALL		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
Deficiency	WATER MAIN: DEFECTIVE VALVE		
Deficiency Location/Instance Deficiency Quantity	Boiler Room 2		
Quantity Uom	EACH		
Potential Action	REPLACE		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
Domestic Hot Water System	Inspected		
Domestic Hot Water Remote Storage Tank	Under construction		
Domestic Water Heat Exchanger	Does not exist		
Electric Domestic Water Heater	Inspected		
Condition	1- Good		
Deficiency	No deficiencies recorded		
Gas Fired Domestic Water Heater	Under construction		
Oil Fired Domestic Water Heater	Does not exist		
Heat Pump Domestic Water Heater	Does not exist		
Domestic Water Distribution Piping	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected		
Interior Storm Piping	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
Sewage/Waste/Vent Piping	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
Sewage Ejector Pump	Under construction		
Sump Pump	Does not exist		
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist		
FIXTURES	Inspected		
Staff And Other	Inspected		
Janitor Sink	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
	Inspected		
Lavatory/Sink Condition	3- Fair		
Condition			

R048

# NYC Department of Education **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

uestion	Response	
FIXTURES	1	
Staff And Other		
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
GAS FIRED FURNACE		
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected 3- Fair	
Condition	No deficiencies recorded	
Deficiency		
Gas Meter Room Exhaust Fan	Does not exist Does not exist	
Gas Meter Room Vent Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Under construction	
HEATING	Inspected	
Heating Coil In Ductwork	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hydronic Heating	Does not exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Heating	Inspected	
F&T/Steam Drip Trap	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
MER Steam and Condensate Piping	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Pumping System	Under construction	
	Inspected	
Steam Piping Condition	3- Fair	

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

iestion		Response	
HEATING		*	
Steam H			
	Piping		
	Deficiency	No deficiencies recorded	
-	nal Unit Thermostatic Trap	Inspected	
Cond		1- Good	
	Deficiency	No deficiencies recorded	
	ipplied by External Sources	Does not exist	
	ater/Cabinet Heater	Inspected	
Condit		3- Fair	
	Deficiency	No deficiencies recorded	
	G PLANT	Inspected	
EATIN	Instance on Basement	Under construction	
	IDF Room	Inspected	
		-	
	Instance on Original Building - Room 125	Inspected	
Dedicate	ed A/C Equipment Instance on Original Building - Room 125	Inspected	
		4- Between Fair and Poor	
	Instance Condition Deficiency	DOES NOT EXIST	
	Deficiency Location/Instance	Original Building - Room 125	
	Deficiency Quantity	l	
	Quantity Uom	EACH	
	Potential Action	INSTALL	
	Urgency of Action	PRIORITY 3	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
KITCHEN		Inspected	
ui entri	Instance on 1st Floor	Inspected	
CO Dete			
CO Deu	Instance on 1st Floor	Inspected	
	Instance Condition	4- Between Fair and Poor	
	Deficiency	DEFECTIVE/MISSING	
	Deficiency Location/Instance	Kitchen	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	MAINTENANCE	
	Urgency of Action	PRIORITY 5	
	Purpose of Action	LEVEL 6	
	Violations	No violations recorded	
Gas Syst	tem		
·	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Grease 7	Frap		
	Instance on 1st Floor	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
Hood	-		
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood Fx	chaust Ductwork		
1000 EA	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

Duestion	Response	
	Response	
KITCHEN Hood Exhaust Ductwork		
Deficiency	No deficiencies recorded	
Hood Exhaust Fan	No deficicites recorded	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hot Water Temperature Booster		
Instance on 1st Floor	Does not exist	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Original Building - Room inside Room 323	Inspected	
Dedicated A/C Equipment Instance on Original Building - Room inside Room 323	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Does not exist	
Sprinkler Head Condition	Inspected 3- Fair	
Deficiency	DEFECTIVE/DETERIORATED	
Deficiency Location/Instance Deficiency Quantity	Room 103 (painted, 2) 2	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Sprinkler Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standpipe System	Does not exist	
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Partial	
Exhaust Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-25	

#### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

lestion	Response		
VENTILATION			
Heating And Ventilating Unit	Does not exist		
Metal Ductwork	Inspected		
Condition	3- Fair		
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes		
Are there chain operated dampers?	Yes		
Deficiency	DAMAGED FLEXIBLE CONNECTION		
Deficiency Location/Instance	Boiler Room Mechanical Area @ Playroom Blower		
Deficiency Quantity	1		
Quantity Uom	EACH		
Potential Action	MAINTENANCE		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
Supply Fan	Inspected		
Condition	3- Fair		
Approximate Total # of Fans	1-5		
Deficiency	No deficiencies recorded		
Unit Ventilator	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		

R048