Building Condition Assessment Survey 2023-2024

ectrical Insp	ection					R0
Asset:	P.S. 50 - STATEN I	ISLAND, 200 ADELAIDI	E AVENUE, STA	TEN ISLAND,	NY, 10306	
Inspection Id	Inspection Type				Time In	Last Edited
3207	ELECTRICAL				2024-02-14 07:28AM	2024-03-06 12:50PM
set Data						
Question				Answer		
Have any Syste	ems/Major Building Con	nponents been upgraded?		Systems:	Partial Emergency Lights Non I	Battery Pack
				Years:	2023, 2013	
				Systems:	LAN, Partial Emergency Lights	Battery Pack
				Years:	2023	
				Systems:	IPDVS/CCTV System	
				Years:	2019	
				Systems:		
				Years:	2018, 2004	
				Systems:	• •	Emergency Lights
				Years:	2018	
				Systems:	•	
				Years:	2017 Partial Maldad Casa Circuit Pres	polson Donal Dara 1
				Systems:		eaker Panel Board
				Years:	2016, 2012, 2005, 2000	
				Systems: Years:	Service Switch, Switchboard 2016	
				Systems:)
				Years:	2015	,
				Systems:		
				Years:	2013	
				Systems:		ev Lighting (Battery
				-,	Pack)	,gg ()
				Years:	2012	
				Systems:	•	Sound System, Fire
				**	Alarm System	
				Years:	2008 Emangan av Light/Evit Light Pa	mal Intervaion Alama
				Systems:	Emergency Light/Exit Light Par System	nei, intrusion Alarm
				Years:	2006	
Type of Service	e			Below G	round	
	re Whiteboard (IWB) Ex	tist?		Yes		
	ion In Electrical Room?			No		
DEDICATE	D INTERCOMS IN I	FIRE RESCUE AREAS				
Question					Response	
-		e Areas, Fire Rescue Areas, ar	nd/or Holding Room	ns in	No	
your building						
iority Condit		C W	<u> </u>	¥	D () D ()	nı ,
	•	Condition Description	Component Affected	Location Description	* / / / / /	Photo Image
No condition re		Description	Milecteu	Description	Totalica Title	
	corded					
spection						
Question				Response	e	
Electrical						
ATHLETIC	FIELD			Does not	exist	
AUDITORI	UM			Inspected	1	
Ir	stance on 1st Floor			Inspected	I	
House Lig						
	stance on 1st Floor			Inspected	I	
D	oes a Chandelier Exist?			No		

Lighting Fixture - Fluorescent

Building Condition Assessment Survey 2023-2024

uestion	Response	
AUDITORIUM		
House Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	9	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Does not exist	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency Deficiency Quantity	LIGHTING FIXTURE BEYOND USEFUL LIFE 32	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
CAFETERIA	Inspected	
Instance on Basement	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection	R050
Question	Response

Question	Response
CAFETERIA	•
Lighting	
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Installation Year	2008
Source of Installation Year	Documented
Deficiency Deficiency	No deficiencies recorded
Projection System Instance on Basement	Does not exist
	Does not exist
Theater Lighting System Instance on Basement	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Lighting_	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	

Building Condition Assessment Survey 2023-2024

Electrical Inspection		R050
Question	Response	

Question	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL	
Deficiency Quantity	12	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	

Building Condition Assessment Survey 2023-2024

rical Inspection		RUS
Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - LED		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on Room 209	Inspected	
Lighting		
Instance on Room 209	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 209	Inspected	
Pendant Mounted		
Instance on Room 209	Does not exist	
Surface Mounted		
Instance on Room 209	Does not exist	
Recessed Mounted		
Instance on Room 209	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 209	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 209	Does not exist	
Lighting Fixture - LED		
Instance on Room 209	Does not exist	
Raceway With Receptacles		
Instance on Room 209	Does not exist	
Projection System		
Instance on Room 209	Does not exist	
LOCKER ROOM	Inspected	
Instance on 1st Floor - Boys, 2nd Floor - Girls	Inspected	
Alternative Use	Yes	
Lighting	100	
Instance on 1st Floor - Boys, 2nd Floor - Girls	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 1st Floor - Boys, 2nd Floor - Girls	Inspected	
Pendant Mounted		
Instance on 1st Floor - Boys, 2nd Floor - Girls	Does not exist	
Surface Mounted	2000 1100 011100	
Instance on 1st Floor - Boys, 2nd Floor - Girls	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	100 deficieles recorded	
Instance on 1st Floor - Boys, 2nd Floor - Girls	Does not exist	
	DOCS HOL CAISE	
Lighting Fixture - HID Instance on 1st Floor - Boys, 2nd Floor - Girls	Does not exist	
	DOES HOT CYIST	
Lighting Fixture - Incandescent Instance on let Floor, Boys, 2nd Floor, Girls	Does not exist	
Instance on 1st Floor - Boys, 2nd Floor - Girls	DOC2 HOLEYISI	
Lighting Fixture - LED	Dean wat arrive	
Instance on 1st Floor - Boys, 2nd Floor - Girls	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Room 205	Inspected	

Building Condition Assessment Survey 2023-2024

· · · · · · · · · · · · · · · · · · ·		11000
Question	Response	
SCIENCE DEMO ROOM		
Alternative Use	No	
Lighting		
Instance on Room 205	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on Room 205	Inspected	
Pendant Mounted	•	
Instance on Room 205	Does not exist	
Surface Mounted		
Instance on Room 205	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 205	Does not exist	
Lighting Fixture - HID		
Instance on Room 205	Does not exist	
Lighting Fixture - Incandescent	Does not enter	
Instance on Room 205	Does not exist	
Lighting Fixture - LED	Does not enter	
Instance on Room 205	Does not exist	
Emergency Gas Shut-Off Valve	Does not exist	
Instance on Room 205	Does not exist	
Emergency Shut-Off Power	Does not enter	
Instance on Room 205	Does not exist	
Power Supply	Does not enter	
Instance on Room 205	Does not exist	
Projection System		
Instance on Room 205	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected Peac not exist	
Pendant Mounted	Does not exist Inspected	
Surface Mounted Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
	Does not exist Does not exist	
Lighting Fixture - HID	Does not exist Does not exist	
Lighting Fixture - Incandescent	Does not exist Does not exist	
Lighting Fixture - LED		
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Recessed Mounted Lighting Fixture - HID Lighting Fixture - Incandescent	Does not exist Does not exist Does not exist	

Building Condition Assessment Survey 2023-2024

icai inspection		KUSU
uestion	Response	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
	Inspected	
Battery Pack Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
	*	
Battery Pack Condition	Inspected 3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Non Battery Pack Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT/EMERGENCY LIGHT	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected 2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected 2- Between Good and Fair	
Condition Deficiency	No deficiencies recorded	
· · · · · · · · · · · · · · · · · · ·		
Fan Shutdown Control Condition	Inspected 2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Elevator Recall Magnetic Door Holder/Contactor	Does not exist Does not exist	
Fused Cutout Panel	Inspected	

Building Condition Assessment Survey 2023-2024

teat inspection		11000
uestion	Response	
FIRE ALARM SYSTEM		
Fused Cutout Panel		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Under construction	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year Source of Installation Year	2008 Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Does not exist	
Main Equipment Rack (MDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
MOTOR CONTROLLER MOTOR CONTROL CENTER	Does not exist	
	DOES HOLEXISE	
MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR Condition	Inspected 3- Fair	

Building Condition Assessment Survey 2023-2024

KU5
Response
Does not exist
Inspected
Does not exist
Does not exist
Inspected
3- Fair
PANEL BOARD BEYOND USEFUL LIFE
Auditorium
1
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No violations recorded
Inspected
3- Fair
PANEL BOARD BEYOND USEFUL LIFE
Throughout the Building
16
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No violations recorded
Inspected
Main Office
3- Fair
1
EACH
Dukane 250
2008
Documented
No deficiencies recorded
Inspected
Inspected
2- Between Good and Fair
2019
Documented
No deficiencies recorded
Inspected
Inspected
Custodian's Office - Room 126
3- Fair
1
EACH
Vista - 128BP
2006
Documented
No deficiencies recorded
Inspected
Inspected 3- Fair
3- Fair

Building Condition Assessment Survey 2023-2024

Question	Response	
SECURITY	Кезронзе	
Intrusion Alarm System Panic Switch		
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity		
	I EACH	
Instance Quantity Uom		
Manufacturer	Siemens	
EquipmentId	1200 Amp Switch for Lighting Panel 1200	
Capacity/Size Quantity		
Capacity/Size UOM	Amps	
Source of Capacity/Size Installation Year	Nameplate 2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
<u></u>		
Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	2500 Amp Switch for Power Panel	
Capacity/Size Quantity	2500	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	9	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	N/A	
Capacity/Size Quantity	2500	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2016	
Source of Installation Year	Documented	
Deficience	N 1 C : 1 1	

No deficiencies recorded

Deficiency

Building Condition Assessment Survey 2023-2024

Question	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	N/A	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	