Building Condition Assessment Survey 2023-2024

Ings4: 11		ISLAND, 450 BUEL AVEN					Lost Edit. 1
Inspection Id	Inspection Type				Time I		Last Edited
	MECHANICAL				2024-0	03-06 09:03AM	2024-04-23 05:101
sset Data				A			
Question	M : D :11: C	. 1 1 10		Answer	Domostia Hat	Water Remote S	taraga Tank
Have any Syste	ms/Major Building Co	omponents been upgraded?		Systems:	2024	water Kemote S	torage rank
				Years:		ter Treatment (A	utomatic)
				Systems: Years:	2023	ter Treatment (A	(utomatic)
				Systems:		f: Lavatory/Sink	s (~90%); Toilets,
				Years:		en - Gas System	s (7070), Tollets,
				Systems:		Detection (1 of 2	2); Fixtures - Student:
				bystems.), Lavatory/Sinks	s (~80%), Urinals,
				Years:	2020		
				Systems:	DX Split Syste	em for Cafeteria	(1 of 9)
				Years:	2019		
				Systems:	Gas Fired Don	nestic Water Hea	ewage Ejector Pumps; ater; Heating And
					Gymnasium (1 Return Pumpir F&T/Steam Dr Assembly; CO Distribution Pi	of 9); Return Fang System; Waterip Traps; Wet Sp //Gas Leak Detect ping (~70%); M	n; DX Split System for an; Steam Condensate r Service (2 of 3); prinkler Alarm Valve ction (1 of 2); Gas ER Steam and
				Years:	Condensate Pi	ping	
				Systems:	Original Build		atrol System - BMS ents (1 of 2); DX Split
				Years:		uditorium (7 of 9	
				Systems:	Terminal Unit Traps	Thermostatic Tr	aps; Kitchen - Grease
				Years:	2014		
				Systems:			riginal Building: Air Dryers, Pneumatic PRV
				Years:	2013		
Are there fuel to	anks?			No			
Total # of water	r main service entries	to the asset		3			
MERs/Fan Roo	oms Locations			Basement	MER		
Are there any s	paces with Missing or	Defective CO Detectors?		No			
	Painted/Obstructed Spr	rinkler Heads?		Yes			
Location(s)					_	nted, 5); Corrido	r near Room 162B
Are there any F	Emergency Stop Swite	hes with Missing Hammers?		(obstructe No compo	. ,		
Priority Condition				110 compo			
	ority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year? Cate	egory	Description	Affected	Description	Notified	Title	Image
No condition re	corded						
Inspection							
				Response	;		
Question							
Question Mechanical							
	TIONING			Inspected			
Mechanical AIR CONDI Chilled Wa	ater System	Piping, Pumps and Auxiliaries		Does not of Does not of	exist		

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	RU52

nical Inspection	RO
stion	Response
R CONDITIONING	
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Outdoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Inspected
Instance	Building Addition - Roof
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	RTU-52-1
Capacity/Size Quantity	8
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2005
Source of Installation Year	Documented
Source of Heating	Gas
Refrigerant Type	R-22
Deficiency	UP TO 20 TONS:DEFECTIVE CONTROLS
Deficiency Location/Instance	Building Addition - Roof
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Building Addition - Roof
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	RTU-52-2
Capacity/Size Quantity	15
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2005
Source of Installation Year	Documented
Source of Heating	Gas
Refrigerant Type	R-22
Deficiency	UP TO 20 TONS: DEFECTIVE CONDENSER FAN
Deficiency Location/Instance	Building Addition - Roof
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Building Addition - Roof
Instance Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Question	Response
AIR CONDITIONING	
Packaged / Rooftop Unit	
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	RTU-52-3
Capacity/Size Quantity	13
Capacity/Size UOM	Tons
Source of Capacity/Size Installation Year	Documented 2005
Source of Installation Year	Documented
Source of Heating	Gas
Refrigerant Type	R-22
Deficiency	No deficiencies recorded
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Return Fan	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Inspected
Instance	Original Building - Throughout except Gymnasium (WPT
	System)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Installation Year	2015
Source of Installation Year	Custodial Staff
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance	Room 227
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TERMINAL UNIT CONTROL VALVE
Deficiency Location/Instance	Room 327
Deficiency Quantity	1
Quantity Uom	EACH MADITENANCE
Potential Action	MAINTENANCE
Urgency of Action Purpose of Action	PRIORITY 3 LEVEL 2
Violations	No violations recorded
Instance	Building Addition - Throughout 3- Fair
Instance Condition	
Instance Quantity	1 EACH
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Installation Year	2005
Source of Installation Year Deficiency	Documented No deficiencies recorded
Deficiency	140 deficielles recorded

Building Condition Assessment Survey 2023-2024

Question	Response
CLIMATE CONTROL SYSTEM	
Pneumatic System	Does not exist
Hybrid System	Does not exist
Electric System	Does not exist
COMPACTOR	Does not exist
CONVEYING	Inspected
Dumbwaiter	Does not exist
Elevator	Inspected
Condition	2- Between Good and Fair
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Basement MER - Crawlspace; Water Service Room 004
Instance Condition	1- Good
Instance Quantity	2
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Instance	Sprinkler Room 150
Instance Condition	2- Between Good and Fair
Instance Quantity	
•	1 EACH
Instance Quantity Uom	
Deficiency	No deficiencies recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lochinvar
EquipmentId	Hot Water Heater
Capacity/Size Quantity	200
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented 2017
Installation Year	2017
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected

Building Condition Assessment Survey 2023-2024

estion	Response
DOMESTIC WATER SYSTEM	
Domestic Water Distribution Piping	
Condition	3- Fair
Deficiency	DEFECTIVE VALVE
Deficiency Location/Instance	Boiler Room, Basement MER - Crawlspace
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Boiler Room, Basement MER
Deficiency Quantity	160
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Custodian's Locker Room - Toilet Room; Basement Janitor Closet
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room - Crawlspace; Room 026 - Crawlspace
Deficiency Quantity	40
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room near Gas Fired Domestic Water Heater; Toilet Room
Deficiency Escation instance	317
Deficiency Quantity	30
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	Inspected
Condition Condition	2- Between Good and Fair
,	
Deficiency	No deficiencies recorded
Sump Pump	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

unicui inspeciion	KU
uestion	Response
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	1- Good
	No deficiencies recorded
Deficiency	
Locker Room Shower	Inspected
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Alternative Use	Yes
Deficiency	No deficiencies recorded
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
U <mark>rinal</mark>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Does not exist
Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Inspected
Instance	Boiler Room, Basement - Crawlspace, Custodian Workshop, Boiler Room, Corridor; 1st and 2nd Floor Corridors (CO Leak Detection)
Instance Condition	1- Good
Instance Quantity	1
	EACH
Instance Quantity Uom	
Installation Year Source of Installation Year	2020 Custodial Staff
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Mechanicai Inspection	KU32

Question	Response
GAS SERVICE	
CO/Gas Leak Detection	
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2017
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	FIN TUBE:DEFECTIVE
Deficiency Location/Instance	Custodian's Locker Room; Exits 9, 10
Deficiency Quantity	30
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	1- Good
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Basement MER
Deficiency Quantity	40
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE VALVE
Deficiency Location/Instance Deficiency Quantity	Room 208
Quantity Uom	EACH
	REPLACE
Potential Action	
Potential Action Urgency of Action	PRIORITY 3
Urgency of Action	PRIORITY 3 LEVEL 2
	PRIORITY 3 LEVEL 2 No violations recorded

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	KU52

Question	Response	
HEATING		
Steam Heating		
Terminal Unit Thermostatic Trap		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	2- Between Good and Fair	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Main Lobby	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
HEATING PLANT	Inspected	
Instance on Basement	Inspected	
Is there a water meter on the boiler make-up water piping?	Yes	
Observed Operational?	Yes	
Burner Manufacturer	Webster	
Burner Model	JB3G-50-LMV37-S-M.30VGD-UL-IRI	
Burner Type	Gas	
Heating Plant Oil Number	N/A	
Boiler Auxiliaries Instance on Basement	Inspected	
	nispected	
Boiler Auxiliary Piping Instance on Basement	Inconated	
	Inspected 1- Good	
Instance Condition	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Feedwater Treatment(Automatic)		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Flue Exhaust		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Safety Valve	10 deficiences recorded	
DUNCE SAICLY VALVE		

Building Condition Assessment Survey 2023-2024

Duestion	Response
HEATING PLANT	1. Copposite
Boiler Auxiliaries	
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	140 deficiences recorded
Boiler System Instance on Basement	Inspected
Coal-fired Boiler	inspected
Instance on Basement	Does not exist
	Does not exist
Hot Water Boiler	D
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	1- Good
Instance Quantity	4,526
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Burnham
EquipmentId	202879-01
Capacity/Size Quantity	5830
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year Source of Installation Year	2017
	Custodial Staff No deficiencies recorded
Deficiency	
Instance	Boiler Room
Instance Condition	1- Good
Instance Quantity	4,526
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Burnham
EquipmentId	202879-02
Capacity/Size Quantity	5830 MDH Cross
Capacity/Size UOM Source of Capacity/Size	MBH Gross Documented
Source of Capacity/Size Installation Year	2017
Installation Year Source of Installation Year	Custodial Staff
Deficiency	DEFECTIVE AUXILIARY (GAUGES, GASKETS ETC.)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Tr. 1.	27

No violations recorded

Inspected

Inspected 1- Good

Automatic

Violations

Boiler Fresh Air Louver/Damper
Instance on Basement

Instance Condition

Type

Fuel System

Building Condition Assessment Survey 2023-2024

R052

Question	Response	
HEATING PLANT		
Fuel System		
Boiler Fresh Air Louver/Damper		
Deficiency	No deficiencies recorded	
Burner/Burner Control Panel		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Fuel Oil Storage/Supply System		
Instance on Basement	Does not exist	
Gas Trains And Vent At The Boiler		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	N. d.f.i.m.i.m.d.d	

Fuel Sy	estem	
Boiler	r Fresh Air Louver/Damper	
	Deficiency	No deficiencies recorded
Burne	er/Burner Control Panel	
	Instance on Basement	Inspected
	Instance Condition	1- Good
	Deficiency	No deficiencies recorded
Fuel (Oil Storage/Supply System	
	Instance on Basement	Does not exist
Gas T	Frains And Vent At The Boiler	
	Instance on Basement	Inspected
	Instance Condition	1- Good
	Deficiency	No deficiencies recorded
	IDF Room	Inspected
nciosea		
D 11	Instance on Building Addition - Room 162B	Inspected
Dedicat	ted A/C Equipment	T4. 1
	Instance on Building Addition - Room 162B	Inspected 4- Between Fair and Poor
	Instance Condition	
	Deficiency	DOES NOT EXIST
	Deficiency Location/Instance Deficiency Quantity	Building Addition - Room 162B
	Quantity Uom	EACH
	Potential Action	INSTALL
	Urgency of Action	PRIORITY 3
	Purpose of Action	LEVEL 2
	Violations	No violations recorded
TECHE		
ІТСНЕ		Inspected
COD	Instance on 1st Fooor	Inspected
CO Det	Instance on 1st Fooor	
		Inspected 1- Good
	Instance Condition	
	Deficiency	No deficiencies recorded
Gas Sys		
	Instance on 1st Fooor	Inspected
	Instance Condition	1- Good
	Deficiency	No deficiencies recorded
Grease		
	Instance on 1st Fooor	Inspected
	Instance Condition	2- Between Good and Fair
	Deficiency	No deficiencies recorded
Hood		
	Instance on 1st Fooor	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
Hood E	Exhaust Ductwork	
	Instance on 1st Fooor	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
Hood E	Exhaust Fan	
	Instance on 1st Fooor	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
	ire Suppression System	

Building Condition Assessment Survey 2023-2024

Question	Response
KITCHEN	
Hood Fire Suppression System	
Instance on 1st Fooor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Hot Water Temperature Booster	
Instance on 1st Fooor	Does not exist
Kitchen Sink	· · · · · · · · · · · · · · · · · · ·
Instance on 1st Fooor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
MDF Room	Inspected
Instance on Original Building - Room 216	Inspected
Dedicated A/C Equipment	
Instance on Original Building - Room 216	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Rooms 025, 026, 121 (painted, 5); Corridor near Room 162B
	(obstructed, 1)
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action Violations	LEVEL 6
	No violations recorded
Sprinkler Piping Condition	Inspected 2- Between Good and Fair
The state of the s	
Deficiency	No deficiencies recorded
Standpipe System W. day G. a. a.	Does not exist Does not exist
Water Gong	
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	DEFECTIVE Original Publishing Peoply HE 12H HE 15H HE 18H
Deficiency Location/Instance	Original Building - Roof / HE-13H, HE-15H, HE-18H

Building Condition Assessment Survey 2023-2024

uestion	Response	
VENTILATION		
Exhaust Fan		
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Heating And Ventilating Unit	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	No	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Does not exist	
Unit Ventilator	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE FRESH AIR INTAKE	
Deficiency Location/Instance	Room 104	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	