Building Condition Assessment Survey 2023-2024

Electrical In	spection	R053
Asset:	P.S. 53 - STATEN ISLAND, 330 DURANT AVENUE, STATEN ISLAND, NY, 10308	

Set Data Question	ELECTRICAL ms/Major Building Components been upgraded?	Answer Systems Years:	2024-02-09 09:40AM : Students Toilet Room (LED Lig	2024-06-19 09:29AN
Question	ms/Major Building Components been upgraded?	Systems	Students Tailet Doom (LED Lie	
Question	ms/Major Building Components been upgraded?	Systems	Students Toilet Doom (LED Lie	
Have any Syste	ms/Major Building Components been upgraded?	•	Students Toilet Doom (I ED I in	
		Years:	. Stauchts folict Room (LED Ligh	hting)
			2022	
		Systems	: Partial Molded Case Circuit Bre	aker Panel Board
		Years:	2021, 2019, 2014, 2008	
		Systems	: Intrusion Alarm System (Partial	Remote Annunciator)
		Years:	2021	
		Systems	 Partial Emergency Lighting (No Gymnasium, Partial Emergency Pack), Auditorium (LED Lightin Local Sound System) 	Lighting (Battery
		Years:	2019	
		Systems	: IPDVS/CCTV System	
		Years:	2015	
		Systems	: Library	
		Years:	2014	
		Systems	: Telephone System, LAN	
		Years:	2012	
		Systems	• • • •	
		Years:	2010	
		Systems	: Interior Fluorescent Lighting, So	eience Lab
		Years:	2008	
		Systems	Sound System (Students Cafeter	ia), Auditorium
		Years:	(Theater Lighting System), Parti 2007	al Service Switch
		Systems		el
		Years:	2006	
Type of Service		Below G		
• •	e Whiteboard (IWB) Exist?	Yes		
	on In Electrical Room?	No		
DEDICATED	INTERCOMS IN FIRE RESCUE AREA	8		
Question			Response	
your building		and/or Holding Rooms in	No	
iority Conditi				
xist Prio ast Year? Cate	rity Condition egory Description	Component Location Affected Description		hoto mage

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Public Address System - Speakers Not	Speakers are out of order.	Public Address System	Cafeteria and 7 Classrooms	Troy Simas	Fireman	No Photo Taken
	Operational						

Response
Does not exist
Inspected
Inspected
Inspected
No
Does not exist

Building Condition Assessment Survey 2023-2024

estion	Response	
AUDITORIUM		
House Lighting		
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Local Sound System		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 2nd Floor	Inspected	
Instance Condition	1- Good	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 2nd Floor	Inspected	
Dimming System		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
AFETERIA	Inspected	
Instance on 2nd Floor - Students		
Instance on 2nd Floor - Students Instance on 2nd Floor - Staff	Inspected Inspected	

Building Condition Assessment Survey 2023-2024

Response
Inspected
Inspected
1
Inspected
Inspected
Does not exist
Does not exist
200 100 0.100
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
No deficiencies recorded
Does not exist
Does not exist Does not exist
Does not exist
Does not exist
Does not exist
Does not exist
Does not exist
Does not exist
Does not exist
Inspected
3- Fair
2007
Documented
No deficiencies recorded
Does not exist
Does not exist
Does not exist
Down and social
Does not exist
Does not exist
Inspected
Inspected
No
Inspected
Inspected
3- Fair
LIGHTING FIXTURE BALLAST DEFECTIVE
8 FACH
EACH DEDIACE DALLAST
REPLACE BALLAST
PRIORITY 3 LEVEL 2

Building Condition Assessment Survey 2023-2024

estion	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	58
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	Does not exist
OMPUTER LAB	Does not exist
YMNASIUM	Inspected
Instance on 2nd Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	-
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist

Building Condition Assessment Survey 2023-2024

iem impeemen	
uestion	Response
GYMNASIUM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Does not exist
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 2nd Floor	Does not exist
Scoreboard	
Instance on 2nd Floor	Does not exist
Theater Lighting System	
Instance on 2nd Floor	Does not exist
KITCHEN	Inspected
Instance on 2nd Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

Building Condition Assessment Survey 2023-2024

tricai Inspection	K
Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Does not exist
LIBRARY	Inspected
Instance on Room 306	Inspected
Lighting	
Instance on Room 306	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 306	Inspected
Pendant Mounted	
Instance on Room 306	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 306	Does not exist
Recessed Mounted	
Instance on Room 306	Does not exist
Lighting Fixture - HID	
Instance on Room 306	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 306	Does not exist
Lighting Fixture - LED	
Instance on Room 306	Does not exist
Raceway With Receptacles	
Instance on Room 306	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 306	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
	Does not exist
SCIENCE DEMO ROOM	
SCIENCE LAB	Inspected
Instance on Room 121	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Room 121	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 121	Inspected
Pendant Mounted	
Instance on Room 121	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	

Building Condition Assessment Survey 2023-2024

icui mspeciion	1403
uestion	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Room 121	Does not exist
Recessed Mounted	
Instance on Room 121	Does not exist
Lighting Fixture - HID	
Instance on Room 121	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 121	Inspected
Pendant Mounted	
Instance on Room 121	Does not exist
Surface Mounted	
Instance on Room 121	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 121	Does not exist
Lighting Fixture - LED	
Instance on Room 121	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 121	Does not exist
Emergency Shut-Off Power	
Instance on Room 121	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 121	Does not exist
Projection System	
Instance on Room 121	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

Building Condition Assessment Survey 2023-2024

aricai Inspection		KUSS
Question	Response	
TOILET ROOM - STAFF		
Lighting		
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
	Does not exist	
EMERGENCY GENERATOR SET		
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Does not exist	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Does not exist	
Duct Smoke Detector	Does not exist	
Area Smoke Detector	Does not exist	
CO Detector	Does not exist	
Heat Detector	Does not exist	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

estion	Response	
IRE ALARM SYSTEM	•	
Fused Cutout Panel		
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Fire Alarm Board	
Installation Year	1966	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	67,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Sub-Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Sprinkler Alarm Board	
Installation Year	1966	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	67,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Remote Annunciator	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

iricai inspection	KU33
Question	Response
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Does not exist
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected Page not suit
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler and Fan Rooms
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Main Office - Room 233
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250

Building Condition Assessment Survey 2023-2024

estion	Response	
UBLIC ADDRESS SYSTEM		
Source of Installation Year	Documented	
Deficiency	CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	7	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	SPEAKER NOT OPERATIONAL	
Deficiency Location/Instance	Cafeteria and 7 Classrooms	
Deficiency Quantity	13	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Main Office - Room 233	
Deficiency Quantity	67,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
ECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	2- Between Good and Fair	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office - Room 235	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista - 50P	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Custodian's Office - Room 235	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 3	
Violations	No violations recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Panic Switch		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	No deficiencies recorded Inspected	

Building Condition Assessment Survey 2023-2024

estion	Response
ECURITY	
Intrusion Alarm System	
Remote Annunciator	
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Perimeter of the Building
Deficiency Quantity	46
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
ERVICE SWITCH	Inspected
Instance	Electrical Room 135
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	Royal Switchboard Co.
EquipmentId	Light
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1966
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room 135
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room 135
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Main Disconnect Switch for Dimming System
Capacity/Size Quantity	600
Capacity/Size Quantity Capacity/Size UOM	
Source of Capacity/Size	Amps
	Nameplate
Installation Year	2007 Decumented
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 135
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric

Building Condition Assessment Survey 2023-2024

ricai Inspection	KUS
Question	Response
SERVICE SWITCH	
EquipmentId	Power
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1966
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room 135
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
	LEVEL 2
Purpose of Action	
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room 135
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	Royal Switchboard Co.
EquipmentId	Light
Capacity/Size Quantity	875
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1966
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room 135
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room 135
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Royal Switchboard Co.
EquipmentId	Power
Capacity/Size Quantity	500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1966
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room 135
Deficiency Quantity	licetteal Room 133
Quantity Uom	EACH
Potential Action	REPLACE

Building Condition Assessment Survey 2023-2024

Question	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSPORTER	D	