Building Condition Assessment Survey 2023-2024

Mechanical Inspection R053

Asset:	P.S. 53 - STATEN ISLAND, 330 DURANT AVENUE, STATEN ISLAND, NY, 10308			
Inspection Id	Inspection Type		Time In	Last Edited
3116	MECHANICAL		2024-02-09 10:18AM	2024-05-15 03:47PM
et Data				
Question		Answer		
Have any Systems/Major Building Components been upgraded?		Systems:	Fixtures - Student: Lavatory/Sink	· /·
		Years:	(~10%); Boiler Feedwater Treatm 2023	ment(Automatic)
		Systems:	Heat Pump Domestic Water Heat	tars: Vitaban Hat
		Systems:	Water Temperature Booster; Fixt	*
			Lavatory/Sinks (~70%), Toilets (
		Years:	2022	-5070), Officials
		Systems:	Water Service refurbished (2 of 3	3)
		Years:	2021	
		Systems:	F&T/Steam Drip Traps	
		Years:	2020	
		Systems:	Water Service (1 of 3); Boiler Sa	fety Valves
		Years:	2018	
		Systems:	Steam Condensate Return Pumpi	ing System; Terminal
			Unit Thermostatic Traps (~70%)	
		Years:	2016	

Yes

15,000

1st Floor MER

No components

Rooms 121, 125, 127, 129, 336 (painted, 27)

2

0

0

3

No

Yes

Location(s)

Are there fuel tanks?

Total # of above ground tanks

Total # of below ground tanks

MERs/Fan Rooms Locations

Total capacity of all above ground tanks in gal.

Total capacity of all below ground tanks in gal.

Are there any spaces with Missing or Defective CO Detectors?

Are there any Emergency Stop Switches with Missing Hammers?

Total # of water main service entries to the asset

Are there any Painted/Obstructed Sprinkler Heads?

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Defective Emergency Stop Switch	Defective Emergency Stop Switch (1 of 2)	Boiler Emergency Stop Switch	Boiler Room Entrance	Troy Simas	Fireman	
Yes	Defective Kitchen Gas System	Defective Master Gas Control Valve (1 of 2)	Gas System	Kitchen	Troy Simas	Fireman	
No	Defective Sprinkler/Standpipe System	Sprinkler Pipe is disconnected.	Sprinkler Piping	1st Floor - Gas/Sprinkler/ Water Meter Room	Troy Simas	Fireman	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Defective Boiler

Safety Auxiliary

Boiler #1: Defective Water Column's Trycocks, Sight Glass is leaking.

Boiler #2: Defective Water Column's Trycocks.

etive Steam Boiler

Boiler Room / Boilers #1, #2 Troy Simas Fireman

R053



Inspection

Yes

o :	
Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Outdoor Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	DEFECTIVE REFRIGERATED AIR DRYER
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TERMINAL UNIT CONTROL VALVE
Deficiency Location/Instance	Rooms 224, 240, 302 and other locations
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance	Cafeteria, Kitchen
Partners Version 2.0 (P)	Page 2 of 13 Print Date: 8/8/2024

Building Condition Assessment Survey 2023-2024

спиниси і інърссион	1035
Question	Response
CLIMATE CONTROL SYSTEM	
Pneumatic System	
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Electric System	Does not exist
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	1st Floor - Gas/Sprinkler/Water Meter Room
Instance Condition	2- Between Good and Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION
•	DEVICE
Deficiency Location/Instance	1st Floor - Gas/Sprinkler/Water Meter Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	1st Floor - Crawlspace
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION
,	DEVICE
Deficiency Location/Instance	1st Floor - Crawlspace
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	1- Good
Instance Quantity	2
mountee Quantity	<u> </u>

Mechanical Inspection	K055

estion	Response
OMESTIC WATER SYSTEM	
Domestic Hot Water System	
Heat Pump Domestic Water Heater	
Instance Quantity Uom	EACH
Manufacturer	A.O. Smith
EquipmentId	N/A
Capacity/Size Quantity	11
Capacity/Size UOM	KW Input
Capacity/Size 2 Quantity	119
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Inspector Estimate
Installation Year	2022
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	60
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	30
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE VALVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	
• • •	1 FACH
Quantity Uom Potential Action	EACH DEDLAGE
	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
RAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	INTERIOR FLOOR DRAIN:DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Inspected

Building Condition Assessment Survey 2023-2024

unicui Inspecuon		KUSS
uestion	Response	
DRAIN/WASTE/VENT AND STORM SYSTEM		
Sump Pump		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)	
Deficiency Location/Instance	Room 324	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Inspected	
	Inspected	
Gas Distribution Piping Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

tanical Inspection	RU53
Question	Response
GAS SERVICE	
Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Does not exist
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	AUXILIARY (VALVE, VENT): DEFECTIVE
Deficiency Location/Instance	1st Floor - Gas/Sprinkler/Water Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	RADIATOR/CONVECTOR:DEFECTIVE
Deficiency Location/Instance	Room 240
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	1st Floor MER @ Supply Fans
Deficiency Quantity	40
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System	Inspected
Condition Security and Condition	2- Between Good and Fair
Deficiency	DEFECTIVE PUMP
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3 LEVEL 2
Purpose of Action Violations	No violations recorded
Deficiency	DEFECTIVE CONTROLS
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1

Building Condition Assessment Survey 2023-2024

inicai inspection		KUS
nestion	Response	
HEATING		
Steam Heating		
Steam Condensate Return Pumping System		
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Terminal Unit Thermostatic Trap	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Steam supplied by External Sources		
Unit Heater/Cabinet Heater Condition	Inspected 3- Fair	
	No deficiencies recorded	
Deficiency		
HEATING PLANT	Inspected	
Instance on 1st Floor	Inspected	
Is there a water meter on the boiler make-up water piping?	Yes	
Observed Operational?	Yes	
Burner Manufacturer	Preferred Utilities	
Burner Model	BHE7V3A4	
Burner Type	Oil	
Heating Plant Oil Number	4	
Boiler Auxiliaries		
Instance on 1st Floor	Inspected	
Boiler Auxiliary Piping		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Boiler Room Entrance	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Boiler Feedwater System		
Instance on 1st Floor	Does not exist	
Boiler Feedwater Treatment(Automatic)		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
	No deficiencies recorded	
Deficiency	no deliciencies recorded	
Boiler Flue Exhaust		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on 1st Floor	Does not exist	

Mechanicai Inspection	K055

tion	Response
ATING PLANT	
oiler Auxiliaries	
Boiler Room Steam And Condensate Piping	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Safety Valve	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
oiler System	
Instance on 1st Floor	Inspected
Coal-fired Boiler	
Instance on 1st Floor	Does not exist
Hot Water Boiler	
Instance on 1st Floor	Does not exist
Modular Boiler	
Instance on 1st Floor	Does not exist
Steam Boiler	
Instance on 1st Floor	Inspected
Instance on 1st Floor	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,720
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Federal Boiler Company
EquipmentId	52078-1
Capacity/Size Quantity	4720
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Documented
Installation Year	1966
Source of Installation Year	Documented
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Quantity	80 G.F.
Quantity Uom Potential Action	S.F. REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE SAFETY AUXILIARY: LOW-WATER CUT-OFF, WATER COLUMN ASSEMBLY
Deficiency Quantity	l
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,720
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Federal Boiler Company
EquipmentId	52078-2

Building Condition Assessment Survey 2023-2024

Response
4720
MBH Net
Documented
1966
Documented
DAMAGED/MISSING INSULATION
40
S.F.
REPLACE
PRIORITY 3
LEVEL 2
No violations recorded
DEFECTIVE SAFETY AUXILIARY: LOW-WATER CUT-OFF, WATER COLUMN ASSEMBLY
1
EACH
MAINTENANCE
PRIORITY 5
LEVEL 6
No violations recorded
Inspected
Inspected
4- Between Fair and Poor
Automatic
DEFECTIVE ACTUATOR
Boiler Room
2
EACH
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded
Inspected
4- Between Fair and Poor
OIL BURNER:DEFECTIVE
Boiler Room
2
EACH
REPAIR
PRIORITY 3
LEVEL 2
No violations recorded
BURNER CONTROL PANEL:DEFECTIVE OPACITY SENSOR
Boiler Room
2
EACH
EACH MAINTENANCE
PRIORITY 3 LEVEL 2
LEVEL /

Mechanical Inspection	R053

	*		
estion		Response	
<u>IEATIN</u>	NG PLANT		
Fuel Sy	ystem		
Fuel	Oil Storage/Supply System		
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Gas	Trains And Vent At The Boiler		
	Instance on 1st Floor	Does not exist	
nclosed	I IDF Room	Does not exist	
ІТСНІ	EN	Inspected	
	Instance on 2nd Floor	Inspected	
CO De		шересси	
COD	Instance on 2nd Floor	Inspected	
	Instance Condition	1- Good	
	Deficiency	No deficiencies recorded	
Gas Sy	·	To deficiences recorded	
Gas Sy	Instance on 2nd Floor	Inspected	
	Instance Condition	4- Between Fair and Poor	
	Deficiency	DEFECTIVE MASTER GAS CONTROL VALVE	
	Deficiency Location/Instance	Defective Master Gas Control Valve (1 of 2)	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	REPLACE	
	Urgency of Action	PRIORITY 5	
	Purpose of Action	LEVEL 6	
	Violations	No violations recorded	
Grease	e Trap		
	Instance on 2nd Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood			
	Instance on 2nd Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood I	Exhaust Ductwork		
	Instance on 2nd Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood I	Exhaust Fan		
11000 1	Instance on 2nd Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood I	Fire Suppression System	No deficiencies recorded	
1100u 1	Instance on 2nd Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
11-4 337		No deficiences recorded	
1101 W	ater Temperature Booster Instance on 2nd Floor	Inspected	
	Instance On 2nd Floor Instance Condition	1- Good	
¥7*.	Deficiency	No deficiencies recorded	
Kitche		Tecesoria d	
	Instance on 2nd Floor Instance Condition	Inspected 3- Fair	
	Instance Condition	5- Fair	

Mechanical Inspection R05	53
---------------------------	----

Question	Response
MDF Room	Inspected
Instance on Room 221	Inspected
Dedicated A/C Equipment	
Instance on Room 221	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
	Inspected
SCIENCE LAB Instance on Room 121	
Alternative Use	Inspected
	No
Acid Waste Neutralizing Tank Instance on Room 121	Dogs not swipt
	Does not exist
CO Detector Instance on Room 121	Not required
	Not required
Emergency Shower Instance on Room 121	Does not exist
Eye Wash	DOCS HOT CAIST
Instance on Room 121	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	No deficiences recorded
Instance on Room 121	Does not exist
Hood Exhaust Fan	Does not exist
Instance on Room 121	Does not exist
Fixed Laboratory Hood	Does not exist
Instance on Room 121	Does not exist
Laboratory Sink	2000 1101 411101
Instance on Room 121	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Room 121	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
	Does not exist
Dry Sprinkler Alarm Valve Assembly Wet Sprinkler Alarm Valve Assembly	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Rooms 121, 125, 127, 129, 336 (painted, 27)
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
ē ;	
Purpose of Action	LEVEL 6
Purpose of Action	LEVEL 6 No violations recorded Inspected
Purpose of Action Violations	LEVEL 6 No violations recorded
Purpose of Action Violations Sprinkler Piping	LEVEL 6 No violations recorded Inspected

Building Condition Assessment Survey 2023-2024

uestion	Response
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Sprinkler Piping	
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Standpipe System	Does not exist
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	DEFECTIVE
Deficiency Location/Instance	Roof / 3T (bearing)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	Yes
Deficiency	DAMAGED FLEXIBLE CONNECTION
Deficiency Location/Instance	1st Floor MER @ Auditorium Supply, Auditorium Exhaust,
	Gymnasium Exhaust
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE DUCTWORK
Deficiency Location/Instance	Roof
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Supply Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-5
Deficiency	DEFECTIVE
Deficiency Location/Instance	1st Floor MER / Auditorium Supply
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Organicy or rection	
Purpose of Action	LEVEL 2

Building Condition Assessment Survey 2023-2024

Question	Response	
VENTILATION		
Unit Ventilator	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE CONTROLS	
Deficiency Location/Instance	Room 108	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	