Building Condition Assessment Survey 2023-2024

Electrical In	espection	R054
Asset:	P.S. 54 - STATEN ISLAND, 1060 WILLOWBROOK ROAD, STATEN ISLAND, NY, 10314	

Inspection Id	Inspection Type		Time In	Last Edited
4799	ELECTRICAL		2024-04-17 07:55AM	2024-05-20 12:49PM
set Data				
Question		Answer		
Have any Syste	ms/Major Building Components been upgraded?	Systems:	IPDVS/CCTV System	
		Years:	2023	
		Systems:	Auditorium (Projection System, Theater Lighting System), Most Pack), Fire Alarm System (Remo Partial Fused Disconnect Switch	Exit Lights (Battery ote Annunciator Panel),
		Years:	2021	
		Systems:	Most Lighting - Security	
		Years:	2020, 2012, 1995	
		Systems:	Partial Service Switch and Switch	hboard
		Years:	2019	
		Systems:	Interior Lighting (Except Library	7)
		Years:	2015	
		Systems:	Library	
		Years:	2010	
		Systems:	Emergency Light/Exit Light Pan System	el, Intrusion Alarm
		Years:	2004	
		Systems:	Partial Molded Case Circuit Brea	ker Panel Board
		Years:	2000, 1995	
Type of Service	•	Below Gro	ound	
Does Interactive	e Whiteboard (IWB) Exist?	Yes		
Water Penetrati	on In Electrical Room?	No		

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response	
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No	
your building?		

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Water Leaks onto Electrical Equipment	Water leaks from the steam pipe onto electrical outlet.	Electrical outlet	Library - Room 220	Juan Morales	Fireman	NO POTES.
No	Public Address System - Speakers Not Operational	All speakers in the Kitchen area for Public Address System are out of order. Nobody can hear any announcements.	Public Address System	Kitchen	Juan Morales	Fireman	No Photo Taken

Inspection

Question	Response	
Electrical		
ATHLETIC FIELD	Does not exist	
AUDITORIUM	Inspected	
Instance on 1st Floor	Inspected	
House Lighting		
Instance on 1st Floor	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		

Building Condition Assessment Survey 2023-2024

R054

Electrical Inspection

Instance on 1st Floor

Instance on 1st Floor

Instance on 1st Floor

Lighting Fixture - Fluorescent
Instance on 1st Floor

Pendant Mounted

Surface Mounted

Lighting

Question	Response	
AUDITORIUM		
House Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Installation Year	2021	
Source of Installation Year	Documented	

Installation Year	2021	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
AFETERIA	Inspected	

Inspected

Inspected

Inspected

Does not exist

Building Condition Assessment Survey 2023-2024

Electrical Inspection	R054

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	1995
Source of Installation Year Deficiency	Documented AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist

Building Condition Assessment Survey 2023-2024

псан Інѕресион		RU54
uestion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Inspected	
Instance on Room 326	Inspected	
Power Panel?	Yes	
Lighting		
Instance on Room 326	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 326	Inspected	
Pendant Mounted		
Instance on Room 326	Does not exist	
Surface Mounted		
Instance on Room 326	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 326	Does not exist	
Lighting Fixture - HID		
Instance on Room 326	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 326	Does not exist	
Lighting Fixture - LED		
Instance on Room 326	Does not exist	
Raceway With Receptacles		
Instance on Room 326	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor		
	Inspected	
Lighting Instance on 1st Floor	Inspected	
	nispected	
Lighting Fixture - Fluorescent Instance on 1st Floor	Inspected	
	inspected	
Pendant Mounted	Door not swipt	
Instance on 1st Floor Surface Mounted	Does not exist	
	Does not exist	
Instance on 1st Floor	Does not exist	
Recessed Mounted Instance on 1st Floor	Inquantad	
	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	D	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 220	Inspected	

Building Condition Assessment Survey 2023-2024

uestion	Response	
LIBRARY		
Lighting		
Instance on Room 220	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 220	Inspected	
Pendant Mounted		
Instance on Room 220	Does not exist	
Surface Mounted		
Instance on Room 220	Does not exist	
Recessed Mounted		
Instance on Room 220	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 220	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 220	Does not exist	
Lighting Fixture - LED		
Instance on Room 220	Does not exist	
Raceway With Receptacles		
Instance on Room 220	Does not exist	
Projection System		
Instance on Room 220	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
	Does not exist	
SCIENCE DEMO ROOM		
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
AUAILIARI SIGNAL/DELL SISIEWI	mspected	

Building Condition Assessment Survey 2023-2024

icai inspection		KU34
uestion	Response	
AUXILIARY SIGNAL/BELL SYSTEM		
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	FIXTURE LAMP NOT OPERATIONAL	
Deficiency Location/Instance	Auditorium and Corridors	
Deficiency Quantity	7	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Does not exist	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Does not exist	
Duct Smoke Detector	Does not exist	
Area Smoke Detector	Does not exist	
CO Detector	Does not exist	
Heat Detector	Does not exist	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection	K054

estion	Response	
IRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Standard)		
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards	
EquipmentId	Fire Control	
Installation Year	1970	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	74,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Sub-Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards	
EquipmentId	Sprinkler Alarm Control Board	
Installation Year	1970	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	74,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Printer	Does not exist	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Zenciency	Inspected	

Building Condition Assessment Survey 2023-2024

ical Inspection		
uestion	Response	
GROUNDING SYSTEM		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
i	Does not exist	
LIGHTNING PROTECTION		
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Inspected	
Condition	3- Fair	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room, Fan Room above Auditorium, Electrical Room,	
	Kitchen	
Deficiency Quantity	5	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Inspected	
Condition	3- Fair	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room, Boiler Room, Kitchen, Fan Room Above	
	Auditorium	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	15	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Main Office - Room 114	
Instance Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

	n	
stion	Response	
JBLIC ADDRESS SYSTEM		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Rauland TC4001	
Installation Year	1970	
Source of Installation Year	Documented	
Deficiency	CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	14	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	SPEAKER NOT OPERATIONAL	
Deficiency Location/Instance	Kitchen and Classrooms	
Deficiency Quantity	7	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Main Office - Room 114	
Deficiency Quantity	74,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
CCURITY	Inspected	
PDVS/CCTV System	Inspected	
Condition	1- Good	
Installation Year	2023	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office - Room 138	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista - 128B	
Installation Year	2004	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Beneficiery	140 deficiencies recorded	
Infrared Congan	Inspected	
Infrared Sensor	Inspected	
Condition	3- Fair	
Condition Deficiency	3- Fair No deficiencies recorded	
Condition Deficiency Panic Switch	3- Fair No deficiencies recorded Inspected	
Condition Deficiency Panic Switch Condition	3- Fair No deficiencies recorded Inspected 3- Fair	
Condition Deficiency Panic Switch	3- Fair No deficiencies recorded Inspected	
Condition Deficiency Panic Switch Condition	3- Fair No deficiencies recorded Inspected 3- Fair	
Condition Deficiency Panic Switch Condition Deficiency	3- Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Duestion	Response
SECURITY	
Intrusion Alarm System	
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected 3- Fair
Condition	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Deficiency Location/Instance	Playground and Back Side of the School
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	TIME CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Storage Closet by Room 102
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
	Electrical Room
Instance	3- Fair
Instance Condition	
Instance Quantity	1 F1 GY
Instance Quantity Uom	EACH
Manufacturer	Lexington
EquipmentId	Main Sw. 800A Fuse
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size 1970
Installation Year Source of Installation Year	
Deficiency	Documented BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	l
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	1- Good
Instance Quantity	
	1 EACH
Instance Quantity Uom	
Manufacturer	Siemens
EquipmentId	AC-DP 400
Capacity/Size Quantity Capacity/Size UOM	400 Amps
Source of Capacity/Size	Amps Nameplate
Installation Year	2019
instantation real	

Documented

Inspected

No deficiencies recorded

Source of Installation Year

Deficiency

SWITCHBOARD

Building Condition Assessment Survey 2023-2024

rical Inspection	R
uestion	Response
SWITCHBOARD	
Number of Spares	2
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
EquipmentId	SWBD Sect 1, 2
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1970
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	AC-DP
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist