Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Asset:	P.S. 58 - STATEN ISLAND, 77 MARSH AVENUE, STATEN ISLAND, NY, 10314				
Inspection Id	Inspection Type		Time In	Last Edited	
4055	MECHANICAL		2024-03-19 09:05AM	2024-04-29 10:32AM	
sset Data					
Question		Answer			
Have any Syste	Have any Systems/Major Building Components been upgraded?		Fire Booster Pump (re-built)		
		Years:	2021		
		Systems:	Climate Control System - Electri Auditorium Gymnasium and Cat Backflow Preventers (2 of 3)	•	
		Years:	2020		

	Years: 2019
Are there fuel tanks?	Yes
Total # of above ground tanks	2
Total capacity of all above ground tanks in gal.	6,275
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	Fire Pump Room B04, Penthouse MER
Are there any spaces with Missing or Defective CO Detectors?	Yes
Location(s)	Kitchen
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Exit 1, Auditorium, Corridors near Rooms 256, 4
	(obstructed, 4)
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Defective Boiler Safety Auxiliary	Secondary Low Water Cut-off Piping is leaking.	Steam Boiler	Boiler Room / Boiler #2	Angelo Carrube	Fireman	
Yes	Other	Penthouse MER	Refrigerant Leak Detection System	Defective System	Angelo Carrube	Fireman	
No	Defective CO/Gas Leak Detection	Fault Signal At Panels	CO/Gas Leak Detection	Boiler Room, Custodian's Office	Angelo Carrube	Fireman	
Yes	Defective Boiler Safety Auxiliary	(4)	Boiler Safety Valve	Boiler Room @ Boilers #1, #2	Angelo Carrube	Fireman	

Inspection

R058

Systems: F&T/Steam Drip Traps; Climate Control System -

Preventer

Electric System; Boiler Make-up Water Backflow

407

NYC Department of Education Building Condition Assessment Survey 2023-2024

Mechanical Inspection

K
-

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

chunicui Inspeciion		1030
Question	Response	
AIR CONDITIONING		
Chilled Water System		
Central Station Air Handler		
Capacity/Size Quantity	10000	
Capacity/Size UOM	CFM	
Source of Capacity/Size	Documented	
Installation Year	2003	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Penthouse MER	
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Carrier	
EquipmentId	AHU-6	
Capacity/Size Quantity	10150	
Capacity/Size UOM	CFM	
Source of Capacity/Size	Documented	
Installation Year	2003	
Source of Installation Year	Documented	
Deficiency	DEFECTIVE COIL	
Deficiency Location/Instance	Penthouse MER	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Penthouse MER	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Carrier	
EquipmentId	AHU-5	
Capacity/Size Quantity	3500	
Capacity/Size UOM	CFM	
Source of Capacity/Size	Documented	
Installation Year	2003	
Source of Installation Year	Documented	
Deficiency	DEFECTIVE FAN	
Deficiency Location/Instance	Penthouse MER	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Penthouse MER	
Instance Condition	3- Fair	
Instance Quantity	l EACH	
Instance Quantity Uom		
Manufacturer	Carrier	
EquipmentId	AHU-4	
Capacity/Size Quantity	12000	
Capacity/Size UOM	CFM	
Source of Capacity/Size	Documented	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

nicui Inspeciion		KU.
stion	Response	
IR CONDITIONING		
Chilled Water System		
Central Station Air Handler		
Installation Year	2003	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Penthouse MER	
Instance Condition	3- Fair	
Instance Quantity	2	
Instance Quantity Uom	EACH	
Manufacturer	Carrier	
EquipmentId	AHU-2, AHU-3	
Capacity/Size Quantity	12500	
Capacity/Size UOM	CFM	
Source of Capacity/Size	Documented	
Installation Year	2003	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Penthouse MER	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Carrier	
EquipmentId	AHU-11	
Capacity/Size Quantity	2200	
Capacity/Size UOM	CFM	
Source of Capacity/Size	Documented	
Installation Year	2003	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Penthouse MER	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Carrier AHU-12	
EquipmentId Capacity/Size Quantity	4275	
Capacity/Size UOM	4275 CFM	
Source of Capacity/Size	Documented	
Installation Year	2003	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fan Coil Unit	Does not exist	
Packaged Air Cooled Chiller	Does not exist	
Water Cooled Chiller	Inspected	
	Penthouse MER	
Instance		
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Carrier	
EquipmentId	CH-1	
Capacity/Size Quantity	209	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	2003	
Source of Installation Year	Documented	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion		Response	
IR CONDITION			
Chilled Water S			
Water Cooled		D 1244	
	rant Type	R-134A	
Deficier		151 - 350 TONS:DEFECTIVE COMPRESSOR	
	iency Quantity	1	
	tity Uom tial Action	EACH	
	ney of Action	REPAIR PRIORITY 3	
-	ose of Action	LEVEL 2	
Violat		No violations recorded	
Instance		Penthouse MER	
	e Condition	4- Between Fair and Poor	
	e Quantity	l EACH	
-	e Quantity Uom		
Manufa		Carrier	
Equipm		CH-2	
	y/Size Quantity	209	
	y/Size UOM of Capacity/Size	Tons Increastor Estimate	
	tion Year	Inspector Estimate 2003	
	of Installation Year	Documented	
	rant Type	R-134A	
Deficier		151 - 350 TONS:DEFECTIVE COMPRESSOR	
	iency Quantity	2	
	tity Uom	EACH	
	tial Action	REPAIR	
	ncy of Action	PRIORITY 3	
	ose of Action	LEVEL 2	
Violat		No violations recorded	
	er Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	T Distribution. Fiping, Fumps and Auximarity	2- Between Good and Fair	
Deficier	ncv	PIPING:DEFECTIVE/LEAKS	
	iency Location/Instance	Roof near Cooling Tower	
	iency Quantity	20	
Quant	tity Uom	L.F.	
	tial Action	REPLACE	
	ncy of Action	PRIORITY 3	
-	ose of Action	LEVEL 2	
Violat	tions	No violations recorded	
Cooling Coil in I	Ductwork	Does not exist	
Cooling Tower		Inspected	-
Instance	2	Roof (Bank of two)	
Instance	e Condition	3- Fair	
Instance	e Quantity	1	
	e Quantity Uom	EACH	
Manufa		Baltimore Air Coil (BAC)	
Equipm		N/A	
	y/Size Quantity	440	
	y/Size UOM	Tons	
	of Capacity/Size	Inspector Estimate	
	tion Year	2003	
	of Installation Year	Documented	
Deficier		No deficiencies recorded	
DX Split System		Inspected	
		Inspected	

Building Condition Assessment Survey 2023-2024

estion	Response
IR CONDITIONING	
DX Split System	
Indoor Unit	
Condition	3- Fair
Deficiency	No deficiencies recorded
Outdoor Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Dry Cooler	Does not exist
Packaged / Rooftop Unit Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE SYSTEM
Deficiency Location/Instance	Penthouse MER
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Refrigerant Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Return Fan	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
ENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
LIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Inspected
Instance	Throughout except Auditorium, Gymnasium, and Cafeteria
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	DEFECTIVE DAMPER ACTUATOR
Deficiency Location/Instance	Penthouse MER @ AHUs
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TEMPERATURE CONTROL ZONE VALVE
Deficiency Location/Instance	Penthouse MER @ AHU-1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Electric System	Inspected
LICCUIC System	Throughout (Heat Timer System)

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response
CLIMATE CONTROL SYSTEM	
Electric System	
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
Instance	Auditorium, Gymnasium, and Cafeteria
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
COMPACTOR	Does not exist
CONVEYING	Inspected
	Does not exist
Dumbwaiter Elevator	Inspected
Condition	3- Fair
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Inspected
Electric Pressure Booster System	Inspected
Instance	Exterior Water Meter Room/Booster Pump Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Liquitrol
EquipmentId	N/A
Capacity/Size Quantity	3
Capacity/Size UOM	Total # Pumps
Capacity/Size 2 Quantity	13
Capacity/Size 2 UOM	Total Pumps HP
Source of Capacity/Size	Documented
Installation Year	2003
Source of Installation Year	Documented
Deficiency	RUSTY/LEAKY VALVES AND PIPE FITTINGS
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hydraulic/Pneumatic Booster System	Does not exist
Water Service	Inspected
Instance	Exterior Water Meter Room/Booster Pump Room, Exterior
Instance Condition	Sprinkler Valve Room 2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

Response	
3	
EACH	
No deficiencies recorded	
-	
Gallons	
Documented	
2003	
Documented	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
2- Between Good and Fair	
DEFECTIVE/LEAKS	
Exterior Water Meter Room/Booster Pump Room	
10	
3- Fair	
DEFECTIVE CONTROLS	
Boiler Room	
1	
EACH	
MAINTENANCE	
	3 EACH No deficiencies recorded Inspected Does not exist Does not exist Boiler Room 3 - Fair 1 EACH PVI N/A 1200 MBH Input 500 Gallons Documented 2003 Documented 2003 Documented 2003 Documented 2003 Documented 2003 Documented Does not exist Inspected 2 - Between Good and Fair DEFECTIVE/LEAKS Exterior Water Meter Room/Booster Pump Room 10 L.F. REPLACE PRIORITY 3 LEVEL 2 No violations recorded Inspected 2 - Between Good and Fair No deficiencies recorded Inspected 2 - Between Good and Fair No deficiencies recorded In

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response
RAIN/WASTE/VENT AND STORM SYSTEM	
Sump Pump	
Purpose of Action	LEVEL 2
Violations	No violations recorded
UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
IXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
	VALVE,ETC.)
Deficiency Location/Instance	Room 141
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Gymnasium, Corridor near Room 146D
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Toilet Room 231
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

uestion	Response	
FIXTURES		
Student		
Toilet		
Condition	3- Fair	
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance	Toilet Room 101A	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Does not exist	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Inspected	
Instance	Boiler Room	
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Installation Year	2003	
Source of Installation Year	Documented	
Deficiency	DEFECTIVE CONTROL PANEL	
Deficiency Location/Instance	Boiler Room, Custodian's Office	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
HEATING	Inspected	
Heating Coil In Ductwork	Does not exist	
Hydronic Heating	Inspected	
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Backflow Preventer	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hot Water Heat Exchanger	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	KU
lestion	Response
IEATING	
Hydronic Heating	
Hot Water Heat Exchanger	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Radiator/Convector/Fin Tube	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System Condition	Inspected 3- Fair
Deficiency	No deficiencies recorded
Steam Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Terminal Unit Thermostatic Trap	Does not exist
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
IEATING PLANT	Inspected
Instance on Basement	Inspected
Is there a water meter on the boiler make-up water piping?	Yes
Observed Operational?	Yes
Burner Manufacturer	Webster
Burner Model	JB3C-50-EP170-M.30-MA-IRI
Burner Type	Dual Fuel (Gas/Oil)
Heating Plant Oil Number	2(B10)
Boiler Auxiliaries	T (1
Instance on Basement	Inspected
Boiler Auxiliary Piping	· · · · ·
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	FEEDWATER TANK:DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	20
Quantity Uom	S.F.

Building Condition Assessment Survey 2023-2024

stion	Response	
EATING PLANT		
Boiler Auxiliaries		
Boiler Feedwater System		
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Feedwater Treatment(Automatic)		
Instance on Basement	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Flue Exhaust		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Basement	Inspected	
Instance On Dasement	3- Fair	
Deficiency	DEFECTIVE RPZ	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Room Steam And Condensate Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
	No deficielles recorded	
Boiler Safety Valve	Inspected	
Instance on Basement	5- Poor	
Instance Condition		
Deficiency	DEFECTIVE	
Deficiency Location/Instance Deficiency Quantity	Boiler Room 4	
	-	
Quantity Uom Potential Action	EACH REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
oiler System	Increated	
Instance on Basement	Inspected	
Coal-fired Boiler	D	
Instance on Basement	Does not exist	
Hot Water Boiler		
Instance on Basement	Does not exist	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion		Response
EATING PLANT		
Boiler System		
Modular Boiler		
	on Basement	Does not exist
Steam Boiler	Ji Dusement	
	on Basement	Inspected
	on Basement	A
	on Basement	Inspected
Instance		Boiler Room
Instance (3- Fair
Instance (Quantity	4,301
Instance (Quantity Uom	MBH NET
Cast Iron	Boiler?	No
Manufact	urer	Kewanee Boiler Corporation
Equipmer	ntId	17875-01
	Size Quantity	5540
	Size UOM	MBH Gross
Source of	Capacity/Size	Documented
Installatio	on Year	2003
Source of	Installation Year	Documented
Deficienc	у	No deficiencies recorded
Instance		Boiler Room
Instance (Condition	3- Fair
Instance (Duantity	4,301
	Quantity Uom	MBH NET
Cast Iron		No
Manufact		Kewanee Boiler Corporation
		17875-02
Equipmen	Size Quantity	5540
		MBH Gross
	Size UOM Capacity/Size	Documented
Installatio		2003
	Installation Year	Documented
		DEFECTIVE SAFETY AUXILIARY: LOW-WATER CUT-OFF,
Deficienc	У	WATER COLUMN ASSEMBLY
Deficie	ncy Quantity	1
Quantit		EACH
	al Action	MAINTENANCE
	y of Action	PRIORITY 5
-	e of Action	LEVEL 6
Violatio		No violations recorded
Fuel System	on Basement	Inspected
		Inspected
	Louver/Damper	×
	on Basement	Inspected
Instance (Condition	3- Fair
Туре		Automatic
Deficienc	У	No deficiencies recorded
Burner/Burner	Control Panel	
Instance of	on Basement	Inspected
Instance (Condition	3- Fair
Deficienc		DUAL FUEL (OIL/GAS) BURNER:DEFECTIVE
	ncy Location/Instance	Boiler Room
	ncy Quantity	2
Quantit		EACH
	al Action	MAINTENANCE
i otentia	y of Action	PRIORITY 3

Building Condition Assessment Survey 2023-2024

uestion	Response	
	Kesponse	
HEATING PLANT Fuel System		
Burner/Burner Control Panel		
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fuel Oil Storage/Supply System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	FUEL OIL PIPING:DEFECTIVE/LEAKS	
Deficiency Location/Instance	Fuel Oil Tank Room B02	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Gas Trains And Vent At The Boiler		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Enclosed IDF Room	Inspected	
Instance on Rooms 111, 213, 313, 413	Inspected	
Dedicated A/C Equipment	inspected	
Instance on Rooms 111, 213, 313, 413	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DOES NOT EXIST	
Deficiency Location/Instance	Rooms 111, 213, 313, 413	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector	inspected	
Instance on 1st Floor	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE/MISSING	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Gas System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Grease Trap		
Instance on 1st Floor	Inspected	
Instance Condition	5- Poor	
Deficiency	DEFECTIVE/CLOGGED	
Deficiency Location/Instance	Kitchen, Room 165	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

		KU3
uestion	Response	
KITCHEN		
Grease Trap		
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Hood		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
· · · · · · · · · · · · · · · · · · ·	No deficiencies recorded	
Hood Fire Suppression System	Turnersted	
Instance on 1st Floor	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Hot Water Temperature Booster		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
ADF Room	Inspected	
Instance on Room 224	Inspected	
Dedicated A/C Equipment		
Instance on Room 224	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CIENCE DEMO ROOM	Inspected	
Instance on Room 302	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank		
Instance on Room 302	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector		
Instance on Room 302	Not required	
Emergency Shower		
Instance on Room 302	Does not exist	
Eye Wash		
Instance on Room 302	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		

Building Condition Assessment Survey 2023-2024

estion	Response	
CIENCE DEMO ROOM		
Hood Exhaust Ductwork		
Instance on Room 302	Does not exist	
Hood Exhaust Fan		
Instance on Room 302	Does not exist	
Fixed Laboratory Hood		
Instance on Room 302	Does not exist	
Laboratory Sink		
Instance on Room 302	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit		
Instance on Room 302	Does not exist	
CIENCE LAB	Does not exist	
CIENCE PREP ROOM	Inspected	
Instance on Room 302A	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank		
Instance on Room 302A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector		
Instance on Room 302A	Not required	
Emergency Shower		
Instance on Room 302A	Does not exist	
Eye Wash		
Instance on Room 302A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on Room 302A	Does not exist	
Hood Exhaust Fan		
Instance on Room 302A	Does not exist	
Fixed Laboratory Hood		
Instance on Room 302A	Does not exist	
Laboratory Sink		
Instance on Room 302A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit		
Instance on Room 302A	Does not exist	
PRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Inspected	
Condition	3- Fair	
Deficiency	NOT IN USE	
Deficiency Location/Instance	Pump Room B04	
Deficiency Quantity		
Quantity Uom	EACH	
Potential Action	NO ACTION	
Urgency of Action	PRIORITY 1	
Purpose of Action Violations	LEVEL 1	
	No violations recorded	
Fire Booster Pump Assembly Condition	Inspected 2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

R	0	58
11	v	50

uestion	Response
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Fire Booster Pump Assembly	
Deficiency	No deficiencies recorded
Roof Tank	Does not exist
Siamese Connection	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Exit 1, Auditorium, Corridors near Rooms 256, 407 (obstructed,
Denetency Escaled Instance	4)
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Inspected
Standpipe System	Inspected
Hose Valve Assembly	-
Condition	3- Fair
Deficiency	No deficiencies recorded
Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	DEFECTIVE
Deficiency Location/Instance	Emergency Generator Room B08 / EF-1 (bearing); Roof / WER-3
Denciency Location/Instance	(bearing)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Does not exist
Heating And Ventilating Unit Metal Ductwork	Inspected
Condition	2- Between Good and Fair
	2- Between Good and Fair No
Are there any uninsulated ductwork by design in Mechanical rooms? Are there chain operated dampers?	No No
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Penthouse MER
Deficiency Quantity	30
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

Building Condition Assessment Survey 2023-2024

chanical Inspection		R058
Question	Response	
VENTILATION		
Metal Ductwork		
Violations	No violations recorded	
Supply Fan	Does not exist	
Unit Ventilator	Does not exist	