Building Condition Assessment Survey 2023-2024

Asset:	THE RICHMOND PRE-K CENTER @ 1 TI STATEN ISLAND, NY, 10311	ELEPORT DRI	VE - STATEN I	SLAND, 1 TEL	EPORT DR	IVE,	
Inspection Id	Inspection Type			Time In		Last Edited	
3409	9 MECHANICAL			2024-02	-23 09:04AN	I 2024-03-31	11:33AM
set Data							
Ouestion			Answer				
	tems/Major Building Components been upgraded?			n Upgraded			
Are there fuel			No	поругания			
	er main service entries to the asset		0				
	ooms Locations			2, Fan Room 111			
	spaces with Missing or Defective CO Detectors?		No	_,			
-	Painted/Obstructed Sprinkler Heads?		Yes				
Location(s)	•		Corridor i	near Room 123 (ob	ostructed, 1)		
Are there any	Emergency Stop Switches with Missing Hammers?		No compo	onents			
iority Condi	ition						
	iority Condition	Component	Location	Person(s)	Person(s)	Photo	
	tegory Description	Affected	Description	* *	Title	Image	
No condition i	• •			1,0011104		ge	
	recorded						
spection							
Question			Response				
Mechanical							
AIR COND	DITIONING		Inspected				
	Vater System		Does not	exist			
	er Water Distribution: Piping, Pumps and Auxiliaries	 S	Inspected				
Condition		-	1- Good				
Ī	Deficiency		No defici	encies recorded			
	Coil in Ductwork		Does not	exist			
Cooling T			Does not	exist			
DX Split			Does not	exist			
Dry Cool	er		Does not	exist			
Packaged	/ Rooftop Unit		Inspected				
Ī	nstance		A/C MER	1.2			
I	nstance Condition		1- Good				
I	instance Quantity		1				
I	nstance Quantity Uom		EACH				
1	Manufacturer		Mammotl	1			
I	EquipmentId		AHU-1				
(Capacity/Size Quantity		68				
	Capacity/Size UOM		Tons				
_	Source of Capacity/Size		Inspector	Estimate			
	nstallation Year		2015				
	Source of Installation Year		Documen	ted			
_	Source of Heating Refrigerant Type		Hydronic R-410A				
_				encies recorded			
	Deficiency		Does not				
	Terminal A/C		Does not Does not				
Refrigera Refrigera	nt Leak Detection System		Does not				
Return Fa			Inspected				
Conditio			3- Fair				
_	Deficiency			IVE MOTOR			
1	Deficiency Location/Instance		Fan Roon				
	Deficiency Quantity		1				
	Quantity Uom		EACH				
	Potential Action			NANCE			

Building Condition Assessment Survey 2023-2024

Mechanical Inspection R068

uestion		Response	
AIR CO	NDITIONING		
Return	n Fan		
	Urgency of Action	PRIORITY 3	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
CENTR	AL ACID WASTE NEUTRALIZING TANK	Does not exist	
CLIMA	TE CONTROL SYSTEM	Inspected	
BMS		Inspected	
	Instance	Throughout	
	Instance Condition	2- Between Good and Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Building Area Covered by Operational System	81-100%	
	Installation Year	2015	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
Pneum	natic System	Does not exist	
	d System	Does not exist	
Electri	ic System	Does not exist	
COMPA	CTOR	Does not exist	
CONVE	YING	Does not exist	
DOMES	STIC WATER SYSTEM	Inspected	
	stic Cold Water System	Does not exist	
	stic Hot Water System	Inspected	
	estic Hot Water Remote Storage Tank	Does not exist	
	estic Water Heat Exchanger	Does not exist	
	tric Domestic Water Heater	Inspected	
Cor	ndition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
Gas l	Fired Domestic Water Heater	Does not exist	
	Fired Domestic Water Heater	Does not exist	
	Pump Domestic Water Heater	Does not exist	
	stic Water Distribution Piping	Inspected	
Cond		1- Good	
	Deficiency	DEFECTIVE VALVE	
	Deficiency Location/Instance	Water Heater Room 111.1	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	REPLACE	
	Urgency of Action	PRIORITY 3	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
DRAIN/	WASTE/VENT AND STORM SYSTEM	Inspected	
Interio	or Storm Piping	Inspected	
Cond	lition	1- Good	
	Deficiency	No deficiencies recorded	
Sewage	e/Waste/Vent Piping	Inspected	
Cond		1- Good	
	Deficiency	No deficiencies recorded	
Sewage	e Ejector Pump	Does not exist	
Sump		Does not exist	
	TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTUR		Inspected	
	and Other	Inspected	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection R068

nunicai Inspection		KUUO
Question	Response	
FIXTURES		
Staff And Other		
Janitor Sink	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Does not exist	
	Inspected	
HEATING		
Heating Coil In Ductwork Condition	Inspected 1- Good	
Deficiency	No deficiencies recorded	
Hydronic Heating	Inspected	
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Backflow Preventer	Does not exist	
Hot Water Heat Exchanger	Does not exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam Heating	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
HEATING PLANT	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector	mspecied	
Instance on 1st Floor	Not required	
Gas System		
Instance on 1st Floor	Does not exist	
	·	

Building Condition Assessment Survey 2023-2024

	NY.	Response	
KITCHE			
Grease	Instance on 1st Floor	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
Hood	Instance on 1st Floor	Does not exist	
Hood F	xhaust Ductwork	DOCS HOT CAIST	
11000 12	Instance on 1st Floor	Does not exist	
Hood F	xhaust Fan		
11004 12	Instance on 1st Floor	Does not exist	
Hood F	ire Suppression System		
11004 1	Instance on 1st Floor	Does not exist	
Hot Wa	ter Temperature Booster		
1100 ***	Instance on 1st Floor	Does not exist	
Kitcher			
11101101	Instance on 1st Floor	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
MDED			
MDF Roo		Inspected	
	Instance on Room 123	Inspected	
Dedicat	ted A/C Equipment	Y 1	
	Instance on Room 123	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
SCIENC	E DEMO ROOM	Does not exist	
SCIENC	E LAB	Does not exist	
SCIENC	E PREP ROOM	Does not exist	
SPRINK	LERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Spi	rinkler Alarm Valve Assembly	Does not exist	
Wet Sp	rinkler Alarm Valve Assembly	Does not exist	
Fire Bo	oster Pump Assembly	Does not exist	
Roof Ta	ınk	Does not exist	
Siames	e Connection	Does not exist	
Sprinkl	er Head	Inspected	
Condi		2- Between Good and Fair	
	Deficiency	DEFECTIVE/DETERIORATED	
	Deficiency Location/Instance	Corridor near Room 123 (obstructed, 1)	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	REPLACE	
	Urgency of Action	PRIORITY 5	
	Purpose of Action	LEVEL 6	
~	Violations	No violations recorded	
	er Piping	Inspected	
Condi		1- Good	
	Deficiency	No deficiencies recorded	
	ipe System	Does not exist	
Water (Does not exist	
SWIMM	ING POOL	Does not exist	
VENTIL.	ATION	Inspected	
Is the b	ouilding Mechanically ventilated?	Yes	
Exhaus	t Fan	Inspected	
Condi		2- Between Good and Fair	
Appro	oximate Total # of Fans	1-25	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection R068

uestion	Response		
VENTILATION			
Exhaust Fan			
Deficiency	No deficiencies recorded		
Heating And Ventilating Unit	Does not exist		
Metal Ductwork	Inspected		
Condition	1- Good		
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes		
Are there chain operated dampers?	No		
Deficiency	No deficiencies recorded		
Supply Fan	Does not exist		
Unit Ventilator	Does not exist		