Building Condition Assessment Survey 2023-2024

Asset:	I.S. 75 - STATEN	ISLAND, 455 HUG	UENOT AVENUE, STA	ATEN ISLAND	, NY, 10312		
Inspection	Id Inspection Type				Time	In	Last Edited
4	497 ELECTRICAL				2024	-04-03 08:59AN	1 2024-04-05 02:21PM
sset Data							
Question				Answer			
Have any S	Systems/Major Building C	Components been upgrade	ed?	Systems:	LED Lightin	g (Gymnasium, F	Rooms 421, 429, 116,
					128)		
				Years:	2023	D - 44 - 10 - 10	
				Systems:	Exit Lights (1	Battery Pack)	
				Years: Systems:	2022 Library (LEE	Lighting Races	way with Receptacles),
				Years:		, Intrusion Alarm	
				Systems:	Auditorium (Most Emergency Lighting
					(Battery Pack Frequency D		⁷ System, Variable
				Years:	2020		
				Systems:		Circuit Breaker	Panel Board
				Years:	2017, 2013, 2		
				Systems:		nnect Switch Typ	e Panel Board
				Years:	2017, 1985	(C	
				Systems:	Gymnasium 2017	(Scoreboard)	
				Years: Systems:	Fire Alarm S		dress System, Local
				Years:	Sound Syster 2016	n, Transformer, I	Partial Service Switch
				Systems:	Computer La	h Room 422	
				Years:	2013	5 ROOM 122	
				Systems:		g - Security	
				Years:	2012, 2006	6 ,	
				Systems:	·	Theater Lighting	System)
				Years:	2010		•
				Systems:	Interior Fluor	rescent Lighting	
				Years:	1997		
				Systems:	All Other Ele	ectrical Systems a	and Components
				Years:	1985		
Type of Se	rvice			Below G	round		
Does Intera	active Whiteboard (IWB)	Exist?		Yes			
	etration In Electrical Roon			No			
	TED INTERCOMS IN	N FIRE RESCUE AR	EAS				
Question	I :f- D A		reas, and/or Holding Roon		Response Yes		
your buil	•	lice Areas, Fire Rescue A	reas, and/or noiding Room	is in	ies		
	dicated intercoms availab	le in all of these spaces f	or use during a fire?		Yes		
	all dedicated intercoms ope				Yes		
riority Con							
Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
lo	Public Address System - Speakers Not Operational	N/A	Public Address System	Auditorium	Marco Saponara	Custodian	No Photo Taken
nspection	operational						
Question				Respons	e		
Electrical							
Encural							

AUDITORIUM

Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection

cal Inspection	RO
stion	Response
UDITORIUM	
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	1
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	l
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	lighting fixture not operational
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency Deficiency Quantity	LIGHTING FIXTURE BEYOND USEFUL LIFE 9
Quantity Uom	9 EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
	3- Fair
Instance Condition	
Deficiency Deficiency Quantity	LIGHTING FIXTURE BEYOND USEFUL LIFE
Quantity Uom	21 EACH
Potential Action	EACH REPLACE-UPGRADE
	PRIORITY 1
Urgency of Action	LEVEL 2
Purpose of Action Violations	LEVEL 2 No violations recorded
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist

Building Condition Assessment Survey 2023-2024

Electrical Inspection

estion	Response
UDITORIUM	
House Lighting	
Lighting Fixture - LED	
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Lighting	×
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Pendant Mounted	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Surface Mounted	
Instance on 1st Floor - Staff	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	63
Quantity Uom	EACH

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui Inspeciion	-	IXU / X
uestion	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	37	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Local Sound System		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Theater Lighting System		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	100	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	^
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	80
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency Deficiency Quantity	LIGHTING FIXTURE BEYOND USEFUL LIFE
Quantity Uom	2,250 EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	40
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
COMPUTER LAB	Inspected
Instance on Room 418	Inspected
Power Panel?	Yes
Instance on Room 422	Inspected
Power Panel?	Yes
Instance on Rooms 413, 420	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 418	Inspected
Instance on Room 422	Inspected
Instance on Rooms 413, 420	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 418	Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection

cai inspection	RU
estion	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Room 422	Inspected
Instance on Rooms 413, 420	Inspected
Pendant Mounted	
Instance on Room 422	Does not exist
Instance on Rooms 413, 420	Does not exist
Instance on Room 418	Does not exist
Surface Mounted	
Instance on Room 422	Does not exist
Instance on Rooms 413, 420	Does not exist
Instance on Room 418	Does not exist
Recessed Mounted	
Instance on Room 422	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 413, 420	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	53
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 418	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on Room 418	Does not exist
Instance on Room 422	Does not exist
Instance on Rooms 413, 420	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 418	Does not exist
Instance on Room 422	Does not exist
Instance on Rooms 413, 420	Does not exist
Lighting Fixture - LED	
Instance on Room 418	Does not exist
Instance on Room 422	Does not exist
Instance on Rooms 413, 420	Does not exist
Raceway With Receptacles	
Instance on Room 418	Does not exist
Instance on Room 422	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 413, 420	Inspected
Instance Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Electrical Inspection

rical Inspection	Response
	Response
COMPUTER LAB	
Raceway With Receptacles Deficiency	No deficiencies recorded
· · · · · · · · · · · · · · · · · · ·	
GYMNASIUM	Inspected
Instance on 2nd Floor	Inspected
Lighting Instance on 2nd Floor	T (1
	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	Descentaria
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Local Sound System	
Instance on 2nd Floor	
Instance Condition	2- Between Good and Fair
Installation Year Source of Installation Year	2016 Documented
Deficiency	No deficiencies recorded
Projection System Instance on 2nd Floor	Does not exist
Scoreboard	Does not exist
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	No deficiencies recorded
Theater Lighting System Instance on 2nd Floor	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	38
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

Building Condition Assessment Survey 2023-2024

Electrical Inspection

R07:		
	Response	Question
		KITCHEN
		Lighting
		Lighting Fixture - Fluorescent
		Recessed Mounted
	PRIORITY 1	Urgency of Action
	LEVEL 2	Purpose of Action
	No violations recorded	Violations
		Lighting Fixture - HID
	Does not exist	Instance on 1st Floor
		Lighting Fixture - Incandescent
	Does not exist	Instance on 1st Floor
		Lighting Fixture - LED
	Does not exist	Instance on 1st Floor
	Inspected	LIBRARY
	Inspected	Instance on Room 322
	^	Lighting
	Inspected	Instance on Room 322
		Lighting Fixture - Fluorescent
	Inspected	Instance on Room 322
		Pendant Mounted
	Does not exist	Instance on Room 322
		Surface Mounted
	Does not exist	Instance on Room 322
		Recessed Mounted
	Inspected	Instance on Room 322
	3- Fair	Instance Condition
EFUL LIFE	LIGHTING FIXTURE BEYOND USEFU	Deficiency
	45	Deficiency Quantity
	EACH	Quantity Uom
	REPLACE-UPGRADE	Potential Action
	PRIORITY 1	Urgency of Action
	LEVEL 2	Purpose of Action
	No violations recorded	Violations
		Lighting Fixture - HID
	Does not exist	Instance on Room 322
		Lighting Fixture - Incandescent
	Does not exist	Instance on Room 322
		Lighting Fixture - LED
	Inspected	Instance on Room 322
		Pendant Mounted
	Does not exist	Instance on Room 322
		Surface Mounted
	Does not exist	Instance on Room 322
		Recessed Mounted
	Inspected	Instance on Room 322
	1- Good	Instance Condition
	Inspected	Instance on Room 322
	Does not exist	
	No deficiencies recorded Inspected 1- Good No deficiencies recorded	Deficiency Raceway With Receptacles

NYC Department of Education **Building Condition Assessment Survey 2023-2024**

Electrical Inspection

uestion	Response	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Rooms 201, 251, 301, 351, 401, 451	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting	Increased	
Instance on Rooms 201, 251, 301, 351, 401, 451	Inspected	
Lighting Fixture - Fluorescent	Turner et al	
Instance on Rooms 201, 251, 301, 351, 401, 451	Inspected	
Pendant Mounted	D	
Instance on Rooms 201, 251, 301, 351, 401, 451	Does not exist	
Surface Mounted	D	
Instance on Rooms 201, 251, 301, 351, 401, 451	Does not exist	
Recessed Mounted		
Instance on Rooms 201, 251, 301, 351, 401, 451	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	119	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1 LEVEL 2	
Purpose of Action Violations		
	No violations recorded	
Lighting Fixture - HID	D	
Instance on Rooms 201, 251, 301, 351, 401, 451	Does not exist	
Lighting Fixture - Incandescent	D	
Instance on Rooms 201, 251, 301, 351, 401, 451	Does not exist	
Lighting Fixture - LED		
Instance on Rooms 201, 251, 301, 351, 401, 451	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Rooms 201, 251, 301, 351, 401, 451	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Rooms 201, 251, 301, 351, 401, 451	Does not exist	
Power Supply		
Instance on Rooms 201, 251, 301, 351, 401, 451	Does not exist	
Projection System		
Instance on Rooms 201, 251, 301, 351, 401, 451	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 323	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Room 323	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 323	Inspected	
Pendant Mounted		
Instance on Room 323	Does not exist	
Surface Mounted		
Instance on Room 323	Does not exist	
Recessed Mounted	2 000 nov exiter	
Instance on Room 323	Inspected	
	moperiou	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on Room 323	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 323	Does not exist
Lighting Fixture - LED	
Instance on Room 323	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 323	Does not exist
Emergency Shut-Off Power	
Instance on Room 323	Does not exist
Power Supply Instance on Room 323	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
	Does not exist
Lighting Fixture - LED	
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection

estion	Response	
OILET ROOM - STUDENT		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	6	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	25	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
UXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
MERGENCY DC STANDBY BATTERY POWER	Does not exist	-
MERGENCY GENERATOR SET	Inspected	
Automatic Transfer Switch (ATS)	Inspected	
Instance	Electrical Room C2	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ASCO	
EquipmentId	N/A	
Capacity/Size Quantity	100	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1985	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room C2	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Battery Charger	Inspected	
Instance	Outside Generator Enclosure	_
The second se	3- Fair	
Instance Condition		
	1	
Instance Condition Instance Quantity Instance Quantity Uom	1 EACH	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ieur Inspection		110
uestion	Response	
EMERGENCY GENERATOR SET		
Battery Charger		
EquipmentId	Battery Charger	
Capacity/Size Quantity	3	
Capacity/Size UOM	AmpsDC	
Capacity/Size 2 Quantity	12	
Capacity/Size 2 UOM	VDC	
Source of Capacity/Size	Nameplate	
Installation Year	1985	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Outside Generator Enclosure	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Emergency Distribution Board	Does not exist	
Diesel	Does not exist	-
Natural Gas	Inspected	
Instance	Outside Generator Enclosure	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Kohler Power Systems	
	Emergency Generator	
EquipmentId	49	
Capacity/Size Quantity		
Capacity/Size UOM Capacity/Size 2 Quantity	kVA 39	
Capacity/Size 2 UOM	kW	
Capacity/Size 3 Quantity	kw 135	
Capacity/Size 3 UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1985	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Outside Generator Enclosure	
Deficiency Quantity	1	
• • •	•	
Quantity Uom Potential Action	EACH REPLACE	
Potential Action Urgency of Action		
	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
MERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
MERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
	No deficiencies recorded	
Deficiency		
EXIT LIGHT	-	
EXIT LIGHT Battery Pack	Inspected Inspected	_

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		KU/
iestion	Response	
EXIT LIGHT		-
Battery Pack		
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
XIT/EMERGENCY LIGHT	Does not exist	
TRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Fire Alarm Digital Communicator Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity		
	1 EACH	
Instance Quantity Uom		
Manufacturer Model	Edwards System Technology	
	EST Fire Alarm Control Panel	
EquipmentId	2016	
Installation Year Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

rical Inspection	R075
Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Inspected
Tamper Flow Switch/Chain Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
	Does not exist
LIGHTNING PROTECTION	
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1985
Source of Installation Year	Documented
Deficiency	COMPARTMENT UNIT IS NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		10/5
Question	Response	
MOTOR CONTROLLER		
MOTOR CONTROL CENTER		
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	N/A	
Capacity/Size Quantity	200	
Capacity/Size UOM	Amps	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1985	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Fan Room 126	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
	MCC 3	
EquipmentId Capacity/Size Quantity	200	
Capacity/Size UOM	Amps	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1985	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	North Penthouse	
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Manufacturer	Federal Pacific Electric	
EquipmentId	MCC 4	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps 2	
Capacity/Size 2 Quantity Capacity/Size 2 UOM	2 Section(s)	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1985	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
	South Penthouse	
Instance Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	MCC 5	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1985	
Source of Installation Year	Documented	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ical inspection	KU.
uestion	Response
MOTOR CONTROLLER	
MOTOR CONTROL CENTER	
Deficiency	No deficiencies recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	North Penthouse
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Kitchen, 3rd Floor Closet
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 326
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2016
Source of Installation Year	Documented
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance Deficiency Quantity	Auditorium 4
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2020
Source of Installation Year	Documented

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response
SECURITY	
IPDVS/CCTV System	
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 133
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2021
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
	Inspected
Remote Annunciator	1- Good
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lighting - Security	Inspected 2- Between Good and Fair
Condition	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance Deficiency Quantity	Building Perimeters
Quantity Uom	8 EACH
Potential Action	EACH REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Deficiency Location/Instance	Building Perimeters
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room C2
Instance Condition	3- Fair
Instance Quantity	
	L EACH
Instance Quantity Uom	Federal Pacific Electric
Manufacturer	
EquipmentId	Main Dist SWBD 1B (LGT & PWR)
Capacity/Size Quantity Capacity/Size UOM	1500 Amps
Source of Capacity/Size	Amps Fuse Size
Installation Year	1985
Source of Installation Year	Documented

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uncui mi	specuon	K075
Question		Response
SERVICI	E SWITCH	
	Deficiency	No deficiencies recorded
	Instance	Electrical Room C2
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Federal Pacific Electric
	EquipmentId	Main Dist. SWBD 1A (LGT & PWR)
	Capacity/Size Quantity	1500
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Fuse Size
	Installation Year	1985
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	Electrical Room C2
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Federal Pacific Electric
		Main Dist SWBD 2
	EquipmentId Capacity/Size Quantity	1500
	Capacity/Size UOM	
	Source of Capacity/Size	Amps Fuse Size
	Installation Year	1985
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	Electrical Room C2
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1 EACH
	Instance Quantity Uom	
	Manufacturer	EATON
	EquipmentId	Main Solar
	Capacity/Size Quantity	400
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate 2016
	Installation Year Source of Installation Year	Documented
		No deficiencies recorded
	Deficiency	
SWITCH		Inspected
	of Spares	6
Fused D	Disconnect Switch Type	Inspected
	Instance	Electrical Room C2
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Federal Pacific Electric
	EquipmentId	N/A
	Capacity/Size Quantity	1500
	Capacity/Size UOM	Amps Total
	Capacity/Size 2 Quantity	3
	Capacity/Size 2 UOM	Section(s)
	Source of Capacity/Size	Service Switch Fuse Size
		1985
	Installation Year	
	Source of Installation Year	Documented

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	K
uestion	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	1500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1985
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C2
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	1500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1985
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
FRANSFORMER	Inspected
Instance	Electrical Room C2
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	MGM Transformer Company
EquipmentId	112.5 KVA Transformer
Equipmentid Capacity/Size Quantity	112.5 KVA Hanstonner 113
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Denelency	