Building Condition Assessment Survey 2023-2024

Asset:	PRE-K CENTE ISLAND, NY, 1	R @ 120 STUYVESANT P 0301	PLACE - STATEN	I ISLAND, 120 S	STUYVESAN	T PLACE, ST	ATEN
Inspection Id	Inspection Type				Time	In	Last Edited
3820) ELECTRICAL				2024-	·03-08 10:22AM	1 2024-03-27 11:42AM
set Data	-						
Question				Answer			
	tems/Major Building	Components been upgraded?		Systems:	All Electrical	Systems and Co	mponents
Have any Syst	icins/iviajor Building	Components occii upgraded:		Years:	2015	Bystems and Co	mponents
Type of Service	ne.			Below Gr			
	ve Whiteboard (IWB)) Exist?		Yes			
	tion In Electrical Roo			No			
DEDICATE	D INTERCOMS I	N FIRE RESCUE AREAS					
Question]	Response		
		ance Areas, Fire Rescue Areas,	and/or Holding Room	ns in	Yes		
your buildin							
		ble in all of these spaces for use	during a fire?		Yes		
	ledicated intercoms of	perational?		<u> </u>	Yes		
riority Condi	tion						
	iority	Condition	Component	Location	Person(s)	Person(s)	Photo
	itegory	Description	Affected	Description	Notified	Title	Image
No condition	recorded						
nspection							
Ouestion				Response	<u> </u>		
Electrical				•			
	TEIELD			Does not	evict		
ATHLETIC FIELD			Does not exist Does not exist				
AUDITORIUM			Does not exist Does not exist				
CAFETER							
	OM/CORRIDOR/A	DMINISTRATIVE SPACE		Inspected			
Lighting	C1 1.11 F.1.40		Inspected				
-	Chandelier Exist?			No			
	g Fixture - Fluoresce ant Mounted	ent		Inspected Inspected			
	dition					<u>, </u>	
_	Deficiency		2- Between Good and Fair				
			No deficiencies recorded				
	ce Mounted dition		Inspected 2- Between Good and Fair				
_			No deficiencies recorded				
Deficiency Recessed Mounted			Inspected				
	dition		2- Between Good and Fair				
			No deficiencies recorded				
Deficiency Lighting Fixture - HID				Does not			
	g Fixture - IIID g Fixture - Incandeso	cont		Does not			
	<u> </u>	tent		Inspected			
Lighting Fixture - LED Pendant Mounted				Does not			
	ce Mounted			Does not			
				Inspected			
Recessed Mounted Condition					en Good and Fai	r	
Deficiency				LIGHTING FIXTURE NOT OPERATIONAL			
1	Deficiency Quantity	<i>I</i>		LIGITIN 1	O I IA I UKE N	OI OILKAIIO.	1.12.12
	Quantity Uom			EACH			
	Potential Action			REPLAC	Е		
	Urgency of Action			PRIORIT			
	Purpose of Action			LEVEL 2			
	Violations			No violati	ions recorded		

Building Condition Assessment Survey 2023-2024

rical Inspection		R07
Question	Response	
COMPUTER LAB	Does not exist	
GYMNASIUM	Does not exist	
KITCHEN	Inspected	
Instance on 2nd Floor	Inspected	
Lighting_		
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Does not exist	
Recessed Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Does not exist	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on Room 238	Inspected	
Lighting		
Instance on Room 238	Inspected	
Lighting Fixture - Fluorescent	-	
Instance on Room 238	Inspected	
Pendant Mounted		
Instance on Room 238	Does not exist	
Surface Mounted		
Instance on Room 238	Does not exist	
Recessed Mounted		
Instance on Room 238	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 238	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 238	Does not exist	
Lighting Fixture - LED		
Instance on Room 238	Does not exist	
Local Sound System		
Instance on Room 238	Does not exist	
Projection System		
Instance on Room 238	Does not exist	
Theater Lighting System		
Instance on Room 238	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	

Building Condition Assessment Survey 2023-2024

ricai inspection		KU/
uestion	Response	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	-
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
	Does not exist	
EMERGENCY GENERATOR SET		
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
ran Shutuown Control		

Building Condition Assessment Survey 2023-2024

		110,
Question	Response	
FIRE ALARM SYSTEM		
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Does not exist	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Does not exist	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Does not exist	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist	
Tamper Flow Switch/Chain	Does not exist	
GROUNDING SYSTEM	Does not exist	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Does not exist	
Main Equipment Rack (MDF)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Telecommunication Room 206	
Instance Instance Condition	2- Between Good and Fair	
Instance Quantity	1	

Building Condition Assessment Survey 2023-2024

F		
Question	Response	
PUBLIC ADDRESS SYSTEM		
Model	Bogen Quantum Multicom IP	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	2- Between Good and Fair	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office - Room 208	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista - 128BP	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Does not exist	
SERVICE SWITCH	Inspected FL 4 in LP	
Instance	Building Owner Electrical Room 2- Between Good and Fair	
Instance Condition		
Instance Quantity	1 FACIL	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	Service Switch #2 2nd Floor	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	1	
Fused Disconnect Switch Type	Inspected	
Instance	Room 201	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	

Building Condition Assessment Survey 2023-2024

Question	Response		
SWITCHBOARD			
Fused Disconnect Switch Type			
Manufacturer	Electrotech		
EquipmentId	MDB		
Capacity/Size Quantity	1200		
Capacity/Size UOM	Amps Total		
Capacity/Size 2 Quantity	1		
Capacity/Size 2 UOM	Section(s)		
Source of Capacity/Size	Service Switch Size		
Installation Year	2015		
Source of Installation Year	Documented		
Deficiency	No deficiencies recorded		
Fused Knife Switch Type	Does not exist		
Molded Case Circuit Breaker Type	Does not exist		
TELEPHONE SYSTEM	Inspected		
PBX/Intercom	Inspected		
Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		
Standard	Inspected		
Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		
TRANSFORMER	Does not exist		