Building Condition Assessment Survey 2023-2024

Mechanical Inspection R091

Asset:	THE RICHMOND PRE-K CENTER @ 20 EBBITTS STREET - STATEN ISLAND, 20 EBBITTS STREET,
	STATEN ISLAND NV 10306

Inspection Id	Inspection Type	Time In	Last Edited
	MECHANICAL	2024-02-09 09:03AM	2024-03-23 03:02PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Boiler Make-up Water Backflow Preventer; Electric
	Domestic Water Heater
	Years: 2023
Are there fuel tanks?	No
Total # of water main service entries to the asset	1
MERs/Fan Rooms Locations	None
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Other	Defective (Flue gas leak in Boiler Room triggers CO/Gas Leak Detection System)	Boiler Flue Exhaust	Boiler Room	Thomas Maddocks	Custodian	

Inspection

uestion	Response
echanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	UP TO 5 TONS:DEFECTIVE CONTROLS
Deficiency Location/Instance	Elevator Machine Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Outdoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Inspected
Instance	Roof
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Carrier
EquipmentId	RTU-1
Capacity/Size Quantity	20

Mechanical Inspection	R091

iteut Inspection	
stion	Response
R CONDITIONING	
ackaged / Rooftop Unit	
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2019
Source of Installation Year	Documented
Source of Heating	Gas
Refrigerant Type	R-410A
Deficiency	No deficiencies recorded
Instance	Roof
Instance Condition	2- Between Good and Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	Carrier
EquipmentId	RTU-2
Capacity/Size Quantity	20
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2019
Source of Installation Year	Documented
Source of Heating	Gas
Refrigerant Type	R-410A
Deficiency	UP TO 20 TONS:DEFECTIVE GAS FURNACE
Deficiency Location/Instance	Roof
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance Instance Condition	Roof 1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Carrier
EquipmentId	RTU-3
Capacity/Size Quantity	13
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2019
Source of Installation Year	Documented
Source of Heating	Gas
Refrigerant Type	R-410A
Deficiency	No deficiencies recorded
Instance	Roof
Instance Condition	2- Between Good and Fair
Instance Quantity	
	1 EACH
Instance Quantity Uom	EACH
Manufacturer	Carrier
EquipmentId	RTU-4
Capacity/Size Quantity	20
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
	2019
Installation Year	2019
Installation Year Source of Installation Year	Documented

Building Condition Assessment Survey 2023-2024

Mechanical Inspection R091

nunicui Inspecuon		KU91
Question	Response	
AIR CONDITIONING		
Packaged / Rooftop Unit		
Refrigerant Type	R-410A	
Deficiency	UP TO 20 TONS:DEFECTIVE CONTROLS	
Deficiency Location/Instance	Roof	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Packaged Terminal A/C	Does not exist	
Refrigerant Leak Detection System	Does not exist	
Refrigerant Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Return Fan	Does not exist	
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist	
CLIMATE CONTROL SYSTEM	Inspected	
BMS	Inspected	
Instance	Throughout	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Building Area Covered by Operational System	81-100%	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Pneumatic System	Does not exist	
Hybrid System	Does not exist	
Electric System	Does not exist	
COMPACTOR	Does not exist	
CONVEYING	Inspected	
Dumbwaiter	Does not exist	
Elevator	Inspected	
Condition	1- Good	
Are all the existing elevators operable?	Yes	
Deficiency	No deficiencies recorded	
Escalator	Does not exist	
Non-auditorium Handicap Lift - Vertical	Does not exist	
Non-auditorium Handicap Lift - Stair	Does not exist	
Ash Hoist	Does not exist	
Sidewalk Elevator	Does not exist	
DOMESTIC WATER SYSTEM	Inspected	
	Inspected	
Domestic Cold Water System	Does not exist	
Gravity System		
Pressure Booster System	Does not exist	
Water Service	Inspected	
Instance	Water Meter Room 108A	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Deficiency	No deficiencies recorded	
	Inspected	
Domestic Hot Water System	Inspected .	

Mechanical Inspection	R091

	KUZ
Response	
1- Good	
No deficiencies recorded	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
Boiler Room	
1- Good	
1	
EACH	
Laars	
N/A	
200	
MBH Input	
0	
Gallons	
Documented	
-	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
No deliciencies recorded	
	1- Good No deficiencies recorded Does not exist Inspected 1- Good No deficiencies recorded Inspected Boiler Room 1- Good 1 EACH Laars N/A 200 MBH Input 0 Gallons Documented 2019 Documented No deficiencies recorded Does not exist Inspected 1- Good No deficiencies recorded Inspected Inspected 1- Good No deficiencies recorded Does not exist Inspected 1- Good No deficiencies recorded Does not exist Inspected 1- Good No deficiencies recorded Does not exist Inspected 1- Good No deficiencies recorded Does not exist Inspected 1- Good No deficiencies recorded Does not exist Inspected 1- Good No deficiencies recorded

Mechanical Inspection	R091
-----------------------	------

unicui Inspeciion		KUS
uestion	Response	
FIXTURES		
Student		
Drinking Fountain	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Does not exist	
Urinal		
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Does not exist	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Inspected	
Instance	Boiler Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
HEATING	Inspected	
Heating Coil In Ductwork	Does not exist	
Hydronic Heating	Inspected	
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Backflow Preventer	Does not exist	
Hot Water Heat Exchanger	Does not exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam Heating	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
HEATING PLANT	Inspected	
Instance on 1st Floor	Inspected	
Is there a water meter on the boiler make-up water piping?	No	
Burner Manufacturer	N/A	
Burner Model	N/A	
Burner Type	Gas	
Heating Plant Oil Number	N/A	

uestion	Response
HEATING PLANT	•
Boiler Auxiliaries	
Instance on 1st Floor	Inspected
Boiler Auxiliary Piping	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Boiler Feedwater System	110 40110101010101
Instance on 1st Floor	Does not exist
Boiler Feedwater Treatment(Automatic)	DOCS HOT CAIST
	December 1997
Instance on 1st Floor	Does not exist
Boiler Flue Exhaust	
Instance on 1st Floor	Does not exist
Boiler Make-up Water Backflow Preventer	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Boiler Room Steam And Condensate Piping	
Instance on 1st Floor	Does not exist
Boiler Safety Valve	
Instance on 1st Floor	Does not exist
Boiler System	
Instance on 1st Floor	Inspected
Coal-fired Boiler	
Instance on 1st Floor	Does not exist
Hot Water Boiler	
Instance on 1st Floor	Does not exist
Instance on 1st Floor Modular Boiler	Does not exist
Modular Boiler	
Modular Boiler Instance on 1st Floor	Inspected
Modular Boiler Instance on 1st Floor Instance on 1st Floor	Inspected Inspected
Modular Boiler Instance on 1st Floor Instance Instance	Inspected Inspected Boiler Room
Modular Boiler Instance on 1st Floor Instance Instance Instance Condition	Inspected Inspected Boiler Room 2- Between Good and Fair
Modular Boiler Instance on 1st Floor Instance on 1st Floor Instance Instance Condition Instance Quantity	Inspected Inspected Boiler Room 2- Between Good and Fair 559
Modular Boiler Instance on 1st Floor Instance Instance Instance Condition Instance Quantity Instance Quantity Uom	Inspected Inspected Boiler Room 2- Between Good and Fair 559 MBH NET
Instance on 1st Floor Instance on 1st Floor Instance Instance Instance Condition Instance Quantity Instance Quantity Uom Manufacturer	Inspected Inspected Boiler Room 2- Between Good and Fair 559 MBH NET Viessmann
Instance on 1st Floor Instance on 1st Floor Instance Instance Instance Condition Instance Quantity Instance Quantity Uom Manufacturer EquipmentId	Inspected Inspected Boiler Room 2- Between Good and Fair 559 MBH NET Viessmann 207170-01
Instance on 1st Floor Instance Instance Instance Instance Condition Instance Quantity Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity	Inspected Inspected Boiler Room 2- Between Good and Fair 559 MBH NET Viessmann 207170-01 643
Instance on 1st Floor Instance on 1st Floor Instance Instance Condition Instance Quantity Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM	Inspected Inspected Boiler Room 2- Between Good and Fair 559 MBH NET Viessmann 207170-01 643 MBH Gross
Instance on 1st Floor Instance on 1st Floor Instance Instance Condition Instance Quantity Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Source of Capacity/Size	Inspected Inspected Boiler Room 2- Between Good and Fair 559 MBH NET Viessmann 207170-01 643 MBH Gross Documented
Instance on 1st Floor Instance on 1st Floor Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Source of Capacity/Size Installation Year	Inspected Boiler Room 2- Between Good and Fair 559 MBH NET Viessmann 207170-01 643 MBH Gross Documented 2019
Instance on 1st Floor Instance on 1st Floor Instance Instance Condition Instance Quantity Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Source of Capacity/Size Installation Year Source of Installation Year	Inspected Boiler Room 2- Between Good and Fair 559 MBH NET Viessmann 207170-01 643 MBH Gross Documented 2019 Documented
Instance on 1st Floor Instance on 1st Floor Instance Instance Condition Instance Quantity Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency	Inspected Boiler Room 2- Between Good and Fair 559 MBH NET Viessmann 207170-01 643 MBH Gross Documented 2019 Documented DEFECTIVE FLUE EXHAUST
Instance on 1st Floor Instance on 1st Floor Instance Instance Condition Instance Quantity Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Deficiency Location/Instance	Inspected Boiler Room 2- Between Good and Fair 559 MBH NET Viessmann 207170-01 643 MBH Gross Documented 2019 Documented DEFECTIVE FLUE EXHAUST Boiler Room
Instance on 1st Floor Instance on 1st Floor Instance Instance Condition Instance Quantity Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Deficiency Quantity	Inspected Boiler Room 2- Between Good and Fair 559 MBH NET Viessmann 207170-01 643 MBH Gross Documented 2019 Documented DEFECTIVE FLUE EXHAUST Boiler Room 1
Instance on 1st Floor Instance Instance Instance Instance Condition Instance Quantity Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom	Inspected Boiler Room 2- Between Good and Fair 559 MBH NET Viessmann 207170-01 643 MBH Gross Documented 2019 Documented DEFECTIVE FLUE EXHAUST Boiler Room 1 EACH
Instance on 1st Floor Instance Instance Instance Instance Condition Instance Quantity Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action	Inspected Boiler Room 2- Between Good and Fair 559 MBH NET Viessmann 207170-01 643 MBH Gross Documented 2019 Documented DEFECTIVE FLUE EXHAUST Boiler Room 1 EACH MAINTENANCE
Instance on 1st Floor Instance Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Deficiency Quantity Quantity Uom Potential Action Urgency of Action	Inspected Boiler Room 2- Between Good and Fair 559 MBH NET Viessmann 207170-01 643 MBH Gross Documented 2019 Documented DEFECTIVE FLUE EXHAUST Boiler Room 1 EACH MAINTENANCE PRIORITY 5
Instance on 1st Floor Instance Instance Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action	Inspected Boiler Room 2- Between Good and Fair 559 MBH NET Viessmann 207170-01 643 MBH Gross Documented 2019 Documented DEFECTIVE FLUE EXHAUST Boiler Room 1 EACH MAINTENANCE PRIORITY 5 LEVEL 6
Instance on 1st Floor Instance Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Deficiency Quantity Quantity Uom Potential Action Urgency of Action	Inspected Boiler Room 2- Between Good and Fair 559 MBH NET Viessmann 207170-01 643 MBH Gross Documented 2019 Documented DEFECTIVE FLUE EXHAUST Boiler Room 1 EACH MAINTENANCE PRIORITY 5

Question	Response	
HEATING PLANT		
Boiler System		
Modular Boiler		
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam Boiler		
Instance on 1st Floor	Does not exist	
Fuel System		
Instance on 1st Floor	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector		
Instance on 1st Floor	Not required	
Gas System		
Instance on 1st Floor	Does not exist	
Grease Trap		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	

Does not exist	
Does not exist	
Inspected	
•	
Not required	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
Inspected	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Page 7 of 8	Print Date: 8/8/2024
	Does not exist Inspected Inspected Not required Does not exist Inspected 1- Good No deficiencies recorded Inspected 1- Good No deficiencies recorded Inspected Inspected Inspected Inspected Inspected Does not exist Does not exist Does not exist Does not exist

Building Condition Assessment Survey 2023-2024

Mechanical Inspection R091

uestion	Response
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected
Condition	1- Good
Approximate Total # of Fans	1-25
Deficiency	DEFECTIVE
Deficiency Location/Instance	Roof / GX1 (bearing)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	1- Good
Are there any uninsulated ductwork by design in Mechanical rooms?	No
Are there chain operated dampers?	No
Deficiency	No deficiencies recorded
Supply Fan	Does not exist
Unit Ventilator	Does not exist