# **Building Condition Assessment Survey 2023-2024**

Asset:	THE RICHMO	ND PRE-K CENTER @ 104	4 HOUSMAN AV	VENUE - STATE	EN ISLAND.	104 HOUSMA	N
113500		TEN ISLAND, NY, 10303	. 110 0000111111111	21.02 51111			- 1
Inspectio	n Id Inspection Type				Time	In	Last Edited
	5042 ELECTRICAL				2024	-04-30 11:52AM	2024-05-28 09:28
Asset Data							
Question	1			Answer			
Have any	Systems/Major Building	Components been upgraded?		Systems:	All Electrical	Systems and Co	mponents
				Years:	2019		
Type of S				Below Gr	ound		
	eractive Whiteboard (IWB) netration In Electrical Roo	<b>,</b>		Yes Yes			
		IN FIRE RESCUE AREAS		ies			
Question		IV FIRE RESCUE AREAS		]	Response		
		ance Areas, Fire Rescue Areas, a	nd/or Holding Roo		Yes		
•	ailding?						
	dedicated intercoms availar all dedicated intercoms or	ble in all of these spaces for use	during a fire?		Yes Yes		
		perationar:			108		
Priority Co Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Water Penetration in Electrical Room	Water penetrates through the foundation wall after	Electrical Equipment	Electrical Room C09	Blair Mathis	Fireman	No Photo Taken
		heavy rain.	1 1				
Inspection	ı						
Question				Response	<u> </u>		
Electrica							
ATHL	ETIC FIELD			Does not	exist		
-	TORIUM			Does not exist			
-	TERIA			Does not	exist		
		DMINISTRATIVE SPACE		Inspected			
Ligh				Inspected			
Do	es a Chandelier Exist?			No			
Lig	hting Fixture - Fluoresce	ent		Does not exist			
	hting Fixture - HID			Does not exist			
	hting Fixture - Incandes	cent		Does not exist			
_	hting Fixture - LED			Inspected Inspected			
Pendant Mounted Condition			2- Between Good and Fair				
Deficiency			No deficiencies recorded				
Surface Mounted			Inspected				
Condition			2- Betwee	en Good and Fa	ir		
Deficiency			No deficiencies recorded				
R	Recessed Mounted			Inspected			
Condition			2- Between Good and Fair				
Deficiency			No deficiencies recorded				
COMPUTER LAB			Does not exist				
GYMN	NASIUM			Does not	exist		
KITCI	HEN			Inspected			
	Instance on 2nd Floor	•		Inspected			
Light							
	Instance on 2nd Floor			Inspected			
Lig	thting Fixture - Fluoresce			Da 1	oviet		
				Does not	CAISI		
	Instance on 2nd Floor shting Fixture - HID			Does not	exist		

#### **Building Condition Assessment Survey 2023-2024**

Question	Response	
KITCHEN	<u> </u>	
Lighting		
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Does not exist	
Recessed Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on Room 103	Inspected	
Lighting		
Instance on Room 103	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 103	Does not exist	
Lighting Fixture - HID		
Instance on Room 103	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 103	Does not exist	

Inspected

Does not exist

Inspected Inspected

2- Between Good and Fair

No deficiencies recorded

Inspected

Instance on Room 103

 $\frac{Instance\ Condition}{Deficiency}$ 

**Pendant Mounted** 

**Surface Mounted** 

**Recessed Mounted** 

**Local Sound System** 

**Projection System** 

**Theater Lighting System** 

SCIENCE DEMO ROOM

SCIENCE PREP ROOM SWIMMING POOL

TOILET ROOM - STAFF

Lighting Fixture - Fluorescent Lighting Fixture - HID

Lighting Fixture - Incandescent

SCIENCE LAB

Lighting

# **Building Condition Assessment Survey 2023-2024**

Electrical Inspection R094

rical Inspection		R094
Question	Response	
TOILET ROOM - STAFF		
Lighting		
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
·	Does not exist	
EMERGENCY DC STANDBY BATTERY POWER		
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	

# **Building Condition Assessment Survey 2023-2024**

Electrical Inspection R094

	KU94
Response	
1- Good	
No deficiencies recorded	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
Inspected	
<del>_</del>	
1- Good	
1	
EACH	
Mircom	
Flex Net	
Fire Alarm Control Panel	
2019	
Does not exist	
<u>-</u>	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
	1- Good No deficiencies recorded Does not exist Inspected 1- Good No deficiencies recorded Inspected 1- Good No deficiencies recorded Does not exist Inspected 1- Good No deficiencies recorded Does not exist Inspected Main Entrance Lobby 1- Good 1 EACH Mircom Flex Net Fire Alarm Control Panel 2019 Documented No deficiencies recorded Does not exist Inspected Does not exist Inspected Toes not exist Inspected Does not exist Does not exist Does not exist Inspected Does not exist Inspected Does not exist Inspected 1- Good No deficiencies recorded Does not exist Does not exist Does not exist Does not exist Inspected 1- Good No deficiencies recorded Inspected Inspected I- Good No deficiencies recorded

# **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	K094

Question	Response
LAN	•
Main Equipment Rack (MDF)	
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
	Inspected
MOTOR CONTROLLER	Does not exist
MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
	Does not exist
Fused Disconnect Switch Type Fused Knife Switch Type	Does not exist  Does not exist
Fused Toggle Switch Type	Does not exist  Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
	Telecom Room 109
Instance Instance Condition	2- Between Good and Fair
Instance Quantity	1 EACH
Instance Quantity Uom	
Model	Bogen Multicom - 2000
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition Installation Year	2- Between Good and Fair
Installation Year Source of Installation Year	2019
Deficiency	Documented  No deficiencies recorded
Intrusion Alarm System	Inspected Inspected
Central Control Panel	
Instance	Custodian's Office - Room C05 2- Between Good and Fair
Instance Condition	
Instance Quantity	1 FACH
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
~ · · · · · · · · · · · · · · · · · · ·	

# **Building Condition Assessment Survey 2023-2024**

Electrical Inspection R094

rical Inspection	ROS
uestion	Response
SECURITY	
Intrusion Alarm System	
Siren/Strobe	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room C09
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
	CON EDISON 298CT CABINET & 1200A SS#1208Y/120V
EquipmentId	3PH
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	5
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room C09
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	MDP Section 1, 2, 3
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
	Lucinostad
Standard	Inspected
Standard Condition	1- Good
	<u> </u>