Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	THE RICHMOND PRE-K CENTER AT 2040 FOREST AVENUE - STATEN ISLAND, 2040 FOREST AVENUE, STATEN ISLAND, NY, 10303						
Inspection Id	Inspection Type			Time	In	Last Edited	
5082	MECHANICAL				2024-	-05-02 10:54AM	2024-05-20 11:00AN
sset Data							
Question				Answer			
Have any Systems/Major Building Components been upgraded?				No Syster	n Upgraded		
Are there fuel ta	anks?			No			
Total # of water	main service entrie	s to the asset		2			
MERs/Fan Roo	ms Locations			None			
	-	or Defective CO Detectors?		No			
	ainted/Obstructed S			No			
		ches with Missing Hammers?		No compo	onents		
riority Conditi	on						
Exist Prio	·	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year? Cate	egory	Description	Affected	Description	Notified	Title	Image
No condition re-	corded						
nspection							
Question				Response	2		
Mechanical							
AIR CONDI	TIONING			Inspected			
Chilled Wa				Does not			
		: Piping, Pumps and Auxiliarie	S	Does not			
	il in Ductwork			Does not			
Cooling To				Does not			
DX Split Sy				Inspected			
Indoor U				Inspected			
Conditio				1- Good			
	eficiency				encies recorded		
Outdoor				Inspected			
Conditio				1- Good			
	eficiency				encies recorded		
Dry Cooler				Does not			
	Rooftop Unit			Inspected			
	stance			Roof 1- Good			
	stance Condition						
	stance Quantity			1 EACH			
	stance Quantity Uon	1					
	anufacturer			Daikin RTU-1			
	uipmentId pacity/Size Quantity	,		40			
	pacity/Size Quantity	/		40 Tons			
	urce of Capacity/Siz	<i>r</i> e		Documen	ted		
	stallation Year			2020			
	urce of Installation	Year		Documen	ted		
So	urce of Heating			Gas			
Re	frigerant Type			R-410A			
De	eficiency			No defici	encies recorded		
Packaged T	erminal A/C			Does not	exist		
Refrigerant Leak Detection System				Does not			
Refrigerant Piping				Inspected			
Condition				1- Good			
	eficiency			No defici	encies recorded		
De	, increase y						

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

nanical Inspection		K09 6
Question	Response	
CLIMATE CONTROL SYSTEM	Inspected	
BMS	Inspected	
Instance	Throughout	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Building Area Covered by Operational System	81-100%	
Installation Year	2020	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Pneumatic System	Does not exist	
Hybrid System	Does not exist	
Electric System	Does not exist	
COMPACTOR	Does not exist	
CONVEYING	Does not exist	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Inspected	
Gravity System	Does not exist	
Pressure Booster System	Does not exist	
Water Service	Inspected	
Instance	Building Exterior - Water Meter Room	
Instance Condition	1- Good	
Instance Quantity	2	
Instance Quantity Uom	EACH	
Deficiency	No deficiencies recorded	
Domestic Hot Water System	Inspected	
Domestic Hot Water Remote Storage Tank	Does not exist	
Domestic Water Heat Exchanger	Does not exist	
Electric Domestic Water Heater	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas Fired Domestic Water Heater	Does not exist	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater	Does not exist	
Domestic Water Distribution Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Does not exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1- Good	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Response	
No deficiencies recorded	
-	
-	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Inspected	
Does not exist	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
	No deficiencies recordedDoes not existDoes not existInspected1- GoodNo deficiencies recordedDoes not existDoes not existInspectedInspected1- GoodNo deficiencies recordedDoes not existDoes not exis

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

		K09
uestion	Response	
KITCHEN		
Gas System		
Instance on 1st Floor	Does not exist	
Grease Trap		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System		
Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 1st Floor	Does not exist	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
ADF Room	Inspected	
Instance on Room 121	Inspected	
Dedicated A/C Equipment		
Instance on Room 121	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
CIENCE DEMO ROOM	Does not exist	
CIENCE LAB	Does not exist	
	Does not exist	
CIENCE PREP ROOM		
PRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Sprinkler Head	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sprinkler Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Standpipe System	Does not exist	
Water Gong	Inspected	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

uestion	Response		
SPRINKLERS, STANDPIPE, FIRE SYSTEM			
Water Gong			
Condition	3- Fair		
Deficiency	No deficiencies recorded		
SWIMMING POOL	Does not exist		
VENTILATION	Inspected		
Is the building Mechanically ventilated?	Yes		
Exhaust Fan	Inspected		
Condition	1- Good		
Approximate Total # of Fans	1-25		
Deficiency	No deficiencies recorded		
Heating And Ventilating Unit	Does not exist		
Metal Ductwork	Inspected		
Condition	1- Good		
Are there any uninsulated ductwork by design in Mechanical rooms?	No		
Are there chain operated dampers?	No		
Deficiency	No deficiencies recorded		
Supply Fan	Does not exist		
Unit Ventilator	Does not exist		