Building Condition Assessment Survey 2023-2024

Asset:	THE RICHMON	D PRE-K CENTER A ISLAND, NY, 10309	T 1275 WOODROW	ROAD - STATI	EN ISLAND,	1275 WOODR	OW
Inspection Id	Inspection Type				Time	In	Last Edited
3284	ELECTRICAL				2024	-02-16 09:55AM	2024-03-06 01:01PM
sset Data							
Question				Answer			
	ems/Major Building C	omponents been upgraded	49	Systems:	All Electrical	Systems and Cor	nnonents
Have any Syste	ems/Major Building Co	omponents been upgraded	11	Years:	2020	bystems and con	пропенс
Type of Servic	A			Below Gro			
	c ve Whiteboard (IWB) I	Exist?		Yes	Julia		
	ion In Electrical Room			No			
DEDICATE	D INTERCOMS IN	FIRE RESCUE ARE	EAS				
Question				F	Response		
		ice Areas, Fire Rescue Are	eas, and/or Holding Room	ms in	l'es		
your building							
		e in all of these spaces for	r use during a fire?		Yes		
	edicated intercoms ope	erational?)	l'es		
riority Condit	tion						
	ority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year? Cat	tegory	Description	Affected	Description	Notified	Title	Image
No condition r	ecorded						
nspection							
Question				Response			
Electrical							
ATHLETIC	FIELD			Does not e	exist		
AUDITORI				Does not e			
CAFETERI				Does not e			
		MINISTRATIVE CRAC	E.		ZAISt		
	JM/CORRIDOR/AD	MINISTRATIVE SPAC	<u>L</u>	Inspected			
Lighting Does a C	Chandelier Exist?			Inspected No			
-	Fixture - Fluorescen	<i>t</i>		Does not e	exist		
	Fixture - HID			Does not e			
	Fixture - Incandesce	ent		Does not e	exist		
	Fixture - LED	int .		Inspected			
<u> </u>	nt Mounted			Inspected			
Cond				1- Good			
	Deficiency				encies recorded		
	e Mounted			Does not e			
	ed Mounted			Inspected			
Cond				1- Good			
	Deficiency			No deficie	encies recorded		
COMPUTE				Does not e	exist		
GYMNASII				Does not e			
-	UIVI			Inspected	ZAISt		
KITCHEN	nstance on 2nd Floor			Inspected			
-	istance on 2nd F100f			mspecied			
Lighting_	nstance on 2nd Floor			Inspected			
-	Fixture - Fluorescen	<i>t</i>		nispected			
_	nstance on 2nd Floor	ı		Does not o	eviet		
				Does not 6	VISI		
_	g Fixture - HID			Does not e	viet		
	nstance on 2nd Floor Fixture - Incandesce	.n.t		Does not e	ZAISU		
T 2 T 4*		9111					
	nstance on 2nd Floor			Does not e	wiat		

Building Condition Assessment Survey 2023-2024

Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	
Pendant Mounted	1	
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Does not exist	
Recessed Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on Room 221	Inspected	
	nispected	
Lighting Instance on Room 221	Inspected	
Lighting Fixture - Fluorescent	inspected	
Instance on Room 221	Does not exist	
Lighting Fixture - HID	DOGS HOT CAIST	
Instance on Room 221	Does not exist	
Lighting Fixture - Incandescent	DOGS HOT CAIST	
Instance on Room 221	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Room 221	Inspected	
Pendant Mounted	Inspected	
Instance on Room 221	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Surface Mounted	110 0011010100	
Instance on Room 221	Does not exist	
Recessed Mounted	2040 100 01110	
Instance on Room 221	Does not exist	
Local Sound System		
Instance on Room 221	Does not exist	
Projection System		
Instance on Room 221	Does not exist	
Theater Lighting System		
Instance on Room 221	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting Eisture Eleganoscapt	Inspected Does not exist	
Lighting Fixture - Fluorescent	Does not exist Does not exist	
Lighting Fixture - HID Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - Incandescent	Learner de d	

Inspected
Does not exist

Inspected

Does not exist

Lighting Fixture - LED

Pendant Mounted

Surface Mounted Recessed Mounted

Building Condition Assessment Survey 2023-2024

ricai inspection		K10.
uestion	Response	
TOILET ROOM - STAFF		
Lighting		
Lighting Fixture - LED		
Recessed Mounted		
Condition	1- Good	
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack Condition	Inspected 1- Good	
	No deficiencies recorded	
Deficiency		
Non Battery Pack	Does not exist	
EXIT LIGHT	Inspected	
Battery Pack	Inspected 1- Good	
Condition		
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	1- Good	

Building Condition Assessment Survey 2023-2024

icui Inspection		KIUI
uestion	Response	
FIRE ALARM SYSTEM		
CO Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Parking Lot - Utility Room	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Notifier	
Model	N/A	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2020	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
HOIGING Area	LOCS HOLEXISI	

Building Condition Assessment Survey 2023-2024

icui Inspection	K
uestion	Response
LAN	
Local Distribution Frame (I/LDF)	Does not exist
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	MDF Room 204
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Multicom - 2000
Installation Year	2020
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2020
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 206
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2020
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	1- Good

Building Condition Assessment Survey 2023-2024

KIUI
Response
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Does not exist
Inspected
Parking Lot - Utility Room
1- Good
1
EACH
Electrotech
Service Disconnect (1275 Woodrow 2nd Floor) 1200
Amps Nameplate
2020
Documented
No deficiencies recorded
Inspected
l
Inspected
Electrical Room 219
1- Good
1
EACH
Electrotech
N/A
1200
Amps Total
1
Section(s)
Service Switch Size
2020
Documented
No deficiencies recorded
Does not exist
Does not exist
Inspected
Inspected
1- Good
No deficiencies recorded
Inspected
Inspected 1- Good
<u> </u>