Building Condition Assessment Survey 2023-2024

Mechanical Inspection

ncenunic	ui Inspection							KI
Asset:	3K CENTE	R @ 365 BAY STREET - STATE	N ISLAND, 36	5 BAY STREET	, STATEN IS	LAND, NY, 10	301	
Inspectio	on Id Inspection T	уре			Time	In	Last Edited	
	5136 MECHANIC	AL			2024	-05-03 10:31AM	1 2024-05-04 12	2:04A1
sset Data	I							
Question				Answer				
Have any Systems/Major Building Components been upgraded?				No Syster	n Upgraded			
Are there	e fuel tanks?			No				
Total # c	of water main service	entries to the asset		1				
	an Rooms Locations			None				
		sing or Defective CO Detectors?		No				
		ted Sprinkler Heads?		No				
		Switches with Missing Hammers?		No compo	onents			
Priority Co	ondition							
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo	
Last Year?	Category	Description	Affected	Description	Notified	Title	Image	
No cond	ition recorded							
nspection	n							
Question				Response	;			
Mechan	ical			*				
AIR C	CONDITIONING			Inspected				
	led Water System			Does not				
	v	ution: Piping, Pumps and Auxiliaries	5	Does not				
	ling Coil in Ductwor		-	Does not	exist			
-	ling Tower			Does not	exist			
DXS	Split System			Inspected				
Inc	door Unit			Inspected				
Condition				1- Good				
	Deficiency			No defici	encies recorded			
-	ıtdoor Unit			Inspected				
(Condition			1- Good				
	Deficiency			No defici	encies recorded			
	Cooler			Does not				
Pack	kaged / Rooftop Unit			Inspected				
	Instance			Roof				
	Instance Condition			1- Good				
	Instance Quantity			2				
	Instance Quantity	y Uom		EACH				
	Manufacturer			York				
	EquipmentId Capacity/Size Qu	iontity		RTU-1, R 15	10-3			
	Capacity/Size U	-		Tons				
	Source of Capaci			Inspector	Estimate			
	Installation Year	-		2022				
	Source of Install			Documen	ted			
	Source of Heatin			Gas				
	Refrigerant Type			R-410A				
	Deficiency			No defici	encies recorded			
	Instance			Roof				
	Instance Condition	on		1- Good				
	Instance Quantity	y		1				
	Instance Quantit	y Uom		EACH				
	Manufacturer			York				
	EquipmentId			RTU-2				
	Capacity/Size Qu			18				
	Capacity/Size U	OM		Tons				

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

1		III00
Juestion	Response	
AIR CONDITIONING		
Packaged / Rooftop Unit		
Source of Capacity/Size	Inspector Estimate	
Installation Year	2022	
Source of Installation Year	Documented	
Source of Heating	Gas	
Refrigerant Type	R-410A	
Deficiency	No deficiencies recorded	
Packaged Terminal A/C	Does not exist	
Refrigerant Leak Detection System	Does not exist	
Refrigerant Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Return Fan	Does not exist	
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist	
CLIMATE CONTROL SYSTEM	Inspected	
BMS	Inspected	
Instance	Throughout	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Building Area Covered by Operational System	81-100%	
Installation Year	2022	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Pneumatic System	Does not exist	
Hybrid System	Does not exist	
Electric System	Does not exist	
COMPACTOR	Does not exist	
CONVEYING	Inspected	
Dumbwaiter	Does not exist	
Elevator	Inspected	
Condition	1- Good	
Are all the existing elevators operable?	Yes	
Deficiency	No deficiencies recorded	
Escalator	Does not exist	
Non-auditorium Handicap Lift - Vertical	Does not exist	
Non-auditorium Handicap Lift - Stair	Does not exist	
Ash Hoist	Does not exist	
Sidewalk Elevator	Does not exist	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Inspected	
Gravity System	Does not exist	
Pressure Booster System	Does not exist	
Water Service	Inspected	
Instance	Basement	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Deficiency	No deficiencies recorded	
	Inspected	
Domestic Hot Water System Domestic Hot Water Remote Storage Tank	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Domestic Water Heat Exchanger	Does not exist	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

unicui Inspeciion		K10
uestion	Response	
DOMESTIC WATER SYSTEM		
Domestic Hot Water System		
Electric Domestic Water Heater	Does not exist	
Gas Fired Domestic Water Heater	Inspected	
Instance	Boiler Room	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Lochinvar	
EquipmentId	N/A	
Capacity/Size Quantity	199	
Capacity/Size UOM	MBH Input	
Capacity/Size 2 Quantity	0	
Capacity/Size 2 UOM	Gallons	
Source of Capacity/Size	Documented	
Installation Year	2022	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater	Does not exist	
Domestic Water Distribution Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Inspected	
Toilet	_	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

iunicai Inspeciion		K10
Question	Response	
FIXTURES		
Student		
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Does not exist	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Inspected	
Instance	Boiler Room	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Installation Year	2022	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
HEATING	Inspected Does not exist	
Heating Coil In Ductwork	Inspected	
Hydronic Heating Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Does not exist	
Backflow Preventer	Does not exist	
Hot Water Heat Exchanger		
Radiator/Convector/Fin Tube Condition	Inspected 1- Good	
	No deficiencies recorded	
Deficiency		
Steam Heating	Does not exist Does not exist	
Steam supplied by External Sources Unit Heater/Cabinet Heater	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
HEATING PLANT	Inspected	
Instance on Penthouse	Inspected	
Is there a water meter on the boiler make-up water piping?	No	
Burner Manufacturer Burner Model	N/A N/A	
Burner Type	IN/A Gas	
Heating Plant Oil Number	N/A	
Boiler Auxiliaries	1971	
Instance on Penthouse	Inspected	
Boiler Auxiliary Piping	r	
Instance on Penthouse	Inspected	
Instance Condition	1- Good	
	No deficiencies recorded	
Boiler Emergency Stop Switch		

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	KIU
Response	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
inspected	
Does not exist	
Does not exist	
Increated	
Does not exist	
Does not exist	
Inspected	
Not required	
Does not exist	
Y . 1	
Inspected	
	Inspected 1- Good No deficiencies recorded Does not exist Does not exist Does not exist Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

anical Inspection	Response	
KITCHEN	Response	
Grease Trap		
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System		
Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 1st Floor	Does not exist	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Room 107	Inspected	
Dedicated A/C Equipment	1	
Instance on Room 107	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist	
Fire Booster Pump Assembly Roof Tank	Does not exist Does not exist	
Siamese Connection	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sprinkler Head	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sprinkler Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Standpipe System	Inspected	
Standpipe System Hose Valve Assembly	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Piping Condition	Inspected 1- Good	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

uestion	Response		
SPRINKLERS, STANDPIPE, FIRE SYSTEM			
Water Gong	Does not exist		
SWIMMING POOL	Does not exist		
VENTILATION	Inspected		
Is the building Mechanically ventilated?	Yes		
Exhaust Fan	Inspected		
Condition	1- Good		
Approximate Total # of Fans	1-25		
Deficiency	No deficiencies recorded		
Heating And Ventilating Unit	Does not exist		
Metal Ductwork	Inspected		
Condition	1- Good		
Are there any uninsulated ductwork by design in Mechanical rooms?	No		
Are there chain operated dampers?	No		
Deficiency	No deficiencies recorded		
Supply Fan	Does not exist		
Unit Ventilator	Does not exist		