## **Building Condition Assessment Survey 2023-2024**

Electrical Insp	pection					R113
Asset:	3K CENTER @ 841 FATHER CAPO BOULEVARD, STATEN ISLAND, N		D - STATEN ISL	AND, 841 FA	ATHER CAPO	DANNO
Inspection Id	Inspection Type			Time	In	Last Edited
373	) ELECTRICAL			2024-	03-06 10:23AM	2024-05-07 12:06PM
Asset Data						
Question			Answer			
Have any Sys	tems/Major Building Components been upgrad	ed?	Systems:	Auxiliary Sign	nal/Bell System	
			Years:	2022		
			Systems:	Public Addres	ss System	
			Years:	2021		
			Systems:		ctrical Systems a	nd Components
			Years:	2019		
Type of Servi			Below Gro	ound		
	ve Whiteboard (IWB) Exist? tion In Electrical Room?		Yes No			
	D INTERCOMS IN FIRE RESCUE AR	FAS	NO			
Question	D INTERCOMS IN FIRE RESCUE AN	LAS	R	esponse		
-	ny Life Rescue Assistance Areas, Fire Rescue A	reas, and/or Holding Roo		•		
your buildir	ng?					
Priority Condi	ition					
	iority Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year? Ca	ntegory Description	Affected	Description	Notified	Title	Image
No condition	recorded					
Inspection						
Question			Response			
Electrical			Response			
	C FIFT B		Does not e	wint		
ATHLETIC						
AUDITOR			Does not e			
CAFETER			Does not e	X1St		
	OM/CORRIDOR/ADMINISTRATIVE SPA	CE	Inspected			
Lighting	Chandelier Exist?		Inspected No			
	g Fixture - Fluorescent		Inspected			
	ant Mounted		Does not e	xist		
-	ce Mounted		Inspected			
	dition			n Good and Fai	r	
]	Deficiency		No deficie	ncies recorded		
Reces	sed Mounted		Does not e	xist		
Lightin	g Fixture - HID		Does not e	xist		
Lightin	g Fixture - Incandescent		Does not e	xist		
Lightin	g Fixture - LED		Inspected			
Penda	ant Mounted		Does not e	xist		
	ce Mounted		Inspected			
-	dition			n Good and Fai	r	
	Deficiency			ncies recorded		
	sed Mounted		Inspected	0 1 15		
-	dition			n Good and Fai	r	
-	Deficiency			ncies recorded		
COMPUTI	ER LAB		Does not e			
GYMNASI	UM		Does not e	xist		
KITCHEN			Inspected			
	nstance on 1st Floor		Inspected			
Lighting						
1	nstance on 1st Floor		Inspected			

## **Building Condition Assessment Survey 2023-2024**

incui Inspection		
Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
	Does not exist	
MULTIPURPOSE ROOM		
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition Condition	1- Good	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	

## **Building Condition Assessment Survey 2023-2024**

icai Inspection		XIIJ
nestion	Response	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT LIGHT	Does not exist	
EXIT/EMERGENCY LIGHT	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
•		
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Does not exist	
Duct Smoke Detector	Does not exist	
Area Smoke Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected 1- Good	
Condition		
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected 1- Good	
Condition		
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Kidde United Technologies	
Model	VS Series	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	

## **Building Condition Assessment Survey 2023-2024**

ricui Inspection		KIIS
Question	Response	
FIRE ALARM SYSTEM		
Sprinkler Flow/Air Pressure Switch		
Condition	1- Good	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Does not exist	
Main Equipment Rack (MDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Main Office - Room 101	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Telecor 125	
Installation Year	2021	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	2- Between Good and Fair	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Does not exist	
Lighting - Security	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Exterior Electrical Room	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer		

## **Building Condition Assessment Survey 2023-2024**

Question	Response	
SERVICE SWITCH		
EquipmentId	N/A	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	