Building Condition Assessment Survey 2023-2024

Electrical Inspection R445

Asset:	PORT RICHMOND HS - S. I., 85 ST JOSEPHS AVE	NUE, STATEN ISLAN	D, NY, 10302	
Inspection Id	Inspection Type		Time In	Last Edited
4912	ELECTRICAL		2024-04-22 08:23AM	2024-05-23 07:33AN
et Data				
Question		Answer		
Have any Systems/Major Building Components been upgraded?		Systems:	Retrofitted Interior LED Lightin	g
		Years:	2024	
		Systems:	Auditorium (LED Lighting, Local	• //
			Floor Gymnasium (LED Lightin	g)
		Years:	2023	
		Systems:	Variable Frequency Drive	
		Years:	2021	
		Systems:	IPDVS/CCTV System	
		Years:	2020	
		Systems:	Lighting - Security	
		Years:	2019, 2010, 1993	
		Systems:	Auditorium (Theater Lighting Sy	ystem)
		Years:	2016	
		Systems:	Fire Alarm System (Electronic S	ub Panel)
		Years:	2015, 2014, 1993	
		Systems:	Transformer	
		Years:	2015, 1993	
		Systems:	Partial Intercom System (Elevator	or)
		Years:	2015	
		Systems:	Library (Raceway with Receptac	eles)
		Years:	2013	
		Systems:	Interior Fluorescent Lighting	

Intrusion Alarm System Years: 2007

Systems: Partial Service Switch, Partial Switchboard

2004, 1993 Years:

Years: Systems:

Systems: Science Rooms (Incandescent Lighting), Emergency

> Generator Set, Public Address System, Fire Alarm System, Motor Control Center, Most Molded Case Circuit Breaker Panel Board, Most Fused Disconnect

Switch Type Panel Board

1993 Years:

Below Ground

Yes No

Does Interactive Whiteboard (IWB) Exist? Water Penetration In Electrical Room?

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

DEDICHTED INTERCOME INTIME IEEE COLUMN				
Question	Response			
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes			
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes			
Are all dedicated intercoms operational?	Yes			

Priority Condition

Type of Service

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Fire Alarm System - Components Not Operational	Pull stations are out order.	Fire Alarm System - Manual Pull Station	Corridors: Pull stations number - 1, 2, 3, 43, 44 and 46	Mike Sapienza	Fireman	No Photo Taken

Electrical Inspection	R445
-----------------------	------

Electrica	al Inspection						R445
No	Emergency Generator Components - Not Operational	Emergency Generator cannot start.	Emergency Generator	Room A514	Mike Sapienza	Fireman	No Photo Taken
Yes	Fire Alarm System - Components Not Operational	Panel is completely out of order.	Fire Alarm System - Sub Panel	Auditorium Stage	Mike Sapienza	Fireman	
No	Water Leaks onto Electrical Equipment	Water leaks from the Plaza deck onto light fixture.	Lighting Fixture	Room 234	Mike Sapienza	Fireman	

pection	
Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 2nd Floor	Inspected
House Lighting	
Instance on 2nd Floor	Inspected
Does a Chandelier Exist?	Yes
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	

Electrical Inspection	R445
Question	Response

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - LED	
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System Instance on 2nd Floor	Inspected
	inspected
Dimming System Instance on 2nd Floor	Inconnected
Instance on 2nd Floor Instance Condition	Inspected 2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	T
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	1993
Source of Installation Year	Documented
Deficiency Quantity	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1 EACH
Quantity Uom Potential Action	EACH REPLACE SYSTEM
Partners Version 2.0 (P)	Page 3 of 23 Print Date: 8/8/2024

Electrical Inspection	K445

Question	Response			
CAFETERIA		Поролог		
Local Sound System				
Urgency of Action	PRIORITY 2			
Purpose of Action	LEVEL 2			
Violations	No violations recorded			
Projection System				
Instance on 1st Floor	Does not exist			
Theater Lighting System				
Instance on 1st Floor	Does not exist			
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected			
Lighting	Inspected			
Does a Chandelier Exist?	No			
Lighting Fixture - Fluorescent	Does not exist			
Lighting Fixture - HID	Does not exist			
Lighting Fixture - Incandescent	Does not exist			
Lighting Fixture - LED	Inspected			
Pendant Mounted	Inspected			
Condition	2- Between Good and Fair			
Deficiency	No deficiencies recorded			
Surface Mounted	Inspected			
Condition	2- Between Good and Fair			
Deficiency	No deficiencies recorded			
Recessed Mounted	Inspected			
Condition	2- Between Good and Fair			
Deficiency	No deficiencies recorded			
COMPUTER LAB	Inspected			
Instance on Rooms: B323, B327, B333, B337	Inspected			
Power Panel?	Yes			
Lighting	103			
Instance on Rooms: B323, B327, B333, B337	Inspected			
Lighting Fixture - Fluorescent	1			
Instance on Rooms: B323, B327, B333, B337	Does not exist			
Lighting Fixture - HID				
Instance on Rooms: B323, B327, B333, B337	Does not exist			
Lighting Fixture - Incandescent				
Instance on Rooms: B323, B327, B333, B337	Does not exist			
Lighting Fixture - LED				
Instance on Rooms: B323, B327, B333, B337	Inspected			
Pendant Mounted				
Instance on Rooms: B323, B327, B333, B337	Does not exist			
Surface Mounted				
Instance on Rooms: B323, B327, B333, B337	Does not exist			
Recessed Mounted				
Instance on Rooms: B323, B327, B333, B337	Inspected			
Instance Condition	2- Between Good and Fair			
Deficiency	No deficiencies recorded			
Raceway With Receptacles				
Instance on Rooms: B323, B327, B333, B337	Inspected			
Instance Condition	3- Fair			
Deficiency	No deficiencies recorded			
GYMNASIUM	Inspected			
Instance on 2nd Floor	Inspected			
Instance on 4th Floor	Inspected			
Lighting	пізресієй			
Enginenis				

Building Condition Assessment Survey 2023-2024

rical Inspection	Domana
uestion	Response
GYMNASIUM	
Lighting	
Instance on 2nd Floor	Inspected
Instance on 4th Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Does not exist
Instance on 4th Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Instance on 4th Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Instance on 4th Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected
Instance on 4th Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on 4th Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Does not exist
Instance on 4th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	no deficieles recorded
Instance on 2nd Floor	Does not exist
Instance on 2nd Floor	
	Does not exist
Local Sound System Instance on 2nd Floor	Towns de d
	Inspected 5- Poor
Instance Condition	1993
Installation Year Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	AMPLIFIER NOT OPERATIONAL 1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 4th Floor	Inspected
Instance Condition	5- Poor
Installation Year	1993
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2

LEVEL 2

Does not exist

Does not exist

No violations recorded

Purpose of Action

Instance on 2nd Floor

Instance on 4th Floor

Violations

Projection System

Electrical Inspection	K445

Question	Response
GYMNASIUM	
Scoreboard	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on 4th Floor	Does not exist
Theater Lighting System	
Instance on 2nd Floor	Does not exist
Instance on 4th Floor	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY_	Inspected
Instance on Room B403	Inspected
Lighting	
Instance on Room B403	Inspected
Lighting Fixture - Fluorescent	
Instance on Room B403	Does not exist
Lighting Fixture - HID	
Instance on Room B403	Does not exist
Lighting Fixture - Incandescent	
Instance on Room B403	Does not exist
Lighting Fixture - LED	
Instance on Room B403	Inspected
Pendant Mounted	
Instance on Room B403	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room B403	Does not exist
Recessed Mounted	
Instance on Room B403	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Raceway With Receptacles	Township
Instance on Room B403	Inspected 2. Petruson Cood and Fair
Instance Condition	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

cai inspection		K44
estion	Response	
IBRARY		
Raceway With Receptacles		
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room B403	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
OCKER ROOM	Inspected	
Instance on 2nd Floor - Boys	Inspected	
Alternative Use	No	
Instance on 2nd Floor - Girls	Inspected	
Alternative Use	No	
Instance on 4th Floor - Girls	Inspected	
Alternative Use	No	
Lighting		
Instance on 2nd Floor - Boys	Inspected	
Instance on 2nd Floor - Girls	Inspected	
Instance on 4th Floor - Girls	Inspected	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor - Boys	Does not exist	
Instance on 2nd Floor - Girls	Does not exist	
Instance on 4th Floor - Girls	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor - Boys	Does not exist	
Instance on 2nd Floor - Girls	Does not exist	
Instance on 4th Floor - Girls	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor - Boys	Does not exist	
Instance on 2nd Floor - Girls	Does not exist	
Instance on 4th Floor - Girls	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor - Boys	Inspected	
Instance on 2nd Floor - Girls	Inspected	
Instance on 4th Floor - Girls	Inspected	
Pendant Mounted		
Instance on 2nd Floor - Boys	Does not exist	
Instance on 2nd Floor - Girls	Does not exist	
Instance on 4th Floor - Girls	Does not exist	
Surface Mounted	DOGS HOL CAISE	
Instance on 2nd Floor - Boys	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on 2nd Floor - Girls		
	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Instance on 4th Floor - Girls	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor - Boys	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on 2nd Floor - Girls	Does not exist	

Electrical Inspection	R445

icai Inspection		10.1.
uestion	Response	
LOCKER ROOM		
Lighting		
Lighting Fixture - LED		
Recessed Mounted		
Instance on 4th Floor - Girls	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Rooms: B419, B421, B423, B427, B429, B438	Inspected	
Power Panel?	No	
Alternative Use	No	
Instance on Room B440	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting	110	
Instance on Rooms: B419, B421, B423, B427, B429, B438	Inspected	
Instance on Room B440	Inspected	
Lighting Fixture - Fluorescent	in passed	
Instance on Rooms: B419, B421, B423, B427, B429, B438	Does not exist	
Instance on Room B440	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on Rooms: B419, B421, B423, B427, B429, B438	Does not exist	
Instance on Room B440	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Rooms: B419, B421, B423, B427, B429, B438	Inspected	
Instance on Room B440	Does not exist	
Pendant Mounted	Does not exist	
Instance on Rooms: B419, B421, B423, B427, B429, B438	Does not exist	
Surface Mounted	Does not exist	
Instance on Rooms: B419, B421, B423, B427, B429, B438	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	No deficiencies recorded	
	Door not eviet	
Instance on Rooms: B419, B421, B423, B427, B429, B438	Does not exist	
Lighting Fixture - LED	Turnes de d	
Instance on Rooms: B419, B421, B423, B427, B429, B438	Inspected	
Instance on Room B440	Inspected	
Pendant Mounted	D	
Instance on Rooms: B419, B421, B423, B427, B429, B438	Does not exist	
Instance on Room B440	Does not exist	
Surface Mounted		
Instance on Rooms: B419, B421, B423, B427, B429, B438	Does not exist	
Instance on Room B440	Does not exist	
Recessed Mounted		
Instance on Rooms: B419, B421, B423, B427, B429, B438	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room B440	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Gas Shut-Off Valve		
Instance on Rooms: B419, B421, B423, B427, B429, B438	Does not exist	
Instance on Room B440	Does not exist	

Building Condition Assessment Survey 2023-2024

ciricai inspection		K443
Question	Response	
SCIENCE DEMO ROOM		
Emergency Shut-Off Power		
Instance on Rooms: B419, B421, B423, B427, B429, B438	Does not exist	
Instance on Room B440	Does not exist	
Power Supply		
Instance on Rooms: B419, B421, B423, B427, B429, B438	Inspected	
Instance on Room B440	Inspected	
Instructor Unit		
Instance on Rooms: B419, B421, B423, B427, B429, B438	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room B440	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Rooms: B419, B421, B423, B427, B429, B438	Does not exist	
Instance on Room B440	Does not exist	
Projection System		
Instance on Rooms: B419, B421, B423, B427, B429, B438	Does not exist	
Instance on Room B440	Does not exist	
SCIENCE LAB	Inspected	
Instance on Rooms: B415, B432, B437	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting	110	
Instance on Rooms: B415, B432, B437	Inspected	
Lighting Fixture - Fluorescent	шерессе	
Instance on Rooms: B415, B432, B437	Does not exist	
Lighting Fixture - HID		
Instance on Rooms: B415, B432, B437	Does not exist	
Lighting Fixture - Incandescent	2000 100 \$1100	
Instance on Rooms: B415, B432, B437	Inspected	
Pendant Mounted	шерессе	
Instance on Rooms: B415, B432, B437	Does not exist	
Surface Mounted	2000 100 \$1100	
Instance on Rooms: B415, B432, B437	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	To deficiences recorded	
Instance on Rooms: B415, B432, B437	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Rooms: B415, B432, B437	Inspected	
Pendant Mounted	nispected	
Instance on Rooms: B415, B432, B437	Does not exist	
Surface Mounted	Does not exist	
	Does not exist	
Instance on Rooms: B415, B432, B437	Does not exist	
Recessed Mounted	Inspected	
Instance on Rooms: B415, B432, B437 Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	ino deficiencies recorded	
Emergency Gas Shut-Off Valve	Ingnosted	
Instance on Rooms: B415, B432, B437	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

	17.7
Response	
Inspected	
3- Fair	
No deficiencies recorded	
Inspected	
Inspected	
3- Fair	
No deficiencies recorded	
Inspected	
3- Fair	
No deficiencies recorded	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Inspected	
-	
No	
Lucanostod	
-	
inspected	
Does not exist	
Does not exist	
Does not exist	
Inspected	
-	
No deficiencies recorded	
Does not exist	
Does not exist	
	Inspected 3 - Fair No deficiencies recorded Does not exist Inspected Inspected Inspected Inspected No No No Inspected Inspected No No No Inspected Does not exist Inspected Inspected Does not exist Inspected Does not exist Inspected Does not exist Does not exist Inspected Does not exist

Building Condition Assessment Survey 2023-2024

icui Inspection		17-7-
estion	Response	
SCIENCE PREP ROOM		
Lighting		
Lighting Fixture - LED		
Recessed Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room B431/B433	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room B428	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room B431/B433	Does not exist	
Emergency Shut-Off Power		
Instance on Room B428	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room B431/B433	Does not exist	
Power Supply		
Instance on Room B428	Inspected	
Instance on Room B431/B433	Does not exist	
Instructor Unit		
Instance on Room B428	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
SWIMMING POOL	Does not exist	
FOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
FOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Deficiency	Two deficiencies recorded	
Recessed Mounted	Inspected	

Building Condition Assessment Survey 2023-2024

icai Inspection	K
estion	Response
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MERGENCY DC STANDBY BATTERY POWER	Does not exist
MERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Basement - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler Power Systems
EquipmentId	Fire Alarm Transfer Switch
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room by Room A102
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler Power Systems
EquipmentId	800 Amp Transfer Switch 800
Capacity/Size Quantity	
Capacity/Size UOM Source of Capacity/Size	Amps
Installation Year	Nameplate 1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
	Inspected
Battery Charger Instance	Room A514
Instance Condition	3- Fair
Instance Quantity	1 EACH
Instance Quantity Uom	EACH
Manufacturer	Kohler Power Systems
EquipmentId	Automatic Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	26 NDG
Capacity/Size 2 UOM Source of Capacity/Size	VDC
	Nameplate 1993
Installation Year Source of Installation Year	Documented
	No deficiencies recorded
Deficiency	
Emergency Distribution Board	Inspected
Number of Spares	3 Increased
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room by Room A102
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
EquipmentId	EMDP-1
Capacity/Size Quantity	800

Building Condition Assessment Survey 2023-2024

iricai Inspection	N44
Question	Response
EMERGENCY GENERATOR SET	
Emergency Distribution Board	
Fused Disconnect Switch Type	
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Molded Case Circuit Breaker Type	Does not exist
Diesel	Inspected
Instance	Room A514
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler Power Systems
EquipmentId	Emergency Generator
Capacity/Size Quantity	250
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	200
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	694
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	GENERATOR NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
EXIT/EMERGENCY LIGHT	3- Fair
Condition	
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected

Building Condition Assessment Survey 2023-2024

		1177
estion	Response	
TRE ALARM SYSTEM		
Bell/Horn		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	PULL STATION NOT OPERATIONAL	
Deficiency Location/Instance	Corridors: number - 1, 2, 3, 43, 44, and 46	
Deficiency Quantity	6	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	E523986	
Fan Shutdown Control	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Does not exist	
Elevator Recall	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Office - Room A119	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Cerberus Pyrotronics	
Model	MXL	
EquipmentId	Fire Alarm Control Panel	
Installation Year	1993	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Inspected	

Building Condition Assessment Survey 2023-2024

m inspection		
tion	Response	
RE ALARM SYSTEM		
ub-Panel		
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Pyrosignal & Suppression, Inc	
Model	N/A	
EquipmentId	Smoke Purge Control Panel	
Installation Year	1993	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Cerberus Pyrotronics	
Model	CP - 35	
EquipmentId	Strobe Panel	
Installation Year	1993	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Honeywell	
Model	N/A	
EquipmentId	N/A	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Auditorium Stage	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Gamewell	
Model	Flex Series	
EquipmentId	Pre Action / Deluge Control	
Installation Year	2014	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Auditorium Stage	
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1 EACH	
Instance Quantity Uom	EACH	
Manufacturer	Faraday	
Model	N/A	
EquipmentId	Fire Alarm System 1993	
Installation Year		

Building Condition Assessment Survey 2023-2024

ricui Inspection		1443
Question	Response	
FIRE ALARM SYSTEM		
Sub-Panel		
Fire Alarm Control Panel (Electronic)		
Deficiency	PANEL NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	E523986	
Fire Alarm Control Panel (Standard)	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Punch Register		
Sprinkler Flow/Air Pressure Switch	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF) Condition	Inspected 3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Inspected	
Instance	Mechanical Room A512	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	MCC-A	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	

Electrical Inspection		K445
Question	Response	

- veur 1115p eeuro 11	Terror
Question	Response
MOTOR CONTROLLER	
MOTOR CONTROL CENTER	
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Mechanical Room A512
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	MCC-B
Capacity/Size Quantity	1200
Capacity/Size UOM	
Capacity/Size 2 Quantity	Amps 6
Capacity/Size 2 Quantity Capacity/Size 2 UOM	o Section(s)
Source of Capacity/Size	Nameplate 1993
Installation Year	
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, Fan Room by Kitchen
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
· · · · · · · · · · · · · · · · · · ·	
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room A123
Instance Condition	3- Fair
Instance Quantity	1 EACH
Instance Quantity Uom	EACH
Model	Rauland FAX 250
Installation Year	1993

Building Condition Assessment Survey 2023-2024

uestion	Response
PUBLIC ADDRESS SYSTEM	
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	49
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2020
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Room by Room B206
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
-	
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Parking Lot Entrance
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Basement - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	General Electric

Building Condition Assessment Survey 2023-2024

Electrical Inspection R445
Question Response

Inspection		11773
on	Response	
VICE SWITCH		
EquipmentId	2500Amp for 500KVA Transformer	
Capacity/Size Quantity	2500	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1993	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Basement - Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	General Electric	
EquipmentId	3000Amp for 750 KVA Transformer	
Capacity/Size Quantity	3000	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1993	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Basement - Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
	General Electric	
Manufacturer		
EquipmentId	4000Amp Main 4000	
Capacity/Size Quantity		
Capacity/Size UOM Source of Capacity/Size	Amps	
Installation Year	Nameplate 1993	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Basement - Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	HTG. EQUP. PWR. PNL	
Capacity/Size Quantity	250	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Fuse Size	
Installation Year	1968	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Basement - Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Basement - Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	

Building Condition Assessment Survey 2023-2024

ricai Inspection		N44
Question	Response	
SERVICE SWITCH		
EquipmentId	Kitch. Dist. PNL	
Capacity/Size Quantity	500	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Fuse Size	
Installation Year	1968	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Basement - Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Basement - Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1 FLOW	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	N/A	
Capacity/Size Quantity	2500	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2004	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Basement - Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	N/A	
Capacity/Size Quantity	2000	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2004	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Basement - Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Cutler Hammer	
EquipmentId	TCU MDP	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2004	-
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	3	
Fused Disconnect Switch Type	Inspected	
Instance	Basement - Electrical Room	
Instance Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

	_	
tion	Response	
TTCHBOARD		
used Disconnect Switch Type		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	General Electric	
EquipmentId	Kitchen	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1993	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Basement - Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Cutler Hammer	
EquipmentId	MDP	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	Amps rotal	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2004	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Basement - Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Manufacturer	General Electric	
EquipmentId	N/A	
Capacity/Size Quantity	4000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate 1993	
Installation Year Source of Installation Year		
	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	General Electric	
EquipmentId	N/A	
Capacity/Size Quantity	2000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	4	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1968	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	

Building Condition Assessment Survey 2023-2024

irea inspection		Ктто
Question	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Fan Room B140	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	N/A	
Capacity/Size Quantity	2000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	3	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1968	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Fan Room B140	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Inspected	
Instance	Basement - Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Hammond	
EquipmentId	112.5 KVA Transformer	
Capacity/Size Quantity	113	
Capacity/Size UOM	kVA	
Source of Capacity/Size	Nameplate	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Basement - Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
	General Electric	
Manufacturer	General Electric	

Building Condition Assessment Survey 2023-2024

Electrical Inspection R445

Question	Response
TRANSFORMER	
EquipmentId	500 KVA Transformer
Capacity/Size Quantity	500
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	International Transformer Corp.
EquipmentId	750 KVA Transformer
Capacity/Size Quantity	750
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded