Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Asset: PORT RICHMOND HS - S. I., 85 ST JOSEPHS AVENUE, STATEN ISLAND, NY, 10302				
Inspection Id	Inspection Type		Time In	Last Edited
4914	MECHANICAL		2024-04-22 07:47AM	2024-06-10 10:55AM
Asset Data				
Question		Answer		

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Fixtures - Drinking Fountains (~50%)
	Years: 2022
	Systems: F&T/Steam Drip Traps; Packaged Air Cooled Chiller
	for Room A219 (1 of 3)
	Years: 2020
	Systems: Boiler Safety Valves (4 of 8)
	Years: 2017
	Systems: Cooling Tower
	Years: 2016
	Systems: Elevator (1 of 2); DX Split System for Elevator Machine Room on 1st Floor (1 of 2); Boiler Make-up Water Backflow Preventer (1 of 2)
	Years: 2015
	Systems: Fixtures - Toilets, Urinals; Elevator refurbished (1 of 2); DX Split System for Elevator Machine Room in Boiler Room (1 of 2)
	Years: 2014
Are there fuel tanks?	Yes
Total # of above ground tanks	3
Total capacity of all above ground tanks in gal.	23,275
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	Boiler Room Mechanical Area; MERs below Kitchen and Stair "J"; Court Yard MER; MERs A102, B140, 501M ; PH MERs A508, A512; Gymnasium PH MER
Are there any spaces with Missing or Defective CO Detectors?	Yes
Location(s)	Emergency Generator Room A514, Science Demo Rooms B423, B427, B429, B438, B440
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Library, Room B142 (obstructed, 6); Rooms A134A, B256, B314 (painted, 4)
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Defective Sprinkler/Standpipe System	No water supply.	Dry Sprinkler Alarm Valve Assembly	Auditorium Stage	Mike Sapienza	Fireman	
Yes	Defective Kitchen Hood Fire Suppression System	Defective	Hood Fire Suppression System	Kitchen	Mike Sapienza	Fireman	
Inspection	1						

Question	Response
Mechanical	
AIR CONDITIONING	Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

nical Inspection	R4
estion	Response
IR CONDITIONING	
Chilled Water System	Inspected
Absorption Chiller	Does not exist
Air Cooled Chiller	Does not exist
Air Cooled Condenser	Does not exist
Chilled Water Distribution: Piping, Pumps and Auxiliaries	Inspected
Condition	3- Fair
Deficiency	PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	PH MER A512
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PIPING:DAMAGED/MISSING INSULATION
Deficiency Location/Instance	
Deficiency Quantity	Original Building - Roof 20
Quantity Uom	20 L.F.
Potential Action	L.r. MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	
	No violations recorded
Backflow Preventer	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Central Station Air Handler	Inspected
Instance	MER below Stair "J"
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	AC-C-1
Capacity/Size Quantity	6150
Capacity/Size UOM	CFM
Source of Capacity/Size	Inspector Estimate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Gymnasium PH MER
Instance Condition	3- Fair
Instance Quantity	
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	AC-B-2
Capacity/Size Quantity	2930
Capacity/Size UOM	CFM
Source of Capacity/Size	Inspector Estimate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Gymnasium PH MER
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

enunieur i	Inspection	K443
Question		Response
AIR CON	DITIONING	
Chilled	Water System	
-	al Station Air Handler	
	Manufacturer	Trane
	EquipmentId	AC-B-3
	Capacity/Size Quantity	6150
	Capacity/Size UOM	CFM
	Source of Capacity/Size	Inspector Estimate
	Installation Year	1993
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	MER B140
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Trane
	EquipmentId	AC-B-1
	Capacity/Size Quantity	8400
	Capacity/Size UOM	CFM
	Source of Capacity/Size	Inspector Estimate
	Installation Year	1993
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	PH MER A508
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Trane
	EquipmentId	AC-A-2
	Capacity/Size Quantity	10
	Capacity/Size UOM	Fan Motor HP
	Source of Capacity/Size	Documented
	Installation Year	1993
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	PH MER A512
	Instance Condition	3- Fair
	Instance Quantity	
		1 EACH
	Instance Quantity Uom	
	Manufacturer	Trane
	EquipmentId	AC-A-3
	Capacity/Size Quantity	15 E. M. E. M.
	Capacity/Size UOM	Fan Motor HP
	Source of Capacity/Size	Documented 1993
	Installation Year Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	Original Building - Courtyard MER
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Trane
	EquipmentId	AC-A-1
	Capacity/Size Quantity	25
	Capacity/Size UOM	Fan Motor HP
	Source of Capacity/Size	Documented

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

nicui Inspeciion		N4 4
estion	Response	
IR CONDITIONING		
Chilled Water System		
Central Station Air Handler		
Installation Year	1993	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Original Building - Roof	
Instance Condition	3- Fair	
Instance Quantity	3	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	AC-C-5, AC-C- 6, AC-C-7	
Capacity/Size Quantity	7100	
Capacity/Size UOM	CFM	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1993	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Original Building - Roof	
Instance Condition	3- Fair	
Instance Quantity	2	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	AC-C-3, AC-C-4	
Capacity/Size Quantity	12200	
Capacity/Size UOM	CFM	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1993	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room Mechanical Area	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	AC-C-2	
Capacity/Size Quantity	6150	
Capacity/Size UOM	CFM	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1993	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fan Coil Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Packaged Air Cooled Chiller	Inspected	
Instance	Original Building - Roof	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	#3	
Capacity/Size Quantity	44	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1993	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

		N44
estion	Response	
IR CONDITIONING		
Chilled Water System		
Packaged Air Cooled Chiller		
Source of Installation Year	Documented	
Refrigerant Type	N/A	
Deficiency	No deficiencies recorded	
Instance	Original Building - Roof	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	#4	
Capacity/Size Quantity	44	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1993	
Source of Installation Year	Documented	
Refrigerant Type	N/A	
Deficiency	No deficiencies recorded	
Instance	2nd Building Addition - Roof	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Daikin	
EquipmentId	ACCU-2A-1	
Capacity/Size Quantity	15	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Documented	
Installation Year	2020	
Source of Installation Year	Documented	
Refrigerant Type	R-410A	
Deficiency	No deficiencies recorded	
Water Cooled Chiller	Inspected	
Instance	PH MER A512	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	CH-1	
Capacity/Size Quantity	380	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Documented	
Installation Year	1993	
Source of Installation Year	Documented	
Refrigerant Type	R-22	
Deficiency	No deficiencies recorded	
Instance	PH MER A512	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	CH-2	
Capacity/Size Quantity	380	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Documented	
Installation Year	1993	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	1\4
Response	
Documented	
R-22	
No deficiencies recorded	
-	
*	
-	
-	
760	
*	
-	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
-	
-	
*	
No deficiencies recorded	
Inspected	
Under construction	
Under construction	
Does not exist	
Does not exist	
Does not exist Does not exist	
Does not exist Does not exist Does not exist Does not exist	
Does not exist Does not exist Does not exist Does not exist Inspected	
Does not exist Does not exist Does not exist Does not exist Inspected Does not exist	
Does not exist Does not exist Does not exist Does not exist Inspected Does not exist Inspected Inspected Inspected	
Does not exist Does not exist Does not exist Does not exist Inspected Does not exist	
	Documented R-22 No deficiencies recorded Inspected 3 - Fair No deficiencies recorded Does not exist Inspected 2nd Building Addition - Roof 1 - Good 1 EACH Evapco N/A 760 Tons Inspector Estimate 2014 Inspector Estimate No deficiencies recorded Inspector Estimate No deficiencies recorded Inspected 1 - Good No deficiencies recorded Inspected 1 - Good No deficiencies recorded Does not exist Inspected 1 - Good No deficiencies recorded Inspected 1 - Good No deficiencies recorded Inspected 1 - Good No deficiencies recorded Inspe

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	K44
Question	Response
CONVEYING	
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Inspected
Condition	4- Between Fair and Poor
Are all the existing non-auditorium vertical handicap lifts operable?	No
Deficiency	No deficiencies recorded
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Does not exist
Sidewalk Elevator	Inspected
Condition	3- Fair
Are all the existing sidewalk elevators operable?	Yes
Deficiency	No deficiencies recorded
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Boiler Room, Boiler Room Mechanical Area
Instance Condition	3- Fair
Instance Quantity	3
	EACH
Instance Quantity Uom	
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION
Deficiency Location (Locations	DEVICE
Deficiency Location/Instance Deficiency Quantity	Boiler Room / Sprinkler main
Quantity Uom	l EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected Does not exist
Domestic Hot Water Remote Storage Tank	Inspected
Domestic Water Heat Exchanger	
Condition	3- Fair
Deficiency	No deficiencies recorded
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sump Pump	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response	
RAIN/WASTE/VENT AND STORM SYSTEM		
Sump Pump		
Deficiency Location/Instance	MER below Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Inspected	
Dual Temperature Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Dual Temperature Terminal Fan Coil Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
IXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	MISSING INDIRECT WASTE	
Deficiency Location/Instance	Culinary Room A301(missing air gap)	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Urinal Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Student	Inspected	
Drinking Fountain		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Inspected	
Instance on 2nd Floor - Boys	Inaccessible	
Instance on 4th Floor - Girls	Inaccessible	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	2- Between Good and Fair	
	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

anical Inspection		K443
uestion	Response	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Does not exist	
HEATING	Inspected	
Heating Coil In Ductwork	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hydronic Heating	Inspected	
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Backflow Preventer	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hot Water Heat Exchanger	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Radiator/Convector/Fin Tube	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Heating	Inspected	
F&T/Steam Drip Trap	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
MER Steam and Condensate Piping	Inspected	
	3- Fair	
	No deficiencies recorded	
Deficiency		
Steam Condensate Return Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Pumping System	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Terminal Unit Thermostatic Trap	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
HEATING PLANT	Inspected	
Instance on Basement	Inspected	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response
IEATING PLANT	
Is there a water meter on the boiler make-up water piping?	Yes
Observed Operational?	No
Burner Manufacturer	Industrial Combustion
Burner Model	DEG- 145S
Burner Type	Dual Fuel (Gas/Oil)
Heating Plant Oil Number	2(B10)
Boiler Auxiliaries	
Instance on Basement	Inspected
Boiler Auxiliary Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
	No deficiencies recorded
Boiler Feedwater Treatment(Automatic)	D
Instance on Basement	Does not exist
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Boiler Room Steam And Condensate Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
	No deficiencies recorded
Boiler Safety Valve	T 1
Instance on Basement	
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Boiler System	
Instance on Basement	Inspected
Coal-fired Boiler	
Instance on Basement	Does not exist
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	6,949
Instance Quantity Uom	MBH NET

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

conunieur inspection		R113
Question	Response	
HEATING PLANT		
Boiler System		
Steam Boiler		
Cast Iron Boiler?	Yes	
Manufacturer	H. B. Smith Co., Inc.	
EquipmentId	7001-01	
Capacity/Size Quantity	6949	
Capacity/Size UOM	MBH Net	
Source of Capacity/Size	Documented	
Installation Year	1993	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	6,949	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	Yes	
Manufacturer	H. B. Smith Co., Inc.	
EquipmentId	7001-02	
Capacity/Size Quantity	6949	
Capacity/Size UOM	MBH Net	
Source of Capacity/Size	Documented	
Installation Year	1993	
Source of Installation Year	Documented	
Deficiency	DAMAGED REFRACTORY	
Deficiency Quantity	30	
	S.F.	
Quantity Uom Potential Action		
	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	6,949	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	Yes	
Manufacturer	H. B. Smith Co., Inc.	
EquipmentId	7001-03	
Capacity/Size Quantity	6949	
Capacity/Size UOM	MBH Net	
Source of Capacity/Size	Documented	
Installation Year	1993	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	6,949	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	Yes	
Manufacturer	H. B. Smith Co., Inc.	
EquipmentId	7001-04	
Capacity/Size Quantity	6949	
Capacity/Size UOM	MBH Net	
Source of Capacity/Size	Documented	
Installation Year	1993	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
=,		

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response
IEATING PLANT	1
Fuel System	
Instance on Basement	Inspected
Boiler Fresh Air Louver/Damper	1
Instance on Basement	Inspected
Instance Condition	3- Fair
Туре	Automatic
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Fuel Oil Storage/Supply System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Trains And Vent At The Boiler	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Enclosed IDF Room	Inspected
Instance on Original Building - Rooms B256, B345, B426; 2nd	Inspected
Building Addition - Room A302	1
Dedicated A/C Equipment	
Instance on Original Building - Rooms B256, B345, B426; 2nd Building Addition - Room A302	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DOES NOT EXIST
Deficiency Location/Instance	Original Building - Rooms B256, B345, B426; 2nd Building Addition - Room A302
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
AITCHEN	Inspected
Instance on 1st Floor	Inspected
CO Detector	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Gas System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Grease Trap	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

anical Inspection		K4 4
uestion	Response	
KITCHEN		
Hood Exhaust Ductwork		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System		
Instance on 1st Floor	Inspected	
Instance Condition	5- Poor	
Deficiency	DEFECTIVE/DETERIORATED	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Hot Water Temperature Booster		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on 2nd Building Addition - Room A103	Inspected	
Dedicated A/C Equipment		
Instance on 2nd Building Addition - Room A103	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Inspected	
Instance on Rooms B419, B421	Inspected	
Alternative Use	No	
Instance on Rooms B423, B427, B429, B438, B440	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank	110	
Instance on Rooms B419, B421	Does not exist	
Instance on Rooms B423, B427, B429, B438, B440	Does not exist	
CO Detector		
Instance on Rooms B419, B421	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Instance on Rooms B423, B427, B429, B438, B440	Inspected 4- Between Fair and Poor	
Instance Condition		
Deficiency	DEFECTIVE/MISSING	
Deficiency Location/Instance Deficiency Quantity	Rooms B423, B427, B429, B438, B440	
	5 EACH	
Quantity Uom Potential Action	EACH MAINTENANCE	
Potential Action	MAINTENANCE	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

unical Inspection		K4
uestion	Response	
SCIENCE DEMO ROOM		
CO Detector		
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Emergency Shower		
Instance on Rooms B419, B421	Does not exist	
Instance on Rooms B423, B427, B429, B438, B440	Does not exist	
Eye Wash		
Instance on Rooms B419, B421	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms B423, B427, B429, B438, B440	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on Rooms B419, B421	Does not exist	
Instance on Rooms B423, B427, B429, B438, B440	Does not exist	
Hood Exhaust Fan		
Instance on Rooms B419, B421	Does not exist	
Instance on Rooms B423, B427, B429, B438, B440	Does not exist	
Fixed Laboratory Hood		
Instance on Rooms B419, B421	Does not exist	
Instance on Rooms B423, B427, B429, B438, B440	Does not exist	
Laboratory Sink		
Instance on Rooms B419, B421	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms B423, B427, B429, B438, B440	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit		
Instance on Rooms B419, B421	Does not exist	
Instance on Rooms B423, B427, B429, B438, B440	Does not exist	
CIENCE LAB	Inspected	
Instance on Room B415	Inspected	
Alternative Use	No	
Instance on Room B432	Inspected	
Alternative Use	No	
Instance on Room B437	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank		
Instance on Room B415	Does not exist	
Instance on Room B432	Does not exist	
Instance on Room B437	Does not exist	
CO Detector		
Instance on Room B415	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Instance on Room B432	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Instance on Room B437	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	

NYC Department of Education Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	K44
lestion	Response
CIENCE LAB	
Emergency Shower	
Instance on Room B415	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room B432	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room B437	Does not exist
Eye Wash	
Instance on Room B415	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room B432	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room B437	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on Room B415	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room B432	Does not exist
Instance on Room B437	Does not exist
Hood Exhaust Fan	
Instance on Room B415	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room B432	Does not exist
Instance on Room B437	Does not exist
Fixed Laboratory Hood	
Instance on Room B415	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room B432	Does not exist
Instance on Room B437	Does not exist
Laboratory Sink	
Instance on Room B415	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
	VALVE,ETC.)
Deficiency Location/Instance	Room B415
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room B432	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room B437	Inspected
Instance Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

		K44
Question	Response	
SCIENCE LAB		
Laboratory Sink		
Deficiency	No deficiencies recorded	
Make-up Air Unit		
Instance on Room B415	Does not exist	
Instance on Room B432	Does not exist	
Instance on Room B437	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room B428	Inspected	
Alternative Use	No	
Instance on Room B431/B433	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank		
Instance on Room B428	Does not exist	
Instance on Room B431/B433	Does not exist	
CO Detector		
Instance on Room B428	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Instance on Room B431/B433	Not required	
Emergency Shower	1	
Instance on Room B428	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room B431/B433	Does not exist	
Eye Wash		
Instance on Room B428	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room B431/B433	Does not exist	
Hood Exhaust Ductwork		
Instance on Room B428	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room B431/B433	Does not exist	
Hood Exhaust Fan		
Instance on Room B428	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room B431/B433	Does not exist	
Fixed Laboratory Hood		
Instance on Room B428	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room B431/B433	Does not exist	
Laboratory Sink		
Instance on Room B428	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room B431/B433	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit Instance on Room B428	Does not exist	
	DOG NOT CAIST	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

lestion	Response
CIENCE PREP ROOM	
Make-up Air Unit	
Instance on Room B431/B433	Does not exist
PRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Auditorium Stage
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Wet Sprinkler Alarm Valve Assembly	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Library, Room B142 (obstructed, 6); Rooms A134A, B256, B314
Definition Quantita	(painted, 4)
Deficiency Quantity	10 E A CH
Quantity Uom	EACH
Potential Action Urgency of Action	REPLACE PRIORITY 5
Purpose of Action	LEVEL 6
Violations	LEVEL 0 11686953P
	Inspected
Sprinkler Piping Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Standpipe System	Inspected
Hose Valve Assembly	
Condition	3- Fair
Deficiency	No deficiencies recorded
Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Gong	Does not exist
WIMMING POOL	Does not exist
ENTILATION	Inspected
Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response
TENTILATION	
Exhaust Fan	
Approximate Total # of Fans	26-50
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	Yes
Deficiency	DEFECTIVE DUCTWORK
Deficiency Location/Instance	Roof @ EF-C12
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE REGISTER/DIFFUSER
Deficiency Location/Instance	Janitor Closet A116; 2nd Floor Gymnasium; Corridor near Rooms A218, B348, B427
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Boiler Room Mechanical Area; MER below Kitchen, MERs A102, B140, 501M ; PH MERs A508, A512; Original Building Roof
Deficiency Quantity	120
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Supply Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-5
Deficiency	No deficiencies recorded
Unit Ventilator	Does not exist