Building Condition Assessment Survey 2023-2024

Electrical Inspection R450

Asset:	CURTIS HS - STATEN ISLAND, 105 HAMILTON AVENUE, STA	ATEN ISL	AND, NY, 10301	
Inspection Id	Inspection Type		Time In	Last Edited
4673	ELECTRICAL		2024-04-10 08:57AM	2024-05-16 10:51AN
et Data				
Question		Answer		
Have any Syste	ms/Major Building Components been upgraded?	Systems:	LAN, Telephone System	
, ,		Years:	2024	
		Systems:	Interior LED Retrofitted Lighting Entrance Lobby, Library), Partia	
			Emergency Lighting (Non Batter	ry Pack)
		Years:	2023	
		Systems:	Exit Lights (Battery Pack), Light	ting - Security,
		Years:	2022	
		Systems:	Partial Molded Case Circuit Brea Boards	aker Type Panel
		Years:	2021, 2017, 2014, 2008, 2003	
		Systems:	Fire Alarm System	
		Years:	2021	1.0
		Systems:	Public Address System, Local So (Auditorium, Gymnasium, Stude Swimming Pool), Auxiliary/Sigr IPDVS/CCTV System	ent Cafeteria,
		Years:	2019	
		Systems:	Intrusion Alarm System (Central	Control Panel)
		Years:	2017, 2004	
		Systems:	Auditorium (Theater Lighting Sy Frequency Drive, Partial Ground Motor Starters	
		Years:	2017	
		Systems:	Science Prep Rooms, Science La	ıb
		Years:	2014	
		Systems:	Auditorium (Projection System)	
		Years:	2012	
		Systems:	Partial Fused Disconnect Switch	Type Panel Board
		Years:	2009, 2005	
		Systems:	Partial Switchboard	
		Years:	2009	
		Systems:	Panel	ency Light/Exit Light
		Years:	2004	
Type of Service		Below Gr	ound	
	e Whiteboard (IWB) Exist?	Yes		
	on In Electrical Room?	No		
	D INTERCOMS IN FIRE RESCUE AREAS			
Question	Tion And A Pinn A 1/ Will by		Response	
	Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in)	Yes	
your building Are dedicate	ed intercoms available in all of these spaces for use during a fire?	•	Yes	
	dicated intercoms operational?		Yes	

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Intercom - Not Connected to Remote Monitoring Station	N/A	Intercom System - Elevator	Elevator - Device ID# 5P264	Joseph Cordero	Custodian	No Photo Taken
Yes	Fire Alarm System - Defective	N/A	Fire Alarm System	Main Entrance Lobby	Joseph Cordero	Custodian	No Photo Taken

lectrica	l Inspection							R45
Yes	Water Leaks onto Electrical Equipment	Roof and Wall Leaks	Lighting Fixture, Manual Pull Station, Emergency Lighting	Room 401, Exit 22 Vestibule, Corridor near Boys Locker Room	Joseph Cordero	Custodian	No Photo Taken	
ves .	Fire Alarm System - Components Missing	N/A	Fire Alarm System - Magnetic Door Holder/Contac tor	Corridor near Rooms 320, 220, 122	Joseph Cordero	Custodian	No Photo Taken	
nspecti	on							
Quest	ion			Response				
Electr	rical							
ATE	HLETIC FIELD			Does not o	exist			
AUI	DITORIUM			Inspected				
	Instance on 1st Floor			Inspected				
He	ouse Lighting							
	Instance on 1st Floor			Inspected				
_	Does a Chandelier Exi	st?		No				
1	Lighting Fixture - Fluoresce	nt						
_	Instance on 1st Floor			Does not o	exist			
1	Lighting Fixture - HID							
_	Instance on 1st Floor			Does not o	exist			
1	Lighting Fixture - Incandesc	eent						
-	Instance on 1st Floor			Does not o	exist			
ı	Lighting Fixture - LED							
	Instance on 1st Floor			Inspected				
	Pendant Mounted			Does not o	.,			
	Instance on 1st Floor			Does not o	exist			
	Surface Mounted			Imamaatad				
	Instance on 1st Floor			Inspected	n Good and F	lain.		
	Instance Condition							
	Deficiency			No deficie	encies recorde	d		
	Recessed Mounted			T., 4 4				
	Instance on 1st Floor Instance Condition			Inspected 2 Petrope	n Good and F	'oir		
	Deficiency				encies recorde			
	ocal Sound System			No deficie	licies recorde	u		
Lo	Instance on 1st Floor			Inspected				
	Instance Condition			*	n Good and F	air		
	Installation Year			2019				
	Source of Installation	Year		Document	ted			
	Deficiency			No deficie	encies recorde	d		
Pr	ojection System							
	Instance on 1st Floor			Inspected				
	Instance Condition			3- Fair				
		art or installed on the ceiling?		Ceiling				
	Deficiency			No deficie	encies recorde	d		
Th	neater Lighting System			T				
=	Instance on 1st Floor			Inspected				
1	Dimming System			*				
	Instance on 1st Floor			Inspected				
	Instance Condition				en Good and F			
	Deficiency			No deficie	encies recorde	d		

Electrical Inspection	R450

uestion	Response	
AUDITORIUM		
Theater Lighting System		
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor - Staff	Inspected	
Instance on 1st Floor - Students	Inspected	
Lighting	1	
Instance on 1st Floor - Staff	Inspected	
Instance on 1st Floor - Students	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor - Staff	Inspected	
Instance on 1st Floor - Students	Inspected	
Pendant Mounted	*	
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Surface Mounted		
Instance on 1st Floor - Staff	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Students	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Theater Lighting System		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	<u> </u>

Building Condition Assessment Survey 2023-2024

uestion	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
COMPUTER LAB	Inspected
Instance on Room 422	Inspected
Power Panel?	Yes
Instance on Room 331	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 422	Inspected
Instance on Room 331	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 422	Does not exist
Instance on Room 331	Does not exist
Lighting Fixture - HID	
Instance on Room 422	Does not exist
Instance on Room 331	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 422	Does not exist
Instance on Room 331	Does not exist
Lighting Fixture - LED	
Instance on Room 422	Inspected
Instance on Room 331	Inspected
Pendant Mounted	
Instance on Room 422	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 331	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 422	Does not exist
Instance on Room 331	Does not exist
Recessed Mounted	
Instance on Room 422	Does not exist
Instance on Room 331	Does not exist
Raceway With Receptacles	
Instance on Room 422	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

Ouestion	Response	
	Kesponse	
COMPUTER LAB		
Raceway With Receptacles	D	
Instance on Room 331	Does not exist	
GYMNASIUM	Inspected	
Instance on 2nd Floor	Inspected	
Lighting		
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Does not exist	
Recessed Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 2nd Floor	Does not exist	
Projection System		
Instance on 2nd Floor	Does not exist	
Scoreboard		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 2nd Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	•	
Instance on 1st Floor	Inspected	
	•	

Building Condition Assessment Survey 2023-2024

Duestion	Response	
	мезропус	
KITCHEN		
Lighting Lighting Firsture, LED		
Lighting Fixture - LED Recessed Mounted		
Deficiency	No deficiencies recorded	
•		
LIBRARY	Inspected	
Instance on Basement	Inspected	
Lighting Instance on Basement	Inspected	
	Inspected	
Lighting Fixture - Fluorescent Instance on Basement	Does not exist	
	Does not exist	
Lighting Fixture - HID Instance on Basement	Does not exist	
	Does not exist	
Lighting Fixture - Incandescent Instance on Basement	Does not exist	
	Does not exist	
Lighting Fixture - LED Instance on Basement	Inspected	
Pendant Mounted	nispected	
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Surface Mounted	No deficiencies recorded	
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Recessed Mounted	No deficiencies recorded	
Instance on Basement	Does not exist	
	Does not exist	
Raceway With Receptacles Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System	No deficiencies recorded	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
LOCKER ROOM	Inspected	
Instance on Basement - Boys Pool, 1st Floor - Girls Pool	Inspected	
Alternative Use	-	
	No Increated	
Instance on Rooms B34A - Girls, B34B - Boys, 100 - Boys, 108 - Girls, 103 Visitors, 155 - Visitors	Inspected	
Alternative Use	No	
Lighting	 	
Instance on Basement - Boys Pool, 1st Floor - Girls Pool	Inspected	
Instance on Rooms B34A - Girls, B34B - Boys, 100 - Boys, 108 - Girls, 103 Visitors, 155 - Visitors	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement - Boys Pool, 1st Floor - Girls Pool	Does not exist	
Instance on Rooms B34A - Girls, B34B - Boys, 100 - Boys, 108 - Girls,	Does not exist	
103 Visitors, 155 - Visitors		

Does not exist

Does not exist

Lighting Fixture - HID

103 Visitors, 155 - Visitors Lighting Fixture - Incandescent

Instance on Basement - Boys Pool, 1st Floor - Girls Pool

Instance on Rooms B34A - Girls, B34B - Boys, 100 - Boys, 108 - Girls,

Building Condition Assessment Survey 2023-2024

Jugation	Dosnonso	
Question	Response	
LOCKER ROOM		
Lighting		
Lighting Fixture - Incandescent	D	
Instance on Basement - Boys Pool, 1st Floor - Girls Pool	Does not exist	
Instance on Rooms B34A - Girls, B34B - Boys, 100 - Boys, 108 - Girls, 103 Visitors, 155 - Visitors	Does not exist	
Lighting Fixture - LED		
Instance on Basement - Boys Pool, 1st Floor - Girls Pool	Inspected	
Instance on Rooms B34A - Girls, B34B - Boys, 100 - Boys, 108 - Girls,	Inspected	
103 Visitors, 155 - Visitors	Inspected	
Pendant Mounted		
Instance on Basement - Boys Pool, 1st Floor - Girls Pool	Does not exist	
Instance on Rooms B34A - Girls, B34B - Boys, 100 - Boys, 108 - Girls,	Does not exist	
103 Visitors, 155 - Visitors		
Surface Mounted		
Instance on Basement - Boys Pool, 1st Floor - Girls Pool	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms B34A - Girls, B34B - Boys, 100 - Boys, 108 - Girls,	Does not exist	
103 Visitors, 155 - Visitors		
Recessed Mounted		
Instance on Basement - Boys Pool, 1st Floor - Girls Pool	Does not exist	
Instance on Rooms B34A - Girls, B34B - Boys, 100 - Boys, 108 - Girls,	Inspected	
103 Visitors, 155 - Visitors		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Room B4	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Room B5L	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Instance on Rooms 201, 202, 203, 213	Inspected	
Power Panel?	No	
Alternative Use	No	
Instance on Rooms 209, 214	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting	110	
Instance on Room B4	Inspected	
Instance on Room B5L	Inspected	
Instance on Rooms 201, 202, 203, 213	Inspected	
Instance on Rooms 201, 202, 203, 213	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room B4	Does not exist	
Instance on Rooms 201, 202, 203, 213	Does not exist	
Instance on Rooms 201, 202, 203, 213	Does not exist	
Instance on Rooms 209, 214 Instance on Room B5L	Does not exist	
instance on Room BJL	Doos not exist	

Does not exist

Does not exist

Does not exist

Instance on Room B4

Instance on Rooms 209, 214

Instance on Rooms 201, 202, 203, 213

ical Inspection		R45
nestion	Response	
SCIENCE DEMO ROOM		
Lighting		
Lighting Fixture - HID	D	
Instance on Room B5L	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room B4	Does not exist	
Instance on Rooms 201, 202, 203, 213	Does not exist	
Instance on Rooms 209, 214	Does not exist	
Instance on Room B5L	Does not exist	
Lighting Fixture - LED		
Instance on Room B4	Inspected	
Instance on Rooms 201, 202, 203, 213	Inspected	
Instance on Rooms 209, 214	Inspected	
Instance on Room B5L	Inspected	
Pendant Mounted		
Instance on Room B4	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 201, 202, 203, 213	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 209, 214	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room B5L	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room B4	Does not exist	
Instance on Rooms 201, 202, 203, 213	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 209, 214	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room B5L	Does not exist	
Recessed Mounted		
Instance on Room B4	Does not exist	
Instance on Rooms 201, 202, 203, 213	Does not exist	
Instance on Rooms 209, 214	Does not exist	
Instance on Room B5L	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room B4	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room B5L	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 201, 202, 203, 213	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 209, 214 Instance Condition	Inspected 3- Fair	

Electrical Inspection	K450
Question	Response

uestion	Response
SCIENCE DEMO ROOM	
Emergency Gas Shut-Off Valve	
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room B4	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room B5L	Does not exist
Instance on Rooms 201, 202, 203, 213	Does not exist
Instance on Rooms 209, 214	Does not exist
Power Supply	
Instance on Room B4	Inspected
Instance on Room B5L	Inspected
Instance on Rooms 201, 202, 203, 213	Inspected
Instance on Rooms 209, 214	Inspected
Instructor Unit	
Instance on Room B4	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 201, 202, 203, 213	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 209, 214	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room B5L	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room B4	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 201, 202, 203, 213	Does not exist
Instance on Rooms 209, 214	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room B5L	Does not exist
Projection System	
Instance on Room B4	Does not exist
Instance on Room B5L	Does not exist
Instance on Rooms 201, 202, 203, 213	Does not exist
Instance on Rooms 209, 214	Does not exist
SCIENCE LAB	Inspected
Instance on Room 205	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 206	Inspected
Power Panel?	Yes
Alternative Use	No No
Lighting	110
Instance on Room 205	Inspected
Instance on Room 206	Inspected
Lighting Fixture - Fluorescent	t

Building Condition Assessment Survey 2023-2024

rical Inspection		R45
uestion	Response	
SCIENCE LAB		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Room 205	Does not exist	
Instance on Room 206	Does not exist	
Lighting Fixture - HID		
Instance on Room 205	Does not exist	
Instance on Room 206	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 205	Inspected	
Instance on Room 206	Inspected	
Pendant Mounted		
Instance on Room 205	Does not exist	
Instance on Room 206	Does not exist	
Surface Mounted		
Instance on Room 205	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 206	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 205	Does not exist	
Instance on Room 206	Does not exist	
Lighting Fixture - LED		
Instance on Room 205	Inspected	
Instance on Room 206	Inspected	
Pendant Mounted	•	
Instance on Room 205	Does not exist	
Instance on Room 206	Does not exist	
Surface Mounted		
Instance on Room 205	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 206	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 205	Does not exist	
Instance on Room 206	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 205	Inspected	
Instance Condition	2- Between Good and Fair	

No deficiencies recorded

2- Between Good and Fair

2- Between Good and Fair

No deficiencies recorded

2- Between Good and Fair

No deficiencies recorded

Inspected

Inspected

Deficiency

Deficiency
Emergency Shut-Off Power

Deficiency

Instance on Room 206

Instance on Room 205
Instance Condition

Instance on Room 206

Instance Condition

Instance Condition

Question	Response	
SCIENCE LAB		
Emergency Shut-Off Power		
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 205	Inspected	
Instance on Room 206	Inspected	
Instructor Unit		
Instance on Room 205	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 206	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit	110 deficiences recorded	
Instance on Room 205	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 206	Inspected	
Instance Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Student Unit Instance on Room 205	Does not exist	
Instance on Room 206 Instance Condition	Inspected 2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Projection System Instance on Room 205	D	
	Does not exist	
Instance on Room 206	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 208A	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Room 208A	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 208A	Does not exist	
Lighting Fixture - HID		
Instance on Room 208A	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 208A	Does not exist	
Lighting Fixture - LED		
Instance on Room 208A	Inspected	
Pendant Mounted		
Instance on Room 208A	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 208A	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 208A	Does not exist	

Building Condition Assessment Survey 2023-2024

R450

uestion	Response
SCIENCE PREP ROOM	
Emergency Gas Shut-Off Valve	
Instance on Room 208A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 208A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 208A	Inspected
Instructor Unit	
Instance on Room 208A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

election	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - LED	
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium, Auditorium, Corridor near Room 505
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Corridor near Rooms 320, 220
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BATTERY

Building Condition Assessment Survey 2023-2024

icui Inspection	
uestion	Response
EXIT LIGHT	
Battery Pack	
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Staff Cafeteria
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EXIT/EMERGENCY LIGHT	Inspected
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Corridor near Rooms B19, B15
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
	Inspected
Strobe Condition	1- Good
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected 1- Good
Condition	
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<u> </u>	Inspected
Magnetic Door Holder/Contactor	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

estion	Response	
IRE ALARM SYSTEM		
Magnetic Door Holder/Contactor		
Deficiency	CONTACTOR MISSING	
Deficiency Location/Instance	Corridor near Rooms 320, 220, 122	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	INSTALL CONTACTOR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Fused Cutout Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Mircom	
Model	Flex Net	
EquipmentId	N/A	
Installation Year	2021	
Source of Installation Year	Documented	
Deficiency	SYSTEM DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR SYSTEM	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	12133894K	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	5- Poor	
Deficiency	PRINTER NOT OPERATIONAL	
Deficiency Location/Instance	Custodian's Office	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	

Building Condition Assessment Survey 2023-2024

iricai Inspection	K430
Question	Response
FIRE ALARM SYSTEM	
Tamper Flow Switch/Chain	
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	NOT CONNECTED TO REMOTE MONITORING STATION
Deficiency Location/Instance	Elevator - Device ID# 5P264
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, Pool Mechanical Room, Mechanical Rooms 440A,
·	B2, Sub Basement Mechanical Room, Corridor near Rooms B9,
	B13
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Corridor near Room B13, Mechanical Room 440A
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2

Building Condition Assessment Survey 2023-2024

estion	Response
ANEL BOARD	
Fused Disconnect Switch Type	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room B9
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Mechanical Room B9
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room, Corridor near Room B15
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Corridor near Room B15
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Corridor near Room B15
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	35
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

Building Condition Assessment Survey 2023-2024

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Corridor near Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Kitchen, Corridor near Rooms 410, 209
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Corridor near Rooms M47, 258A
Deficiency Quantity	2
Quantity Uom Potential Action	EACH
	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3 LEVEL 2
Purpose of Action	
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Gymnasium, Corridor near Room 340
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 146
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen HTA250A
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
•	
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 121
Instance Condition	4- Between Fair and Poor

Electrical Inspection		K450
Question	Response	

estion	Response
ECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2004
Source of Installation Year	Documented
Deficiency	PANEL NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Instance	Custodian's Office - Room 121
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2017
Source of Installation Year	Documented
Deficiency	PANEL NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
ERVICE SWITCH	Inspected
Instance	Electrical Room (Original Building)
Instance Condition	3- Fair
	1
Instance Quantity	
Instance Quantity Instance Quantity Llom	
Instance Quantity Uom	EACH
Instance Quantity Uom Manufacturer	EACH Federal Pacific Electric
Instance Quantity Uom Manufacturer EquipmentId	EACH Federal Pacific Electric Kit Refrig.
Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity	EACH Federal Pacific Electric Kit Refrig. 100
Instance Quantity Uom Manufacturer EquipmentId	EACH Federal Pacific Electric Kit Refrig.

Building Condition Assessment Survey 2023-2024

Electrical Inspection R450

ui Inspection		IX+30
tion	Response	
RVICE SWITCH		
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room (Original Building)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room (Original Building)	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	ЕАСН	
Manufacturer	Standard Switchboard	
EquipmentId	S. S. Power	
Capacity/Size Quantity	2500	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1964	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room (Original Building)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room (Original Building)	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Standard Switchboard	_
EquipmentId	S.S. Lights	
Capacity/Size Quantity	2000	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1964	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room (Original Building)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room (Original Building)	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	Kitchen Power	
Capacity/Size Quantity	400	

Electrical Inspection	R450
	_

Question	Response
SERVICE SWITCH	
Source of Capacity/Size	Nameplate
Installation Year	1964
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room (Original Building)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room (Original Building)
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Standard Switchboard
Manufacturer	
EquipmentId Capacity/Size Quantity	Light 2000
Capacity/Size Quantity Capacity/Size UOM	
Capacity/Size 2 Quantity	Amps Total
Capacity/Size 2 Quantity Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1964
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room (Original Building)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room (Original Building)
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	Standard Switchboard
EquipmentId	Power 2500
Capacity/Size Quantity	
Capacity/Size UOM Capacity/Size 2 Quantity	Amps Total 2
Capacity/Size 2 Quantity Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1964
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room (Original Building)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
_	
Purpose of Action Violations	LEVEL 2 No violations recorded

Building Condition Assessment Survey 2023-2024

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance	Electrical Room (Original Building)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	East Coast
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist