Building Condition Assessment Survey 2023-2024

Architectural Inspection R456

Asset:	TOTTENVILLE HS AF - STATEN ISLAND, 100 LUTEN AVENUE, STATEN ISLAND, NY, 10312				
Inspection Id	pection Type Time In Last Edited				
4968	ARCHITECTURAL - ASSOCIATE	2024-04-24 02:12PM	2024-04-26 01:35PM		
5006	ARCHITECTURAL - SENIOR	2024-04-24 08:15AM	2024-05-28 12:34PM		
set Data					

As

Weather

Facade Photo

sset Data	
Question	Answer
Was the Building Fully Accessible for Inspection?	Yes
Principal(s) Information	
Principal Name	Gina Battista
Principal Organization	Tottenville HS - Staten Island
Meeting with Principal?	No
Principal Feedback	No Feedback from Principal
Custodian	Evan Manca
Was the Custodian Present?	Yes
Fireman	Mark Duymich
Was the Fireman Present?	Yes
Building Square Footage	0
Comments on the Area (for Athletic Field, Playing Surfaces, Leased Spaces)	Total Site Area: 457,396 SF; Playing Surface Area: 320,000 SF
Comments on the Stories (Floors) plus Basements	None
Comments on the Year Built	1971
Student Population	4100
Staff Population	5
Comments on the Number of Classrooms	0

Fair

Football Field - South View from Main Asset R455



Main Entrance Photo



Main Entrance - North View from Main Asset R455

Building Condition Assessment Survey 2023-2024

Architectural Inspection

Roof Photo

R456

Do Stormwater Management/Green Infrastructure systems exist?

Type

Have any Systems/Major Building Components been upgraded?

Athletic Fields - North View from Main Asset R455

No Storm Water Management Type Selected

Systems: Artificial Turf replacement of Football Field and

Running Track

2022 Years:

Systems: Artificial Turf replacement (partial - Softball Field)

Years:

Systems: Artificial Turf replacement (partial - Baseball Field)

Years:

Asphalt Playing Surfaces replacement (full-Basketball, Systems:

Handball, Tennis)

Years: No New Construction

No Tandem

No

Priority Condition

Leased Space?

Tandem

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No condi	tion recorded						

Structural Engineer Required

Have there been any New Building Additions?


Structural	Condition	Component	Location	Person(s)	Person(s)	Photo
Condition Type	Description	Affected	Description	Notified	Title	Image

No condition recorded

Programmatic Accessibility

Programmatic Accessibility Status Question	Response					
Physical Breakdown Structure	Exists	Complies	Required	Deficiency	Assistive Listening System	Fire Alarm Strobe

Building Template



•	. •	
INC	nactiai	12
11113	pection	ı

Question	Response
Architectural	
EXTERIOR	Does not exist
INTERIOR	Does not exist
ATHLETIC FIELDS	Inspected
PLAYING SURFACE	Inspected
Replacement Quantity	320,000
Replacement Uom	S.F.
Synthetic Turf Field exists?	Yes
Synthetic Turf Installation Year	2022
Instance on Baseball Field	Inspected
Instance Condition	3- Fair
Instance Quantity	120,000
Instance Quantity Uom	S.F.
Deficiency	ARTIFICIAL TURF:DAMAGED/WORN OUT

ficiency ARTIFICIAL TURF:DAMAGED/WORN OF Baseball Field

Deficiency Location/Instance

Baseball Fi
Deficiency Location/Instance



Deficiency Quantity

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Building Condition Assessment Survey 2023-2024

Architectural Inspection R456

ATHLETIC FIELDS

Question

PLAYING SURFACE

Deficiency Photo 1

Deficiency Location/Instance

Deficiency Photo 1



	Outfield (left)
Deficiency Photo 2	No photo recorded
Violations	No violations recorded

Instance on Basketball Courts	Inspected
Instance Condition	3- Fair
Instance Quantity	8,000
Instance Quantity Uom	S.F.

ASPHALT:DAMAGED/DETERIORATED Deficiency Deficiency Location/Instance

Basketball Courts

Response



Deficiency Quantity 150 Quantity Uom S.F. REPAIR Potential Action Urgency of Action PRIORITY 3 LEVEL 2 Purpose of Action

Basketball Courts Deficiency Photo 2 No photo recorded Violations No violations recorded

Instance on Football Field	Inspected
Instance Condition	1- Good
Instance Quantity	90,000
Instance Quantity Uom	S.F.
Deficiency	No deficiencies recorded
Instance on Handball Courts	Inspected
Instance Condition	3- Fair
Instance Quantity	5,000
Instance Quantity Uom	S.F.
Deficiency	ASPHALT:DAMAGED/DETERIORATED

Handball Courts Deficiency Location/Instance

Building Condition Assessment Survey 2023-2024

Architectural Inspection R456

Question Response

ATHLETIC FIELDS

PLAYING SURFACE

Deficiency Location/Instance

Deficiency Photo 1

Instance on Running Track

Deficiency Location/Instance Deficiency Location/Instance

Deficiency Photo 1



Deficiency Quantity 150
Quantity Uom S.F.
Potential Action REPAIR
Urgency of Action PRIORITY 3
Purpose of Action LEVEL 2



Handball Court

Deficiency Photo 2

No photo recorded

Violations

No violations recorded

 Instance Condition
 1- Good

 Instance Quantity
 35,000

 Instance Quantity Uom
 S.F.

 Deficiency
 No defic

 Instance on Softball Field
 Inspecte

Deficiency
No deficiencies recorded
Instance on Softball Field
Inspected
Instance Condition
3- Fair
Instance Quantity
50,000
Instance Quantity Uom
S.F.
Deficiency
ARTIFICIAL TURF: DAI

ARTIFICIAL TURF:DAMAGED/WORN OUT

Softball Field

Inspected



Deficiency Quantity 75
Quantity Uom S.F.
Potential Action REPLACE
Urgency of Action PRIORITY 3
Purpose of Action LEVEL 2



Building Condition Assessment Survey 2023-2024

ectural Inspection	Response
	Response
ATHLETIC FIELDS	
PLAYING SURFACE	Home Plate
Deficience Phase 2	
Deficiency Photo 2 Violations	No photo recorded No violations recorded
Instance on Tennis Courts	
Instance Condition	Inspected 3- Fair
Instance Quantity	12,000 S.F.
Instance Quantity Uom	
Deficiency	ASPHALT:DAMAGED/DETERIORATED Tennis Courts
Deficiency Location/Instance Deficiency Location/Instance	
Denote Lecture I I I I I I I I I I I I I I I I I I I	Production of the control of the con
D.S. in the Constitution	
Deficiency Quantity	600 S.F.
Quantity Uom Potential Action	S.F. REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
	Tennis Courts
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
FIXED EQUIPMENT	Inspected
Basketball Backboard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Basketball Hoops	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Basketball Posts	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Football Goal Posts	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Tennis Net Posts	Inaccessible
SEATING	Inspected
Benches	Inspected
Concrete	Does not exist
Metal/Wood/Plastic	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

Inspected

Bleachers

tectural Inspection	R45
uestion	Response
ATHLETIC FIELDS	
SEATING	
Bleachers	
Concrete	Does not exist
Metal/Wood/Plastic	Inspected
Condition	2- Between Good and Fair
Deficiency	DAMAGED
Deficiency Location/Instance	Football field
Deficiency Quantity	10 S.F.
Quantity Uom Potential Action	S.F. REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	LEVEL 2
231010109 1 1000 1	The regime of th
	Football field
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
SITE	Inspected
CONTAINERIZATION	Does not exist
DRAINAGE SYSTEM FOR ASPHALT	Inspected
Catch Basins/Manhole - Surrounded by Asphalt	Inspected
Condition	5- Poor
Deficiency	DAMAGED COVER
Deficiency Location/Instance	Basketball court, Tennis court
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo 1	
	Basketball court
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Culverts - Asphalt Covering	Does not exist
DRAINAGE SYSTEM FOR CONCRETE	Inspected
Catch Basins/Manhole - Surrounded by Concrete	Inspected
Condition	5- Poor
Deficiency	BLOCKED
Deficiency Location/Instance	Football field
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE

uestion	Response
SITE	•
DRAINAGE SYSTEM FOR CONCRETE	
Catch Basins/Manhole - Surrounded by Concrete	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Culverts - Concrete Covering	Does not exist
DRAINAGE SYSTEM FOR SOIL	Inspected
Catch Basins/Manhole - Surrounded by Soil	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Culverts - Soil Covering	Does not exist
DRINKING FOUNTAINS	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FENCES	Inspected
Condition	3- Fair
Deficiency	CHAIN LINK:DAMAGED/DETERIORATED
Deficiency Deficiency Location/Instance	Chisholm Street, Handball court
Deficiency Quantity	150
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Handball court
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Deficiency	CHAIN LINK:DAMAGED POST/RAIL
Deficiency Location/Instance	Chisholm Street, Handball court
Deficiency Quantity	100
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Handball court
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
	Does not exist
IRRIGATION SYSTEM PAVING	Inspected

estion	Response
ITE	•
PAVING	
Student Non-Use	Inspected
Gravel Exists?	No
Asphalt	Does not exist
Concrete	Inspected
Condition	3- Fair
Deficiency	CRACKS - MAJOR
Deficiency Location/Instance	Under bleachers, Football field
Deficiency Quantity	350
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Football field
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Pavers	Does not exist
Student Use	Inspected
Gravel Exists?	No
Asphalt	Does not exist
Concrete	Inspected
Condition	3- Fair
Deficiency	CRACKS - MAJOR
Deficiency Location/Instance	Baseball field
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Baseball field
Deficience Place 2	
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Pavers	Does not exist
Site Sidewalks & Walkways	Inspected
Asphalt	Does not exist
Concrete	Inspected
Condition	3- Fair
Deficiency	CRACKS - MAJOR
Deficiency Location/Instance	South side, Football field

uestion	Response
SITE	
PAVING	
Site Sidewalks & Walkways	
Concrete	
Deficiency Quantity	350
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	South side
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Deficiency	HEAVING
Deficiency Location/Instance	Football field, Baseball field
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Football field
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Pavers	Does not exist
DOT Sidewalk	Inspected
Asphalt	Does not exist
Concrete	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Pavers	Does not exist
PLAYGROUNDS	Does not exist
PLAYING SURFACE	Does not exist
RETAINING WALLS	Inspected
Condition	3- Fair
Are there any Retaining Walls 6' OR higher facing public street/sidewalk?	No
Deficiency	CAST IN PLACE CONCRETE: CRACKS/SPALLING - MAJOR
Deficiency Location/Instance	Chisholm Street, Handball court
Definionary Quantity	50
Deficiency Quantity	
Quantity Uom Potential Action	S.F. REPLACE

uestion	Response
SITE	<u> </u>
RETAINING WALLS	
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Chisholm Street
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Deficiency	CAST IN PLACE CONCRETE: DETERIORATED EXPANSION JOINT
Deficiency Location/Instance	Basketball court, Handball court
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action Deficiency Photo 1	LEVEL 2
	Basketball court
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
SEATING	Does not exist
SITE WALLS (NOT RETAINING WALLS)	Inspected
Condition	3- Fair
Condition Deficiency	3- Fair CAST IN PLACE CONCRETE:CRACKS/SPALLING - MAJOR
Condition Deficiency Deficiency Location/Instance	3- Fair CAST IN PLACE CONCRETE:CRACKS/SPALLING - MAJOR Handball court
Condition Deficiency Deficiency Location/Instance Deficiency Quantity	3- Fair CAST IN PLACE CONCRETE:CRACKS/SPALLING - MAJOR Handball court 50
Condition Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom	3- Fair CAST IN PLACE CONCRETE:CRACKS/SPALLING - MAJOR Handball court 50 S.F.
Condition Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action	3- Fair CAST IN PLACE CONCRETE:CRACKS/SPALLING - MAJOR Handball court 50 S.F. REPLACE
Condition Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action	3- Fair CAST IN PLACE CONCRETE:CRACKS/SPALLING - MAJOR Handball court 50 S.F. REPLACE PRIORITY 3
Condition Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action	3- Fair CAST IN PLACE CONCRETE:CRACKS/SPALLING - MAJOR Handball court 50 S.F. REPLACE
Condition Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action	3- Fair CAST IN PLACE CONCRETE: CRACKS/SPALLING - MAJOR Handball court 50 S.F. REPLACE PRIORITY 3 LEVEL 2
Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo 1	3- Fair CAST IN PLACE CONCRETE:CRACKS/SPALLING - MAJOR Handball court 50 S.F. REPLACE PRIORITY 3 LEVEL 2 Handball court
Condition Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action	3- Fair CAST IN PLACE CONCRETE:CRACKS/SPALLING - MAJOR Handball court 50 S.F. REPLACE PRIORITY 3 LEVEL 2

Building Condition Assessment Survey 2023-2024

ectural Inspection	R456
estion	Response
ITE	
STAIRS/RAMPS: EXTERIOR	
Site Cheek/flank Walls	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Railings	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Stairs/ramps	Inspected
Condition	2- Between Good and Fair
Deficiency	CAST IN PLACE CONCRETE:CRACKS/SPALLING - MAJOR
Deficiency Location/Instance	Football field
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Football field
Deficiency Photo 2	No photo recorded

No violations recorded

Violations

NYC Department of Education Building Condition Assessment Survey 2023-2024

Architectural Inspection	R456
--------------------------	------

Does the SCA expect asset to have artwork?

No