Building Condition Assessment Survey 2023-2024

Asset:	SUSAN E. WA	GNER HS - STATEN ISLA	ND, 1200 MANOI	R ROAD, STAT	EN ISLAND, NY, 10314	
Inspection Id	Inspection Type				Time In	Last Edited
425	0 ELECTRICAL				2024-03-25 09:01AM	2024-04-22 08:35A
set Data						
Question				Answer		
Have any Systems/Major Building Components been upgraded?			Systems:	Students Cafeteria (Retrofitted L Computer Lab - Room B62 (Rac Receptacles)		
				Years: Systems:	2023 Battery Pack Exit Lights, LED L Auditorium (Recessed LED Ligh System (Except Siren/Strobe), Vi	nting), Intrusion Alarm
				V	Drive 2022	
				Years:		
				Systems:	Partial Switchboard	
				Years:	2021 Partial Lighting Security	
				Systems:	Partial Lighting - Security	
				Years:	2020, 2015 IPDVS/CCTV System	
				Systems:	·	
				Years:	2020 Partial Fused Disconnect Switch	True Donal Doord
				Systems: Years:	2019, 1998	Type Panel Board
				Systems:	Recessed LED Lighting (Health Emergency Lights, Partial Motor (Local Sound System), Public Ad	Starters, Gymnasiums
				Years:	(Amplifier) 2019	idiess System
				Systems:	Gymnasiums (LED Lighting)	
				Years:	2015	
				Systems:	Auditorium (Theater Lighting Sy	vstem)
				Years:	2012	
				Systems: Years:	Intrusion Alarm System (Siren/S 2011	trobe)
				Systems:	Auditorium (Local Sound System	m)
				Years:	2008	
				Systems:	Fire Alarm System	
				Years:	2007	
				Systems:	Students Cafeteria (Local Sound	System)
				Years:	2006	
				Systems:	Interior Fluorescent Lighting	
				Years:	1999	
				Systems:	Emergency Light/Exit Light Pan	el
				Years:	1998	
Type of Servi				Below Gr	round	
	tive Whiteboard (IWE	<i>'</i>		Yes		
	ation In Electrical Ro		1	No		
Ouestion Ouestion	ED INTERCOMS	IN FIRE RESCUE AREAS)		Response	
	•	tance Areas, Fire Rescue Areas,	and/or Holding Roor		No	
iority Cond	lition					
Exist Pi	riority ategory	Condition Description	Component Affected	Location Description		hoto nage

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Intercom - Not	N/A	Intercom	Elevator -	Stephen	Fireman	No Photo Taken
	Operational		System -	Device ID	Napoli		
			Elevator	#5P293			

3	Water Leaks onto	Pipe Leak	Electrical	Electrical	Stephen	Fireman	No Photo Taken	
	Electrical Equipment		Equipment	Meter Room	Napoli			
3	Fire Alarm System -	N/A	Fire Alarm	Students	Stephan	Fireman	No Photo Taken	
	Components Not		System -	Cafeteria,	Napoli			
	Operational		Magnetic	Corridor near				
			Door	Rooms 190,				
			Holder/Contac tor	236				
specti	ion							
Quest	ion			Response				
Electr	rical							
ATE	HLETIC FIELD			Does not o	exist			
AUI	DITORIUM			Inspected				
	Instance on 1st Floor			Inspected				
He	ouse Lighting			T 4. 4				
	Instance on 1st Floor	-49		Inspected				
-	Does a Chandelier Exi			No				
	Lighting Fixture - Fluorescer Instance on 1st Floor	III .		Does not o	exist			
Ī	Lighting Fixture - HID			Dogs not				
	Instance on 1st Floor			Does not	exist			
Ī	Lighting Fixture - Incandesc	ent						
	Instance on 1st Floor			Inspected				
	Pendant Mounted							
	Instance on 1st Floor			Inspected				
	Instance Condition			3- Fair				
	Deficiency				G FIXTURE	BEYOND USE	FUL LIFE	
	Deficiency Quantity			10				
	Quantity Uom			EACH	E LIDOD A DE			
	Potential Action				E-UPGRADE			
	Urgency of Action			PRIORIT LEVEL 2	Y I			
	Purpose of Action Violations				ons recorded			
	Surface Mounted			No violati	ons recorded			
	Instance on 1st Floor			Inspected				
	Instance Condition			3- Fair				
	Deficiency				G FIXTURE 1	BEYOND USE	FUL LIFE	
	Deficiency Quantity			10	ornirene.	BETOIND COL	I OL EN E	
	Quantity Uom			EACH				
	Potential Action				E-UPGRADE			
	Urgency of Action			PRIORIT	Y 1			
	Purpose of Action			LEVEL 2				
	Violations			No violati	ons recorded			
	Recessed Mounted							
_	Instance on 1st Floor			Does not	exist			
I	Lighting Fixture - LED							
	Instance on 1st Floor			Inspected				
	Pendant Mounted			D :	:-4			
	Instance on 1st Floor			Does not o	exist			
	Surface Mounted			D- :	int			
	Instance on 1st Floor Recessed Mounted			Does not o	exist			
	Instance on 1st Floor			Inspected				
	Instance On 1st Floor Instance Condition			1- Good				
	Deficiency				CEIVTIDE	NOT OPERAT	IONAI	
	Deficiency Quantity			LIGHTIN 1	O I IA I UNE	OLEKAI	IONAL	

Electrical Inspection	R460

- III		
estion	Response	
AUDITORIUM		
House Lighting		
Lighting Fixture - LED		
Recessed Mounted		
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System	Y 4.1	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling No deficiencies recorded	
Deficiency	No deficiencies recorded	
Theater Lighting System	Y 4.1	
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor - Staff	Inspected	
Instance on 1st Floor - Students	Inspected	
Lighting		
Instance on 1st Floor - Staff	Inspected	
Instance on 1st Floor - Students	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Inspected	
Pendant Mounted		
Instance on 1st Floor - Staff	Does not exist	
Surface Mounted		
Instance on 1st Floor - Staff	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor - Staff	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Inspected	
Pendant Mounted	peersou	

Duestion	Response
CAFETERIA	Response
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	
Instance on 1st Floor - Staff	Does not exist
Surface Mounted	
Instance on 1st Floor - Staff	Does not exist
Recessed Mounted	
Instance on 1st Floor - Staff	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Does not exist
Pendant Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor - Students	Does not exist
Recessed Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Theater Lighting System	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

· · · · · · · · · · · · · · · · · · ·		
Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Inspected	
Instance on Rooms 162, 161/163, 355	Inspected	
Power Panel?	Yes	
Instance on Room B62	Inspected	
Power Panel?	Yes	
	105	
Lighting Instance on Rooms 162, 161/163, 355	Inspected	
Instance on Room B62	Inspected	
Lighting Fixture - Fluorescent	Hispected	
Instance on Rooms 162, 161/163, 355	Inspected	
Instance on Room B62	Inspected	
Pendant Mounted	inspected	
Instance on Rooms 162, 161/163, 355	Does not exist	
Instance on Room B62	Does not exist Does not exist	
	Does not exist	
Surface Mounted	Y 1	
Instance on Rooms 162, 161/163, 355	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Instance on Room B62	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Rooms 162, 161/163, 355	Does not exist	
Instance on Room B62	Does not exist	
Lighting Fixture - HID		
Instance on Rooms 162, 161/163, 355	Does not exist	
Instance on Room B62	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms 162, 161/163, 355	Does not exist	
Instance on Room B62	Does not exist	
Lighting Fixture - LED		
Instance on Rooms 162, 161/163, 355	Does not exist	
Instance on Room B62	Does not exist	
Raceway With Receptacles		
Instance on Rooms 162, 161/163, 355	Inspected	
Raceway With Receptacles		

Building Condition Assessment Survey 2023-2024

Question	Response
COMPUTER LAB	Кезронч
Raceway With Receptacles Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room B62	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on 1st Floor - Large	Inspected
Instance on 1st Floor - Small	Inspected
Lighting	
Instance on 1st Floor - Large	Inspected
Instance on 1st Floor - Small	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Large	Inspected
Instance on 1st Floor - Small	Inspected
Pendant Mounted	
Instance on 1st Floor - Large	Does not exist
Instance on 1st Floor - Small	Does not exist
Surface Mounted	
Instance on 1st Floor - Large	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Small	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor - Large	Does not exist
Instance on 1st Floor - Small	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor - Large	Does not exist
Instance on 1st Floor - Small	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Large	Does not exist
Instance on 1st Floor - Small	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - Large	Inspected
Instance on 1st Floor - Small	Inspected
Pendant Mounted	
Instance on 1st Floor - Large	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 1st Floor - Small	Inspected
Instance Condition	2- Between Good and Fair
	A ACAMED AC ENVIRONDE ANOM ORDER ARRONALA

1 EACH

REPLACE

LIGHTING FIXTURE NOT OPERATIONAL

Deficiency

Deficiency Quantity

Quantity Uom Potential Action

Question	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - LED		
Pendant Mounted		
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted		
Instance on 1st Floor - Large	Does not exist	
Instance on 1st Floor - Small	Does not exist	
Recessed Mounted		
Instance on 1st Floor - Large	Does not exist	
Instance on 1st Floor - Small	Does not exist	
Local Sound System		
Instance on 1st Floor - Large	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Small	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor - Large	Does not exist	
Instance on 1st Floor - Small	Does not exist	
Scoreboard		
Instance on 1st Floor - Large	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Small	Does not exist	
Theater Lighting System		
Instance on 1st Floor - Large	Does not exist	
Instance on 1st Floor - Small	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	

Electrical Inspection	R460
Question	Response

· · · · · · · · · · · · · · · · · · ·		
Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 290	Inspected	
Lighting		
Instance on Room 290	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 290	Inspected	
Pendant Mounted		
Instance on Room 290	Does not exist	
Surface Mounted		
Instance on Room 290	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 290	Does not exist	
Lighting Fixture - HID		
Instance on Room 290	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 290	Does not exist	
Lighting Fixture - LED		
Instance on Room 290	Does not exist	
Raceway With Receptacles		
Instance on Room 290	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 290	Does not exist	
LOCKER ROOM	Inspected	
Instance on Room B60 - Girls, Basement - Girls, Basement - Boys	Inspected	
Alternative Use	No	
Lighting		
Instance on Room B60 - Girls, Basement - Girls, Basement - Boys	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room B60 - Girls, Basement - Girls, Basement - Boys	Inspected	
Pendant Mounted		
Instance on Room B60 - Girls, Basement - Girls, Basement - Boys	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room B60 - Girls, Basement - Girls, Basement - Boys	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room B60 - Girls, Basement - Girls, Basement - Boys	Does not exist	
Lighting Fixture - HID		
Instance on Room B60 - Girls, Basement - Girls, Basement - Boys	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room B60 - Girls, Basement - Girls, Basement - Boys	Does not exist	
Lighting Fixture - LED		
Instance on Room B60 - Girls, Basement - Girls, Basement - Boys	Does not exist	

Electrical Inspection	R460
Question	Response

estion	Response	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Room 355	Inspected	
Power Panel?	Yes	
Alternative Use	Yes	
Instance on Room 459	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Room 351, 353A, 353B, 359, 451, 453A, 453B, 455		
	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting	N 1	
Instance on Room 355	Not required	
Instance on Room 459	Inspected	
Instance on Room 351, 353A, 353B, 359, 451, 453A, 453B, 455	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 459	Inspected	
Instance on Room 351, 353A, 353B, 359, 451, 453A, 453B, 455	Inspected	
Pendant Mounted		
Instance on Room 459	Does not exist	
Instance on Room 351, 353A, 353B, 359, 451, 453A, 453B, 455	Does not exist	
Surface Mounted		
Instance on Room 459	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 351, 353A, 353B, 359, 451, 453A, 453B, 455	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 459	Does not exist	
Instance on Room 351, 353A, 353B, 359, 451, 453A, 453B, 455	Does not exist	
Lighting Fixture - HID		
Instance on Room 459	Does not exist	
Instance on Room 351, 353A, 353B, 359, 451, 453A, 453B, 455	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 459	Does not exist	
Instance on Room 351, 353A, 353B, 359, 451, 453A, 453B, 455	Does not exist	
Lighting Fixture - LED		
Instance on Room 459	Does not exist	
Instance on Room 351, 353A, 353B, 359, 451, 453A, 453B, 455	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 355	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 459	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 351, 353A, 353B, 359, 451, 453A, 453B, 455	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	To deficiencies recorded	
Instance on Room 355	Inspected	
Instance Condition	3- Fair	

Electrical Inspection	R460
Question	Response

Puestion	Response
SCIENCE DEMO ROOM	
Emergency Shut-Off Power	
Deficiency	No deficiencies recorded
Instance on Room 459	Does not exist
Instance on Room 351, 353A, 353B, 359, 451, 453A, 453B, 455	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 355	Does not exist
Instance on Room 459	Inspected
Instance on Room 351, 353A, 353B, 359, 451, 453A, 453B, 455	Inspected
Instructor Unit	
Instance on Room 459	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 351, 353A, 353B, 359, 451, 453A, 453B, 455	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 459	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 351, 353A, 353B, 359, 451, 453A, 453B, 455	Does not exist
Projection System	Does not exist
Instance on Room 355	Does not exist
Instance on Room 459	Does not exist
Instance on Room 351, 353A, 353B, 359, 451, 453A, 453B, 455	Does not exist
	Inspected
SCIENCE LAB Instance on Room 458	
Power Panel?	Inspected
	Yes
Alternative Use	No
Instance on Rooms 352, 358, 452	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Room 458	Inspected
Instance on Rooms 352, 358, 452	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 352, 358, 452	Inspected
Instance on Room 458	Inspected
Pendant Mounted	
Instance on Room 458	Does not exist
Instance on Rooms 352, 358, 452	Does not exist
Surface Mounted	
Instance on Room 458	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 352, 358, 452	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 458	Does not exist
Instance on Rooms 352, 358, 452	Does not exist

Building Condition Assessment Survey 2023-2024

uestion	Response	
	Response	
SCIENCE LAB		
Lighting Lighting Fixture - HID		
Instance on Rooms 352, 358, 452	Does not exist	
Instance on Room 458	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Rooms 352, 358, 452	Does not exist	
Instance on Room 458	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Rooms 352, 358, 452	Does not exist	
Instance on Room 458	Does not exist	
Emergency Gas Shut-Off Valve	Does not exist	
Instance on Room 458	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 352, 358, 452	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 458	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 352, 358, 452	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 458	Inspected	
Instance on Rooms 352, 358, 452	Inspected	
Instructor Unit		
Instance on Rooms 352, 358, 452	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 458	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Rooms 352, 358, 452	Does not exist	
Instance on Room 458	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Student Unit		
Instance on Rooms 352, 358, 452	Does not exist	
Instance on Room 458	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	

Does not exist

Does not exist

Inspected

Inspected

Inspected

Yes

No

Instance on Room 458

Instance on Room 457

Power Panel?

Alternative Use

SCIENCE PREP ROOM

Instance on Rooms 352, 358, 452

Instance on Rooms 354, 357, 454

Building Condition Assessment Survey 2023-2024

iestion	Response	
	Response	
SCIENCE PREP ROOM	AY.	
Power Panel?	No	
Alternative Use	No	
Lighting	I	
Instance on Room 457	Inspected	
Instance on Rooms 354, 357, 454	Inspected	
Lighting Fixture - Fluorescent	Y 1	
Instance on Room 457	Inspected	
Instance on Rooms 354, 357, 454	Inspected	
Pendant Mounted		
Instance on Rooms 354, 357, 454	Does not exist	
Instance on Room 457	Does not exist	
Surface Mounted		
Instance on Rooms 354, 357, 454	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 457	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Rooms 354, 357, 454	Does not exist	
Instance on Room 457	Does not exist	
Lighting Fixture - HID		
Instance on Room 457	Does not exist	
Instance on Rooms 354, 357, 454	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 457	Does not exist	
Instance on Rooms 354, 357, 454	Does not exist	
Lighting Fixture - LED		
Instance on Room 457	Does not exist	
Instance on Rooms 354, 357, 454	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 457	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 354, 357, 454	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 457	Does not exist	
Instance on Rooms 354, 357, 454	Does not exist	
Power Supply		
Instance on Room 457	Inspected	
Instance on Rooms 354, 357, 454	Inspected	
Instructor Unit		
Instance on Room 457	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 354, 357, 454	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	

Does not exist

Inspected

SWIMMING POOL

TOILET ROOM - STAFF

Building Condition Assessment Survey 2023-2024

Question	Response
TOILET ROOM - STAFF	
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition Condition	3- Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
,	

Building Condition Assessment Survey 2023-2024

uestion	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Corridor near Room 219
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	By Stair C/3, Corridor near Rooms 158, 249, 252, 355
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action Violations	LEVEL 2 No violations recorded
Non Battery Pack	Inspected 3- Fair
Condition	
Deficiency Deficiency Location/Instance	FIXTURE LAMP NOT OPERATIONAL Locker Rooms
Deficiency Quantity	Locker Rooms 4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EXIT/EMERGENCY LIGHT	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
•	
FIRE ALARM SYSTEM	Inspected
Bell/Horn Condition	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected

Building Condition Assessment Survey 2023-2024

-	
estion	Response
IRE ALARM SYSTEM	
Manual Pull Station	
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Inspected
Condition	3- Fair
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	Students Cafeteria, Corridor near Rooms 190, 236
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	12102831L
Fused Cutout Panel Condition	Inspected 2- Between Good and Fair
Deficiency	No deficiencies recorded
	Does not exist
Fire Alarm Digital Communicator	Inspected
Main Panel Bell At Panel	Inspected
Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	
Fire Alarm Control Panel (Electronic)	Inspected
Instance Instance Condition	Main Entrance Lobby 2- Between Good and Fair
Instance Quantity	1 EACH
Instance Quantity Uom	
Manufacturer Model	Edwards System Technology EST 3
EquipmentId	Fire Alarm Control Panel
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

ricui Inspection	1370
Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	4- Between Fair and Poor
Deficiency	INTERCOM CABINET NOT OPERATIONAL
Deficiency Location/Instance	Elevator - Device ID #5P293
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Holding Area	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Inspected
Instance	4th Floor Mechanical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	N/A
EquipmentId	MCC-1
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate 1968
Installation Year	
Source of Installation Year	Documented BEYOND LISEFUL LIFE
Deficiency Deficiency Location/Instance	BEYOND USEFUL LIFE 4th Floor Mechanical Room

Electrical Inspection	R460
Question	Response

n	Response
OR CONTROLLER	
FOR CONTROL CENTER	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Mechanical Room next to Room 288
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	N/A
EquipmentId	MCC - 2
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1968
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room next to Room 288
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Mechanical Room 211
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	ЕАСН
Manufacturer	N/A
EquipmentId	MCC - 4
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1968
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room 211
Deficiency Quantity	1
Quantity Uom	EACH
	DEDI ACE
Potential Action	REPLACE
Potential Action Urgency of Action	PRIORITY I
Urgency of Action	PRIORITY 1
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2
Urgency of Action Purpose of Action Violations	PRIORITY 1 LEVEL 2 No violations recorded
Urgency of Action Purpose of Action Violations Instance Instance Condition	PRIORITY 1 LEVEL 2 No violations recorded Boiler Room 3- Fair
Urgency of Action Purpose of Action Violations Instance Instance Condition Instance Quantity	PRIORITY 1 LEVEL 2 No violations recorded Boiler Room 3- Fair
Urgency of Action Purpose of Action Violations Instance Instance Condition Instance Quantity Instance Quantity Uom	PRIORITY 1 LEVEL 2 No violations recorded Boiler Room 3- Fair 1 EACH
Urgency of Action Purpose of Action Violations Instance Instance Condition Instance Quantity	PRIORITY 1 LEVEL 2 No violations recorded Boiler Room 3- Fair

uestion	Response
MOTOR CONTROLLER	· · · · · · · · · · · · · · · · · · ·
MOTOR CONTROL CENTER	
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1968
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
-	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	N/A
EquipmentId	Area - C
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1968
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Rooms, Boiler Room
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected

Building Condition Assessment Survey 2023-2024

estion	Response
ANEL BOARD	
Fused Toggle Switch Type	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the building
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Kitchen, Gymnasium, Corridor near Rooms 284, 170, B52
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
•	
Deficiency Location/Instance Deficiency Quantity	Boys Locker Room
	1 FACH
Quantity Uom Potential Action	EACH MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Electrical Meter Room, Electrical Room By Room B60
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Meter Room, Electrical Room By Room B60
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
UBLIC ADDRESS SYSTEM	Inspected
Instance	Room A108C
Instance Condition	3- Fair
Instance Quantity	1

Building Condition Assessment Survey 2023-2024

estion	Response
UBLIC ADDRESS SYSTEM	
Instance Quantity Uom	EACH
Model	NQ-E7030
Installation Year	1980
Source of Installation Year	Inspector Estimate
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room A108C
Deficiency Quantity	316,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
ECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2020
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room A114
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2022
Source of Installation Year	Custodial Staff
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REWIRE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	1- Good
	No deficiencies recorded
Deficiency	
Panic Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Question	Response
SECURITY	
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Building Perimeters
Deficiency Quantity	57
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	TIME CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	SDP 3000A Service Switch Fuse 2500A
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1968
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	MDP Section B 2500A Service Switch Fuse 2000A
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1968
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1

Building Condition Assessment Survey 2023-2024

ciricui Inspection	K400
Question	Response
SERVICE SWITCH	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	MDP Section A 2500A Service Switch Fuse 2000A
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1968
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Inspected
Instance	Electrical Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan Electric
EquipmentId	K.D.P
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1968
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance Deficiency Quantity	Electrical Meter Room
	1 FACH
Quantity Uom Potential Action	EACH REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room By Room B60
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan Electric
EquipmentId	N/A
Capacity/Size Quantity	1000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	4
Capacity/Size 2 UOM	Section(s)

Building Condition Assessment Survey 2023-2024

uestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Source of Capacity/Size	Inspector Estimate	
Installation Year	1968	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room By Room B60	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room By Room B60	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
Manutacturer EquipmentId	Distribution Panel ACDP	
Equipmentid Capacity/Size Quantity	400	
Capacity/Size Quality Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	Amps Iotal	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2021	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Meter Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Metropolitan Electric	
EquipmentId	N/A	
Capacity/Size Quantity	1000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	6	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1968	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Meter Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
FELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	

ctrical Inspection		R460
Question	Response	
TELEPHONE SYSTEM		
Standard		
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	