Building Condition Assessment Survey 2023-2024

Electrical Inspection R831

Asset:	P.S. 74 - STATEN ISLAND, 211 DANIEL LOW TERRACE, STATEN ISLAND, NY, 10301				
Inspection Id Inspection Type Time In Last Edited					
4307	ELECTRICAL	2024-03-28 10:41AM	2024-04-16 02:37PM		

Ass

4507 ELECTRICAL	2024-03-28 10:41AM 2024-04-10 02:3/FM
sset Data	
Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: LED Lighting
	Years: 2023, 2019
	Systems: LAN
	Years: 2022
	Systems: Molded Case Circuit Breaker Panel Board
	Years: 2018, 2010, 1992
	Systems: Intrusion Alarm System (Partial Remote Annunciator)
	Years: 2018
	Systems: IPDVS/CCTV System
	Years: 2015
	Systems: Partial Emergency Lighting (Battery Pack)
	Years: 2014
	Systems: Switchboard, Service Switch
	Years: 2010
	Systems: Lighting - Security
	Years: 2008
	Systems: Intrusion Alarm System (Central Control Panel)
	Years: 2006
	Systems: Public Address System, Local Sound System,
	Emergency Light/Exit Light Panel
	Years: 2001
	Systems: Intrusion Alarm System
	Years: 1999

Does Interactive Whiteboard (IWB) Exist?

Water Penetration In Electrical Room?

DEDICATED INTERCOMS IN FIRE RESCUE AREAS	
Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No
your building?	

Below Ground

Yes

No

Priority Condition

Type of Service

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Water Leaks onto Electrical Equipment	Water leaks from the Condensate pipe.	Lighting Fixture	Boiler Room	Justin Settanni	Fireman	

Inspection

Question	Response	
Electrical		
ATHLETIC FIELD	Does not exist	
AUDITORIUM	Does not exist	
CAFETERIA	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		

Building Condition Assessment Survey 2023-2024

Question	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	27	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2001	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Cafeteria-1st Floor	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
	No violations recorded	
Projection System Instance on 1st Floor	Does not exist	
	Does not exist	
Theater Lighting System	D	
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	382	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted	Inspected	

Building Condition Assessment Survey 2023-2024

	n	
estion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted	2 F :	
Condition	3- Fair	
Deficiency Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	42 FACH	
Quantity Uom Potential Action	EACH REPLACE-UPGRADE	
Urgency of Action	PRIORITY I	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted	Inspected	
	3- Fair	
Condition		
Deficiency Deficiency Quantity	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Quantity Uom	20 EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
	Does not exist	
Lighting Fixture - HID	Inspected	
Lighting Fixture - Incandescent		
Pendant Mounted	Inspected 3- Fair	
Condition		
Deficiency Deficiency Operation	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	8 FACH	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1 LEVEL 2	
Purpose of Action Violations	No violations recorded	
-		
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	6	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not exist	
Recessed Mounted	Does not exist	
COMPUTER LAB	Does not exist	
SYMNASIUM	Does not exist	
ATCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	1	

Building Condition Assessment Survey 2023-2024

· veur inspection	110
Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
	Does not exist
SWIMMING POOL	
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8 EAGH
Quantity Uom Potential Action	EACH REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Does not exist
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting Lighting Flydressont	Inspected Inspected
Lighting Fixture - Fluorescent	Inspected
Dandont Mounted	HINDEGEO
Pendant Mounted Condition	3- Fair

Building Condition Assessment Survey 2023-2024

incui inspection		1051
Question	Response	
TOILET ROOM - STUDENT		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Deficiency Quantity	12	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted	Does not exist	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
	Inspected	
Battery Pack Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack Condition	Inspected 3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Does not exist	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Does not exist	
Duct Smoke Detector	Does not exist	
Area Smoke Detector	Does not exist	
CO Detector	Does not exist	
Heat Detector	Does not exist	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency		

Building Condition Assessment Survey 2023-2024

icui Inspection		Koyı
uestion	Response	
FIRE ALARM SYSTEM		
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Fire Alarm Control Board	
Installation Year	1954	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	25,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Sub-Panel	Does not exist	
Remote Annunciator	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Does not exist	
	Does not exist	
LIGHTNING PROTECTION		
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	

Building Condition Assessment Survey 2023-2024

F		
uestion	Response	
PUBLIC ADDRESS SYSTEM		
Instance	Room 215	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Rauland TC2100	
Installation Year	2001	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	2- Between Good and Fair	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista - 128BP	
Installation Year	2006	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inaccessible	
SERVICE SWITCH	Inspected Electrical Meter Room	
Instance		
Instance Condition	2- Between Good and Fair	
Instance Quantity	1 Except	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	800/3P Service Switch	
Capacity/Size Quantity	800	
Capacity/Size UOM Source of Capacity/Size	Amps	
Installation Year	Nameplate 2010	
Installation Year Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD Number of Spares	Inspected 2	
Dillimphor of Vinoros	',	

Building Condition Assessment Survey 2023-2024

Question	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	N/A	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Size	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	