Building Condition Assessment Survey 2023-2024

Electrical Inspection

| Asset: | MORRISANIA SEC | C ED COMPLEX - BRO | DNX, 1365 FULT | ON AVENUE, F | BRONX, NY, 1 | 10456 | |
|---|-------------------------|--------------------|--------------------|--------------------|------------------------|---|---|
| Inspection Id | Inspection Type | | | | Time | In | Last Edited |
| 123 | ELECTRICAL | | | | 2023- | 10-11 08:11AN | M 2023-11-07 08:27A |
| sset Data | | | | | | | |
| Question | | | | Answer | | | |
| Have any Systems/Major Building Components been upgraded? | | | Systems: Years: | | ymnasium and | l Sound Systems in Cafeteria. Auditorium | |
| | | | | Systems: | | | |
| | | | | Years: | 2022 | | |
| | | | | Systems: | | tection, Fused I | Disconnect Switch Type |
| | | | | Years: | 2019 | | |
| | | | | Systems: | Security Light | s | |
| | | | | Years: | 2017, 2011 | | |
| | | | | Systems: | Computer Lab | Room 229, Se Molded Case C | rvice Switch, 'ircuit Breaker Panel |
| | | | | Years: | | rium (Projector | |
| | | | | Systems: | Intrusion Alar | m System | |
| | | | | Years: | 2015 | | |
| | | | | Systems: | Library, Scien | ce Labs, Scien | (Except Locker Rooms, ce Prep Room, Recessed ights (Battery Pack) |
| | | | | Years: | 2012 | | |
| | | | | Systems: | Telephone Sys | stem, Library | |
| | | | | Years: | 2010 | | |
| | | | | Systems: | Lighting | nce Rooms, Re | cessed Fluorescent |
| | | | | Years: | 2009 | · (El | (-1.4) ····· |
| | | | | Systems: | | s (Fluorescent I | Lighting) |
| | | | | Years: | 2007 2nd Floor Scie | naa Daama | |
| | | | | Systems: Years: | | ence Rooms | |
| | | | | Systems: | | | c Sub Panel, Area Smoke for Panel, Printer) |
| | | | | Years: | 2005 | |) |
| | | | | Systems: | Emergency Li | ght/Exit Light 1 | Panel |
| | | | | Years: | 1992 | | |
| Type of Servic | e | | | Below Gr | ound | | |
| | e Whiteboard (IWB) Exi | st? | | Yes | | | |
| | ion In Electrical Room? | | | No | | | |
| | D INTERCOMS IN F | IRE RESCUE AREAS | | | D | | |
| Question Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and | | nd/or Holding Room | | Response No | | | |
| your building | | | | | | | |
| iority Condit | ion | | | | | | |
| | · | Condition | Component | Location | Person(s) | Person(s) | Photo |
| | | Description | Affected | Description | Notified | Title | Image |
| No condition r | ecorded | | | | | | |
| nspection | | | | | | | |
| Question | | | | Response | • | | |
| Electrical | | | | | | | |
| ATHLETIC | FIELD | | | Does not | exist | | |
| AUDITORIUM | | | | Inspected | | | |

BCAS Partners Version 2.0 (P)

Instance on 1st Floor

Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| ricui Inspeciion | | Λ00 |
|---|---------------------------------------|-----|
| Question | Response | |
| AUDITORIUM | | |
| House Lighting | | |
| Instance on 1st Floor | Inspected | |
| Does a Chandelier Exist? | No | |
| Lighting Fixture - Fluorescent | | |
| Instance on 1st Floor | Inspected | |
| Pendant Mounted | | |
| Instance on 1st Floor | Does not exist | |
| Surface Mounted | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | | |
| Instance on 1st Floor | Does not exist | |
| Lighting Fixture - HID | | |
| Instance on 1st Floor | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on 1st Floor | Does not exist | |
| Lighting Fixture - LED | Does not exist | |
| Instance on 1st Floor | Does not exist | |
| Local Sound System | Does not exist | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 1- Good | |
| Installation Year | 2023 | |
| Source of Installation Year | Documented | |
| Deficiency | No deficiencies recorded | |
| Projection System | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Is the projector on a cart or installed on the ceiling? | Ceiling | |
| Deficiency | No deficiencies recorded | |
| Theater Lighting System | | |
| Instance on 1st Floor | Inspected | |
| Dimming System | | |
| Instance on 1st Floor | Does not exist | |
| Theater Lighting | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| CAFETERIA | Inspected | |
| Instance on 1st Floor | Inspected | |
| Lighting | inspected | |
| Instance on 1st Floor | Inspected | |
| Lighting Fixture - Fluorescent | inspecied | |
| Instance on 1st Floor | Inspected | |
| Pendant Mounted | inspected | |
| Instance on 1st Floor | Does not exist | |
| Surface Mounted | Does not exist | |
| Instance on 1st Floor | Inspected | |
| Instance on 1st Floor Instance Condition | Inspected 2- Between Good and Fair | |
| | No deficiencies recorded | |
| Deficiency | no deficiencies recorded | |
| Recessed Mounted | Deserved | |
| Instance on 1st Floor Lighting Fixture - HID | Does not exist | |

Building Condition Assessment Survey 2023-2024

| uestion | Response | |
|---|---------------------------------------|--|
| CAFETERIA | Response | |
| Lighting | | |
| Lighting Fixture - HID | | |
| Instance on 1st Floor | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on 1st Floor | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on 1st Floor | Does not exist | |
| | Does not exist | |
| Local Sound System Instance on 1st Floor | Inspected | |
| Instance Condition | 1- Good | |
| Installation Year | 2023 | |
| Source of Installation Year | Documented | |
| Deficiency | No deficiencies recorded | |
| | No deficición recorded | |
| Projection System Instance on 1st Floor | Does not exist | |
| | | |
| Theater Lighting System Instance on 1st Floor | Does not exist | |
| | | |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Inspected | |
| Lighting Does a Chandelier Exist? | Inspected | |
| | No Inspected | |
| Lighting Fixture - Fluorescent | - | |
| Pendant Mounted | Inspected 2- Between Good and Fair | |
| Condition | | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Lighting Fixture - HID | Does not exist | |
| Lighting Fixture - Incandescent | Does not exist | |
| Lighting Fixture - LED | Does not exist | |
| COMPUTER LAB | Inspected | |
| Instance on Room 310 | Inspected | |
| Power Panel? | No | |
| Instance on Room 229 | Inspected | |
| Power Panel? | No | |
| Lighting | 110 | |
| Instance on Room 310 | Inspected | |
| Instance on Room 229 | Inspected | |
| Lighting Fixture - Fluorescent | inspected | |
| Instance on Room 310 | Inspected | |
| Instance on Room 229 | | |
| | Inspected | |
| Pendant Mounted | | |
| Instance on Room 310 | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 229 | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | | |
| Instance on Room 310 | Does not exist | |

Building Condition Assessment Survey 2023-2024

| lestion | Response |
|---|-------------------------------------|
| COMPUTER LAB | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Surface Mounted | |
| Instance on Room 229 | Does not exist |
| Recessed Mounted | |
| Instance on Room 310 | Does not exist |
| Instance on Room 229 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Room 310 | Does not exist |
| Instance on Room 229 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 310 | Does not exist |
| Instance on Room 229 | Does not exist |
| Lighting Fixture - LED | |
| Instance on Room 310 | Does not exist |
| Instance on Room 229 | Does not exist |
| Raceway With Receptacles | |
| Instance on Room 310 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 229 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| GYMNASIUM | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting | inspected |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | inspected |
| Instance on 1st Floor | Does not exist |
| | |
| Lighting Fixture - HID Instance on 1st Floor | Inspected |
| Pendant Mounted | inspected |
| Instance on 1st Floor | Does not exist |
| Surface Mounted | |
| Instance on 1st Floor | Does not exist |
| Recessed Mounted | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 20 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

Building Condition Assessment Survey 2023-2024

| uestion | Response | |
|---------------------------------|--------------------------|--|
| GYMNASIUM | | |
| | | |
| Lighting Fixture - HID | | |
| Recessed Mounted | | |
| Violations | No violations recorded | |
| Lighting Fixture - Incandescent | | |
| Instance on 1st Floor | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on 1st Floor | Does not exist | |
| Local Sound System | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 1- Good | |
| Installation Year | 2023 | |
| Source of Installation Year | Documented | |
| Deficiency | No deficiencies recorded | |
| Projection System | | |
| Instance on 1st Floor | Does not exist | |
| Scoreboard | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Theater Lighting System | | |
| Instance on 1st Floor | Does not exist | |
| KITCHEN | Inspected | |
| Instance on 1st Floor | Inspected | |
| Lighting | | |
| Instance on 1st Floor | Inspected | |
| Lighting Fixture - Fluorescent | | |
| Instance on 1st Floor | Inspected | |
| Pendant Mounted | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | | |
| Instance on 1st Floor | Does not exist | |
| Lighting Fixture - HID | | |
| Instance on 1st Floor | Does not exist | |
| Lighting Fixture - Incandescent | D | |
| Instance on 1st Floor | Does not exist | |
| Lighting Fixture - LED | D | |
| Instance on 1st Floor | Does not exist | |
| LIBRARY | Inspected | |
| Instance on 2nd Floor | Inspected | |
| Lighting | · · · · | |
| Instance on 2nd Floor | Inspected | |
| Lighting Fixture - Fluorescent | | |
| Instance on 2nd Floor | Inspected | |
| Pendant Mounted | | |
| Instance on 2nd Floor | Inspected 3- Fair | |

Building Condition Assessment Survey 2023-2024

| rical Inspection | Demonso | X00 |
|---|--------------------------|-----|
| uestion | Response | |
| LIBRARY | | |
| Lighting | | |
| Lighting Fixture - Fluorescent Pendant Mounted | | |
| Deficiency | No deficiencies recorded | |
| | No deficiencies recorded | |
| Surface Mounted | Daga not evict | |
| Instance on 2nd Floor | Does not exist | |
| Recessed Mounted Instance on 2nd Floor | Inspected | |
| | 3- Fair | |
| Instance Condition | No deficiencies recorded | |
| Deficiency | No deficiencies recorded | |
| Lighting Fixture - HID | | |
| Instance on 2nd Floor | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on 2nd Floor | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on 2nd Floor | Does not exist | |
| Raceway With Receptacles | Y , 1 | |
| Instance on 2nd Floor | Inspected 3- Fair | |
| Instance Condition | | |
| Deficiency | No deficiencies recorded | |
| Projection System | | |
| Instance on 2nd Floor | Does not exist | |
| LOCKER ROOM | Inspected | |
| Instance on 1st Floor - Boys, 1st Floor - Girls | Inspected | |
| Alternative Use | No | |
| Lighting | | |
| Instance on 1st Floor - Boys, 1st Floor - Girls | Inspected | |
| Lighting Fixture - Fluorescent | | |
| Instance on 1st Floor - Boys, 1st Floor - Girls | Inspected | |
| Pendant Mounted | | |
| Instance on 1st Floor - Boys, 1st Floor - Girls | Does not exist | |
| Surface Mounted | | |
| Instance on 1st Floor - Boys, 1st Floor - Girls | Does not exist | |
| Recessed Mounted | | |
| Instance on 1st Floor - Boys, 1st Floor - Girls | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Lighting Fixture - HID | | |
| Instance on 1st Floor - Boys, 1st Floor - Girls | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on 1st Floor - Boys, 1st Floor - Girls | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on 1st Floor - Boys, 1st Floor - Girls | Does not exist | |
| MULTIPURPOSE ROOM | Does not exist | |
| SCIENCE DEMO ROOM | Does not exist | |
| SCIENCE LAB | Inspected | |
| Instance on Room 202 | Inspected | |
| Power Panel? | Yes | |
| Alternative Use | | |
| | No | |
| Instance on Room 206 | Inspected | |
| Power Panel? | Yes | |
| Alternative Use | No | |
| | | |

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

| cal Inspection | 1 | X00 |
|---------------------------------|--------------------------|-----|
| stion | Response | |
| CIENCE LAB | | - |
| Instance on Room 302 | Inspected | |
| Power Panel? | Yes | |
| Alternative Use | No | |
| Instance on Room 306 | Inspected | |
| Power Panel? | Yes | |
| Alternative Use | No | |
| Lighting | | |
| Instance on Room 202 | Inspected | |
| Instance on Room 206 | Inspected | |
| Instance on Room 302 | Inspected | |
| Instance on Room 306 | Inspected | |
| Lighting Fixture - Fluorescent | 1 | |
| Instance on Room 202 | Inspected | |
| Instance on Room 206 | Inspected | |
| Instance on Room 302 | Inspected | |
| Instance on Room 306 | Inspected | |
| Pendant Mounted | inspected | |
| Instance on Room 202 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 206 | Inspected | |
| Instance Condition | 3- Fair | |
| | No deficiencies recorded | |
| Deficiency | | |
| Instance on Room 302 | Inspected 3- Fair | |
| Instance Condition | | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 306 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | | |
| Instance on Room 202 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 206 | Does not exist | |
| Instance on Room 302 | Does not exist | |
| Instance on Room 306 | Does not exist | |
| Recessed Mounted | | |
| Instance on Room 202 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 206 | Does not exist | |
| Instance on Room 302 | Does not exist | |
| Instance on Room 306 | Does not exist | |
| Lighting Fixture - HID | | |
| Instance on Room 202 | Does not exist | |
| Instance on Room 206 | Does not exist | |
| Instance on Room 302 | Does not exist | - |
| Instance on Room 306 | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on Room 202 | Inspected | |
| Instance on Room 206 | Inspected | |
| Instance on Room 302 | Inspected | |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| | | Л |
|---------------------------------|--------------------------|---|
| lestion | Response | |
| CIENCE LAB | | |
| Lighting | | |
| Lighting Fixture - Incandescent | | |
| Instance on Room 306 | Inspected | |
| Pendant Mounted | | |
| Instance on Room 202 | Does not exist | |
| Instance on Room 206 | Does not exist | |
| Instance on Room 302 | Does not exist | |
| Instance on Room 306 | Does not exist | |
| Surface Mounted | | |
| Instance on Room 202 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 206 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 302 | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 306 | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| | No deficiencies recorded | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | | |
| Instance on Room 202 | Does not exist | |
| Instance on Room 206 | Does not exist | |
| Instance on Room 302 | Does not exist | |
| Instance on Room 306 | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on Room 202 | Does not exist | |
| Instance on Room 206 | Does not exist | |
| Instance on Room 302 | Does not exist | |
| Instance on Room 306 | Does not exist | |
| Emergency Gas Shut-Off Valve | | |
| Instance on Room 202 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 206 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 302 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 306 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Emergency Shut-Off Power | | |
| Instance on Room 202 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 206 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 302 | Inspected | |
| | Inspected | |

Building Condition Assessment Survey 2023-2024

| estion | Response | |
|----------------------------|--------------------------|--|
| CIENCE LAB | | |
| Emergency Shut-Off Power | | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 306 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Power Supply | | |
| Instance on Room 202 | Inspected | |
| Instance on Room 206 | Inspected | |
| Instance on Room 302 | Inspected | |
| Instance on Room 306 | Does not exist | |
| Instructor Unit | | |
| Instance on Room 202 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 206 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 302 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Meter Demonstration Unit | | |
| Instance on Room 202 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 206 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 302 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Student Unit | | |
| Instance on Room 202 | Does not exist | |
| Instance on Room 206 | Does not exist | |
| Instance on Room 302 | Does not exist | |
| Projection System | | |
| Instance on Room 202 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 206 | Does not exist | |
| Instance on Room 302 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 306 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| | | |
| CIENCE PREP ROOM | Inspected | |
| Instance on Rooms 204, 304 | Inspected | |
| Power Panel? | No | |
| Alternative Use | No | |

Building Condition Assessment Survey 2023-2024

| uestion | Response | |
|---------------------------------|--------------------------|--|
| SCIENCE PREP ROOM | | |
| Lighting | | |
| Lighting Fixture - Fluorescent | | |
| Instance on Rooms 204, 304 | Inspected | |
| Pendant Mounted | 1 | |
| Instance on Rooms 204, 304 | Does not exist | |
| Surface Mounted | | |
| Instance on Rooms 204, 304 | Does not exist | |
| Recessed Mounted | | |
| Instance on Rooms 204, 304 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Lighting Fixture - HID | | |
| Instance on Rooms 204, 304 | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on Rooms 204, 304 | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on Rooms 204. 304 | Does not exist | |
| Emergency Gas Shut-Off Valve | | |
| Instance on Rooms 204, 304 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Emergency Shut-Off Power | | |
| Instance on Rooms 204, 304 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Power Supply | | |
| Instance on Rooms 204, 304 | Does not exist | |
| SWIMMING POOL | Does not exist | |
| TOILET ROOM - STAFF | Inspected | |
| Lighting | Inspected | |
| Lighting Fixture - Fluorescent | Inspected | |
| Pendant Mounted | Does not exist | |
| Surface Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | Does not exist | |
| Lighting Fixture - HID | Does not exist | |
| Lighting Fixture - Incandescent | Does not exist | |
| Lighting Fixture - LED | Does not exist | |
| TOILET ROOM - STUDENT | Inspected | |
| Lighting | Inspected | |
| Lighting Fixture - Fluorescent | Inspected | |
| Pendant Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | Does not exist | |
| Lighting Fixture - HID | Does not exist | |
| Lighting Fixture - Incandescent | Does not exist | |
| Lighting Fixture - LED | Does not exist | |

Building Condition Assessment Survey 2023-2024

| | ~ ~ |
|----|-----|
| X0 | 02 |

| | Λ0 |
|--|--|
| uestion | Response |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY DC STANDBY BATTERY POWER | Does not exist |
| EMERGENCY GENERATOR SET | Does not exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| | Inspected |
| EMERGENCY LIGHTING | Inspected |
| Battery Pack Condition | 3- Fair |
| | BATTERY NOT OPERATIONAL |
| Deficiency Deficiency Location/Instance | |
| Deficiency Quantity | Corridors 2nd and 3rd Floor, Auditorium, Cafeteria, Gymnasium 6 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BATTERY |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 4 |
| Violations | 35644118R |
| violations | 35671869L |
| Non Battery Pack | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| | |
| EXITLIGHT | Inspected |
| Battery Pack Condition | Inspected 3- Fair |
| | No deficiencies recorded |
| Deficiency | |
| Non Battery Pack | Does not exist |
| EXIT/EMERGENCY LIGHT | Does not exist |
| FIRE ALARM SYSTEM | Inspected |
| Bell/Horn | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Strobe | Does not exist |
| Manual Pull Station | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Fan Shutdown Control | Does not exist |
| Duct Smoke Detector | Does not exist |
| Area Smoke Detector | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| CO Detector | Does not exist |
| Heat Detector | Does not exist |
| Elevator Recall | Does not exist |
| Magnetic Door Holder/Contactor | Does not exist |
| Fused Cutout Panel | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Digital Communicator | Does not exist |
| Main Panel | Inspected |
| Bell At Panel | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| cui Inspection | Λ |
|---------------------------------------|---------------------------|
| stion | Response |
| RE ALARM SYSTEM | |
| Main Panel | |
| Fire Alarm Control Panel (Electronic) | Does not exist |
| Fire Alarm Control Panel (Standard) | Inspected |
| Instance | Basement by Boiler Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | ACME |
| EquipmentId | N/A |
| Installation Year | 1954 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Basement by Boiler Room |
| Deficiency Quantity | 76,000 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Sub-Panel | Inspected |
| Bell At Panel | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Electronic) | Inspected |
| Instance | Main Entrance Lobby |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Edwards System Technology |
| Model | EST 2 |
| EquipmentId | Smoke Dumper Control |
| Installation Year | 2005 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Standard) | Inspected |
| Instance | Basement by Boiler Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | ACME |
| EquipmentId | Water Flow |
| Installation Year | 1954 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Basement by Boiler Room |
| Deficiency Quantity | 76,000 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Remote Annunciator | Inspected |
| | Does not exist |
| Display Monitor | Does not exist |

Building Condition Assessment Survey 2023-2024

| encies recorded |
|------------------|
| 1 |
| 1 |
| 1 |
| 1 |
| |
| |
| |
| encies recorded |
| exist |
| 1 |
| |
| encies recorded |
| I |
| |
| encies recorded |
| |
| 1 |
| |
| encies recorded |
| exist |
| l |
| 1 |
| |
| encies recorded |
| l |
| |
| encies recorded |
| 1 |
| |
| encies recorded |
| |
| 1 |
| exist |
| 1 |
| |
| encies recorded |
| exist |
| 1 |
| |
| |
| encies recorded |
| exist |
| exist |
| |
| en Good and Fair |
| encies recorded |
| l |
| 's Office |
| |
| |
| |
| |
| |
| ТА250А |
| - |

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

| ctrical Inspection | X002 |
|------------------------------|------------------------------------|
| Question | Response |
| SECURITY | Inspected |
| IPDVS/CCTV System | Does not exist |
| Intrusion Alarm System | Inspected |
| Central Control Panel | Inspected |
| Instance | Custodian Office - Room 112 |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Vista 128BPT |
| Installation Year | 2015 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Infrared Sensor | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Panic Switch | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Siren/Strobe | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting - Security | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Location/Instance | Main Roof |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 3 |
| Violations | No violations recorded |
| SERVICE SWITCH | Inspected |
| Instance | Electrical Room |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Siemens |
| EquipmentId | Service A |
| Capacity/Size Quantity | 800 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2017 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Electrical Room |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Siemens |
| EquipmentId | Service B |
| Capacity/Size Quantity | 800 |
| Capacity/Size UOM | Amps |
| | |

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

| icui Inspeciion | | AUU. |
|---|--------------------------|------|
| uestion | Response | |
| SERVICE SWITCH | | |
| Source of Capacity/Size | Nameplate | |
| Installation Year | 2017 | |
| Source of Installation Year | Documented | |
| Deficiency | No deficiencies recorded | |
| SWITCHBOARD | Inspected | |
| Number of Spares | 11 | |
| Fused Disconnect Switch Type | Does not exist | |
| Fused Knife Switch Type | Does not exist | |
| Molded Case Circuit Breaker Type | Inspected | |
| Instance | Electrical Room | |
| Instance Condition | 2- Between Good and Fair | |
| Instance Quantity | 1 | |
| | EACH | |
| Instance Quantity Uom | | |
| Manufacturer | Siemens | |
| EquipmentId | MDB - A | |
| Capacity/Size Quantity | 800 | |
| Capacity/Size UOM | Amps Total | |
| Capacity/Size 2 Quantity Capacity/Size 2 UOM | 1 Section(r) | |
| Source of Capacity/Size | Section(s) Nameplate | |
| Installation Year | 2017 | |
| Source of Installation Year | Documented | |
| Deficiency | No deficiencies recorded | |
| Instance | Electrical Room | |
| Instance Condition | 2- Between Good and Fair | |
| | | |
| Instance Quantity | 1 | |
| Instance Quantity Uom | EACH | |
| Manufacturer | Siemens | |
| EquipmentId | MDB - B | |
| Capacity/Size Quantity | 800 | |
| Capacity/Size UOM | Amps Total | |
| Capacity/Size 2 Quantity | 1 | |
| Capacity/Size 2 UOM | Section(s) | |
| Source of Capacity/Size | Nameplate | |
| Installation Year | 2017 | |
| Source of Installation Year | Documented | |
| Deficiency | No deficiencies recorded | |
| TELEPHONE SYSTEM | Inspected | |
| PBX/Intercom | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Standard | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| TRANSFORMER | Does not exist | |