Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Mechanical In	spection			X005
Asset:	P.S. 5 - BRONX, 564 JACKSON AVENUE, BRONX, NY, 10455			
Inspection Id	Inspection Type		Time In	Last Edited
4012	MECHANICAL		2024-03-15 07:38AM	2024-04-26 10:36AM
Asset Data				
Question		Answer		
Have any Syste	ems/Major Building Components been upgraded?	Systems:	Fuel Oil Storage/Supply System system	- Fuel Oil Transfer
		Years:	2023	
		Systems:	Heat Pump Domestic Water Hea Kitchen - Grease Trap (1 of 2); I	
		Years:	2022	0
		Systems:	DX Split Systems for Cafeteria (2 of 3); Terminal Unit
			Thermostatic Traps (~50%); Clir	nate Control System -
			Electric System	
		Years:	2021	
		Systems:	F&T/Steam Drip Traps	
		Years:	2020	
		Systems:	MDF Room - Dedicated A/C Eq	uipment (DX Split
			System); DX Split System for Te	elecom Room 126 (1 of
			3)	
		Years:	2014	
		Systems:	Gas Distribution Piping; Boiler H	Fresh Air
			Louver/Dampers	
		Years:	2013	

Yes

15,000

Boiler Room Mechanical Area, Basement MER

2

0

0

3

Yes

No

Boiler Room

No components

Priority Condition

Location(s)

Are there fuel tanks?

Total # of above ground tanks

Total # of below ground tanks

MERs/Fan Rooms Locations

Total capacity of all above ground tanks in gal.

Total capacity of all below ground tanks in gal.

Are there any spaces with Missing or Defective CO Detectors?

Are there any Emergency Stop Switches with Missing Hammers?

Total # of water main service entries to the asset

Are there any Painted/Obstructed Sprinkler Heads?

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo	
Last Year?	Category	Description	Affected	Description	Notified	Title	Image	

No condition recorded

Response	
Inspected	
Inspected	
Does not exist	
Does not exist	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
	Inspected Inspected Does not exist Does not exist Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Inspected 2- Between Good and Fair No deficiencies recorded No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

iestion	Response
AIR CONDITIONING	
Chilled Water System	
Packaged Air Cooled Chiller	
Instance	Roof
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	Chiller-1
Capacity/Size Quantity	100
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year Source of Installation Year	2007 Custodial Staff
Refrigerant Type	R-22
Deficiency	No deficiencies recorded
-	Roof
Instance	2- Between Good and Fair
Instance Condition	
Instance Quantity	1 EACH
Instance Quantity Uom	
Manufacturer	Trane
EquipmentId	Chiller-2
Capacity/Size Quantity	100
Capacity/Size UOM	Tons
Source of Capacity/Size Installation Year	Inspector Estimate 2007
Source of Installation Year	Custodial Staff
Refrigerant Type	R-22
Deficiency	No deficiencies recorded
Water Cooled Chiller	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Outdoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
LIMATE CONTROL SYSTEM	Inspected
BMS	Inspected
Instance	Throughout except Auditorium, Cafeteria, Gymnasium
Instance Condition	3- Fair
Instance Quantity	1
	EACH

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

nunicui Inspeciion	A005
Question	Response
CLIMATE CONTROL SYSTEM	
BMS	
Building Area Covered by Operational System	81-100%
Installation Year	2007
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Pneumatic System	Does not exist
Hybrid System	Does not exist
Electric System	Inspected
Instance	Auditorium, Cafeteria, Gymnasium and 1st Floor Lobby
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
	Basement MER
Instance Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Basement MER
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Sprinkler/Water/Gas Meter Room B4
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance Deficiency Quantity	Sprinkler/Water/Gas Meter Room B4
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Sprinkler/Water/Gas Meter Room B4
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
	EACH
Instance Quantity Uom	
Deficiency	WATER MAIN:DEFECTIVE VALVE
Deficiency Location/Instance	Sprinkler/Water/Gas Meter Room B4
Deficiency Quantity	1

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

stion	Response
DMESTIC WATER SYSTEM	
Domestic Cold Water System	
Water Service	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	WATER MAIN: MISSING BACKFLOW PREVENTION
Deneterey	DEVICE
Deficiency Location/Instance	Sprinkler/Water/Gas Meter Room B4
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water System Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Does not exist
	Does not exist
Oil Fired Domestic Water Heater	Inspected
Heat Pump Domestic Water Heater	Boiler Room Mechanical Area
	l- Good
Instance Condition	
Instance Quantity	2
Instance Quantity Uom	EACH
Manufacturer	A.O. Smith
EquipmentId	#1, #2
Capacity/Size Quantity	5
Capacity/Size UOM	KW Input
Capacity/Size 2 Quantity	58
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2022
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Kitchen
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	A.O. Smith
EquipmentId	N/A
Capacity/Size Quantity	5
Capacity/Size UOM	KW Input
Capacity/Size 2 Quantity	50
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2022
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
	Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

		A00.
uestion	Response	
DOMESTIC WATER SYSTEM		
Domestic Water Distribution Piping		
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sump Pump	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Lavatory/Sink Condition	3- Fair	
	No deficiencies recorded	
Deficiency		
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Inspected	
Instance on 1st Floor - Boys	Inspected	
Instance Condition	3- Fair	
Alternative Use	Yes	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Girls	Inaccessible	
Sink And Fountain Combo Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	

NYC Department of Education **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

anical Inspection	D	X00
uestion	Response	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected 1- Good	
Condition		
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent Condition	Inspected 3- Fair	
Deficiency	No deficiencies recorded	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Does not exist	
HEATING	Inspected	
Heating Coil In Ductwork	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hydronic Heating	Does not exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Heating	Inspected	
F&T/Steam Drip Trap	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
MER Steam and Condensate Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Steam Condensate Return Pumping System	3- Fair	
Deficiency	DEFECTIVE PUMP	
Deficiency Location/Instance Deficiency Quantity	Basement MER 2	
Quantity Uom	2 EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Terminal Unit Thermostatic Trap	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Steam supplied by External Sources Unit Heater/Cabinet Heater	Does not exist	
HEATING PLANT	Inspected	
	-	
Instance on Basement Is there a water meter on the boiler make-up water piping?	Inspected No	
Is there a water meter on the boller make-up water piping? Burner Manufacturer	Preferred Utilities	
Burner Model	B HE 6V 3A4	
Burner Type	Oil	
Heating Plant Oil Number	2(B10)	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

ucui Inspeciion		AU
stion	Response	
EATING PLANT		
Boiler Auxiliaries		
Instance on Basement	Inspected	
Boiler Auxiliary Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on Basement	Does not exist	
Boiler Feedwater Treatment(Automatic)		
Instance on Basement	Does not exist	
Boiler Flue Exhaust		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Basement	Does not exist	
Boiler Room Steam And Condensate Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Safety Valve		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler System		
Instance on Basement	Inspected	
Coal-fired Boiler	A	
Instance on Basement	Does not exist	
Hot Water Boiler		
Instance on Basement	Does not exist	
Modular Boiler		
Instance on Basement	Does not exist	
Steam Boiler		
Instance on Basement	Inspected	
Instance on Basement	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	4,044	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	Fitzgibbons Boiler Company	
EquipmentId	49062-1	
Capacity/Size Quantity	5370	
Capacity/Size UOM	Lbs/Hr steam	
Source of Capacity/Size	Documented	
Installation Year	1961	
Source of Installation Year	Documented	
Deficiency	LEAKY/PLUGGED TUBES	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

-		Δ
stion		Response
EATING PLANT		
Boiler System		
Steam Boiler		
Quantity Uor		EACH
Potential Acti	on	REPLACE
Urgency of A	tion	PRIORITY 3
Purpose of Ac	tion	LEVEL 2
Violations		No violations recorded
Deficiency		DAMAGED REFRACTORY
Deficiency Q	antity	20
Quantity Uor		S.F.
Potential Acti	on	MAINTENANCE
Urgency of A	tion	PRIORITY 3
Purpose of Ac		LEVEL 2
Violations		No violations recorded
Instance		Boiler Room
Instance Condit	on	3- Fair
Instance Quanti		4.044
		4,044 MBH NET
Instance Quanti	•	
Cast Iron Boiler	?	No Fitzgibbons Boiler Company
Manufacturer		49062-2
EquipmentId	nontity.	5370
Capacity/Size Q		
Capacity/Size U Source of Capac		Lbs/Hr steam Documented
Installation Year		1961
Source of Instal		Documented
Deficiency		LEAKY/PLUGGED TUBES
Deficiency Q	iontity	3
Quantity Uom Potential Activ		EACH REPLACE
Urgency of A		PRIORITY 3
Purpose of Ac	tion	LEVEL 2
Violations		No violations recorded
Deficiency		DAMAGED REFRACTORY
Deficiency Q	•	20
Quantity Uon		S.F.
Potential Activ		MAINTENANCE
Urgency of A		PRIORITY 3
Purpose of Ac	tion	LEVEL 2
Violations		No violations recorded
Fuel System		
Instance on Bas	ement	Inspected
Boiler Fresh Air Louv	er/Damper	
Instance on Bas	ement	Inspected
Instance Condit	on	2- Between Good and Fair
Туре		Automatic
Deficiency		No deficiencies recorded
Burner/Burner Contro	l Panel	
Instance on Bas		Inspected
Instance Condit		3- Fair
		No deficiencies recorded
Deficiency		no deficiêncies recorded
Fuel Oil Storage/Supp		· · · · ·
Instance on Bas		Inspected
Instance Condit	on	3- Fair
Deficiency		No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

uestion	Response
HEATING PLANT	
Fuel System	
Gas Trains And Vent At The Boiler	
Instance on Basement	Does not exist
Enclosed IDF Room	Inspected
Instance on Room 104	Inspected
Dedicated A/C Equipment Instance on Room 104	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DOES NOT EXIST
Deficiency Location/Instance	Room 104
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
AITCHEN	Inspected
Instance on 1st Floor	Inspected
CO Detector	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
	No deficiencies recorded
Gas System Instance on 1st Floor	Under construction
Grease Trap Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood	
Instance on 1st Floor	Inspected 3- Fair
Instance Condition	
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Fire Suppression System	
Instance on 1st Floor	Does not exist
Hot Water Temperature Booster	
Instance on 1st Floor	Does not exist
Kitchen Sink	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
MDF Room	Inspected
Instance on Room 432	Inspected
Dedicated A/C Equipment	
Instance on Room 432	Inspected
Instance Condition	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	AUU 5
Response	
	-
No deficiencies recorded	
Does not exist	
-	
Does not exist	
Does not exist	
Inspected	
Yes	
Inspected	
3- Fair	
1-25	
DEFECTIVE	
Roof / EF #3 (bearing)	
1	
EACH	
MAINTENANCE	
No deficiencies recorded	
Inspected	
3- Fair	
Yes	
No	
DAMAGED/MISSING INSULATION	
Roof	
DEFECTIVE DUCTWORK	
Roof (EF Cover)	
10	
L.F.	
	No deficiencies recorded Does not exist Does not exist Inspected Does not exist Inspected 3 - Fair No deficiencies recorded Does not exist Inspected 3 - Fair No deficiencies recorded Inspected 3 - Fair No deficiencies recorded Does not exist Inspected 3 - Fair 1-25 DEFECTIVE Roof / EF #3 (bearing) 1 EACH MAINTENANCE PRIORITY 3 LEVEL 2 No violations recorded Inspected 3 - Fair No DEFECTIVE

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response	
TENTILATION		
Metal Ductwork		
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-5	
Deficiency	No deficiencies recorded	
Unit Ventilator	Does not exist	