Building Condition Assessment Survey 2023-2024

Electrical Inspection X006

Asset:	P.S. 6 - BRONX, 1000 EAST TREMONT AVENUE, B	RONX, NY, 10460		
Inspection Id	Inspection Type		Time In	Last Edited
121	ELECTRICAL		2023-10-10 08:08AM	2024-06-19 02:17PM
set Data				
Question		Answer		
Have any Syste	ms/Major Building Components been upgraded?	Systems:	Most Exit Lights (Battery Pack)	
		Years:	2022, 2019	
		Systems:	Emergency lighting	
		Years:	2022	
		Systems:	Security Lighting	
		Years:	2021, 2015, 2006, 1990	
		Systems:	Fire Alarm System (Remote Ann	unciator)
		Years:	2021	
		Systems:	Partial Molded Case Circuit Brea	aker Panel Boards
		Years:	2019, 2011, 2006, 2000, 1991	
		Systems:	LAN (MDF)	
		Years:	2019	
		Systems:	Interior Fluorescent Lighting Exc	cept (Library,
			Bathrooms - Recessed Fluoresce	nt Lighting), Intrusion
			Alarm System (Panic Switch)	
		Years:	2014	
		Systems:	Auditorium (Partial Theatre Ligh System)	ting, Projection
		Years:	2010	
		Systems:	Library (Fluorescent Lighting)	
		Years:	2007	
		Systems:	Bathrooms (Recessed Fluorescer	nt Lighting)
		Years:	2005	
		Systems:	Emergency Light/Exit Panel	
		Years:	2001, 1991	
		Systems:	Intrusion Alarm System	
		Years:	1996	
		Systems:	Public Address System (Amplific	er, Turner)
		Years:	1995	
Type of Service		Below Gr	ound	
• •	e Whiteboard (IWB) Exist?	Yes		
Water Penetrati	on In Electrical Room?	Yes		

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response	
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No	
your building?		

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Public Address System - Speakers Not Operational	All speakers for Public Address System are not operational in Cafeteria.	Public Address System	Cafeteria	Eliezer Vargas	Fireman	No Photo Taken
Yes	Emergency Lighting - Not Operational	Emergency lights are out of order.	Emergency Lighting	Staircase C/D 4th, 3rd and 2nd Floor	Eliezer Vargas	Fireman	No Photo Taken
Yes	Water Penetration in Electrical Room	Water penetration into Electrical Room after each heavy rain.	Electrical Equipment	Basement	Eliezer Vargas	Fireman	No Photo Taken
No	Exit Light - Not Operational	Emergency lights are out of order	Exit Light	4th and 3rd Floor by Exits 1 and 2	Eliezer Vargas	Fireman	No Photo Taken

Building Condition Assessment Survey 2023-2024

Electrical Inspection X006

Yes Other Lever of Main Disconnect Service Electrical Eliezer Fireman Switch is broken. Switch Room Vargas



pection	
Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on Ground Floor	Inspected
House Lighting	1
Instance on Ground Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on Ground Floor	Inspected
Pendant Mounted	•
Instance on Ground Floor	Does not exist
Surface Mounted	
Instance on Ground Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	No deficiences recorded
Instance on Ground Floor	Does not exist
	Does not exist
Lighting Fixture - HID Instance on Ground Floor	Does not exist
	Does not exist
Lighting Fixture - Incandescent	D
Instance on Ground Floor	Does not exist
Lighting Fixture - LED	
Instance on Ground Floor	Does not exist
Local Sound System	
Instance on Ground Floor	Does not exist
Projection System	
Instance on Ground Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Cart
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on Ground Floor	Inspected
Dimming System	
Instance on Ground Floor	Does not exist
Theater Lighting	
Instance on Ground Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	38
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Inspected
Instance on Ground Floor	Inspected
Lighting	

Building Condition Assessment Survey 2023-2024

Duestion	Response	
CAFETERIA	Response	
Lighting		
Instance on Ground Floor	Inspected	
Lighting Fixture - Fluorescent	пороско	
Instance on Ground Floor	Inspected	
Pendant Mounted	inspected	-
Instance on Ground Floor	Does not exist	
	Does not exist	
Surface Mounted	Y 1	
Instance on Ground Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Ground Floor	Does not exist	
Lighting Fixture - HID		
Instance on Ground Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on Ground Floor	Inspected	
Pendant Mounted		
Instance on Ground Floor	Does not exist	
Surface Mounted		
Instance on Ground Floor	Does not exist	
Recessed Mounted		
Instance on Ground Floor	Inspected	-
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - LED		
Instance on Ground Floor	Does not exist	
Local Sound System		
Instance on Ground Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	1960	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on Ground Floor	Does not exist	
Theater Lighting System		
Instance on Ground Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
	p	

Building Condition Assessment Survey 2023-2024

Electrical Inspection X006

incui Inspection		28000
Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	12	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Does not exist	
KITCHEN	Inspected	
Instance on Ground Floor	Inspected	
Lighting	nispected	
Instance on Ground Floor	Inspected	
Lighting Fixture - Fluorescent	поресси	
Instance on Ground Floor	Inspected	
Pendant Mounted	Inspected	
Instance on Ground Floor	Does not exist	
	DOCS HOT CAIST	
Surface Mounted Instance on Ground Floor	Inquested	
	Inspected 2- Between Good and Fair	
Instance Condition	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Recessed Mounted Instance on Ground Floor	Dear and societ	
	Does not exist	
Lighting Fixture - HID	D	
Instance on Ground Floor	Does not exist	
Lighting Fixture - Incandescent	D	
Instance on Ground Floor	Does not exist	
Lighting Fixture - LED		
Instance on Ground Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 302	Inspected	
Lighting		
Instance on Room 302	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 302	Inspected	
Pendant Mounted		
Instance on Room 302	Inspected	
Instance Condition	4- Between Fair and Poor	

Building Condition Assessment Survey 2023-2024

Electrical InspectionX006QuestionResponse

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Room 302	Does not exist
Recessed Mounted	
Instance on Room 302	Does not exist
Lighting Fixture - HID	
Instance on Room 302	Does not exist
Lighting Fixture - Incandescent	Description's
Instance on Room 302	Does not exist
Lighting Fixture - LED	
Instance on Room 302	Does not exist
Raceway With Receptacles	Dogs not aviet
Instance on Room 302	Does not exist
Projection System Instance on Room 302	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected

Building Condition Assessment Survey 2023-2024

2- Between Good and Fair No deficiencies recorded Does not exist Does not exist Does not exist Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Does not exist
No deficiencies recorded Does not exist Does not exist Does not exist Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Does not exist
No deficiencies recorded Does not exist Does not exist Does not exist Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Does not exist
No deficiencies recorded Does not exist Does not exist Does not exist Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Does not exist
No deficiencies recorded Does not exist Does not exist Does not exist Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Does not exist
Does not exist Does not exist Does not exist Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Does not exist
Does not exist Does not exist Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Does not exist
Does not exist Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Does not exist
Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Does not exist
Inspected 3- Fair No deficiencies recorded Does not exist Does not exist
3- Fair No deficiencies recorded Does not exist Does not exist
No deficiencies recorded Does not exist Does not exist
Does not exist Does not exist
Does not exist
111519 4 0711
3- Fair
No deficiencies recorded
Inspected
Inspected 3- Fair
BATTERY NOT OPERATIONAL
Staircase C/D 4th, 3rd and 2nd Floor
8
EACH
REPLACE BATTERY
PRIORITY 5
LEVEL 6
No violations recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
Inspected
1- Good
No deficiencies recorded
Inspected
3- Fair
FIXTURE NOT OPERATIONAL
4th and 3rd Floor by Exit 1 and 2
4
EACH
REPLACE
PRIORITY 5
LEVEL 6
No violations recorded
Does not exist
Under construction
Inspected
3- Fair
J- 1'4II
No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Electrical Inspection X006

iricai inspection	Auto
Question	Response
LAN	
Local Distribution Frame (I/LDF)	
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROLLER MOTOR CONTROL CENTER	Does not exist
MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
	•
Fused Disconnect Switch Type	Inspected 3- Fair
Condition	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance Deficiency Quantity	4th Floor, Kitchen, Electrical Room, Boiler Room
	5
Quantity Uom Potential Action	EACH REDIAGE UDGRADE
	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1 LEVEL 2
Purpose of Action	
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance Deficiency Quantity	Cafeteria 1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	MainOffice - Room 111
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1960
Installation Year Source of Installation Year	Documented
Double of mountainon feat	Documentou

Building Condition Assessment Survey 2023-2024

Electrical Inspection X006 Question Response PUBLIC ADDRESS SYSTEM Deficiency Location/Instance Throughout the Building Deficiency Quantity Quantity Uom EACH Potential Action REPLACE Urgency of Action PRIORITY 3 Purpose of Action LEVEL 2 Violations No violations recorded Deficiency SPEAKER NOT OPERATIONAL Deficiency Location/Instance Cafeteria Deficiency Quantity 10 EACH Quantity Uom Potential Action REPLACE PRIORITY 5 Urgency of Action Purpose of Action LEVEL 6 Violations No violations recorded Deficiency MASTER CLOCK NOT OPERATIONAL Deficiency Location/Instance Main Office Deficiency Quantity 1 Quantity Uom **EACH** Potential Action REPLACE Urgency of Action PRIORITY 3 Purpose of Action LEVEL 2 Violations No violations recorded BEYOND USEFUL LIFE Deficiency Deficiency Location/Instance MainOffice - Room 111 Deficiency Quantity 82,000 Quantity Uom S.F. REPLACE Potential Action

VIOIATIONS	No violations recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Does not exist	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Room inside the Cafeteria	

PRIORITY 1

No violations recorded

LEVEL 2

Urgency of Action

Purpose of Action

Urgency of Action

Violetions

inspected
Room inside the Cafeteria
3- Fair
1
EACH
Vista - 50P
1996
Documented
PANEL NOT CONNECTED TO DOE CENTRAL STATION
1
EACH
INSTALL CONNECTION
PRIORITY 4
LEVEL 3
No violations recorded
BEYOND USEFUL LIFE
Room inside the Cafeteria
1
EACH
REPLACE

PRIORITY 1

Building Condition Assessment Survey 2023-2024

Question	Response	
SECURITY	•	
Intrusion Alarm System		
Central Control Panel		
Purpose of Action	LEVEL 3	
Violations	No violations recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
	No deficiencies recorded	
Deficiency		
Lighting - Security	Inaccessible	
SERVICE SWITCH	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Challenger	
EquipmentId	Main Service Switch	
Capacity/Size Quantity	1800	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Fuse Size	
Installation Year	1964	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1 LEVEL 2	
Purpose of Action Violations		
	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	0	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Gallagher Switchboard Co.	
EquipmentId	MDP #1, #2	
Capacity/Size Quantity	1800	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Fuse Size 1964	
Installation Year Source of Installation Year		
Deficiency	Documented BEYOND USEFUL LIFE	

Building Condition Assessment Survey 2023-2024

Electrical Inspection X006

Question	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	