## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

Asset:	P.S. 8 - BRONX, 3010 BRIGGS AVENUE, BRONX, NY, 10458		
Inspection Id	Inspection Type	Time In	Last Edited
350	MECHANICAL	2023-10-18 09:15AM	2023-12-14 03:44PM
set Data			

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Boiler #4 re-tubed
	Years: 2023
	Systems: Boiler #3 re-tubed; Exhaust Fans (~80%); Domestic
	Hot Water Remote Storage Tank; Fixtures - Toilets
	Years: 2022
	Systems: CO/Gas Leak Detection; Climate Control System:
	Refrigerated Air Dryer
	Years: 2020
	Systems: F&T/Steam Drip Traps (~40%); Climate Control System: Temperature Control Zone Valves
	Years: 2019
	Systems: F&T/Steam Drip Traps (~50%)
	Years: 2017
Are there fuel tanks?	Yes
Total # of above ground tanks	1
Total capacity of all above ground tanks in gal.	10,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	MER 213
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Room 209 (painted, 2)
Are there any Emergency Stop Switches with Missing Hammers?	No components

### **Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condi	tion recorded	<u>r</u>					
Inspection	1						
Question				Response			
Mechani	cal						
AIR C	ONDITIONING			Inspected			
Chill	ed Water System			Does not	exist		
Cond	lenser Water Distril	bution: Piping, Pumps and Auxiliaries		Does not	exist		
Cooli	ing Coil in Ductwor	·k		Does not	exist		
Cooli	ing Tower			Does not	exist		
DX S	plit System			Inspected			
Ind	oor Unit			Inspected			
С	ondition			2-Betwee	n Good and Fai	ir	
	Deficiency			No defici	encies recorded		
Outdoor Unit			Inspected				
C	ondition			2- Betwee	n Good and Fai	ir	
	Deficiency			No defici	encies recorded		
Dry (	Cooler			Does not	exist		
Pack	aged / Rooftop Unit	t		Inspected			
	Instance			Cafeteria	Roof		
	Instance Conditi	ion		3- Fair			
	Instance Quantit	ty		1			
	Instance Quantit	ty Uom		EACH			
	Manufacturer	-		York			

# Building Condition Assessment Survey 2023-2024

#### **Mechanical Inspection**

unicui Inspeciion	Αθ
uestion	Response
AIR CONDITIONING	
Packaged / Rooftop Unit	
EquipmentId	N/A
Capacity/Size Quantity	4
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2000
Source of Installation Year	Custodial Staff
Source of Heating	Electric
Refrigerant Type	R-22
Deficiency	No deficiencies recorded
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Cafeteria Roof
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Return Fan	Does not exist
	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance	Rooms 102, 202, 305, 306, 307 and other locations
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Electric System	Does not exist
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Basement - Sprinkler/Water/Gas Meter Room B2
Instance Instance Condition	Basement - Sprinkler/Water/Gas Meter Room B2 3- Fair
	-

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

estion	Response
OMESTIC WATER SYSTEM	
Domestic Cold Water System	
Water Service	
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Basement - Sprinkler/Water/Gas Meter Room B2
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement - Crawlspace (Brainbridge Ave Side)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Basement - Crawlspace
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition	1- Good
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room (1 of 2)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1 EACH
Instance Quantity Uom	EACH
Manufacturer	RayPak
EquipmentId	N/A
Capacity/Size Quantity	512 MPH Input
Capacity/Size UOM Capacity/Size 2 Quantity	MBH Input 0
Capacity/Size 2 Quantity Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2009
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected

### **Building Condition Assessment Survey 2023-2024**

Response

#### **Mechanical Inspection**

DOMESTIC WATER SYSTEM

Question

JOMESTIC WATER STSTEM	
Domestic Water Distribution Piping	
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	SEWAGE/WASTE PIPING:CLOGGED
Deficiency Location/Instance	Basement (backs-up during heavy rain)
Deficiency Quantity	100
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	Boiler Room (1 of 2)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
IXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE A LIVILLA BY (FALLCET, SUUT OFF
Deneterey	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
Denenicy	VALVE,ETC.)
Deficiency Location/Instance	
	VALVE,ETC.)

### **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

	-
iestion	Response
FIXTURES	
Student	
Lavatory/Sink	
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Toilet Rooms 114, 214
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
AS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist Does not exist
Gas Meter Room Vent	Does not exist
Gas Pressure Booster CO/Gas Leak Detection	Inspected
Instance	Boiler Room, Sprinkler/Water/Gas Meter Room B2
Instance Condition	1- Good
Instance Quantity	
	1 EACH
Instance Quantity Uom	
Installation Year	
Source of Installation Year	Custodial Staff No deficiencies recorded
Deficiency	
IEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	MER 213 @ Gymnasium Blower (re-heat)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

		XUU
lestion	Response	
IEATING		
Steam Heating	Inspected	
F&T/Steam Drip Trap	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
MER Steam and Condensate Piping	Inspected	
Condition	3- Fair	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	MER 213	
Deficiency Quantity	60	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam Condensate Return Piping	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE VALVE	
Deficiency Location/Instance	Basement - Crawlspace	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 4	
Violations	39054722Z	
Steam Condensate Return Pumping System	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Terminal Unit Thermostatic Trap	•	
Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE/DETERIORATED	
Deficiency Location/Instance	Various Locations	
Deficiency Quantity	70	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
IEATING PLANT	Inspected	
Instance on Basement	Inspected	
Is there a water meter on the boiler make-up water piping?	No	
Burner Manufacturer	Gordon-Piatt	
Burner Model	N/A	
Burner Type	Oil	
Heating Plant Oil Number	2	
Boiler Auxiliaries		
Instance on Basement	Inspected	

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

stion	Response	
EATING PLANT	× ×	
Boiler Auxiliaries		
Boiler Auxiliary Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	20	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Emergency Stop Switch		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on Basement	Does not exist	
Boiler Feedwater Treatment(Automatic)		
Instance on Basement	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Flue Exhaust		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	DRAFT FAN:DEFECTIVE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	60	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

stion	Response	
EATING PLANT	A	
Boiler Auxiliaries		
Boiler Room Steam And Condensate Piping		
Violations	No violations recorded	
Boiler Safety Valve		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler System		
Instance on Basement	Inspected	
Coal-fired Boiler		
Instance on Basement	Does not exist	
Hot Water Boiler		
Instance on Basement	Does not exist	
Modular Boiler		
Instance on Basement	Does not exist	
Steam Boiler		
Instance on Basement	Inspected	
Instance on Basement	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	4,037	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	National U.S. Radiator Corp.	
EquipmentId	7112-3	
Capacity/Size Quantity	5360	
Capacity/Size UOM	Lbs/Hr steam	
Source of Capacity/Size	Documented	
Installation Year	1958	
Source of Installation Year	Documented	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Quantity	20	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	4,037	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	National U.S. Radiator Corp.	
EquipmentId	7112-4 5360	
Capacity/Size Quantity Capacity/Size UOM	Lbs/Hr steam	
Source of Capacity/Size	Documented	
Installation Year	1958	
Source of Installation Year	Documented	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Quantity	80	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

uestion	Response	
HEATING PLANT		
Boiler System		
Steam Boiler		
Violations	No violations recorded	
Fuel System		
Instance on Basement	Inspected	
Boiler Fresh Air Louver/Damper	* · · · · · · · · · · · · · · · · · · ·	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Туре	Automatic	
Deficiency	No deficiencies recorded	
Burner/Burner Control Panel		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fuel Oil Storage/Supply System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Trains And Vent At The Boiler		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	NOT IN USE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	NO ACTION	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 1	
Violations	No violations recorded	
Enclosed IDF Room	Inspected	
Instance on 1st Floor Room near Stair "B", Room 218	Inspected	
Dedicated A/C Equipment	Inspected	
Instance on 1st Floor Room near Stair "B", Room 218	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DOES NOT EXIST	
Deficiency Location/Instance	1st Floor Room near Stair "B", Room 218	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
AITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas System Instance on 1st Floor	Inspected	<u> </u>
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
	no deficiencies recorded	
Grease Trap Instance on 1st Floor	Does not exist	

### **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

unical Inspection	Αυ
Question	Response
KITCHEN	
Grease Trap	
Hood	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Fire Suppression System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hot Water Temperature Booster	
Instance on 1st Floor	Does not exist
Kitchen Sink	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
MDF Room	Inspected
Instance on Original Building - Cafeteria Entrance	Inspected
Dedicated A/C Equipment	
Instance on Original Building - Cafeteria Entrance	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Inspected 3- Fair
Condition Deficiency	NOT IN USE
Deficiency Location/Instance	Basement - Sprinkler/Water/Gas Meter Room B2
Deficiency Quantity	Basement - Sprinkler/ water/Gas Meter Room B2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Room 209 (painted, 2)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE

## **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

uestion	Response	
SPRINKLERS, STANDPIPE, FIRE SYSTEM		
Sprinkler Head		
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Sprinkler Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standpipe System	Does not exist	
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Partial	
Exhaust Fan	Inspected	
Condition	1- Good	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	Yes	
Deficiency	No deficiencies recorded	
Supply Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-5	
Deficiency	No deficiencies recorded	
Unit Ventilator	Does not exist	