Building Condition Assessment Survey 2023-2024

Electrical Inspection

Asset:	P.S. 14 - BRON	X, 3047 BRUCKNER BLVD	, BRONX, NY, 1	0461			
Inspectio	n Id Inspection Type				Time I	n	Last Edited
	4231 ELECTRICAL				2024-0	03-26 09:28AN	A 2024-05-17 12:17P
sset Data							
Question				Answer			
Have any Systems/Major Building Components been upgraded?				Systems:	Auditorium (Pr	rojection System	m)
				Years:	2023		
				Systems:	Multipurpose I	Room	
				Years:	2021		
				Systems:	•	et Rooms (LED	Recessed Lighting)
				Years: Systems:	2020 Security Lighti	na	
				Years:	2018, 2010	ng	
				Systems:	·	al/Bell System	, Lightning Protection,
					Service Switch Most Molded (Partial Motor S Battery Pack), Most Exit Ligh Science Lab Ro Intercom Syste	, Switchboard, Case Circuit Br Starters, Emerge Emergency Lig ats (Battery Pac bom 432, LED m (Fire Rescue	IPDVS/CCTV System, eaker Panel Boards, ency Lighting (Non ghting (Battery Pack), cafeteria, Kitchen, Lighting, Transformers, e/Holding Rooms, ystem, Public Address
							em, New Wing Toilet
						larm System, V	ariable Frequency Drives
				Years:	2018		
				Systems:	Bathrooms), Li		(Original Building Except
				Years:	2014 Auditorium (L	a a al C a un d C ru	stow)
				Systems: Years:	Auditorium (Lo 2013	ocal Sound Sys	stem)
				Systems:	Auditorium (D	nnasium (Local	n, Partial Theatre l Sound System), Fused el Boards
				Years:	2005		
				Systems:	Emergency Lig	ght/Exit Panel	
				Years:	1993		
Type of S				Below Gr	ound		
	ractive Whiteboard (IWB) netration In Electrical Roo			Yes Yes			
		IN FIRE RESCUE AREAS		105			
Question				1	Response		
-	re any Life Rescue Assista	ance Areas, Fire Rescue Areas, an	id/or Holding Roon		Yes		
		ble in all of these spaces for use of	luring a fire?	•	Yes		
	all dedicated intercoms of		<u> </u>		Yes		
riority Co	ondition						
Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Fire Alarm System - Components Not Operational	Duct Smoke detectors creating false alarms and are temporarily turned off.	Fire Alarm System - Duct Smoke Detector	Roof - Existing RTU Duct	John Santiago	Fireman	No Photo Taken
No	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Rooms C01, 522	John Santiago	Fireman	No Photo Taken
Inspection	1						
Question	I			Response	•		
Electrica				*			

BCAS Partners Version 2.0 (P)

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

SEFUL LIFE

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response	
AUDITORIUM		
Theater Lighting System		
Theater Lighting		
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
CAFETERIA	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2018	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	Yes	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	21011
Response	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
Inspected	
Yes	
Inspected	
Inspected	
Inspected	
2- Between Good and Fair	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Doos not avist	
Does not exist	
Insurante d	
Inspected	
Inspected	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Inspected	
Inspected	
	Inspected Inspected Yes Inspected Inspected Inspected Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Inspected 3- Fair No deficiencies recorded Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ricai Inspection		A014
Question	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - LED		
Recessed Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2005	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 3rd Floor	Does not exist	
Scoreboard		
Instance on 3rd Floor	Does not exist	
Theater Lighting System		
Instance on 3rd Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Inspected	
Instance on Room 306	Inspected	
Lighting	ľ	
Instance on Room 306	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 306	Inspected	
Pendant Mounted		
Instance on Room 306	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 306	Does not exist	
Recessed Mounted		
Instance on Room 306	Does not exist	
Lighting Fixture - HID		

Building Condition Assessment Survey 2023-2024

Electrical Inspection

trical Inspection	Despense	
Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - HID Instance on Room 306	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Room 306	Does not exist	
Lighting Fixture - LED		
Instance on Room 306	Does not exist	
Raceway With Receptacles		
Instance on Room 306	Does not exist	
Projection System		
Instance on Room 306	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on Room 211	Inspected	
Lighting	hispeeted	
Instance on Room 211	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 211	Does not exist	
Lighting Fixture - HID		
Instance on Room 211	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 211	Does not exist	
Lighting Fixture - LED		
Instance on Room 211	Inspected	
Pendant Mounted	1	
Instance on Room 211	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 211	Does not exist	
Recessed Mounted		
Instance on Room 211	Does not exist	
Local Sound System		
Instance on Room 211	Inspected	
Instance Condition	1- Good	
Installation Year	2021	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 211	Does not exist	
Theater Lighting System		
Instance on Room 211	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 432	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Room 432	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 432	Does not exist	
Lighting Fixture - HID		
Instance on Room 432	Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui Inspection		
uestion	Response	
SCIENCE LAB		
Lighting		
Lighting Fixture - Incandescent		
Instance on Room 432	Does not exist	
Lighting Fixture - LED		
Instance on Room 432	Inspected	
Pendant Mounted		
Instance on Room 432	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 432	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 432	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 432	Does not exist	
Emergency Shut-Off Power		
Instance on Room 432	Does not exist	
Power Supply		
Instance on Room 432	Does not exist	
Projection System		
Instance on Room 432	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
	-	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icai Inspeciion	AUI
uestion	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
•	
	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	4- Between Fair and Poor
Deficiency	DETECTOR NOT OPERATIONAL
Deficiency Location/Instance	Roof - Existing RTU Duct
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Does not exist
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui Inspection		AUI
uestion	Response	
FIRE ALARM SYSTEM		
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	-
Manufacturer	N/A	
Model	EST	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2018	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	-
Sprinkler Flow/Air Pressure Switch	Inspected	-
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	-
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Inspected	
	Inspected	
Elevator Condition	1- Good	
Deficiency	No deficiencies recorded	
	Does not exist	
Holding Area	Inspected	
AN	Inspected	
Local Distribution Frame (I/LDF) Condition	1- Good	
	No deficiencies recorded	
Deficiency	Inspected	
Main Equipment Rack (MDF) Condition	1- Good	
Deficiency	No deficiencies recorded	
JGHTNING PROTECTION	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		1101
iestion	Response	
MOTOR CONTROLLER		
Variable Frequency Drive	Inspected	
Condition	1- Good	
Deficiency	Variable Frequency Drive Not Operational	
Deficiency Location/Instance	Boiler Room - Penthouse	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
ANEL BOARD	Inspected	
Fused Disconnect Switch Type	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Inspected	
Condition	3- Fair	
Deficiency Deficiency Location/Instance	PANEL BOARD BEYOND USEFUL LIFE	
•	Corridor near Room 206, 306, 406	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	2- Between Good and Fair	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance	Corridor Near Room 206, 306, 402	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
	Inspected	
PUBLIC ADDRESS SYSTEM	-	
Instance	MDF Room 228 2- Between Good and Fair	
Instance Condition		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Bogen HTA250A	
Installation Year	2018	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	2- Between Good and Fair	
Installation Year	2018	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
	Custodian's Office - Room 123	
Instance	Custodian's Office - Room 125	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

iestion	Response	
SECURITY		
Intrusion Alarm System		
Central Control Panel		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista 128BPT	
Installation Year	2018	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
ERVICE SWITCH	Inspected	
Instance	Electrical Room C01	
Instance Condition	2- Between Good and Fair	
Instance Quantity		
	1 EACH	
Instance Quantity Uom	Siemens	
Manufacturer	Fire Pump Disconnect	
EquipmentId Capacity/Size Quantity	800	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2018	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room C01	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	MSB-A	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2018	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room C01	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

· · · · · · · · · · · · · · · · · · ·	centon		110
uestion		Response	
SERVICE S	SWITCH		
	EquipmentId	MSB-B	
	Capacity/Size Quantity	2000	
	Capacity/Size UOM	Amps	
	Source of Capacity/Size	Nameplate	
	nstallation Year	2018	
S	Source of Installation Year	Documented	
I	Deficiency	No deficiencies recorded	
-	nstance	Electrical Room C01	
-	nstance Condition	2- Between Good and Fair	
-	nstance Quantity	1	
-		EACH	
-	nstance Quantity Uom		
	<i>A</i> anufacturer	Siemens	
	EquipmentId	SS1	
	Capacity/Size Quantity	2000	
	Capacity/Size UOM	Amps	
	Source of Capacity/Size	Nameplate	
-	nstallation Year	2018	
-	Source of Installation Year	Documented	
-	Deficiency	No deficiencies recorded	
_	nstance	Electrical Room C01	
I	nstance Condition	2- Between Good and Fair	
Ι	nstance Quantity	1	
Ι	nstance Quantity Uom	EACH	
N	Manufacturer	Siemens	
I	EquipmentId	LP-EM-A	
	Capacity/Size Quantity	200	
	Capacity/Size UOM	Amps	
	Source of Capacity/Size	Nameplate	
-	nstallation Year	2018	
S	Source of Installation Year	Documented	
Ī	Deficiency	No deficiencies recorded	
-	nstance	Electrical Room C01	
Ī	nstance Condition	2- Between Good and Fair	
-	nstance Quantity	1	
-	nstance Quantity Uom	EACH	
-		Siemens	
	Aanufacturer	Spare	
	EquipmentId Capacity/Size Quantity	400	
	Capacity/Size UOM		
		Amps	
	Source of Capacity/Size	Nameplate 2018	
	nstallation Year Source of Installation Year	Documented	
-		No deficiencies recorded	
	Deficiency		
SWITCHB		Inspected	
Number of		17	
	connect Switch Type	Inspected	
-	nstance	Electrical Room C01	
Ī	nstance Condition	2- Between Good and Fair	
Ι	nstance Quantity	1	
I	nstance Quantity Uom	EACH	
-	/anufacturer	Siemens	
	EquipmentId	MSB-A	
	Capacity/Size Quantity	1600	
	Capacity/Size UOM	Amps Total	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icai Inspection	Δ
uestion	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C01
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	SS1
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	
Capacity/Size 2 UOM Source of Capacity/Size	Section(s)
Installation Year	Nameplate 2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
	Penthouse - Electrical Closet 522
Instance Instance Condition	2- Between Good and Fair
Instance Quantity	L EACH
Instance Quantity Uom	
Manufacturer	Siemens
EquipmentId	MSB-2
Capacity/Size Quantity	2000
Capacity/Size UOM Capacity/Size 2 Quantity	Amps Total 2
Capacity/Size 2 UOM	Z Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
FRANSFORMER	Inspected
	*
Instance	Penthouse - Electrical Closet 522 2- Between Good and Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	MGM Transformer Company
EquipmentId	30KVA XFER
Capacity/Size Quantity	30
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2018
Source of Installation Year	Documented

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Question

TRANSFORMER

Deficiency

Response

No deficiencies recorded