

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X019

Asset: P.S. 19 - BRONX, 311 EAST 237TH STREET, BRONX, NY, 10470

| Inspection Id | Inspection Type | Time In | Last Edited |
|---------------|-----------------|--------------------|--------------------|
| 1858 | ELECTRICAL | 2023-12-21 07:51AM | 2024-01-16 08:39AM |

Asset Data

| Question | Answer |
|---|--|
| Have any Systems/Major Building Components been upgraded? | Systems: Exit Lights Years: 2020, 2017 Systems: Partial Motor Starters Years: 2020, 2013 Systems: Partial Molded Case Circuit Breaker Panel Boards Years: 2020, 2008, 2000, 1996 Systems: LED Lights, Cafeteria, Science Lab - Room 338, Science Prep Room 342, Partial Grounding System, Elevator Intercom. New Wing Service Switch, Switchboard, Most Battery Pack Emergency Lights, LAN, Telephone System, Local Sound System, Auxiliary Signal/Bell System, Lightning Protection, IPDVS/CCTV System, Public Address System, Intrusion Alarm System, Holding Room Intercom System, Variable Frequency Drives, Library - Room 110, Fire Alarm System Years: 2020 Systems: Interior Fluorescent Lighting (Except Science Lab - Room 311) Years: 2014 Systems: Exit/Emergency Lighting Years: 2011 Systems: Science Lab - Room 311 Years: 2009 Systems: Emergency Light/ Exit Panel Years: 1992 |
| Type of Service | Below Ground |
| Does Interactive Whiteboard (IWB) Exist? | Yes |
| Water Penetration In Electrical Room? | No |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

| Question | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | Yes |
| Are dedicated intercoms available in all of these spaces for use during a fire? | Yes |
| Are all dedicated intercoms operational? | Yes |

Priority Condition

| Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Photo Image | |
|------------------|-------------------|-----------------------|--------------------|----------------------|--------------------|-----------------|-------------|--|
| | | No condition recorded | | | | | | |

Inspection

| Question | Response |
|---------------------------------------|----------------|
| Electrical | |
| ATHLETIC FIELD | Does not exist |
| AUDITORIUM | Does not exist |
| CAFETERIA | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting | |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - HID | |

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X019

| Question | Response |
|---|--------------------------|
| CAFETERIA | |
| Lighting | |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on 1st Floor | Does not exist |
| Recessed Mounted | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Local Sound System | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Installation Year | 2020 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 1- Good |
| Is the projector on a cart or installed on the ceiling? | Ceiling |
| Deficiency | No deficiencies recorded |
| Theater Lighting System | |
| Instance on 1st Floor | Inspected |
| Dimming System | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Theater Lighting | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| Lighting | |
| Does a Chandelier Exist? | No |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Recessed Mounted | |
| Lighting Fixture - HID | |
| Lighting Fixture - Incandescent | |
| Lighting Fixture - LED | |
| Pendant Mounted | |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X019

| Question | Response |
|--|--------------------------|
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| Lighting | |
| Lighting Fixture - LED | |
| Surface Mounted | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| COMPUTER LAB | |
| Instance on Room 314 | Inspected |
| Power Panel? | Yes |
| Lighting | |
| Instance on Room 314 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 314 | Inspected |
| Pendant Mounted | |
| Instance on Room 314 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 314 | Does not exist |
| Recessed Mounted | |
| Instance on Room 314 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room 314 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 314 | Does not exist |
| Lighting Fixture - LED | |
| Instance on Room 314 | Does not exist |
| Raceway With Receptacles | |
| Instance on Room 314 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| GYMNASIUM | |
| Instance on 4th Floor | Inspected |
| Lighting | |
| Instance on 4th Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 4th Floor | Does not exist |
| Lighting Fixture - HID | |
| Instance on 4th Floor | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on 4th Floor | Does not exist |
| Lighting Fixture - LED | |
| Instance on 4th Floor | Inspected |
| Pendant Mounted | |
| Instance on 4th Floor | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on 4th Floor | Does not exist |
| Recessed Mounted | |

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X019

| Question | Response |
|--|--------------------------|
| GYMNASIUM | |
| Lighting | |
| Lighting Fixture - LED | |
| Recessed Mounted | |
| Instance on 4th Floor | Does not exist |
| Local Sound System | |
| Instance on 4th Floor | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Installation Year | 2020 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Instance on 4th Floor | Does not exist |
| Scoreboard | |
| Instance on 4th Floor | Does not exist |
| Theater Lighting System | |
| Instance on 4th Floor | Does not exist |
| KITCHEN | |
| Instance on 1st Floor | Inspected |
| Lighting | |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | |
| Instance on 1st Floor | Does not exist |
| Surface Mounted | |
| Instance on 1st Floor | Does not exist |
| Recessed Mounted | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| LIBRARY | |
| | Does not exist |
| LOCKER ROOM | |
| | Does not exist |
| MULTIPURPOSE ROOM | |
| | Does not exist |
| SCIENCE DEMO ROOM | |
| | Does not exist |
| SCIENCE LAB | |
| Instance on Room 311 | Inspected |
| Power Panel? | No |
| Alternative Use | No |
| Instance on Room 338 | Inspected |
| Power Panel? | No |
| Alternative Use | No |
| Lighting | |
| Instance on Room 311 | Inspected |
| Instance on Room 338 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 311 | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X019

| Question | Response |
|--|--------------------------|
| SCIENCE LAB | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Instance on Room 338 | Does not exist |
| Pendant Mounted | |
| Instance on Room 311 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 311 | Does not exist |
| Recessed Mounted | |
| Instance on Room 311 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room 311 | Inspected |
| Instance on Room 338 | Does not exist |
| Pendant Mounted | |
| Instance on Room 311 | Does not exist |
| Surface Mounted | |
| Instance on Room 311 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Room 311 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 311 | Does not exist |
| Instance on Room 338 | Does not exist |
| Lighting Fixture - LED | |
| Instance on Room 311 | Does not exist |
| Instance on Room 338 | Inspected |
| Pendant Mounted | |
| Instance on Room 338 | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 338 | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Room 338 | Does not exist |
| Emergency Gas Shut-Off Valve | |
| Instance on Room 311 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 338 | Does not exist |
| Emergency Shut-Off Power | |
| Instance on Room 311 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 338 | Does not exist |
| Power Supply | |
| Instance on Room 311 | Inspected |
| Instance on Room 338 | Does not exist |
| Instructor Unit | |
| Instance on Room 311 | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X019

| Question | Response |
|--|--------------------------|
| SCIENCE LAB | |
| Power Supply | |
| Instructor Unit | |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Meter Demonstration Unit | |
| Instance on Room 311 | Does not exist |
| Student Unit | |
| Instance on Room 311 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Instance on Room 311 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 338 | Does not exist |
| SCIENCE PREP ROOM | Inspected |
| Instance on Room 342 | Inaccessible |
| SWIMMING POOL | Does not exist |
| TOILET ROOM - STAFF | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not exist |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Does not exist |
| Lighting Fixture - LED | Inspected |
| Pendant Mounted | Does not exist |
| Surface Mounted | Does not exist |
| Recessed Mounted | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| TOILET ROOM - STUDENT | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Does not exist |
| Lighting Fixture - LED | Inspected |
| Pendant Mounted | Does not exist |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X019

| Question | Response |
|---|--------------------------|
| TOILET ROOM - STUDENT | |
| Lighting | |
| Lighting Fixture - LED | |
| Surface Mounted | Does not exist |
| Recessed Mounted | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| EMERGENCY DC STANDBY BATTERY POWER | Does not exist |
| EMERGENCY GENERATOR SET | Does not exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY LIGHTING | Inspected |
| Battery Pack | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | BATTERY NOT OPERATIONAL |
| Deficiency Location/Instance | Throughout Old Building |
| Deficiency Quantity | 14 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BATTERY |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Non Battery Pack | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| EXIT LIGHT | Inspected |
| Battery Pack | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Non Battery Pack | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| EXIT/EMERGENCY LIGHT | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| FIRE ALARM SYSTEM | Inspected |
| Bell/Horn | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Strobe | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Manual Pull Station | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Fan Shutdown Control | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Duct Smoke Detector | Inspected |
| Condition | 1- Good |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X019

| Question | Response |
|--|---------------------------|
| FIRE ALARM SYSTEM | |
| Duct Smoke Detector | |
| Deficiency | No deficiencies recorded |
| Area Smoke Detector | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| CO Detector | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Heat Detector | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Elevator Recall | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Magnetic Door Holder/Contactor | Does not exist |
| Fused Cutout Panel | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Fire Alarm Digital Communicator | Does not exist |
| Main Panel | Inspected |
| Bell At Panel | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Electronic) | Inspected |
| Instance | Main Entrance Lobby |
| Instance Condition | 1- Good |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Edwards System Technology |
| Model | EST 3 |
| EquipmentId | Fire Alarm Control Panel |
| Installation Year | 2020 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Standard) | Does not exist |
| Sub-Panel | Inspected |
| Bell At Panel | Does not exist |
| Fire Alarm Control Panel (Electronic) | Inspected |
| Instance | Exit 3 Vestibule |
| Instance Condition | 1- Good |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Edwards System Technology |
| Model | EST 2 |
| EquipmentId | Fire Alarm Control Panel |
| Installation Year | 2020 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Standard) | Does not exist |
| Remote Annunciator | Inspected |
| Display Monitor | Does not exist |
| Panel | Inspected |
| Condition | 1- Good |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X019

| Question | Response |
|---|------------------------------------|
| FIRE ALARM SYSTEM | |
| Remote Annunciator | |
| Panel | |
| Deficiency | No deficiencies recorded |
| Printer | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Punch Register | Does not exist |
| Sprinkler Flow/Air Pressure Switch | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Tamper Flow Switch/Chain | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| GROUNDING SYSTEM | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| INTERCOM SYSTEM | Inspected |
| Elevator | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Holding Area | Does not exist |
| LAN | Inspected |
| Local Distribution Frame (I/LDF) | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Main Equipment Rack (MDF) | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| LIGHTNING PROTECTION | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| MOTOR CONTROLLER | Inspected |
| MOTOR CONTROL CENTER | Does not exist |
| MOTOR STARTER/CONTACTOR | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Variable Frequency Drive | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| PANEL BOARD | Inspected |
| Fused Disconnect Switch Type | Inspected |
| Condition | 3- Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Boiler Room by Old Electrical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Fused Knife Switch Type | Does not exist |
| Fused Toggle Switch Type | Inspected |
| Condition | 3- Fair |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X019

| Question | Response |
|---|--------------------------------------|
| PANEL BOARD | |
| Fused Toggle Switch Type | |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Boiler Room By Old Electrical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Molded Case Circuit Breaker Type | |
| Condition | Inspected |
| Deficiency | 2- Between Good and Fair |
| Deficiency Location/Instance | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Quantity | Throughout Corridors in Old Building |
| Quantity Uom | 8 |
| Potential Action | EACH |
| Urgency of Action | REPLACE-UPGRADE |
| Purpose of Action | PRIORITY 1 |
| Violations | LEVEL 2 |
| Violations | No violations recorded |
| PUBLIC ADDRESS SYSTEM | |
| Instance | Inspected |
| Instance Condition | MDF Room 419 |
| Instance Quantity | 1- Good |
| Instance Quantity Uom | 1 |
| Model | EACH |
| Installation Year | Bogen HTA250A |
| Source of Installation Year | 2020 |
| Deficiency | Documented |
| Deficiency | No deficiencies recorded |
| SECURITY | |
| IPDVS/CCTV System | |
| Condition | Inspected |
| Installation Year | 1- Good |
| Source of Installation Year | 2020 |
| Deficiency | Documented |
| Deficiency | No deficiencies recorded |
| Intrusion Alarm System | |
| Central Control Panel | |
| Instance | Inspected |
| Instance Condition | Custodian's Office - Room 117 |
| Instance Quantity | 1- Good |
| Instance Quantity Uom | 1 |
| Model | EACH |
| Installation Year | Vista 128BPT |
| Source of Installation Year | 2020 |
| Deficiency | Documented |
| Deficiency | No deficiencies recorded |
| Infrared Sensor | |
| Condition | Inspected |
| Deficiency | 1- Good |
| Deficiency | No deficiencies recorded |
| Panic Switch | |
| Condition | Inspected |
| Deficiency | 1- Good |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | |
| Condition | Inspected |
| Deficiency | 1- Good |
| Deficiency | No deficiencies recorded |
| Siren/Strobe | |
| Condition | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X019

| Question | Response |
|-------------------------------|--------------------------|
| SECURITY | |
| Intrusion Alarm System | |
| Siren/Strobe | |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Lighting - Security | Inaccessible |
| SERVICE SWITCH | Inspected |
| Instance | Old Electrical Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Metropolitan |
| EquipmentId | Main Serv. Sw. 800A |
| Capacity/Size Quantity | 800 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Fuse Size |
| Installation Year | 1965 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Old Electrical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance | New Electrical Room |
| Instance Condition | 1- Good |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Siemens |
| EquipmentId | Fire Pump |
| Capacity/Size Quantity | 400 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2020 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | New Electrical Room |
| Instance Condition | 1- Good |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Siemens |
| EquipmentId | SSW#1 HDB |
| Capacity/Size Quantity | 1600 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2020 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | New Electrical Room |
| Instance Condition | 1- Good |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Siemens |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X019

| Question | Response |
|-------------------------------------|-------------------------------|
| SERVICE SWITCH | |
| EquipmentId | SSW#2 MDB |
| Capacity/Size Quantity | 800 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2020 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | New Electrical Room |
| Instance Condition | 1- Good |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Siemens |
| EquipmentId | SSW#3 EMDB |
| Capacity/Size Quantity | 400 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2020 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| SWITCHBOARD | Inspected |
| Number of Spares | 10 |
| Fused Disconnect Switch Type | Inspected |
| Instance | Mechanical Equipment Room 421 |
| Instance Condition | 1- Good |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Siemens |
| EquipmentId | HDB Section #1, Section #2 |
| Capacity/Size Quantity | 1600 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size 2 Quantity | 2 |
| Capacity/Size 2 UOM | Section(s) |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2020 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | New Electrical Room |
| Instance Condition | 1- Good |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Siemens |
| EquipmentId | MDB Section #1, Section #2 |
| Capacity/Size Quantity | 800 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size 2 Quantity | 2 |
| Capacity/Size 2 UOM | Section(s) |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2020 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | New Electrical Room |
| Instance Condition | 1- Good |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Siemens |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X019

| Question | Response |
|---|--------------------------|
| SWITCHBOARD | |
| Fused Disconnect Switch Type | |
| EquipmentId | EMDB |
| Capacity/Size Quantity | 400 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size 2 Quantity | 1 |
| Capacity/Size 2 UOM | Section(s) |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2020 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Old Electrical Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Metropolitan Electric |
| EquipmentId | N/A |
| Capacity/Size Quantity | 800 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size 2 Quantity | 2 |
| Capacity/Size 2 UOM | Section(s) |
| Source of Capacity/Size | Service Switch Fuse Size |
| Installation Year | 1965 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Old Electrical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Fused Knife Switch Type | Does not exist |
| Molded Case Circuit Breaker Type | Does not exist |
| TELEPHONE SYSTEM | Inspected |
| PBX/Intercom | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Standard | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| TRANSFORMER | Does not exist |