Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Asset:	P.S. 24 -	BRONX, 660 WEST 236 STREET	, BRONX, NY, 1	0463			
Inspectio	n Id Inspection	1 Туре			Time	ĺn	Last Edited
	2049 MECHAN	IICAL			2024-	01-02 08:04AN	M 2024-02-15 07:52AN
sset Data							
Question	I			Answer			
Have any	Systems/Major B	Building Components been upgraded?		Systems:	Sewage Ejecto	or Pumps (2 of	4)
				Years:	2020		
				Systems:			s Fired Domestic Water Remote Storage Tank;
					Ductwork (2 c Unit Thermos Pumping Syst	of 4); F&T/Stea tatic Traps; Stea	ervice; Heating Coils in m Drip Traps; Terminal am Condensate Return er/Cabinet Heaters;
				Years:	Heating Plant 2019		
				Systems:		Dedicated A/C	Equipment (DX Split
				Systems.	System); Encl		n - Dedicated A/C
				Years:	2018	A opin bystem)
				Systems:		/entilating Unit	s for Building Addition
				·			p Unit for 2nd Floor
				Years:	2017		
Are there	e fuel tanks?			No			
Total # of	f water main servi	ce entries to the asset		3			
MERs/Fa	an Rooms Location	ns		Sub-Baser	ment Mechanica	l Area, Boiler I	Room Mechanical Area,
						Room B24, M	ER inside Room CL-5,
					Fan Room		
		Missing or Defective CO Detectors? ructed Sprinkler Heads?		No Yes			
	e any Painted/()hst	ructed Sprinkler Heads?					
	-	rueted sprinkler freuds.			Votor Motor Po	m P10 (nointo	4 2)
Location	(s)	-		Sprinker/	Water Meter Roo	om B10 (painte	d, 3)
Location Are there	(s) any Emergency S	Stop Switches with Missing Hammers?				om B10 (painte	d, 3)
Location Are there riority Co	(s) any Emergency S ondition	-	Component	Sprinker/	onents		
Location Are there riority Co	(s) any Emergency S	Stop Switches with Missing Hammers?	Component Affected	Sprinker/\ No compo		om B10 (painte Person(s) Title	d, 3) Photo Image
Location Are there riority Co Exist Last Year?	(s) any Emergency S ondition Priority	Stop Switches with Missing Hammers?	•	Sprinker/ ¹ No compo Location	Person(s)	Person(s)	Photo
Location Are there riority Co Exist Last Year? No condition	(s) any Emergency S ondition Priority Category tion recorded	Stop Switches with Missing Hammers?	•	Sprinker/ ¹ No compo Location	Person(s)	Person(s)	Photo
Location Are there riority Co Exist Last Year? No condition	(s) any Emergency S ondition Priority Category tion recorded	Stop Switches with Missing Hammers?	•	Sprinker/ ¹ No compo Location	Person(s) Notified	Person(s)	Photo
Location Are there riority Co Exist Last Year? No condit	(s) any Emergency S ondition Priority Category tion recorded	Stop Switches with Missing Hammers?	•	Sprinker/^ No compo Location Description	Person(s) Notified	Person(s)	Photo
Location Are there riority Co Exist Last Year? No condit nspection Question Mechani	(s) any Emergency S ondition Priority Category tion recorded	Stop Switches with Missing Hammers?	•	Sprinker/^ No compo Location Description	Person(s) Notified	Person(s)	Photo
Location Are there riority Co Exist Last Year? No condit nspection Question Mechani AIR Co	(s) any Emergency S ondition Priority Category tion recorded	Stop Switches with Missing Hammers? Condition Description	•	Sprinker/ No compo Location Description Response	Person(s) Notified	Person(s)	Photo
Location Are there riority Co Exist Last Year? No condit Inspection Question Mechani AIR Co Chill	(s) any Emergency S ondition Priority Category tion recorded tion cal ONDITIONING ed Water System	Stop Switches with Missing Hammers? Condition Description	Affected	Sprinker/ No compo Location Description Response	Person(s) Notified	Person(s)	Photo
Location Are there riority Co Exist Last Year? No condit nspection Question Mechani AIR Co Chill Cond	(s) any Emergency S ondition Priority Category tion recorded tion cal ONDITIONING ed Water System	Condition Description	Affected	Sprinker/ No compo Location Description Response Inspected Does not of	Person(s) Notified	Person(s)	Photo
Location Are there riority Co Exist Last Year? No condit nspection Question Mechani AIR Co Chill Cond Cooli	(s) any Emergency S ondition Priority Category tion recorded cal ONDITIONING ed Water System lenser Water Dist	Condition Description	Affected	Sprinker/ No compo Location Description Response Inspected Does not o Does not o Does not o	Person(s) Notified	Person(s)	Photo
Location Are there riority Co Exist Last Year? No condit nspection Question Mechani AIR Co Chill Cooli Cooli DX S	(s) any Emergency S ondition Priority Category tion recorded cal ONDITIONING ed Water System lenser Water Dist ing Coil in Ductw ing Tower oplit System	Condition Description	Affected	Sprinker/ No compo Location Description Response Inspected Does not Does not Does not Does not	Person(s) Notified	Person(s)	Photo
Locationd Are there riority Co Exist Last Year? No condit nspection Question Mechani AIR CO Chill Cooli Cooli DX S Dry C	(s) any Emergency S ondition Priority Category tion recorded t cal ONDITIONING ed Water System lenser Water Dist ing Coil in Ductw ing Tower plit System Cooler	Stop Switches with Missing Hammers? Condition Description	Affected	Sprinker/ No compo Location Description Response Inspected Does not Does not Does not Does not Does not	Person(s) Notified	Person(s)	Photo
Locationd Are there riority Co Exist Last Year? No condit nspection Question Mechani AIR CO Chill Cooli Cooli DX S Dry C	(s) any Emergency S ondition Priority Category tion recorded t ical ONDITIONING ed Water System lenser Water Dist ing Coil in Ductw ing Tower oplit System Cooler aged / Rooftop Un	Stop Switches with Missing Hammers? Condition Description	Affected	Sprinker/ No compo Location Description Response Inspected Does not Does not Does not Does not Does not Does not	Person(s) Notified	Person(s)	Photo
Locationd Are there iority Co Exist Last Year? No condit mspection Mechani AIR CO Chill Cooli Cooli DX S Dry C	(s) any Emergency S ondition Priority Category tion recorded tion recorded d acal ONDITIONING ed Water System lenser Water Dist ing Coil in Ductw ing Tower oplit System Cooler aged / Rooftop Un Instance	Condition Condition Description tribution: Piping, Pumps and Auxiliari	Affected	Sprinker/ No compo Location Description Response Inspected Does not o Does not o Does not o Does not o Does not o	Person(s) Notified	Person(s)	Photo
Locationd Are there iority Co Exist Last Year? No condit mspection Mechani AIR CO Chill Cooli Cooli DX S Dry C	(s) any Emergency S ondition Priority Category tion recorded cal ONDITIONING ed Water System lenser Water Dist ing Coil in Ductw ing Tower cooler aged / Rooftop Un Instance Instance Cond	Condition Condition Description	Affected	Sprinker/ No compo Location Description Response Inspected Does not o Does not o DOE DOE DOE DOE DOE DOE DOE DOE DOE DOE	Person(s) Notified	Person(s)	Photo
Locationd Are there riority Co Exist Last Year? No condit nspection Question Mechani AIR CO Chill Cooli Cooli DX S Dry C	(s) any Emergency S ondition Priority Category tion recorded cal ONDITIONING ed Water System lenser Water Dist ing Coil in Ductw ing Tower oplit System Cooler aged / Rooftop Un Instance Quan	Condition Condition Description tribution: Piping, Pumps and Auxiliari ork nit lition nity	Affected	Sprinker/ No compo Location Description Response Inspected Does not o Does not o D	Person(s) Notified	Person(s)	Photo
Locationd Are there riority Co Exist Last Year? No condit nspection Question Mechani AIR CO Chill Cooli Cooli DX S Dry C	(s) any Emergency S ordition Priority Category tion recorded t cal ONDITIONING ed Water System lenser Water Dist ing Coil in Ductw ing Tower pilit System Cooler aged / Rooftop Un Instance Quan Instance Quan	Stop Switches with Missing Hammers? Condition Description tribution: Piping, Pumps and Auxiliari tork nit lition nit utity nity Uom	Affected	Sprinker/ No compo Location Description Response Inspected Does not o Does not o Does not o Does not o Does not o Does not o Does not o Inspected Gymnasiu 1- Good 1 EACH	Person(s) Notified	Person(s)	Photo
Location Are there riority Co Exist Last Year? No condit (nspection Mechani AIR CO Chill Cooli Cooli DX S Dry C	(s) any Emergency S ondition Priority Category tion recorded cal ONDITIONING ed Water System lenser Water Dist ing Coil in Ductw ing Tower oplit System Cooler aged / Rooftop Un Instance Instance Quan Manufacturer	Stop Switches with Missing Hammers? Condition Description tribution: Piping, Pumps and Auxiliari tork nit lition nit utity nity Uom	Affected	Sprinker/ No compo Location Description Response Inspected Does not o Does not o Does not o Does not o Does not o Does not o Inspected Gymnasiu 1- Good 1 EACH Carrier	Person(s) Notified	Person(s)	Photo
Location Are there riority Co Exist Last Year? No condit Inspection Mechani AIR CO Chill Cooli Cooli DX S Dry C	(s) any Emergency S ondition Priority Category tion recorded t cal ONDITIONING ed Water System lenser Water Dist ing Coil in Ductw ing Tower pilit System Cooler aged / Rooftop Un Instance Quan Instance Quan Manufacturer EquipmentId	Stop Switches with Missing Hammers? Condition Description tribution: Piping, Pumps and Auxiliari rork nit lition nit nity nity Uom	Affected	Sprinker/ No compo Location Description Response Inspected Does not o Does not o Does not o Does not o Does not o Does not o Inspected Gymnasiu 1- Good 1 EACH Carrier RTU-1	Person(s) Notified	Person(s)	Photo
Locationd Are there riority Co Exist Last Year? No condit Mechani AIR CO Chill Cooli Cooli DX S Dry C	(s) any Emergency S ondition Priority Category tion recorded cal ONDITIONING ed Water System lenser Water Dist ing Coil in Ductw ing Tower oplit System Cooler aged / Rooftop Un Instance Quan Instance Quan Manufacturer EquipmentId Capacity/Size	Condition Condition Description	Affected	Sprinker/ No compo Location Description Response Inspected Does not a Does not a Does not a Does not a Does not a Inspected Gymnasiu 1- Good 1 EACH Carrier RTU-1 8	Person(s) Notified	Person(s)	Photo
Locationd Are there riority Co Exist Last Year? No condit Mechani AIR CO Chill Cooli Cooli DX S Dry C	(s) any Emergency S ondition Priority Category tion recorded t cal ONDITIONING ed Water System lenser Water Dist ing Coil in Ductw ing Tower pilit System Cooler aged / Rooftop Un Instance Quan Instance Quan Manufacturer EquipmentId	Condition Condition Description	Affected	Sprinker/ No compo Location Description Response Inspected Does not o Does not o Does not o Does not o Does not o Does not o Inspected Gymnasiu 1- Good 1 EACH Carrier RTU-1	Person(s) Notified	Person(s)	Photo

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	Inspection	
uestion		Response
AIR CON	NDITIONING	
	ed / Rooftop Unit	
8	Source of Installation Year	Custodial Staff
	Source of Heating	Gas
	Refrigerant Type	R-410A
	Deficiency	No deficiencies recorded
Packag	ed Terminal A/C	Does not exist
	erant Leak Detection System	Does not exist
	erant Piping	Does not exist
Return		Does not exist
	AL ACID WASTE NEUTRALIZING TANK	Does not exist
		Inspected
	TE CONTROL SYSTEM	•
BMS	x .	Inspected
	Instance	Building Addition - 1st and 2nd Floors
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Building Area Covered by Operational System	81-100%
	Installation Year	2019
	Source of Installation Year	Custodial Staff
	Deficiency	No deficiencies recorded
Pneum	atic System	Inspected
	Instance	Building Addition - Basement
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Building Area Covered by Operational System	81-100%
	Deficiency	DEFECTIVE REFRIGERATED AIR DRYER
	Deficiency Location/Instance	Boiler Room (1 of 2)
	Deficiency Quantity	1
	Quantity Uom	EACH
	Potential Action	MAINTENANCE
	Urgency of Action	PRIORITY 3
	Purpose of Action	LEVEL 2
	Violations	No violations recorded
		
	System	Does not exist Inspected
Electric	c System	-
	Instance	Original Building Throughout 2- Between Good and Fair
	Instance Condition	
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Building Area Covered by Operational System	81-100%
	Deficiency	No deficiencies recorded
COMPA	CTOR	Does not exist
CONVE	VING	Inspected
Dumby		Does not exist
Elevato		Does not exist
Escalat		Does not exist
	nditorium Handicap Lift - Vertical	Does not exist
-	iditorium Handicap Lift - Vertical	Does not exist
Ash Ho		Inspected
Condi		3- Fair
Condi	Il the existing ash hoists operable?	Yes
Areal		
Are al	Deficiency	No deficiencies recorded

NYC Department of Education Building Condition Assessment Survey 2023-2024

Mechanical Inspection

X024

	Δ	
estion	Response	
OMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Inspected	
Gravity System	Does not exist	
Pressure Booster System	Does not exist	
Water Service	Inspected	
Instance	Sprinker/Water Meter Room B10	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE	
Deficiency Location/Instance Deficiency Quantity	Sprinker/Water Meter Room B10 1	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Sub-Basement Mechanical Area, Sprinker/Water Meter Room B10	
Instance Condition	2- Between Good and Fair	
Instance Quantity	2	
Instance Quantity Uom	EACH	
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE	
Deficiency Location/Instance	Sub-Basement Mechanical Area, Sprinker/Water Meter Room B10	
Deficiency Quantity	2	
Quantity Uom	2 EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Domestic Hot Water System	Inspected	
Domestic Hot Water Remote Storage Tank	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Domestic Water Heat Exchanger	Inspected	
Condition	3- Fair	
Deficiency	NOT IN USE	
Deficiency Location/Instance Deficiency Quantity	Sub-Basement Mechanical Area	
Quantity Uom	EACH	
Potential Action Urgency of Action	NO ACTION DRIODITY 1	
Purpose of Action	PRIORITY 1 LEVEL 1	
Violations		
	No violations recorded	
Electric Domestic Water Heater	Does not exist	
Gas Fired Domestic Water Heater	Inspected	
Instance	Sub-Basement Mechanical Area	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	RayPak	
EquipmentId	N/A	
Capacity/Size Quantity	334	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

inicui Inspection	
lestion	Response
DOMESTIC WATER SYSTEM	
Domestic Hot Water System	
Gas Fired Domestic Water Heater	
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Inspector Estimate
Installation Year	2007
Source of Installation Year	Custodial Staff
Deficiency	NOT IN USE
Deficiency Location/Instance	Sub-Basement Mechanical Area
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Instance	Boiler Room Mechanical Area
Instance Condition	1- Good
Instance Quantity	L EACH
Instance Quantity Uom	
Manufacturer	Laars
EquipmentId	N/A
Capacity/Size Quantity	300
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2019
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	Building Addition - Pump Room B24 (1 of 4)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sump Pump	Inspected
Condition	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

nunicui Inspeciion	Δι
Question	Response
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Urinal	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Boy's Toilet Room B18
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
	Inspected
Gas Distribution Piping Condition	1- Good
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Exhaust Fan Gas Meter Room Vent	Does not exist
Gas Meter Room vent Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Inspected
Instance	Boiler Room, Boiler Room Mechanical Area
Instance Condition	2- Between Good and Fair
Instance Quantity	1 EACH
Instance Quantity Uom	
Installation Year	2019 Custo dial Staff
Source of Installation Year	Custodial Staff

NYC Department of Education Building Condition Assessment Survey 2023-2024

Mechanical Inspection

anical Inspection	Χι
iestion	Response
GAS SERVICE	
CO/Gas Leak Detection	
Deficiency	No deficiencies recorded
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance Deficiency Quantity	Building Addition - Pump Room B24
	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Pumping System	Inspected
Condition	1- Good
Deficiency	DEFECTIVE PUMP
Deficiency Location/Instance	Building Addition - Pump Room B24
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Rooms CL-4, B21
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Does not exist
Steam supplied by External Sources	Inspected
Unit Heater/Cabinet Heater Condition	l- Good
	No deficiencies recorded
Deficiency	ino deficiencies recorded

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response	
IEATING PLANT	Inspected	
Instance on Original Building - Basement	Inspected	
Is there a water meter on the boiler make-up water piping?	Yes	
Observed Operational?	No	
Burner Manufacturer	Webster	
Burner Model	JB3G-50-LMV37-S-M.30-VGD-UL-IRI	
Burner Type	Gas	
Heating Plant Oil Number	N/A	
Boiler Auxiliaries		
Instance on Original Building - Basement	Inspected	
Boiler Auxiliary Piping		
Instance on Original Building - Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Original Building - Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
	Increased	
Instance on Original Building - Basement	Inspected 1- Good	
Instance Condition		
Deficiency	No deficiencies recorded	
Boiler Feedwater Treatment(Automatic)		
Instance on Original Building - Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Flue Exhaust		
Instance on Original Building - Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Original Building - Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	No deficicles recorded	
Boiler Room Steam And Condensate Piping	Turner et al	
Instance on Original Building - Basement	Inspected 1- Good	
Instance Condition		
Deficiency	DEFECTIVE ISOLATION VALVE	
Deficiency Location/Instance	Boiler Room @ Boiler #1	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Safety Valve		
Instance on Original Building - Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler System		
Instance on Original Building - Basement	Inspected	
Coal-fired Boiler		
Instance on Original Building - Basement	Does not exist	
Hot Water Boiler		
Instance on Original Building - Basement	Does not exist	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response
EATING PLANT	
Boiler System	
Hot Water Boiler	
Modular Boiler	
Instance on Original Building - Basement	Does not exist
Steam Boiler	
Instance on Original Building - Basement	Inspected
Instance on Original Building - Basement	Inspected
Instance	Boiler Room
Instance Condition	1- Good
Instance Quantity	4,526
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Burnham
EquipmentId	42002-01
Capacity/Size Quantity	5830
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented 2019
Installation Year Source of Installation Year	2019 Custodial Staff
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	1- Good
Instance Quantity	
	4,526 MBH NET
Instance Quantity Uom	
Cast Iron Boiler? Manufacturer	No Burnham
EquipmentId	42002-02
Capacity/Size Quantity	5830
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	2019
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Fuel System	
Instance on Original Building - Basement	Inspected
Boiler Fresh Air Louver/Damper	
Instance on Original Building - Basement	Inspected
Instance Condition	1- Good
Туре	Automatic
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Original Building - Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Fuel Oil Storage/Supply System	
Instance on Original Building - Basement	Does not exist
Gas Trains And Vent At The Boiler	
Instance on Original Building - Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
nclosed IDF Room	Inspected
Instance on Room 209A	Inspected
Dedicated A/C Equipment	Inspecce
Instance on Room 209A	Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

uestion	Response	
Enclosed IDF Room		
Dedicated A/C Equipment		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector	mipeled	
Instance on 1st Floor	Not required	
Gas System	1	
Instance on 1st Floor	Does not exist	
Grease Trap		
Instance on 1st Floor	Does not exist	
Hood		
Instance on 1st Floor	Does not exist	
Hood Exhaust Ductwork		
Instance on 1st Floor	Does not exist	
Hood Exhaust Fan		
Instance on 1st Floor	Does not exist	
Hood Fire Suppression System		
Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 1st Floor	Does not exist	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	Missing Air Gap	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
ADF Room	Inspected	
Instance on Building Addition - Room 229	Inspected	
Dedicated A/C Equipment		
Instance on Building Addition - Room 229	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Inspected	
Condition	3- Fair	
Deficiency	NOT IN USE	
Deficiency Location/Instance	Sprinker/Water Meter Room B10	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	NO ACTION	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 1	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response
PRINKLERS, STANDPIPE, FIRE SYSTEM	
Wet Sprinkler Alarm Valve Assembly	
Violations	No violations recorded
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Sprinker/Water Meter Room B10 (painted, 3)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Standpipe System	Does not exist
Water Gong	
WIMMING POOL	Does not exist
/ENTILATION	Inspected
Is the building Mechanically ventilated?	Partial
Exhaust Fan	Inspected
Condition	2- Between Good and Fair
Approximate Total # of Fans	1-25
Deficiency	DEFECTIVE
Deficiency Location/Instance	Penthouse Fan Room / Lunch Kitchen Exhauster 6K (bearing)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Inspected
Heating And Ventilating Unit	1- Good
Condition	
Deficiency	No deficiencies recorded
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	No
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Sub-Basement Mechanical Area
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Supply Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-5
Deficiency	No deficiencies recorded
Dentency	Does not exist