Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Asset:	F	P.S. 25 - BRON	X, 811 EAST 149 STREET,	BRONX, NY, 1045	55			
Inspection	n Id I	nspection Type				Time	In	Last Edited
	2770 N	IECHANICAL				2024-	01-26 07:24A	M 2024-06-20 02:13PM
sset Data								
Question					Answer			
Have any	Systems	s/Major Building	Components been upgraded?		Systems:	Boiler Safety	Valves	
					Years:	2023		
					Systems:	Electric Press	ure Booster Sys	stem
					Years:	2022		
					Systems: Years:	Refrigerated A Thermostats (Heater; Studer (~50%); F&T.	Air Dryers, Tem ~95%); Gas Fir nt's Fixtures: To /Steam Drip Tra	umatic PRV Station, perature Control ed Domestic Water bilets (~50%), Urinals aps; Terminal Unit Leak Detection
					Systems:	Water Service	;	
					Years:	2016		
					Systems: Years:	System); Encl		Equipment (DX Split n - Dedicated A/C)
Are there	fuel tan	ks?			Yes			
Total	# of abo	ve ground tanks			2			
		of all above grou	and tanks in gal.		6,000			
Total	# of belo	ow ground tanks			0			
		of all below grou	•		0			
Total # of	f water n	nain service entri	es to the asset		2			
		s Locations				om Mechanical	Area, Basemen	t Mechanical Area
		-	or Defective CO Detectors?		No			
	•	nted/Obstructed S	Sprinkler Heads?		Yes			
Location(anaan ay 64 6	tahaa mith Missing II		Basement Mechanical Area - Supply Room (painted, 4) No components			
riority Co			tches with Missing Hammers?		ino compo	onents		
F <i>lority</i> Co Exist	Priori		Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Categ	•	Description	Affected	Description	Notified	Title	Image
Yes		ive CO/Gas Detection	Fault Signal At Control Panel (2)	CO/Gas Leak Detection	Boiler Room Mechanical Area, 1st Floor	Paul Santana	Fireman	

Inspection

Question	Response	
Aechanical		
AIR CONDITIONING	Inspected	
Chilled Water System	Does not exist	
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist	
Cooling Coil in Ductwork	Does not exist	
Cooling Tower	Does not exist	
DX Split System	Inspected	
Indoor Unit	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Outdoor Unit	Inspected	
Condition	2- Between Good and Fair	

Custodian Office

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

unicui Inspeciion	240
uestion	Response
AIR CONDITIONING	
DX Split System	
Outdoor Unit	
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	PNEUMATIC TUBING: DEFECTIVE/LEAKS AIR
Deficiency Location/Instance	Auditorium
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance	Multipurpose Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Electric System	Does not exist
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
	Inspected
Domestic Cold Water System Gravity System	Does not exist
	Inspected
Pressure Booster System	Inspected
Electric Pressure Booster System	-
Instance	Boiler Room Mechanical Area
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Grundfos
EquipmentId	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Total # Pumps
Capacity/Size 2 Quantity	10

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

ical Area, Cafeteria Office
ical Area, Cafeteria Office
GGED

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

uestion	Response
DRAIN/WASTE/VENT AND STORM SYSTEM	
Sewage/Waste/Vent Piping	
Deficiency Quantity	100
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room Mechanical Area
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
	Inspected
FIXTURES	Inspected
Staff And Other	*
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	CLOGGED/LEAKING
Deficiency Location/Instance	1st Floor Staff Toilet Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	4th Floor Man's Toilet Room
Deficiency Quantity	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

uestion	Response
FIXTURES	
Student	· · · · ·
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	CLOGGED/LEAKING
Deficiency Location/Instance	2nd Floor Boys Toilet Room; 3rd Floor Girls Toilet Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
	VALVE,ETC.)
Deficiency Location/Instance	1st Floor Girls Toilet Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
·	VALVE,ETC.)
Deficiency Location/Instance	Rooms 103, 104
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Inspected
Urinal Condition	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Does not exist
	Inspected
CO/Gas Leak Detection	
Instance	Basement - Boiler Room, Boiler Room Mechanical Area, 1st Floor Custodian Office
Instance Condition	3- Fair
Instance Quantity	1

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

lestion	Response
GAS SERVICE	
CO/Gas Leak Detection	2010
Installation Year	2019 Curte dial Staff
Source of Installation Year	
Deficiency	DEFECTIVE CONTROL PANEL
Deficiency Location/Instance	Basement - Boiler Room Mechanical Area, 1st Floor Custodian Office
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
IEATING	Inspected
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	AUXILIARY (VALVE, VENT): DEFECTIVE
Deficiency Location/Instance	1st, 2nd, 3rd Floors Corridors
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	RADIATOR/CONVECTOR:MISSING GUARD/SHIELD
Deficiency Location/Instance	Room 109
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Kitchen
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Pumping System	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE CONTROLS
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response
EATING	
Steam Heating	
Steam Condensate Return Pumping System	
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TANK
Deficiency Location/Instance	Boiler Room (rusted)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Terminal Unit Thermostatic Trap	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	5- Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Main Entrance, Multipurpose Room, Room 214 (7 of 7)
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
EATING PLANT	Inspected
Instance on Basement	Inspected
Is there a water meter on the boiler make-up water piping?	Yes
Observed Operational?	Yes
Burner Manufacturer	N/A
Burner Model	N/A
Burner Type	Dual Fuel (Gas/Oil)
Heating Plant Oil Number	2
Boiler Auxiliaries	2
Instance on Basement	Inspected
	nspected
Boiler Auxiliary Piping	T / 1
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater System	
Boiler Feedwater System Instance on Basement	Inspected
Boiler Feedwater System Instance on Basement Instance Condition	Inspected 3- Fair

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

nicul Inspection	λ
stion	Response
EATING PLANT	
Boiler Auxiliaries	
Boiler Feedwater Treatment(Automatic)	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Room Steam And Condensate Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Boiler System	
Instance on Basement	Inspected
Coal-fired Boiler	
Instance on Basement	Does not exist
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	3,248
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Cleaver Brooks
EquipmentId	7111-01
Capacity/Size Quantity	5230
Capacity/Size UOM	MBH Input
Source of Capacity/Size	Documented
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

lestion		Response	
IEATING	T DI ANT	Response	
Boiler Sy			
Steam			
	Instance Quantity	3,248	
	Instance Quantity Uom	MBH NET	
	Cast Iron Boiler?	No	
	Manufacturer	Cleaver Brooks	
	EquipmentId	7111-02	
	Capacity/Size Quantity	5230	
	Capacity/Size UOM	MBH Input	
	Source of Capacity/Size	Documented	
	Installation Year	1999	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
Fuel Sys	tem		
-	Instance on Basement	Inspected	
Boiler	Fresh Air Louver/Damper		
	Instance on Basement	Inspected	
	Instance Condition	3- Fair	
	Туре	Automatic	
	Deficiency	DEFECTIVE ACTUATOR	
	Deficiency Location/Instance	Boiler Room @ Boiler #1 (1 of 2)	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	MAINTENANCE	
	Urgency of Action	PRIORITY 3	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
Burner	r/Burner Control Panel		
	Instance on Basement	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
	il Storage/Supply System		
rucio	Instance on Basement	Inspected	
	Instance Condition	4- Between Fair and Poor	
	Deficiency	FUEL OIL TANK:DEFECTIVE	
	Deficiency Location/Instance		
	Deficiency Quantity	Basement - Tank Room (sedimentation) 2	
	Quantity Uom	EACH	
	Potential Action	REPAIR	
	Urgency of Action	PRIORITY 3	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
Cas Tr	rains And Vent At The Boiler	No violations recorded	
Gas If	Instance on Basement	Inspected	
		3- Fair	
	Instance Condition	No deficiencies recorded	
	Deficiency		
	DF Room	Inspected	
	Instance on Room in Basement Mechanical Area	Inspected	
	ed A/C Equipment		
	Instance on Room in Basement Mechanical Area	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
KITCHEN	Ň	Inspected	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Response	
Kisponse	
Not required	
Not required	
Does not exist	
Doos not avist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Door not ovict	
Does not exist	
Doos not avist	
D005 1101 CA151	
Inspected	
Missing Air Gap	
Kitchen	
1	
EACH	
MAINTENANCE	
PRIORITY 3	
LEVEL 2	
No violations recorded	
Inspected	
Inspected	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
Inspected	
3- Fair	
	1 EACH MAINTENANCE PRIORITY 3 LEVEL 2 No violations recorded Inspected Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Does not exist

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

lestion	Response
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Sprinkler Head	
Deficiency Location/Instance	Basement Mechanical Area - Supply Room (painted, 4)
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	No
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	No
Deficiency	No deficiencies recorded
Supply Fan	Does not exist
Unit Ventilator	Does not exist