### **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

Inspection	n Id Inspection Typ	e			Time	[n	Last Edited
	3836 MECHANICAI	L			2024-	03-08 07:09AM	1 2024-04-24 12:17PM
sset Data							
Question				Answer			
Have any	Systems/Major Buildin	ng Components been upgraded?		Systems:	Drinking Fountains (~75%); Enclosed IDF Room - Dedicated A/C Equipment (Window A/C)		
				Years:	2023		
				Systems:	MDF Room - System)	Dedicated A/C E	Equipment (DX Split
				Years:	2018		
				Systems:	DX Split Syst	em for Swimmin	ng Pool Area (1 of 2)
				Years:	2015		
				Systems:	Domestic Hot Water System; Supply Fans; Heating Coils In Ductwork (6 of 7); MER Steam and Condensate Piping; Heating And Ventilating Unit (1 of 2) for Cafeteria		
				Years:	2014		10
				Systems:	Heating Plant; Climate Control System (except pneumatic tubing); Gas Service; Steam Condensate Return Pumping System (1 of 2) in Boiler Room; Sun Pumps (2 of 4) in Boiler Room; Sprinkler System; Swimming Pool - Heater (Gas Fired Heater, 1 of 2); Unit Heater/Cabinet Heaters		e; Steam Condensate 2) in Boiler Room; Sump n; Sprinkler System;
				Years:	2013		
Are there	fuel tanks?			No			
Total # of	f water main service en	tries to the asset		4			
MERs/Fa	in Rooms Locations				- Boiler Room	Mechanical Area	, Pool Mechanical
Are there Are there	any spaces with Missi any Painted/Obstructe	ng or Defective CO Detectors? d Sprinkler Heads?		Basement Area, Sou Pool HVA No No	th MER below A		ı, Pool Mechanical Floor - Swimming
Are there Are there Are there	any spaces with Missi any Painted/Obstructe any Emergency Stop S	ng or Defective CO Detectors?		Basement Area, Sou Pool HVA No	th MER below A		
Are there Are there Are there <b>riority Co</b>	any spaces with Missi any Painted/Obstructe any Emergency Stop S <i>ndition</i>	ng or Defective CO Detectors? d Sprinkler Heads? witches with Missing Hammers?	Component	Basement Area, Sou Pool HVA No No No compo	th MER below a C Room	Auditorium; 1st I	Floor - Swimming
Are there Are there Are there <b>riority Co</b> Exist	any spaces with Missi any Painted/Obstructe any Emergency Stop S	ng or Defective CO Detectors? d Sprinkler Heads? witches with Missing Hammers? Condition	Component Affected	Basement Area, Sou Pool HVA No No	th MER below A		
Are there Are there Are there riority Co Exist Last Year?	any spaces with Missi any Painted/Obstructe any Emergency Stop S <i>ndition</i> <b>Priority</b>	ng or Defective CO Detectors? d Sprinkler Heads? witches with Missing Hammers?	•	Basement Area, Sou Pool HVA No No No compo	th MER below A C Room onents Person(s)	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there Are there <b>riority Co</b> Exist Last Year? No condit	any spaces with Missi any Painted/Obstructe any Emergency Stop S <i>ndition</i> <b>Priority</b> <b>Category</b> tion recorded	ng or Defective CO Detectors? d Sprinkler Heads? witches with Missing Hammers? Condition	•	Basement Area, Sou Pool HVA No No No compo	th MER below A C Room onents Person(s)	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there riority Co Exist Last Year? No condit	any spaces with Missi any Painted/Obstructe any Emergency Stop S <i>ndition</i> Priority Category tion recorded	ng or Defective CO Detectors? d Sprinkler Heads? witches with Missing Hammers? Condition	•	Basement Area, Sou Pool HVA No No compo Location Description	th MER below A C Room onents Person(s) Notified	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there riority Co Exist Last Year? No condit (nspection Question	any spaces with Missi any Painted/Obstructe any Emergency Stop S <i>ndition</i> Priority Category tion recorded	ng or Defective CO Detectors? d Sprinkler Heads? witches with Missing Hammers? Condition	•	Basement Area, Sou Pool HVA No No No compo	th MER below A C Room onents Person(s) Notified	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there riority Co Exist Last Year? No condit (nspection Question Mechanic	any spaces with Missi any Painted/Obstructe any Emergency Stop S <i>ndition</i> Priority Category tion recorded	ng or Defective CO Detectors? d Sprinkler Heads? witches with Missing Hammers? Condition	•	Basement Area, Sou Pool HVA No No compo Location Description	th MER below a C Room onents Person(s) Notified	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there Are there riority Co Exist Last Year? No condit Inspection Question Mechanic AIR CO	any spaces with Missi any Painted/Obstructe any Emergency Stop S <i>ndition</i> Priority Category tion recorded	ng or Defective CO Detectors? d Sprinkler Heads? witches with Missing Hammers? Condition	•	Basement Area, Sou Pool HVA No No compo Location Description Response	th MER below A C Room onents Person(s) Notified	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there Are there <b>riority Co</b> Exist Last Year? No condit Inspection Question Mechanic AIR Co Chille	any spaces with Missi any Painted/Obstructe any Emergency Stop S milition Priority Category tion recorded tion recorded cal ONDITIONING ed Water System	ng or Defective CO Detectors? d Sprinkler Heads? witches with Missing Hammers? Condition	Affected	Basement Area, Sou Pool HVA No No compo Location Description Response	th MER below 4 C Room onents Person(s) Notified	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there Are there <b>riority Co</b> Exist Last Year? No condit Inspection Question Mechanic AIR CO Chille Cond	any spaces with Missi any Painted/Obstructe any Emergency Stop S milition Priority Category tion recorded tion recorded cal ONDITIONING ed Water System	ng or Defective CO Detectors? d Sprinkler Heads? switches with Missing Hammers? Condition Description	Affected	Basement Area, Sou Pool HVA No No No compo Location Description Response Inspected Does not of Does not of	th MER below A C Room onents Person(s) Notified exist exist exist exist	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there Are there <b>riority Co</b> Exist Last Year? No condit <b>Inspection</b> Question Mechanic AIR CO Chille Cooli Cooli	any spaces with Missi any Painted/Obstructe any Emergency Stop S <i>indition</i> Priority Category tion recorded cal ONDITIONING ed Water System lenser Water Distribut ng Coil in Ductwork ng Tower	ng or Defective CO Detectors? d Sprinkler Heads? switches with Missing Hammers? Condition Description	Affected	Basement Area, Sou Pool HVA No No No compo Location Description Response Inspected Does not of Does not of Does not of	th MER below A C Room ments Person(s) Notified exist exist exist exist exist	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there Are there <b>riority Co</b> Exist Last Year? No condit <b>Inspection</b> Mechanic AIR CO Chille Cooli Cooli DX S	any spaces with Missi any Painted/Obstructe any Emergency Stop S ndition Priority Category tion recorded cal ONDITIONING ed Water System lenser Water Distribut ng Coil in Ductwork ng Tower plit System	ng or Defective CO Detectors? d Sprinkler Heads? switches with Missing Hammers? Condition Description	Affected	Basement Area, Sou Pool HVA No No No compo Location Description Response Inspected Does not of Does not of Does not of Does not of	th MER below A C Room onents Person(s) Notified exist exist exist exist exist	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there riority Co Exist Last Year? No condit Mechanic AIR CC Cooli Cooli DX S Ind	any spaces with Missin any Painted/Obstructe any Emergency Stop S ndition Priority Category tion recorded cal ONDITIONING ed Water System lenser Water Distribut ng Coil in Ductwork ng Tower plit System oor Unit	ng or Defective CO Detectors? d Sprinkler Heads? switches with Missing Hammers? Condition Description	Affected	Basement Area, Sou Pool HVA No No No compo Location Description Response Inspected Does not of Does not of Does not of Does not of Does not of Does not of Does	th MER below A C Room onents Person(s) Notified exist exist exist exist exist	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there riority Co Exist Last Year? No condit Mechanic AIR CC Cooli Cooli DX S Ind	any spaces with Missi any Painted/Obstructe any Emergency Stop S addition Priority Category tion recorded to cal ONDITIONING ed Water System lenser Water Distribut ng Coil in Ductwork ng Tower plit System oor Unit ondition	ng or Defective CO Detectors? d Sprinkler Heads? switches with Missing Hammers? Condition Description	Affected	Basement Area, Sou Pool HVA No No No compo Location Description Response Inspected Does not of Does not of Does not of Does not of Does not of Does not of Does	th MER below A C Room onents Person(s) Notified exist exist exist exist exist	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there Are there <b>riority Co</b> Exist Last Year? No condit <b>Inspection</b> Question Mechanic AIR CO Chille Cooli Cooli DX S Ind Cooli	any spaces with Missi any Painted/Obstructe any Emergency Stop S milition Priority Category tion recorded cal ONDITIONING ed Water System enser Water Distribut ng Coil in Ductwork ng Tower plit System oor Unit ondition Deficiency	ng or Defective CO Detectors? d Sprinkler Heads? switches with Missing Hammers? Condition Description	Affected	Basement Area, Sou Pool HVA No No No compo Location Description Response Inspected Does not of Does	th MER below A C Room onents Person(s) Notified exist exist exist exist exist exist exist	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there Are there <b>riority Co</b> Exist Last Year? No condit <b>Inspection</b> Mechanic AIR Co Cooli Cooli Cooli DX S Ind Cou	any spaces with Missi any Painted/Obstructe any Emergency Stop S mdition Priority Category tion recorded cal ONDITIONING ed Water System lenser Water Distribut ng Coil in Ductwork ng Tower plit System oor Unit ondition Deficiency tdoor Unit	ng or Defective CO Detectors? d Sprinkler Heads? switches with Missing Hammers? Condition Description	Affected	Basement Area, Sou Pool HVA No No No compo Location Description Response Inspected Does not of Does	th MER below A C Room onents Person(s) Notified exist exist exist exist exist exist exist	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there Are there <b>riority Co</b> Exist Last Year? No condit <b>Inspection</b> Mechanic AIR Coll Cooli Cooli DX S Ind Cou	any spaces with Missi any Painted/Obstructe any Emergency Stop S indition Priority Category tion recorded cal ONDITIONING ed Water System lenser Water Distribut ng Coil in Ductwork ng Tower plit System oor Unit ondition Deficiency tdoor Unit ondition	ng or Defective CO Detectors? d Sprinkler Heads? switches with Missing Hammers? Condition Description	Affected	Basement Area, Sou Pool HVA No No No compo Location Description Response Inspected Does not of Does not of Does not of Does not of Inspected	th MER below 4 C Room ments Person(s) Notified exist exist exist exist exist exist encies recorded	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there Are there <b>riority Co</b> Exist Last Year? No condit Inspection Question Mechania AIR CO Chilla Cooli Cooli DX S Ind Col	any spaces with Missi any Painted/Obstructe any Emergency Stop S addition Priority Category tion recorded to cal ONDITIONING ed Water System lenser Water Distribut ng Coil in Ductwork ng Tower plit System oor Unit ondition Deficiency tdoor Unit ondition Deficiency	ng or Defective CO Detectors? d Sprinkler Heads? switches with Missing Hammers? Condition Description	Affected	Basement Area, Sou Pool HVA No No No compo Location Description Response Inspected Does not of Does	th MER below A C Room ments Person(s) Notified exist exist exist exist exist exist exist encies recorded encies recorded	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there Are there <b>riority Co</b> Exist Last Year? No condit (Inspection) Question Mechanic AIR Co Chilla Cooli Cooli Cooli DX S Ind Cou	any spaces with Missi any Painted/Obstructe any Emergency Stop S milition Priority Category tion recorded cal ONDITIONING ed Water System enser Water Distribut ng Coil in Ductwork ng Tower plit System oor Unit ondition Deficiency tdoor Unit ondition Deficiency Cooler	ng or Defective CO Detectors? d Sprinkler Heads? switches with Missing Hammers? Condition Description	Affected	Basement Area, Sou Pool HVA No No No compo Location Description Response Inspected Does not of Does not of No deficie Does not of No deficie	th MER below A C Room onents Person(s) Notified exist exist exist exist exist exist exist exist exist exist exist exist exist	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there Are there riority Co Exist Last Year? No condit Inspection Mechanic AIR CO Chille Cooli DX S Ind Cooli DX S Ind Coult Cooli	any spaces with Missi any Painted/Obstructe any Emergency Stop S milition Priority Category tion recorded cal ONDITIONING ed Water System lenser Water Distribut ng Coil in Ductwork ng Tower plit System oor Unit ondition Deficiency tdoor Unit ondition Deficiency Cooler aged / Rooftop Unit	ng or Defective CO Detectors? d Sprinkler Heads? switches with Missing Hammers? Condition Description	Affected	Basement Area, Sou Pool HVA No No No compe Location Description Response Inspected Does not of Does not of Does not of Does not of Inspected Inspected Inspected Inspected Inspected Inspected No deficie Does not of No deficie Does not of Does not of No deficie Does not of Does not of Does not of Does not of Does not	th MER below A C Room onents Person(s) Notified exist exist exist exist exist exist exist exist exist exist exist exist exist exist exist exist exist	Auditorium; 1st I	Floor - Swimming Photo
Are there Are there Are there <b>riority Co</b> Exist Last Year? No condit Inspection Mechanic AIR CO Cooli Cooli DX S Ind Cooli DX S Ind Coult Coult Coult Cooli DX S	any spaces with Missi any Painted/Obstructe any Emergency Stop S milition Priority Category tion recorded cal ONDITIONING ed Water System enser Water Distribut ng Coil in Ductwork ng Tower plit System oor Unit ondition Deficiency tdoor Unit ondition Deficiency Cooler	ng or Defective CO Detectors? d Sprinkler Heads? Switches with Missing Hammers? Condition Description tion: Piping, Pumps and Auxiliarie	Affected	Basement Area, Sou Pool HVA No No No compo Location Description Response Inspected Does not of Does not of No deficie Does not of No deficie	th MER below A C Room onents Person(s) Notified exist	Auditorium; 1st I	Floor - Swimming Photo

# **Building Condition Assessment Survey 2023-2024**

### Mechanical Inspection

uestion	Response
AIR CONDITIONING	
Refrigerant Piping	
Condition	1- Good
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Swimming Pool HVAC Room Roof
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Inspected
Instance	Throughout except Swimming Pool Area and Locker Rooms
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	41-60%
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance	Throughout building addition
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Electric System	Does not exist
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
	Inspected
Domestic Cold Water System Gravity System	Does not exist
	Inspected
Pressure Booster System Electric Pressure Booster System	Inspected
Instance	Boiler Room Mechanical Area
	2- Between Good and Fair
Instance Condition	
Instance Quantity	
Instance Quantity Uom	EACH
Manufacturer	Canariis
EquipmentId	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Total # Pumps
Capacity/Size 2 Quantity	15 Total Pumpe HP
Capacity/Size 2 UOM	Total Pumps HP Documented
Source of Capacity/Size	2011
Installation Year Source of Installation Year	2011 Custodial Staff
Deficiency	No deficiencies recorded
	Does not exist
Hydraulic/Pneumatic Booster System	DUES HULEAISL

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

nicui Inspeciion	A0.
estion	Response
OMESTIC WATER SYSTEM	
Domestic Cold Water System	
Water Service	
Instance	Basement - Sprinkler/Water Meter Room C05, North Area by
	183rd Street, South MER below Auditorium
Instance Condition	2- Between Good and Fair
Instance Quantity	4
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	2- Between Good and Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room Mechanical Area
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room Mechanical Area
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Laars
EquipmentId	N/A
Capacity/Size Quantity	818
Capacity/Size UOM	MBH Output
Capacity/Size 2 Quantity	0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year Source of Installation Year	2014 Documented
	No deficiencies recorded
Deficiency           Oil Fired Domestic Water Heater	Does not exist
	Does not exist
Heat Pump Domestic Water Heater	Inspected
Domestic Water Distribution Piping	3- Fair
Deficiency	No deficiencies recorded
RAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected 3- Fair
Condition	
Deficiency	INTERIOR FLOOR DRAIN: DEFECTIVE
Deficiency Location/Instance	Swimming Pool Area
Deficiency Location/Instance Deficiency Quantity Quantity Uom	Swimming Pool Area 1 EACH

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

r	110
estion	Response
RAIN/WASTE/VENT AND STORM SYSTEM	
Sewage/Waste/Vent Piping	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE CONTROLS
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
XTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Does not exist
Student	Inspected
Drinking Fountain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Locker Room Shower	Inspected
Instance on 1st Floor - Boys	Inspected
Instance Condition	3- Fair
Alternative Use	No
Deficiency	No deficiencies recorded
Instance on 1st Floor - Girls	Inspected
Instance Condition	3- Fair
Alternative Use	No
Deficiency	CLOGGED/LEAKING
Deficiency Location/Instance	1st Floor - Girls Shower Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Purpose of Action Violations	LEVEL 2 No violations recorded

# **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

lestion	Response
FIXTURES	
Student	
Toilet	
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Meter Room Vent	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Gas Pressure Booster	Inspected
Instance	Basement - Gas Meter Room C04
Instance Condition	2- Between Good and Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Manufacturer	Etter
EquipmentId	N/A
Capacity/Size Quantity	1
Capacity/Size UOM	HP
Source of Capacity/Size	Documented
Installation Year	2013
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
CO/Gas Leak Detection	Inspected
Instance	Basement - Gas M eter Room C04, Boiler Room, Boiler Room M echanical Area (Gas Leak Detection)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2013
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Boiler Room, Boiler Room Mechanical Area (CO Leak Detection)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2013
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
IEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

stion	Response
EATING	
Radiator/Convector/Fin Tube	
Condition	3- Fair
Deficiency	RADIATOR/CONVECTOR:DEFECTIVE
Deficiency Location/Instance	Room 202
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action Purpose of Action	PRIORITY 3 LEVEL 2
Violations	No violations recorded
Deficiency	
Deficiency Location/Instance	AUXILIARY (VALVE,VENT):DEFECTIVE Exit "8"
Deficiency Quantity	l
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Corridor near 1st Floor - Swimming Pool HVAC Room
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Pumping System	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE PUMP
Deficiency Location/Instance	Boiler Room, South MER below Auditorium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
-	Does not exist
iteam supplied by External Sources Jnit Heater/Cabinet Heater	Inspected
In regier/L annot Hoater	HINDEULEU

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

estion	Response	-
IEATING		
Unit Heater/Cabinet Heater		
Deficiency	No deficiencies recorded	
EATING PLANT	Inspected	
Instance on Basement	Inspected	
Is there a water meter on the boiler make-up water piping?	Yes	
Observed Operational?	No	
Burner Manufacturer Burner Model	Webster HDSG-250A-5V-50-RM7840L-F-M.30H-UL/IRI	
Burner Type	Gas	
Heating Plant Oil Number	N/A	
Boiler Auxiliaries	- · · · ·	
Instance on Basement	Inspected	
Boiler Auxiliary Piping	1	
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater System	No deficielles recorded	
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Boiler Feedwater Treatment(Automatic)	Y , 1	
Instance on Basement	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Boiler Flue Exhaust	·	
Instance on Basement		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler Safety Valve		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler System		
Instance on Basement	Inspected	
Coal-fired Boiler		
Instance on Basement	Does not exist	
Hot Water Boiler		
Instance on Basement	Does not exist	
Modular Boiler		
Instance on Basement	Does not exist	_

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

	uon		AU
uestion		Response	
HEATING PLAN	Τ		
<b>Boiler System</b>			
Steam Boiler			
Instanc	e on Basement	Inspected	
Instanc	e on Basement	Inspected	
Instanc	e	Boiler Room	
Instanc	e Condition	2- Between Good and Fair	
Instanc	e Quantity	6,498	
Instanc	e Quantity Uom	MBH NET	
Cast Ir	on Boiler?	No	
Manufa	acturer	Burnham	
Equipn		1175-01	
	ty/Size Quantity	8369	
-	ty/Size UOM	MBH Gross	
	of Capacity/Size	Documented	
	tion Year of Installation Year	2013 Custodial Staff	
		No deficiencies recorded	
Deficie			
Instanc		Boiler Room	
	e Condition	2- Between Good and Fair	
	e Quantity	6,498	
Instanc	e Quantity Uom	MBH NET	
	on Boiler?	No	
Manufa		Burnham	
Equipn		1175-02	
	ty/Size Quantity	8369	
-	ty/Size UOM	MBH Gross	
	of Capacity/Size	Documented 2013	
	of Installation Year	Custodial Staff	
Deficie		No deficiencies recorded	
	itey		
Fuel System	e on Basement	Inspected	
	sir Louver/Damper	inspected	
	e on Basement	Inspected	
	e Condition	2- Between Good and Fair	
Type	e Condition	Mechanical	
Deficie	201	No deficiencies recorded	
	er Control Panel	No deficicies recorded	
	e on Basement	Inspected	
		Inspected 2- Between Good and Fair	
	e Condition		
Deficie		No deficiencies recorded	
	ge/Supply System		
	e on Basement	Does not exist	
	d Vent At The Boiler	×	
	e on Basement		
	e Condition	2- Between Good and Fair	
Deficie		No deficiencies recorded	
Enclosed IDF Ro		Inspected	
Instanc	e on Building Addition - Room 353	Inspected	
Dedicated A/C			
Instanc	e on Building Addition - Room 353	Inspected	
Instanc	e Condition	1- Good	
Deficie	ncy	No deficiencies recorded	
KITCHEN		Inspected	

# **Building Condition Assessment Survey 2023-2024**

### Mechanical Inspection

unicui	Inspection		X032
uestion		Response	
кітсні	EN		
	Instance on 1st Floor	Inspected	
CO De	tector		
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Gas Sy	stem		
·	Instance on 1st Floor	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
Grease	-		
	Instance on 1st Floor	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
Hood			
11000	Instance on 1st Floor	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
Hood I	Exhaust Ductwork		
1100u I	Instance on 1st Floor	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
	Exhaust Fan		
Hood I	Instance on 1st Floor	Inspected	
		2- Between Good and Fair	
	Instance Condition		
	Deficiency	No deficiencies recorded	
Hood I	Fire Suppression System	T ( 1	
	Instance on 1st Floor	Inspected 2- Between Good and Fair	
	Instance Condition		
	Deficiency	No deficiencies recorded	
Hot Wa	ater Temperature Booster		
	Instance on 1st Floor	Does not exist	
Kitche			
	Instance on 1st Floor	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
1DF Ro		Inspected	
	Instance on Original Building - Room 213	Inspected	
Dedica	te <u>d A/C Equipment</u>		
	Instance on Original Building - Room 213	Inspected	
	Instance Condition	3- Fair	
	Deficiency	DEFECTIVE	
	Deficiency Location/Instance	Original Building - Room 213	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	MAINTENANCE	
	Urgency of Action	PRIORITY 3	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
SCIENC	E DEMO ROOM	Does not exist	
SCIENC	CE LAB	Does not exist	
SCIENC	E PREP ROOM	Does not exist	
<u>SPRINK</u>	LERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sn	orinkler Alarm Valve Assembly	Does not exist	

### **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

uestion		Response
SPRINKI	LERS, STANDPIPE, FIRE SYSTEM	
	rinkler Alarm Valve Assembly	Inspected
Condi		2- Between Good and Fair
	Deficiency	NOT IN USE
	Deficiency Location/Instance	Basement - Sprinkler/Water Meter Room C05
	Deficiency Quantity	1
	Quantity Uom	EACH
	Potential Action	NO ACTION
	Urgency of Action	PRIORITY 1
	Purpose of Action	LEVEL 1
	Violations	No violations recorded
Fire Boo	oster Pump Assembly	Does not exist
Roof Ta	nk	Does not exist
Siamese	Connection	Inspected
Condit	tion	1- Good
	Deficiency	No deficiencies recorded
Sprinkle	er Head	Inspected
Condit		2- Between Good and Fair
	Deficiency	No deficiencies recorded
Sprinkl	er Piping	Inspected
Condit		1- Good
condi	Deficiency	No deficiencies recorded
Standni	pe System	Does not exist
Water C		Does not exist
	NG POOL	Inspected
5 W HVHVH		
	Instance on Building Addition - 1st Floor	Inspected
Filter		
	cement Quantity	11 EACH
Replac	cement Uom	
	Instance on Building Addition - 1st Floor	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
Heater		
	Instance on Building Addition - 1st Floor	Inspected
	Instance Condition	2- Between Good and Fair
	Deficiency	No deficiencies recorded
Piping		
	Instance on Building Addition - 1st Floor	Inspected
	Instance Condition	2- Between Good and Fair
	Deficiency	DEFECTIVE/LEAKS
	Deficiency Location/Instance	Mechanical Pool Area
	Deficiency Quantity	10
	Quantity Uom	L.F.
	Potential Action	REPLACE
	Urgency of Action	PRIORITY 3
	Purpose of Action	LEVEL 2
	Violations	No violations recorded
Pump		
Ľ	Instance on Building Addition - 1st Floor	Inspected
	Instance Condition	2- Between Good and Fair
	Deficiency	No deficiencies recorded
VENTER		Inspected
VENTILA In the b		Partial
is the h	uilding Mechanically ventilated?	
Exhaust	For	Inspected

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

· · · · · · · · · · · · · · · · · · ·		
iestion	Response	
VENTILATION		
Exhaust Fan		
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Metal Ductwork	Inspected	
Condition	2- Between Good and Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Inspected	
Condition	2- Between Good and Fair	
Approximate Total # of Fans	1-5	
Deficiency	No deficiencies recorded	
Unit Ventilator	Does not exist	