Building Condition Assessment Survey 2023-2024

Mechanical Inspection X034

Asset:	P.S. 34 - BRONX, 770 GROTE STREET, BRONX, NY, 10460		
Inspection Id	Inspection Type	Time In	Last Edited
447	MECHANICAL	2023-10-25 09:05AM	2024-01-05 09:07PM

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Sump Pumps (rebuild); Student - Drinking Fountain (~90%); Boiler #2 refractory
	Years: 2022
	Systems: Boiler Feedwater System
	Years: 2020
	Systems: Electric Pressure Booster System; CO/Gas Leak Detection; F&T/Steam Drip Traps; Kitchen - Hot Wi Temperature Booster
	Years: 2018
	Systems: DX Split System for Telecom Room 304 (1 of 2); M Room Dedicated A/C Equipment (DX Split System)
	Years: 2017
Are there fuel tanks?	Yes
Total # of above ground tanks	2
Total capacity of all above ground tanks in gal.	7,775
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	Basement - MER 9, Boiler Room Mechanical Area
Are there any spaces with Missing or Defective CO Detectors?	Yes
Location(s)	Basement - Generator Room
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	1st Floor near Main Office (obstructed, 1)

No components

Priority Condition

Are there any Emergency Stop Switches with Missing Hammers?

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Defective Kitchen Gas System	MER 9 / Defective Master Gas Control Valve; Kitchen / Defective Shut-Off Switch	Gas System	Kitchen, Basement - MER 9	Jay Gomez	Fireman	
Yes	Other	Defective Shut-Off Switch	Culinary Room Gas System	Culinary Room 327	Jay Gomez	Fireman	
No	Defective CO/Gas Leak Detection	Fault Signal At Panel	CO/Gas Leak Detection	Basement - MER 9	Jay Gomez	Fireman	

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Inspected
Absorption Chiller	Does not exist

Building Condition Assessment Survey 2023-2024

Duestion	Response
AIR CONDITIONING	Tesponse .
Chilled Water System	
Air Cooled Chiller	Inspected
Instance	Basement - MER 9
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	McQuay
Manufacturer EquipmentId	Chiller#1
Capacity/Size Quantity	130
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1996
Source of Installation Year	Documented
Refrigerant Type	R-22
Deficiency	No deficiencies recorded
Instance	Basement - MER 9
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	McQuay
Manufacturer EquipmentId	Chiller#2
Equipmentid Capacity/Size Quantity	130
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1996
Source of Installation Year	Documented
Refrigerant Type	R-22
Deficiency	No deficiencies recorded
Instance	Basement - MER 9
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	McQuay
Manufacturer EquipmentId	Chiller#3
Equipmentid Capacity/Size Quantity	130
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1996
Source of Installation Year	Documented
Refrigerant Type	R-22
Deficiency	No deficiencies recorded
Air Cooled Condenser	Inspected
Instance	Main Roof
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	McQuay
Manufacturer	ACC-1
EquipmentId Capacity/Size Quantity	130
Capacity/Size Quantity Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1996
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
	M. D. C

Main Roof

Instance

Building Condition Assessment Survey 2023-2024

nestion	Response	
AIR CONDITIONING	Teoponic .	
Chilled Water System		
Air Cooled Condenser		
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Manufacturer	McQuay ACC-2	
EquipmentId Capacity/Size Quantity	130	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Main Roof	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	McQuay	
EquipmentId	ACC-3	
Capacity/Size Quantity	130	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Chilled Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	3- Fair	
Deficiency	PIPING:DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	Basement - MER 9	
Deficiency Quantity	20	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Backflow Preventer	Does not exist	
Central Station Air Handler	Inspected	
Instance	Basement -MER 9	
Instance Condition	3- Fair	
Instance Quantity	2	
Instance Quantity Uom	EACH	
Manufacturer	McQuay	
EquipmentId	AHU-1, AHU-3	
Capacity/Size Quantity	10	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Basement - MER 9	
Instance Condition	3- Fair	
Instance Quantity	1	

Manufacturer

McQuay

Building Condition Assessment Survey 2023-2024

Duestion	Response	
AIR CONDITIONING	Response	
Chilled Water System Central Station Air Handler		
	AHU-4	
EquipmentId Capacity/Size Quantity	15	
	Fan Motor HP	
Capacity/Size UOM Source of Capacity/Size	Inspector Estimate	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Basement - MER 9	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	McQuay	
EquipmentId	AHU-5	
Capacity/Size Quantity	8	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Basement - MER 9	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	McQuay	
EquipmentId	AHU-6	
Capacity/Size Quantity	30	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	DEFECTIVE CONTROLS	
Deficiency Location/Instance	Basement - MER 9	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fan Coil Unit	Does not exist	
	Does not exist	
Packaged Air Cooled Chiller	Does not exist Does not exist	
Water Cooled Chiller	Does not exist	

Page 4 of 14

Condenser Water Distribution: Piping, Pumps and Auxiliaries

Deficiency Location/Instance

Deficiency Quantity Quantity Uom

Potential Action

Cooling Coil in Ductwork

Deficiency

Cooling Tower

DX Split System

Indoor Unit

Condition

BCAS Partners Version 2.0 (P)

Does not exist

Does not exist

Does not exist

2- Between Good and Fair UP TO 5 TONS:DEFECTIVE

Boiler Room Mechanical Area / AHU-7

Print Date: 8/8/2024

Inspected

Inspected

EACH

REPAIR

Building Condition Assessment Survey 2023-2024

Ouestion		Response	
	UNITIONING	response	
	NDITIONING		
	it System r Unit		
Indoo		LEVEL 2	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
	oor Unit	Inspected	
Con	dition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
Dry Co		Does not exist	
	ed / Rooftop Unit	Does not exist	
	ed Terminal A/C	Does not exist	
	rant Leak Detection System	Inspected	
Condi		3- Fair	
	Deficiency	No deficiencies recorded	
Refrige	rant Piping	Inspected	
Condi	tion	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
Return	Fan	Inspected	
Condi	tion	3- Fair	
	Deficiency	No deficiencies recorded	
CENTRA	LACID WASTE NEUTRALIZING TANK	Does not exist	
CLIMAT	E CONTROL SYSTEM	Inspected	
BMS		Inspected	
	Instance	Throughout	
	Instance Condition	5- Poor	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Building Area Covered by Operational System	0-20%	
	Installation Year	1996	
	Source of Installation Year	Documented	
	Deficiency	DEFECTIVE SYSTEM	
	Deficiency Location/Instance	Throughout	

1

EACH

Deficiency Quantity

Quantity Uom

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	X034
Question	Response

stion	Response
OMESTIC WATER SYSTEM	
Domestic Cold Water System	
Gravity System	Does not exist
Pressure Booster System	Inspected
Electric Pressure Booster System	Inspected
Instance	Basement - MER 9
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	N/A
EquipmentId	N/A
Capacity/Size Quantity	3
Capacity/Size UOM	Total # Pumps
Capacity/Size 2 Quantity	9
Capacity/Size 2 UOM	Total Pumps HP
Source of Capacity/Size Installation Year	Documented 2018
Source of Installation Year	Documented
Deficiency	DEFECTIVE CONTROLS
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hydraulic/Pneumatic Booster System	Does not exist
Water Service	Inspected
Instance	Basement - Water Meter Room 18, MER 9 - Sprinkler/Gas/Water Meter Room 10
Instance Condition	3- Fair
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
instance Quantity	-
	EACH
Instance Quantity Uom	EACH Lochinvar
Instance Quantity Uom Manufacturer	
Instance Quantity Uom Manufacturer EquipmentId	Lochinvar
Instance Quantity Uom Manufacturer	Lochinvar N/A
Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity	Lochinvar N/A 645
Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM	Lochinvar N/A 645 MBH Input 0 Gallons
Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size	Lochinvar N/A 645 MBH Input 0 Gallons Documented
Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size Installation Year	Lochinvar N/A 645 MBH Input 0 Gallons Documented
Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size Installation Year Source of Installation Year	Lochinvar N/A 645 MBH Input 0 Gallons Documented 2010 Custodial Staff
Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size Installation Year	Lochinvar N/A 645 MBH Input 0 Gallons Documented

Building Condition Assessment Survey 2023-2024

unicui Inspection	Ave
uestion	Response
DOMESTIC WATER SYSTEM	
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Under construction
Sump Pump	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Inspected
Dual Temperature Distribution: Piping, Pumps and Auxiliaries	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Dual Temperature Terminal Fan Coil Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Does not exist
Student	Inspected
Drinking Fountain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Rooms 204, 209, 219, 306, 325, 417
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Toilet	Inspected

Building Condition Assessment Survey 2023-2024

unicui Inspecuon	Λ
uestion	Response
FIXTURES	
Student	
Toilet	
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	1st Floor- Boy's Toilet Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Vent	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Inspected
Instance	Basement - MER 9 - Sprinkler/Gas/Water Meter Room 10
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Eclipse
EquipmentId	N/A
Capacity/Size Quantity	15000
Capacity/Size UOM	SCFH
Source of Capacity/Size	Documented
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
CO/Gas Leak Detection	Inspected
Instance	Basement - Boiler Room, MER 9 - Sprinkler/Gas/Water Meter Room 10
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2018
Source of Installation Year	Custodial Staff
Deficiency	DEFECTIVE CONTROL PANEL
Deficiency Location/Instance Deficiency Quantity	Basement - MER 9
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	EL TEL O

Building Condition Assessment Survey 2023-2024

	1034
Response	
Inspected	
Does not exist	
Inspected	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Inspected	
3- Fair	
No deficiencies recorded	
Inspected	
3- Fair	
No deficiencies recorded	
Inspected	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
•	
-	
-	
-	
Inspected	
mspecied	
Inspected	
-	
110 deficiences recorded	
Inspected	
*	
no denciencies recorded	
T 1	
*	
1- D00D -1	
	Response Inspected Does not exist Inspected Inspected 3- Fair No deficiencies recorded Does not exist Inspected 3- Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded Inspected Inspected 3- Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded Inspected Inspected Inspected Inspected Inspected Inspected

Building Condition Assessment Survey 2023-2024

estion	Response	
IEATING PLANT		
Boiler Auxiliaries		
Boiler Feedwater System		
Deficiency	No deficiencies recorded	
Boiler Feedwater Treatment(Automatic)		
Instance on Basement	Does not exist	
Boiler Flue Exhaust		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
	100 deficiencies recorded	
Boiler Make-up Water Backflow Preventer Instance on Basement	Inspected	
	4- Between Fair and Poor	
Instance Condition		
Deficiency Location/Instance	DEFECTIVE RPZ	
Deficiency Location/Instance Deficiency Quantity	Sprinkler/Gas/Water Meter Room 10	
Quantity Uom	I EACH	
Quantity Uom Potential Action	EACH MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Room Steam And Condensate Piping	Manda Isolada	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	Boiler Room	
Deficiency Location/instance Deficiency Quantity	20	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Safety Valve		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler System	110 delibiolicio feccided	
Instance on Basement	Inspected	
Coal-fired Boiler	тороской	
Instance on Basement	Does not exist	
Hot Water Boiler	DOGS HOT CAIST	
	Door not awint	
Instance on Basement	Does not exist	
Modular Boiler	D (' ' '	
Instance on Basement	Does not exist	
Steam Boiler	*	
Instance on Basement	Inspected	
Instance on Basement	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	3,304	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	Cleaver Brooks	

Manufacturer

EquipmentId Capacity/Size Quantity

Cleaver Brooks

108332-01

38

Building Condition Assessment Survey 2023-2024

uestion	Response	
HEATING PLANT		
Boiler System		
Steam Boiler		
Capacity/Size UOM	Burner GPH	
Source of Capacity/Size	Documented	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	3,304	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Cast Iron Boiler? Manufacturer	Cleaver Brooks	
	108332-02	
EquipmentId Capacity/Size Quantity	38	
Capacity/Size Quantity Capacity/Size UOM	Burner GPH	
Source of Capacity/Size	Documented Documented	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fuel System	10 401101010101	
Instance on Basement	Inspected	
Boiler Fresh Air Louver/Damper	поросос	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
	Automatic	
Type		
Deficiency	No deficiencies recorded	
Burner/Burner Control Panel		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fuel Oil Storage/Supply System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Trains And Vent At The Boiler		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Enclosed IDF Room	Inspected	
Instance on Rooms 131, 225, 323, 427	Inspected	
Dedicated A/C Equipment	Incorporad	
Instance on Rooms 131, 225, 323, 427	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DOES NOT EXIST	
Deficiency Location/Instance	Rooms 131, 225, 323, 427	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
KITCHEN	Inspected	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection		X034
	_	

Question	-	Response
KITCH	EN	
CO De	tector	
	Instance on 1st Floor	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
Gas Sy	rstem	
-	Instance on 1st Floor	Inspected
	Instance Condition	5- Poor
	Deficiency	DEFECTIVE SHUT-OFF SWITCH
	Deficiency Location/Instance	Kitchen
	Deficiency Quantity	1
	Quantity Uom	EACH
	Potential Action	MAINTENANCE
	Urgency of Action	PRIORITY 5
	Purpose of Action	LEVEL 6
	Violations	No violations recorded
	Deficiency	DEFECTIVE MASTER GAS CONTROL VALVE
	Deficiency Location/Instance Deficiency Quantity	Basement - MER 9
		1 EACH
	Quantity Uom Potential Action	REPLACE
	Urgency of Action	PRIORITY 5
	Purpose of Action	LEVEL 6
	Violations	No violations recorded
Grease		10 100000
Grease	Instance on 1st Floor	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
Hood	201101010	
11000	Instance on 1st Floor	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
Hood 1	Exhaust Ductwork	
	Instance on 1st Floor	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
Hood 1	Exhaust Fan	
	Instance on 1st Floor	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
Hood 1	Fire Suppression System	
	Instance on 1st Floor	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
Hot W	ater Temperature Booster	
1100	Instance on 1st Floor	Inspected
	Instance Condition	2- Between Good and Fair
	Deficiency	No deficiencies recorded
Kitche	•	
	Instance on 1st Floor	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
MDF Ro	·	Inspected
MINI K	Instance on Room 431	Inspected
Dodice	ted A/C Equipment	пърски
Deales	and are equipment	

Building Condition Assessment Survey 2023-2024

Question	Response
MDF Room	
Dedicated A/C Equipment	
Instance on Room 431	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	1st Floor near Main Office (obstructed, 1)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Inspected
Hose Valve Assembly	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	No
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Basement - MER 9
Deficiency Quantity	20
Quantity Uom	L.F.

Building Condition Assessment Survey 2023-2024

hanical Inspection		X034
Question	Response	
VENTILATION		
Metal Ductwork		
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Does not exist	

Unit Ventilator

Does not exist