Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Asset:	P.S. 36 - BRONX, 1070 CASTLE HILL AVENUE, BRONX, NY, 10472		
Inspection Id	Inspection Type	Time In	Last Edited
2852	MECHANICAL	2024-01-31 07:01AM	2024-05-15 03:34PM
set Data			

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Elevator
	Years: 2020
	Systems: DX Split Systems for Room 414, Exit 7A Vestibule, Basement and 1st Floor Elevator Vestibules; Staff Fixtures - Lavatory/Sinks (~50%), Toilets (~50%)
	Years: 2019
	Systems: Terminal Unit Thermostatic Traps (~70%); F&T/Stea Drip Traps (~80%); Student Fixtures - Lavatory/Sink (~80%), Toilets (~70%), Urinals (~50%), Drinking Fountains; Unit Heater/Cabinet Heaters; Water Servic (1 of 3)
	Years: 2018
	Systems: Sump Pumps; Kitchen - Grease Trap; Unit Ventilator MDF Room Dedicated A/C Equipment (1 of 2, DX Split System)
	Years: 2017
	Systems: CO/Gas Leak Detection
	Years: 2015
Are there fuel tanks?	Yes
Total # of above ground tanks	1
Total capacity of all above ground tanks in gal.	10,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	Sub-Basement Booster Pump Area; Boiler Room Mechanical Area; Bulkhead "C" Fan Room
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Sub-Basement - Paint Room; Basement - Kitchen Storage
· ·	Room, Storage Room B05 (painted, painted, 15)
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Last Year?CategoryDescriptionAffectedDescriptionNotifiedTitleImage

Inspection

ection	
Duestion	Response
Iechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	UP TO 5 TONS:DEFECTIVE
Deficiency Location/Instance	Basement by Exit 8A, Ground Floor Exit 7A, 1st Floor and
	Elevator Machine Room
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPAIR

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	n	
iestion	Response	
AIR CONDITIONING		
DX Split System		
Indoor Unit		
Urgency of Action	PRIORITY 3 LEVEL 2	
Purpose of Action Violations		
	No violations recorded	
Outdoor Unit	Inspected	
Condition	1- Good	
Deficiency	UP TO 5 TONS:DEFECTIVE	
Deficiency Location/Instance Deficiency Quantity	Roof	
	l EACH	
Quantity Uom Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
	Does not exist	
Dry Cooler Packaged / Rooftop Unit	Does not exist	
Packaged / Rootop Unit Packaged Terminal A/C	Does not exist	
Refrigerant Leak Detection System	Does not exist	
Refrigerant Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Return Fan	Does not exist	
ENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist	
LIMATE CONTROL SYSTEM	Inspected	
BMS	Does not exist	
Pneumatic System	Inspected	
Instance	Throughout	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Building Area Covered by Operational System	81-100%	
Deficiency	No deficiencies recorded	
Hybrid System	Does not exist	
Electric System	Does not exist	
COMPACTOR	Does not exist	
ONVEYING	Inspected	
Dumbwaiter	Does not exist	
Elevator	Inspected	
Condition	1- Good	
Are all the existing elevators operable?	Yes	
Deficiency	No deficiencies recorded	
Escalator	Does not exist	
Non-auditorium Handicap Lift - Vertical	Does not exist	
Non-auditorium Handicap Lift - Vertical	Does not exist	
Ash Hoist	Does not exist	
Sidewalk Elevator	Does not exist	
OMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Inspected	
Gravity System	Does not exist	
Pressure Booster System	Inspected	
Electric Pressure Booster System	Inspected	
Instance	Sub-Basement Booster Pump Area	
	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

tion	Response
MESTIC WATER SYSTEM	•
omestic Cold Water System	
Pressure Booster System	
Electric Pressure Booster System	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pump
EquipmentId	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Total # Pumps
Capacity/Size 2 Quantity	15
Capacity/Size 2 UOM	Total Pumps HP
Source of Capacity/Size	Documented
Installation Year	2010
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Hydraulic/Pneumatic Booster System	Inspected
Water Pressure Booster - Compressor	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Sub-Basement Booster Pump Area
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Pressure Booster Pump	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Sub-Basement Booster Pump Area
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1 No violations recorded
Violations	
Domestic Cold Water Tank	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Sub-Basement Booster Pump Area
Deficiency Quantity	
Quantity Uom Potential Action	EACH NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Water Service	Inspected
·	Cafeteria
Instance	1- Good
Instance Condition	
Instance Quantity	
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
5	Sub-Basement Booster Pump Area

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

inicui Inspection	1
iestion	Response
OOMESTIC WATER SYSTEM	
Domestic Cold Water System	
Water Service	
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Sub-Basement Booster Pump Area
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room Mechanical Area
Instance Condition	3- Fair
Instance Quantity	
	l EACH
Instance Quantity Uom	
Manufacturer	Lochinvar
EquipmentId	N/A 495
Capacity/Size Quantity	
Capacity/Size UOM Capacity/Size 2 Quantity	MBH Input 0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2009
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
RAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

X036
1000

iunicui Inspeciion	Λυ
Question	Response
DRAIN/WASTE/VENT AND STORM SYSTEM	
Interior Storm Piping	
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
	VALVE,ETC.)
Deficiency Location/Instance	Janitor Closet near Room 302A
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lavatory/Sink	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Does not exist
Student	Inspected
Drinking Fountain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Locker Room Snower Sink And Fountain Combo Unit	Does not exist
Toilet	Inspected
Condition	2- Between Good and Fair
	2- Between Good and Fair No deficiencies recorded
Deficiency	
Urinal	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

inicui Inspeciion	A03
estion	Response
GAS SERVICE	
Gas Meter Room Exhaust Fan	
Deficiency	No deficiencies recorded
Gas Meter Room Vent	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Inspected
Instance	Sub-Basement - Gas Meter Room, Boiler Room, Boiler Room
	Mechanical Area
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2015
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
IEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Hydronic Heating Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	AUXILIARY (VALVE, VENT): DEFECTIVE
Deficiency Location/Instance Deficiency Quantity	Rooms 163, 253, 404
Quantity Uom	3 EACH
Potential Action	EACH MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected Inspected
F&T/Steam Drip Trap	2- Between Good and Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE CONTROLS
Deficiency Location/Instance	Boiler Room (flout switch)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Inspected
Steam Piping	
Condition	3- Fair
Deficiency	No deficiencies recorded
Terminal Unit Thermostatic Trap	Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

anicai Inspeciion		A03
uestion	Response	
HEATING		
Steam Heating		
Terminal Unit Thermostatic Trap		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	2- Between Good and Fair	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Near Rooms 201, 301, 401	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
HEATING PLANT	Inspected	
Instance on Sub-Basement	Inspected	
Is there a water meter on the boiler make-up water piping?	Yes	
Observed Operational?	Yes	
Burner Manufacturer	Iron Fireman	
Burner Model	900-208.83%	
Burner Type	Dual Fuel (Gas/Oil)	
Heating Plant Oil Number	2	
Boiler Auxiliaries		
Instance on Sub-Basement	Inspected	
Boiler Auxiliary Piping		
Instance on Sub-Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Sub-Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on Sub-Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater Treatment(Automatic)		
Instance on Sub-Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Flue Exhaust	To succede al	
Instance on Sub-Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Sub-Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on Sub-Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	Boiler Room	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

-		
estion	Response	
EATING PLANT		
Boiler Auxiliaries		
Boiler Room Steam And Condensate Piping		
Deficiency Quantity	20	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Safety Valve		
Instance on Sub-Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler System		
Instance on Sub-Basement	Inspected	
Coal-fired Boiler	1	
Instance on Sub-Basement	Does not exist	
Hot Water Boiler		
Instance on Sub-Basement	Does not exist	
Modular Boiler	Does not exist	
Instance on Sub-Basement	Does not exist	
	Does not exist	
Steam Boiler	Y , 1	
Instance on Sub-Basement	Inspected	
Instance on Sub-Basement	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	6,017	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	Kewanee Boiler Corporation	
EquipmentId	4909-01	
Capacity/Size Quantity	7750	
Capacity/Size UOM	MBH Gross	
Source of Capacity/Size	Documented	
Installation Year	1999	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	6,017	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	Kewanee Boiler Corporation	
EquipmentId	4909-02	
Capacity/Size Quantity	7750	
Capacity/Size UOM	MBH Gross	
Source of Capacity/Size	Documented 1999	
Installation Year Source of Installation Year	1999 Custodial Staff	
Deficiency	RUSTED CASING	
Deficiency Deficiency Quantity	20	
	20 S.F.	
Quantity Uom Potential Action	S.F. REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

		A030
Duestion	Response	
HEATING PLANT		
Fuel System		
Instance on Sub-Basement	Inspected	
Boiler Fresh Air Louver/Damper		
Instance on Sub-Basement	Inspected	
Instance Condition	3- Fair	
Туре	Automatic	
Deficiency	DEFECTIVE ACTUATOR	
Deficiency Location/Instance	Boiler Room (1 of 2)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Burner/Burner Control Panel		
Instance on Sub-Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fuel Oil Storage/Supply System		
Instance on Sub-Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Trains And Vent At The Boiler		
Instance on Sub-Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Enclosed IDF Room	Inspected	
Instance on Room inside Library	Inspected	
Dedicated A/C Equipment		
Instance on Room inside Library	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DOES NOT EXIST	
Deficiency Location/Instance	Room inside Library	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
KITCHEN	Inspected	
Instance on Basement	Inspected	
CO Detector		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas System Instance on Basement	Inspected	
	3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Grease Trap	Turne et al.	
Instance on Basement	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response
KITCHEN	
Hood	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Fire Suppression System	
Instance on Basement	Does not exist
Hot Water Temperature Booster	
Instance on Basement	Does not exist
Kitchen Sink	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
1DF Room	Inspected
Instance on Building Addition - Room 307B	Inspected
Dedicated A/C Equipment	I
Instance on Building Addition - Room 307B	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CIENCE DEMO ROOM	Does not exist
	Does not exist
CIENCE LAB	
CIENCE PREP ROOM	Does not exist
PRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected
Condition	5- Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Sub-Basement - Paint Room; Basement - Kitchen Storage Room,
Deficiency Quantity	Storage Room B05 (painted, 15) 15
Quantity Uom	IS EACH
Potential Action	EACH REPLACE
Urgency of Action	PRIORITY 5
	LEVEL 6
Purpose of Action	No violations recorded
Purpose of Action Violations	No violations recorded
Purpose of Action Violations Sprinkler Piping	Inspected
Purpose of Action Violations Sprinkler Piping Condition	Inspected 3- Fair
Purpose of Action Violations Sprinkler Piping Condition Deficiency	Inspected 3- Fair No deficiencies recorded
Purpose of Action Violations Sprinkler Piping Condition Deficiency Standpipe System	Inspected 3- Fair No deficiencies recorded Does not exist
Purpose of Action Violations Sprinkler Piping Condition Deficiency	Inspected 3- Fair No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

iestion	Response
VENTILATION	
Is the building Mechanically ventilated?	Partial
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	No
Deficiency	DAMAGED FLEXIBLE CONNECTION
Deficiency Location/Instance	Cafeteria - Boys Toilet Room @ EF
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Supply Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-5
Deficiency	No deficiencies recorded
Unit Ventilator	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded