Electrical Inspection	X037

Asset:	P.S. 37 - BRONX	K, 360 W 230TH STREET	, BRONX, NY, 104	163			
Inspectio	n Id Inspection Type				Time	In	Last Edited
	3632 ELECTRICAL				2024	-03-01 08:49AN	1 2024-03-22 02:49PM
sset Data							
Question				Answer	D	ED Y LLL (CL	
Have any	r Systems/Major Building C	Components been upgraded?		Years: Systems: Years: Systems: Years: Systems: Years: Systems: Years: Systems: Years: Systems: Years:	Kitchen, Libr LED Lighting Corridors), R (Gymnasium (Stairways), I Battery Pack) 2023 Public Addre 2022	rary, Toilet Room g (Gymnasium, S etrofitted Surface , Student Cafeter Retrofitted Emery ) ss System, Local D Lighting (Main exstem	ia), Surface LED Lighting gency Lighting (Non
				Systems: Years:		ectrical Systems a	and Components
Type of S	Service			Below Gr	round		
	eractive Whiteboard (IWB)			Yes			
	netration In Electrical Room	<sup>n?</sup> N FIRE RESCUE AREAS		No			
Question		V FIRE RESCUE AREAS	<u> </u>	]	Response		
Are the	ere any Life Rescue Assista	nce Areas, Fire Rescue Areas,	and/or Holding Room		Yes		
	ailding?	1 : 11 0.1	1 :		**		
		ole in all of these spaces for use	e during a fire?				
Aic	all dedicated intercome on	erational?			Yes		
riority Co	all dedicated intercoms op	erational?			Yes		
riority Co	ondition			,	Yes	Person(s)	Photo
<i>riority Co</i> Exist Last Year?		Condition Description	Component Affected			Person(s) Title	Photo Image
Exist	ondition Priority	Condition	Component	Location	Yes Person(s)	` '	
Exist Last Year?	Priority Category Water Leaks onto	Condition Description	Component Affected Lighting	Location Description Corridor near Boy's Toilet Room 2nd	Person(s) Notified Diego	Title	Image
Exist Last Year? Yes	Priority Category Water Leaks onto Electrical Equipment  Emergency Generator Components - Not	Condition Description Roof Leak Generator isn't in Auto	Component Affected Lighting Fixture Emergency	Location Description Corridor near Boy's Toilet Room 2nd Floor Emergency Generator	Person(s) Notified Diego Villarraga	Title Fireman	Image
Exist Last Year?  Ves	Priority Category  Water Leaks onto Electrical Equipment  Emergency Generator Components - Not Operational  Fire Alarm System - Components Not Operational	Condition Description Roof Leak Generator isn't in Auto Mode	Component Affected Lighting Fixture  Emergency Generator  Fire Alarm System - Digital	Location Description  Corridor near Boy's Toilet Room 2nd Floor Emergency Generator Room	Person(s) Notified Diego Villarraga Diego Villarraga	Title Fireman Fireman	Image No Photo Taken
Exist Last Year? Ves Ves	Priority Category  Water Leaks onto Electrical Equipment  Emergency Generator Components - Not Operational  Fire Alarm System - Components Not Operational	Condition Description Roof Leak Generator isn't in Auto Mode	Component Affected Lighting Fixture  Emergency Generator  Fire Alarm System - Digital	Location Description  Corridor near Boy's Toilet Room 2nd Floor Emergency Generator Room	Person(s) Notified Diego Villarraga Diego Villarraga	Title Fireman Fireman	Image No Photo Taken
Exist Last Year? Ves Ves	Priority Category  Water Leaks onto Electrical Equipment  Emergency Generator Components - Not Operational  Fire Alarm System - Components Not Operational	Condition Description Roof Leak Generator isn't in Auto Mode	Component Affected Lighting Fixture  Emergency Generator  Fire Alarm System - Digital	Location Description  Corridor near Boy's Toilet Room 2nd Floor Emergency Generator Room  Boiler Room	Person(s) Notified Diego Villarraga Diego Villarraga	Title Fireman Fireman	Image No Photo Taken
Exist Last Year?  Ves  Ves  Market Ves  Ma	Priority Category  Water Leaks onto Electrical Equipment  Emergency Generator Components - Not Operational  Fire Alarm System - Components Not Operational	Condition Description Roof Leak Generator isn't in Auto Mode	Component Affected Lighting Fixture  Emergency Generator  Fire Alarm System - Digital	Location Description  Corridor near Boy's Toilet Room 2nd Floor Emergency Generator Room  Boiler Room	Person(s) Notified Diego Villarraga Diego Villarraga	Title Fireman Fireman	Image No Photo Taken

## **Building Condition Assessment Survey 2023-2024**

ai inspection	
stion	Response
DITORIUM	
Instance on 2nd Floor	Inspected
louse Lighting	
Instance on 2nd Floor	Inspected
Does a Chandelier Exist?	Yes
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
ocal Sound System	140 deficiences recorded
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Installation Year	2022
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
rojection System	
Instance on 2nd Floor	Does not exist
heater Lighting System	
Instance on 2nd Floor	Inspected
Dimming System	-
Instance on 2nd Floor	Inspected
Instance Condition	5- Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

## **Building Condition Assessment Survey 2023-2024**

estion	Response
UDITORIUM	
Theater Lighting System	
Theater Lighting	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	164
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
AFETERIA	Inspected
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Lighting	
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Pendant Mounted	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Surface Mounted	Does not exist
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	No deficiencies recorded
Recessed Mounted	Tourseted
Instance on 1st Floor - Staff	Inspected  2- Between Good and Fair
Instance Condition	
Deficiency	No deficiencies recorded
Instance on 1st Floor - Students	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Inspected
Instance Condition	1- Good
Installation Year	2022
Source of Installation Year	Documented  No deficiencies recorded
Deficiency	

## **Building Condition Assessment Survey 2023-2024**

nicui inspection		A037
Question	Response	
CAFETERIA		
Projection System		
Instance on 1st Floor - Students	Does not exist	
Theater Lighting System		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 2nd Floor	Inspected	
Lighting		
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	
Pendant Mounted	1	
Instance on 2nd Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	No deficiences recorded	
Instance on 2nd Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
*	No deficiencies recorded	
Local Sound System  Instance on 2nd Floor	Inspected	
Instance Condition	Inspected 1- Good	
Installation Year	2022	
Installation Year Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System	140 deficiencies recorded	

ical Inspection	n.	X03
estion	Response	
GYMNASIUM		
Projection System Instance on 2nd Floor	Does not exist	
Scoreboard	DOCS HOT CAIST	
Instance on 2nd Floor	Does not exist	
Theater Lighting System	Does not exist	
Instance on 2nd Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	nispected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	поресска	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	2000 100 01100	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	2000 100 01100	
Instance on 1st Floor	Inspected	
Pendant Mounted	поресска	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted	2000 100 01100	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Inspected	
Instance on 4th Floor	Inspected	
Lighting	nispected	
Instance on 4th Floor	Inspected	
Lighting Fixture - Fluorescent	nispected	
Instance on 4th Floor	Does not exist	
Lighting Fixture - HID	2000 100 01100	
Instance on 4th Floor	Does not exist	
Lighting Fixture - Incandescent	2000 100 01100	
Instance on 4th Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 4th Floor	Inspected	
Pendant Mounted	nispected	
Instance on 4th Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	delicipiles feedadd	
Instance on 4th Floor	Does not exist	
Recessed Mounted	Does not exist	
Instance on 4th Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	140 deficieles fecolded	
Raceway With Receptacles  Instance on 4th Floor	Inspected	
Instance On 4th Floor Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	

Electrical Inspection	X037
-----------------------	------

uestion	Response
LIBRARY	
Projection System	
Instance on 4th Floor	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Inspected
Instance on Room 408	Inspected
Power Panel?	Yes
Alternative Use	No
	140
Lighting Instance on Room 408	Inspected
Lighting Fixture - Fluorescent	inspected
Instance on Room 408	Does not exist
Lighting Fixture - HID	DOCS HOT CAIST
Instance on Room 408	Does not exist
	DOCS HOT CAIST
Lighting Fixture - Incandescent  Instance on Room 408	Inspected
Pendant Mounted	inspected
Instance on Room 408	Does not exist
Surface Mounted	Does not exist
Instance on Room 408	Inchested
Instance On Room 408  Instance Condition	Inspected 3- Fair
	No deficiencies recorded
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Instance on Room 408	Does not exist
Lighting Fixture - LED	Tuomootod
Instance on Room 408	Inspected
Pendant Mounted	Does not exist
Instance on Room 408	Does not exist
Surface Mounted Instance on Room 408	December of the second second
	Does not exist
Recessed Mounted	Y 1
Instance on Room 408	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Gas Shut-Off Valve Instance on Room 408	Y 1
	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Your and d
Instance on Room 408	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 408	Inspected
Instructor Unit	Inconcatad
Instance on Room 408	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 408	Does not exist

.037	7
.(	<b>J3</b> 7

Question	Response
SCIENCE LAB	
Power Supply	
Student Unit	
Instance on Room 408	Does not exist
Projection System	
Instance on Room 408	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Master Control Systems
EquipmentId	Automatic Transfer Switch
Capacity/Size Quantity	15
Capacity/Size UOM	HP
Source of Capacity/Size	Nameplate 1994
Installation Year Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	ASCO
Manufacturer EquipmentId	Fire Alarm Automatic Transfer Switch
Ечирисии	1 no 1 maini 1 maini e i maini e i maini

Electrical Inspection	A03/

s recorded
n
s recorded
s recorded
nerator Room
ies
•
recorded
n
c
22
; 2
s recorded
nerator Room

## **Building Condition Assessment Survey 2023-2024**

icui Inspection		1105
estion	Response	
EMERGENCY GENERATOR SET		
Diesel		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Caterpillar	
EquipmentId	Emergency Generator	
Capacity/Size Quantity	191	
Capacity/Size UOM	kVA	
Capacity/Size 2 Quantity	153	
Capacity/Size 2 UOM	kW	
Capacity/Size 3 Quantity	531	
Capacity/Size 3 UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1994	
Source of Installation Year	Documented	
Deficiency	GENERATOR NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Natural Gas	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Does not exist	
Non Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Under construction	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
	No deficiencies recorded	
Deficiency		
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
	3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	

## **Building Condition Assessment Survey 2023-2024**

ciricai Inspection	AU3 /
Question	Response
FIRE ALARM SYSTEM	
Elevator Recall	
Condition	3- Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Inspected
Instance	Boiler Room
Instance Condition	5- Poor
Instance Quantity	1
Instance Quantity Uom	EACH
	Radionics
EquipmentId	Fire Alarm Communicator
Installation Year	1994
Source of Installation Year	Documented
Deficiency	COMMUNICATOR NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Notifier
Model	AFP - 1010
EquipmentId	Fire Alarm Control Panel
Installation Year	1994
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	3- Fair
Instance Quantity	1 EACH
Instance Quantity Uom	
Manufacturer	Notifier
Model	N/A
EquipmentId	Fire Alarm Purge Panel
Installation Year	1994

## **Building Condition Assessment Survey 2023-2024**

cirical Inspection		A03/
Question	Response	
FIRE ALARM SYSTEM		
Sub-Panel		
Fire Alarm Control Panel (Electronic)		
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Does not exist	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
	Inspected	
MOTOR CONTROLLER	Does not exist	
MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	
	Inspected	
Fused Disconnect Switch Type Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist  Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	MDF Room 212	
Instance Condition	1- Good	
Instance Quantity	1	

## **Building Condition Assessment Survey 2023-2024**

incui inspection	AUS
Question	Response
PUBLIC ADDRESS SYSTEM	
Instance Quantity Uom	EACH
Model	Rauland Telecenter
Installation Year	2022
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Under construction
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition Condition	3- Fair
	No deficiencies recorded
Deficiency	
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Under construction
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	Service Switch #1 EDP Via ATS-1
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	Service Switch #5 Sprinkler Booster Pump Via ATS3
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994

Electrical Inspection	A03/
Question Response	

Question Response	
SERVICE SWITCH	
Source of Installation Year Documented	
Deficiency No deficiencies recorded	
Instance Electrical Room	
Instance Condition 3- Fair	
Instance Quantity 1	
Instance Quantity Uom EACH	
Manufacturer Gallagher	
EquipmentId Service Switch #4 PDP-3	
Capacity/Size Quantity 1200	
Capacity/Size UOM Amps	
Source of Capacity/Size Nameplate	
Installation Year 1994	
Source of Installation Year Documented	
Deficiency No deficiencies recorded	
Instance Electrical Room	
Instance Condition 3- Fair	
Instance Quantity 1	
Instance Quantity Uom EACH	
Manufacturer Gallagher	
EquipmentId Service Switch #3 MDP Main Switch	
Capacity/Size Quantity 1200	
Capacity/Size UOM Amps	
Source of Capacity/Size Nameplate	
Installation Year 1994	
Source of Installation Year Documented	
Deficiency No deficiencies recorded	
Instance Electrical Room	
Instance Condition 3- Fair	
Instance Quantity 1	
Instance Quantity Uom EACH	
Manufacturer Gallagher	
EquipmentId Service Switch #2 PDP-1	
Capacity/Size Quantity 1200	
Capacity/Size UOM Amps	
Source of Capacity/Size Nameplate	
Installation Year 1994	
Source of Installation Year Documented	
Deficiency No deficiencies recorded	
SWITCHBOARD Inspected	
Number of Spares 3	
Fused Disconnect Switch Type Inspected	
Instance Electrical Room	
Instance Condition 3- Fair	
Instance Quantity 1	
Instance Quantity Uom EACH	
Manufacturer Gallagher Switchboard Co.	
EquipmentId N/A	
Capacity/Size Quantity 1000	
Capacity/Size UOM Amps Total	
Capacity/Size 2 Quantity 2	
Capacity/Size 2 UOM Section(s)	
Source of Capacity/Size Nameplate	
Installation Year 1994	
Installation Year 1994 Source of Installation Year Documented Deficiency No deficiencies recorded	

## **Building Condition Assessment Survey 2023-2024**

*		
Question	Response	
SWITCHBOARD		
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	