Inspection Id	P.S. 220 - BRONY	X, 468 EAST 140 STREET,	, BRONX, NY, 1	0454			
680	Inspection Type				Time I	n	Last Edited
009	ELECTRICAL				2023-1	1-03 08:25AM	I 2023-11-03 02:23PM
sset Data							
Question				Answer			
Have any Syster	ms/Major Building Co	omponents been upgraded?		Systems:	Emergency Lig	hting (Battery	Pack), Exit Lights
				Years:	2022		
				Systems:	Partial Molded	Case Circuit B	reaker Panel Boards
				Years:	2020, 2018, 20	13, 2006, 1998	
				Systems:	Public Address	System (Clock	s, Master Clock)
				Years:	2019		
				Systems:	_		Lights (Non-Battery
				Years:	Pack), Intrusion 2015	n Alarm System	(Infrared Sensors)
				Systems:		tarters Lightni	ng Protection, Fire Alarm
				Systems.	System (CO De		ng i rotection, i ne Alaim
				Years:	2013	,	
				Systems:			Alarm System, Public
							System, Auditorium
				37	(Theatre Lighti	ng System)	
T				Years: Below Gro	2006		
Type of Service	e Whiteboard (IWB) F	Exist?		Yes	ound		
	on In Electrical Room			No			
		FIRE RESCUE AREAS					
Question				F	Response		
your building riority Conditi	ion	C. IV		T	D ()	D ()	DI 4
Exist Prio Last Year? Cate	egory	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condition rec	corded						
Inspection							
Ouestion				Response	:		
Electrical							
ATHLETIC 1	FIELD			Does not e	exist		
AUDITORIU				Inspected			
	stance on 1st Floor			F			
	Junior our root root			Inspected			
Ins	ting			Inspected			
Ins House Ligh	nting stance on 1st Floor			Inspected			
Ins House Ligh Ins		?					
House Ligh Ins Do	stance on 1st Floor			Inspected			
House Ligh Ins Do Lighting	stance on 1st Floor oes a Chandelier Exist			Inspected			
House Ligh Ins Do Lighting Ins Pendan	stance on 1st Floor oes a Chandelier Exist Fixture - Fluorescent stance on 1st Floor t Mounted			Inspected No Inspected			
House Ligh Ins Do Lighting Ins Pendant	stance on 1st Floor oes a Chandelier Exist Fixture - Fluorescent stance on 1st Floor t Mounted stance on 1st Floor			Inspected No	exist		
House Ligh Ins Do Lighting I Ins Pendant Ins Surface	stance on 1st Floor oes a Chandelier Exist Fixture - Fluorescent stance on 1st Floor t Mounted stance on 1st Floor			Inspected No Inspected Does not o			
House Ligh Ins Do Lighting I Ins Pendant Ins Surface	stance on 1st Floor oes a Chandelier Exist Fixture - Fluorescent stance on 1st Floor t Mounted stance on 1st Floor Mounted stance on 1st Floor			Inspected No Inspected Does not of			
House Ligh Ins Do Lighting I Ins Pendant Ins Surface Ins Ins	stance on 1st Floor bes a Chandelier Exist Fixture - Fluorescent stance on 1st Floor t Mounted stance on 1st Floor Mounted stance on 1st Floor stance on 1st Floor stance Condition			Inspected No Inspected Does not of Inspected 2- Between	en Good and Fair		
House Ligh Ins Do Lighting Ins Pendant Ins Surface Ins De	stance on 1st Floor oes a Chandelier Exist Fixture - Fluorescent stance on 1st Floor t Mounted stance on 1st Floor Mounted stance on 1st Floor stance on 1st Floor stance Condition efficiency			Inspected No Inspected Does not of Inspected 2- Between			
House Ligh Ins Do Lighting I Ins Pendant Ins Surface Ins De Recesse	stance on 1st Floor oes a Chandelier Exist Fixture - Fluorescent stance on 1st Floor t Mounted stance on 1st Floor Mounted stance on 1st Floor stance Condition eficiency d Mounted			Inspected No Inspected Does not of Inspected 2- Betwee No deficie	en Good and Fair encies recorded		
House Ligh Ins Do Lighting I Ins Pendant Ins Surface Ins De Recessee	stance on 1st Floor bes a Chandelier Exist Fixture - Fluorescent stance on 1st Floor t Mounted stance on 1st Floor Mounted stance on 1st Floor stance Condition efficiency d Mounted stance on 1st Floor			Inspected No Inspected Does not of Inspected 2- Between	en Good and Fair encies recorded		
House Ligh Ins Do Lighting Ins Pendan Ins Surface Ins De Recesse Ins Lighting I	stance on 1st Floor bes a Chandelier Exist Fixture - Fluorescent stance on 1st Floor t Mounted stance on 1st Floor e Mounted stance on 1st Floor stance Condition efficiency d Mounted stance on 1st Floor Fixture - HID			Inspected No Inspected Does not of Inspected 2- Betwee No deficie	en Good and Fair encies recorded exist		
House Ligh Ins Do Lighting I Ins Pendant Ins Surface Ins De Recessee Ins Lighting I	stance on 1st Floor bes a Chandelier Exist Fixture - Fluorescent stance on 1st Floor t Mounted stance on 1st Floor Mounted stance on 1st Floor stance Condition efficiency d Mounted stance on 1st Floor			Inspected No Inspected Does not of Inspected 2- Betwee No deficie	en Good and Fair encies recorded exist		

Response	
Inspected	
msp•••••	
Does not exist	
Does not exist	
Does not exist	
DOCS NOT CAUSE	
Increated	
No deficiencies recorded	
Lucanostod	
No deficiencies recorded	
Inspected	
PRIORITY 3	
LEVEL 2	
No violations recorded	
Inspected	
Inspected	
3- Fair	
No deficiencies recorded	
Inspected	
EACH	
REPAIR	
PRIORITY 3	
LEVEL 2	
No violations recorded	
Inspected	
*	
Inspected	
1	
Inspected	
	Inspected Inspected Inspected 3- Fair No deficiencies recorded Inspected 4- Between Fair and Poor LIGHTING FIXTURE NOT OPERATIONAL 52 EACH REPAIR PRIORITY 3 LEVEL 2 No violations recorded

	n.	
uestion	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted Instance on 1st Floor Staff	Increased	
Instance Condition	Inspected 2- Between Good and Fair	
	No deficiencies recorded	
Deficiency Instance on 1st Floor Students	Does not exist	
	Does not exist	
Surface Mounted	Does not exist	
Instance on 1st Floor Staff		
Instance on 1st Floor Students	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Recessed Mounted	D	
Instance on 1st Floor Staff	Does not exist	
Instance on 1st Floor Students	Does not exist	
Lighting Fixture - HID Instance on 1st Floor Staff	December 1991	
	Does not exist	
Instance on 1st Floor Students	Does not exist	
Lighting Fixture - Incandescent	D	
Instance on 1st Floor Staff	Does not exist	
Instance on 1st Floor Students	Does not exist	
Lighting Fixture - LED	De-constant	
Instance on 1st Floor Staff	Does not exist	
Instance on 1st Floor Students	Inspected	
Pendant Mounted	Y 1	
Instance on 1st Floor Students	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Surface Mounted	D	
Instance on 1st Floor Students	Does not exist	
Recessed Mounted	D	
Instance on 1st Floor Students	Does not exist	
Local Sound System Instance on 1st Floor Students	Inspected	
Instance Condition	3- Fair	
Installation Year	2006	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance on 1st Floor Staff	Does not exist	
Projection System		
Instance on 1st Floor Students	Does not exist	
Instance on 1st Floor Staff	Does not exist	
Theater Lighting System		
Instance on 1st Floor Students	Does not exist	
Instance on 1st Floor Staff	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	

Electrical Inspection	X040

•		
Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	- Inspection	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted	Does not exist	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	No deficiencies recorded	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on 1st Floor	Does not exist	
	Does not exist	
Lighting Fixture - Incandescent Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 1st Floor	Inconnected	
	Inspected	
Pendant Mounted	To an and all	
Instance on 1st Floor	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System	Y 1	
Instance on 1st Floor	Inspected	
Instance Condition Installation Year	3- Fair 2006	
Installation Year Source of Installation Year	2006 Documented	
Deficiency	No deficiencies recorded	
Projection System	No deficiencies recorded	
Instance on 1st Floor	Does not exist	
Scoreboard	Does not exist	
Instance on 1st Floor	Does not exist	
Theater Lighting System	Does not exist	
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	nispecieu	

Question	Response	
KITCHEN	•	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	-	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 206	Inspected	
Lighting	1	
Instance on Room 206	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on Room 206	Inspected	
Pendant Mounted		
Instance on Room 206	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 206	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 206	Does not exist	
Lighting Fixture - HID		
Instance on Room 206	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 206	Does not exist	
Lighting Fixture - LED		
Instance on Room 206	Does not exist	
Raceway With Receptacles		
Instance on Room 206	Does not exist	
Projection System		
Instance on Room 206	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection X040

F		
Question	Response	
TOILET ROOM - STAFF		
Lighting		
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - Incandescent Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected 3- Fair	
Condition	No deficiencies recorded	
Deficiency		
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Manual I uli Stativii	тороски	

Building Condition Assessment Survey 2023-2024

Electrical Inspection X040

estion	Response	
IRE ALARM SYSTEM		
Manual Pull Station		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Does not exist	
Duct Smoke Detector	Does not exist	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2006	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	

ical Inspection	X04
uestion	Response
FIRE ALARM SYSTEM	
Tamper Flow Switch/Chain	N 10 1 1
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Fan Room, Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected 3- Fair
Condition	
Deficiency Location/Instance	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance Deficiency Quantity	Throughout the Building
	18 EACH
Quantity Uom Potential Action	EACH REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
1 u1pose 01/100011	

Building Condition Assessment Survey 2023-2024

Electrical Inspection X040

estion	DDDEGG CVCTEM	Response
	ADDRESS SYSTEM	Inspected
	Instance	Main Office Room 116
	Instance Condition	4- Between Fair and Poor
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Model	Dukane 250
	Installation Year	2006
	Source of Installation Year	Documented
	Deficiency	SYSTEM DEFECTIVE
	Deficiency Location/Instance Deficiency Quantity	Main Office 1
	Quantity Uom	EACH
	Potential Action	REPAIR SYSTEM
	Urgency of Action	PRIORITY 5
	Purpose of Action	LEVEL 2
	Violations	No violations recorded
ECURIT	Y	Inspected
IPDVS/C	CCTV System	Does not exist
Intrusion	Alarm System	Inspected
Centra	l Control Panel	Inspected
	Instance	Custodian's Office
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Model	Vista - 128BP
	Installation Year	2006
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	ed Sensor	Inspected
Cond		3- Fair
	Deficiency	SENSOR NOT OPERATIONAL
	Deficiency Location/Instance Deficiency Quantity	Exit 7
		1 FACH
	Quantity Uom Potential Action	EACH REPLACE
		PRIORITY 4
	Urgency of Action Purpose of Action	LEVEL 3
	Violations	No violations recorded
- · ·		
Panic S		Inspected
Cond		3- Fair
	Deficiency	No deficiencies recorded
	e Annunciator	Inspected
Cond	ition	3- Fair
	Deficiency	No deficiencies recorded
Siren/S	trobe	Inspected
Cond	ition	4- Between Fair and Poor
	Deficiency	SIREN/STROBE NOT OPERATIONAL
	Deficiency Location/Instance Deficiency Quantity	3rd Floor Above Main Entrance
	Quantity Uom	EACH
	Potential Action	REPLACE
	Urgency of Action	PRIORITY 4
	Purpose of Action	LEVEL 3
	Violations	No violations recorded
	- Security	Under construction

Building Condition Assessment Survey 2023-2024

uestion	Response	
SERVICE SWITCH	Inspected	
Instance	Electrical Room B6	
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Manufacturer	Lexington	
EquipmentId	Main Switch	
Capacity/Size Quantity	1500	
Capacity/Size UOM	Amps Fuse Size	
Source of Capacity/Size Installation Year	1967	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B6	
Deficiency Quantity	l	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	0	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room B6	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Lexington	
EquipmentId	N/A	
Capacity/Size Quantity	1250	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1967	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B6	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
FELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
	3- Fair	
Condition		
Condition Deficiency	No deficiencies recorded	
	No deficiencies recorded Inspected	
Deficiency		

Does not exist

TRANSFORMER