Building Condition Assessment Survey 2023-2024

Electrical Inspection

Last Edited 1 2024-03-04 10:59A ghting (Corridors) reaker Panel Board Retrofitted Pendant Emergency Lighting, Exit rium (House Lighting, n (Lighting) n) E Lighting
ghting (Corridors) reaker Panel Board Retrofitted Pendant Emergency Lighting, Exit rium (House Lighting, n (Lighting) n)
reaker Panel Board Retrofitted Pendant Emergency Lighting, Exit rium (House Lighting, n (Lighting) n)
reaker Panel Board Retrofitted Pendant Emergency Lighting, Exit rium (House Lighting, n (Lighting) n)
reaker Panel Board Retrofitted Pendant Emergency Lighting, Exit rium (House Lighting, n (Lighting) n)
Retrofitted Pendant Emergency Lighting, Exit rium (House Lighting, n (Lighting) n)
Retrofitted Pendant Emergency Lighting, Exit rium (House Lighting, n (Lighting) n)
Retrofitted Pendant Emergency Lighting, Exit rium (House Lighting, n (Lighting) n)
Retrofitted Pendant Emergency Lighting, Exit rium (House Lighting, n (Lighting) n)
Emergency Lighting, Exit rium (House Lighting, n (Lighting) n)
Emergency Lighting, Exit rium (House Lighting, n (Lighting) n)
Emergency Lighting, Exit rium (House Lighting, n (Lighting) n)
Emergency Lighting, Exit rium (House Lighting, n (Lighting) n)
Lighting
Lighting
anel
larm System, Intrusion Center, Service Switch,
Dhata
Photo Image
innige

Instance Condition

2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response	
AUDITORIUM		
House Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2016	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on Basement	Inspected	
Dimming System		
Instance on Basement	Does not exist	
Theater Lighting		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	24	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
CAFETERIA	Inspected	
Instance on Basement - East	Inspected	
Instance on Basement - West	Inspected	
Lighting		
Instance on Basement - East	Inspected	
Instance on Basement - West	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

cai inspection		XU4
estion	Response	
AFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Basement - West	Inspected	
Pendant Mounted		
Instance on Basement - East	Does not exist	
Instance on Basement - West	Does not exist	
Surface Mounted		
Instance on Basement - East	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Basement - West	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement - East	Does not exist	
Instance on Basement - West	Does not exist	
Lighting Fixture - HID		
Instance on Basement - East	Does not exist	
Instance on Basement - West	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement - East	Does not exist	
Instance on Basement - West	Does not exist	
Lighting Fixture - LED		
Instance on Basement - East	Does not exist	
Instance on Basement - West	Does not exist	
Local Sound System		
Instance on Basement - East	Inspected	
Instance Condition	5- Poor	
Installation Year	1970	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance on Basement - West	Inspected	_
Instance Condition	5- Poor	
Installation Year	1970	-
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on Basement - East	Does not exist	
Instance on Basement - West	Does not exist	
Theater Lighting System		
Instance on Basement - East	Does not exist	
Instance on Basement - West	Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	Λ04
Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
GYMNASIUM	Inspected
Instance on 3rd Floor	Inspected
Lighting	
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	1
Instance on 3rd Floor	Inspected
Pendant Mounted	
Instance on 3rd Floor	Does not exist
Surface Mounted	
Instance on 3rd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 3rd Floor	Does not exist
Lighting Fixture - HID	
Instance on 3rd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not exist
Lighting Fixture - LED	
Instance on 3rd Floor	Does not exist
Local Sound System	
Instance on 3rd Floor	Inspected
Instance Condition	5- Poor
Installation Year	1979
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response	
GYMNASIUM	response	
Projection System		
Instance on 3rd Floor	Does not exist	
Scoreboard		
Instance on 3rd Floor	Does not exist	
Theater Lighting System		
Instance on 3rd Floor	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting	inspected	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent	inspected	
Instance on Basement	Inspected	
Pendant Mounted	inspected	
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Surface Mounted	т. , 1	
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on Room 106	Inspected	
Lighting		
Instance on Room 106	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 106	Inspected	
Pendant Mounted		
Instance on Room 106	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 106	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 106	Does not exist	
Lighting Fixture - HID		
Instance on Room 106	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 106	Does not exist	
	DUCS HOUCKIST	
Lighting Fixture - LED	Does not exist	
Instance on Room 106	נסבא ווטו באוא	
Raceway With Receptacles	×	
Instance on Room 106	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

lestion	Response	
JBRARY	. 1	
Raceway With Receptacles		
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 106	Does not exist	
LOCKER ROOM	Does not exist	
AULTIPURPOSE ROOM	Does not exist	
CIENCE DEMO ROOM	Does not exist	
CIENCE LAB	Does not exist	
CIENCE PREP ROOM	Does not exist	
WIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
OILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
MERGENCY DC STANDBY BATTERY POWER	Does not exist	
MERGENCY GENERATOR SET	Does not exist	
CMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack Condition	Inspected 3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack Condition	Inspected 3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency Deficiency Location/Instance	BATTERY NOT OPERATIONAL Sub - Basement near Mechanical Area	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui Inspection	1	AU7
uestion	Response	
EXIT LIGHT		
Battery Pack		
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE BATTERY	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
	Does not exist	
Non Battery Pack EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Under construction	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Inspected	
Instance	Sub Basement by Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Square D	
EquipmentId	MCC-1	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1997	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Variable Frequency Drive PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Inspected	
Condition	3- Fair	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance	Sub Basement Electrical Closet	
Deficiency Quantity	1	
	EACH	
Quantity Uom		
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response
PANEL BOARD	
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 154
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter System 21
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office Room - B1
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1997
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Custodian's Office Room - B1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ricui Inspeciion		AU4/
Question	Response	
SECURITY		
Lighting - Security		
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	-
Instance	Electrical Room Sub Basement	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Square D	
EquipmentId	N/A	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1997	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	3	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room Sub Basement	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Square D	
EquipmentId	ACCP-2, ACCP-3	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity		
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate 1997	
Installation Year Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	

TRANSFORMER