Building Condition Assessment Survey 2023-2024

P.S. 56 - BRONX, 341 EAST 207 STREET, BRONX, NY, 10467

Electrical Inspection

Asset:

Inspectio					Time	In	Last Edited
	2058 ELECTRICAL				2024-	-01-02 07:58A	M 2024-05-20 02:00PM
sset Data	!						
Question	1			Answer			
Have any	y Systems/Major Building Co	omponents been upgraded?		Systems:	Service Swite	ch, Switchboard	l, Security Lights
				Years:	2016, 2007		
				Systems:	All Other Ele	ctrical Systems	and Components
				Years:	2016		
				Systems:		nect Switch Ty	pe Panel Boards
				Years:	2007		
Type of S		5.1.0		Below Gr	ound		
	eractive Whiteboard (IWB) I netration In Electrical Room			Yes Yes			
		FIRE RESCUE AREAS		Ies			
Question		FIRE RESCUE AREAS			Response		
· ·		ce Areas, Fire Rescue Areas, a	nd/or Holding Rooi		Yes		
	uilding?	, , ,	8				
		e in all of these spaces for use	during a fire?		Yes		
Are	e all dedicated intercoms ope	erational?		`	Yes		
Priority Co	ondition						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Emergency Generator	Generator is out of order.	Emergency	Roof -	Victor	Fireman	No Photo Taken
	Components - Not		Generator	Emergency	Costello		
	Operational			Generator Enclosure			
Yes	Fire Alarm System -	Two Fire Alarm CO	Fire Alarm	Boiler Room	Victor	Fireman	No Photo Taken
103	Components Not	sensors are out of order.	System - CO	Boner Room	Costello	Theman	
	Operational		Detector				
Yes	Water Leaks onto	Water penetrates through	Electrical	By Exit 7	Victor	Fireman	No Photo Taken
	Electrical Equipment	Foundation wall	Switch and		Costello		
			Electrical Junction Box				
Yes	Water Penetration in	Water Penetration	Electrical	Electrical	Victor	Fireman	No Photo Taken
103	Electrical Room	Through CT Cabinet	Equipment	Room C24	Coste	Theman	
Inspection	1		1 1				
				D			
Question				Response	;		
Electrica					• ,		
	ETIC FIELD			Does not			
AUDI	TORIUM			Does not			
CAFE	TERIA			Inspected			
	Instance on Basement			Inspected			
Ligh							
	Instance on Basement			Inspected			
Lig	ghting Fixture - Fluorescen	t					
_	Instance on Basement			Inspected			
Р	Pendant Mounted				• .		
	Instance on Basement			Does not	ex1st		
S	urface Mounted				• ,		
	Instance on Basement			Does not	exist		
	Recessed Mounted						
R				т . •			
R	Instance on Basement Instance Condition			Inspected	en Good and Fa		

Building Condition Assessment Survey 2023-2024

lestion	Response	
	Response	
CAFETERIA		
Lighting Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted	mspeccea	
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Basement	Does not exist	
Theater Lighting System		
Instance on Basement	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	Yes	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not exist	
Recessed Mounted	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	

Building Condition Assessment Survey 2023-2024

estion	Response	
SYMNASIUM	A	
Instance on 2nd Floor	Inspected	
Lighting	1	
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	2	
Quantity Uom	2 EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
	No violations recorded	
Surface Mounted		
Instance on 2nd Floor	Does not exist	
Recessed Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	
Pendant Mounted	1	
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 2nd Floor	Does not exist	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Local Sound System		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Scoreboard		
Instance on 2nd Floor	Does not exist	
Theater Lighting System		
Instance on 2nd Floor	Inspected	
Dimming System		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

uestion	Response	
GYMNASIUM		
Theater Lighting System		
Dimming System		
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Basement	Inspected	
Pendant Mounted	Ĩ	
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on Room B14	Inspected	
Lighting		
Instance on Room B14	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room B14	Inspected	
Pendant Mounted		
Instance on Room B14	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room B14	Does not exist	
Recessed Mounted		
Instance on Room B14	Does not exist	
Lighting Fixture - HID		
Instance on Room B14	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room B14	Does not exist	
Lighting Fixture - LED		
Instance on Room B14	Does not exist	
Raceway With Receptacles		
Instance on Room B14	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room B14	Does not exist	

NYC Department of Education **Building Condition Assessment Survey 2023-2024**

rical Inspection		X05
uestion	Response	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on Room 109	Inspected	
Lighting		
Instance on Room 109	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 109	Inspected	
Pendant Mounted		
Instance on Room 109	Does not exist	
Surface Mounted		
Instance on Room 109	Does not exist	
Recessed Mounted		
Instance on Room 109	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 109	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 109	Does not exist	
Lighting Fixture - LED		
Instance on Room 109	Inspected	
Pendant Mounted		
Instance on Room 109	Does not exist	
Surface Mounted		
Instance on Room 109	Does not exist	
Recessed Mounted		
Instance on Room 109	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on Room 109	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 109	Inspected	
Instance Condition	2- Between Good and Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on Room 109	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
CIENCE LAB	Inspected	
Instance on Room 320	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Room 320	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 320	Inspected	
Pendant Mounted		
Instance on Room 320	Inspected	
Instance Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		A050
Question	Response	
SCIENCE LAB		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 320	Does not exist	
Recessed Mounted		
Instance on Room 320	Does not exist	
Lighting Fixture - HID		
Instance on Room 320	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 320	Does not exist	
Lighting Fixture - LED		
Instance on Room 320	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 320	Does not exist	
Emergency Shut-Off Power		
Instance on Room 320	Does not exist	
Power Supply		
Instance on Room 320	Does not exist	
Projection System		
Instance on Room 320	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 320A	Inaccessible	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - Incandescent Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

-	
uestion	Response
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Fire Pump Room C30
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metron Inc
EquipmentId	Fire Pump Automatic Transfer Switch
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C25 - Emergency Service
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE Zenith Controls
EquipmentId	ATS-ESP
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C25 - Emergency Service
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE Zenith Controls
EquipmentId	ATS-SDP
Capacity/Size Quantity	225
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C25 - Emergency Service
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE Zenith Controls
EquipmentId	Fire Alarm ATS
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation Year	Documented
Deficiency Battery Charger	No deficiencies recorded Does not exist

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	ispection	A03
uestion		Response
EMERG	ENCY GENERATOR SET	
Emerg	ency Distribution Board	Inspected
Numl	ber of Spares	7
Fused	d Disconnect Switch Type	Does not exist
Mold	led Case Circuit Breaker Type	Inspected
	Instance	Room C25 - Emergency Service
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	All City Switchboard
	EquipmentId	ESB
	Capacity/Size Quantity	800
	Capacity/Size UOM	Amps Total
	Capacity/Size 2 Quantity	1
	Capacity/Size 2 UOM	Section(s)
	Source of Capacity/Size	Nameplate
	Installation Year Source of Installation Year	2016
		Documented
	Deficiency	No deficiencies recorded
Diesel	.	Inspected
	Instance	Roof - Outside Generator Enclosure
	Instance Condition	4- Between Fair and Poor
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Generac
	EquipmentId	Emergency Generator
	Capacity/Size Quantity	438
	Capacity/Size UOM	kVA
	Capacity/Size 2 Quantity Capacity/Size 2 UOM	350 kW
	Capacity/Size 3 Quantity	kw 1,215
	Capacity/Size 3 UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	2016
	Source of Installation Year	Documented
	Deficiency	GENERATOR NOT OPERATIONAL
	Deficiency Quantity	1
	Quantity Uom	EACH
	Potential Action	REPAIR
	Urgency of Action	PRIORITY 5
	Purpose of Action	LEVEL 6
	Violations	No violations recorded
Natura	ll Gas	Does not exist
EMERG	ENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERG	ENCY LIGHTING	Inspected
Battery	y Pack	Does not exist
Non Ba	attery Pack	Inspected
Cond	ition	2- Between Good and Fair
	Deficiency	No deficiencies recorded
EXIT LI	GHT	Inspected
Battery	y Pack	Inspected
Cond	v	2- Between Good and Fair
	Deficiency	No deficiencies recorded
Non Ba	attery Pack	Does not exist
	MERGENCY LIGHT	Does not exist
	LARM SYSTEM	Inspected

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

	Λυ
estion	Response
TRE ALARM SYSTEM	
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	DETECTOR NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Does not exist
Fire Alarm Digital Communicator Main Panel	Inspected
Bell At Panel	Does not exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby 2- Between Good and Fair
Instance Condition	
Instance Quantity	
Instance Quantity Uom	EACH
Manufacturer	Honeywell
Model	E3 Series
EquipmentId	Fire Alarm Control Panel
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ineui Inspection	11030
Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Does not exist
Holding Area	
	Inspected Inspected
Local Distribution Frame (I/LDF) Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Inspected
Main Equipment Rack (MDF) Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui Inspeciion		AU.
uestion	Response	
PANEL BOARD		
Molded Case Circuit Breaker Type		
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	MDF Room 131	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Telecor II	
Installation Year	2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	2- Between Good and Fair	
Installation Year	2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office - Room C26	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista 128BPT	
Installation Year	2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room C24	
Instance Condition	2- Between Good and Fair 1	
Instance Quantity		

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ion	Response	
VICE SWITCH		
Manufacturer	All City Switchboard	
EquipmentId	Fire Pump	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Fuse Size	
Installation Year	2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room C24	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	Service Switch #1	
Capacity/Size Quantity	3000	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room C24	
Instance Condition	2- Between Good and Fair	
Instance Quantity		
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	Service Switch #2	
Capacity/Size Quantity	2000	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room C24	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	Service Switch #3	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance Instance Condition	Electrical Room C24 2- Between Good and Fair	
Instance Condition		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	Service Switch #4	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2016	
Source of Installation Year	Documented	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

iestion	Response	
SERVICE SWITCH		
Deficiency	No deficiencies recorded	
Instance	Switchgear Room B7-D	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Electrotech	
EquipmentId	Section 2	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	14	
	Inspected	
Fused Disconnect Switch Type	Electrical Room C24	
Instance		
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	N/A	
Capacity/Size Quantity	3000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Switchgear Room B7-D	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Electrotech	
	Section 3, 4, 5	
EquipmentId Capacity/Size Quantity	1600	
Capacity/Size Quantity Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	3	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Size	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	