### **Building Condition Assessment Survey 2023-2024**

Asset:	P.S. 333 - BRON	X, 888 REV. J.A. POLITE	AVENUE, BRO	NX, NY, 10459			
Inspection		. ,			Time	In	Last Edited
	3070 ELECTRICAL				2024-	02-08 10:55AN	1 2024-03-04 10:56A
set Data							
Question				Answer			
	Systems/Major Building (	Components been upgraded?		Systems:	Partial Molde	d Case Circuit E	Breaker Panel Boards
riave arry s	Systems Major Banding	components seen apgraded.		Years:		001, 1998, 1993	
				Systems:		(Battery Pack)	
				Years:	2018, 2010	(=)	
				Systems:		ncy Lighting (B	attery Pack)
				Years:	2018	)88 (	
				Systems:			usion Alarm System
				Years:	2017	)	
				Systems:		stem (Electroni	c Sub Panels)
				Years:	2014, 1997	stem (Electronic	e suo i uneis)
				Systems:		stem (Digital C	ommunicator)
				Years:	2014	Digital C	ommunicator)
				Systems:	Interior Light		brary, Student Bathrooms
				Vacuus	System (Moti		s), Intrusion Alarm
				Years:	2013	and Cound Cre	stem, Projection System)
				Systems:	`	Local Sound Sys	tem, Projection System)
				Years:	2012	ont Dathraams (	Dandant Elwarasaant
				Systems:	Lighting)	ent Bathrooms (.	Pendant Fluorescent
				Years:	2010	Ct E	(D : . C:4-1 . I f
				Systems:	Sensors)	m System Exce	pt (Panic Switch, Infrared
				Years:	2003		
				Systems:	Security Light	tıng	
				Years:	2000		
				Systems:	Emergency Li	ight/Exit Panel	
				Years:	1993		
Type of Se				Below Gro	ound		
	active Whiteboard (IWB)			Yes			
	etration In Electrical Roo			Yes			
Question	TED INTERCOMS I	N FIRE RESCUE AREAS		T	Response		
	•	ance Areas, Fire Rescue Areas, ar	nd/or Holding Room		No		
riority Con							
exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
'es	Water Penetration in	Water Penetration inside	Electrical	Electrical	Andrija	Fireman	No Photo Taken
	Electrical Room	Electrical Room Through Foundation Wall	Equipment	Room	Markic		
o	Water Leaks onto Electrical Equipment	Water Leaks on Lighting Fixture.	Lighting Fixture	Basement Exit 8 and 9	Gjergj Markaj	Fireman	No Photo Taken
o	Fire Alarm System -	Panel is in Trouble Mode	Fire Alarm	Electrical	Andrija	Fireman	No Photo Taken
	Defective		System - Sub Panel	Room	Markic		
spection							
Question				Response			

#### **Building Condition Assessment Survey 2023-2024**

westion	Dosmonso	
uestion	Response	
AUDITORIUM	Inspected	
Instance on 2nd Floor	Inspected	
House Lighting		
Instance on 2nd Floor	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Does not exist	
Local Sound System		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2012	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 2nd Floor	Inspected	
Dimming System	•	
Instance on 2nd Floor	Does not exist	
Theater Lighting		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	32	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
CAFETERIA	Inspected	
Instance on 1st Floor	Inspected	

Inspected

Inspected

Does not exist

Lighting

Instance on 1st Floor

Instance on 1st Floor

Instance on 1st Floor

**Lighting Fixture - Fluorescent** 

**Pendant Mounted** 

Question	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	1965	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action Violations	LEVEL 2	
	No violations recorded	
Projection System	Does not exist	
Instance on 1st Floor	Does not exist	
Theater Lighting System Instance on 1st Floor	Does not exist	
	Inspected	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 3rd Floor - Annex	Inspected	
Lighting		
Instance on 3rd Floor - Annex	Inspected	
Lighting Fixture - Fluorescent		
Instance on 3rd Floor - Annex	Inspected	

Duestion	Response	
GYMNASIUM	14. 11	
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Instance on 3rd Floor - Annex	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	140 deficiencies recorded	
Instance on 3rd Floor - Annex	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on 3rd Floor - Annex	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on 3rd Floor - Annex	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 3rd Floor - Annex	Inspected	
Pendant Mounted	mspected	
Instance on 3rd Floor - Annex	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	ivo deficiencies recorded	
Instance on 3rd Floor - Annex	Does not exist	
Recessed Mounted	Does not exist	
Instance on 3rd Floor - Annex	Does not exist	
Local Sound System	Does not exist	
Instance on 3rd Floor - Annex	Inspected	
Instance Condition	5- Poor	
Installation Year	1965	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 3rd Floor - Annex	Does not exist	
Scoreboard		
Instance on 3rd Floor - Annex	Does not exist	
Theater Lighting System		
Instance on 3rd Floor - Annex	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	·	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	

Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 306	Inspected	
Lighting		
Instance on Room 306	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 306	Inspected	
Pendant Mounted		
Instance on Room 306	Does not exist	
Surface Mounted		
Instance on Room 306	Does not exist	
Recessed Mounted		
Instance on Room 306	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 306	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 306	Does not exist	
Lighting Fixture - LED		
Instance on Room 306	Does not exist	
Raceway With Receptacles		
Instance on Room 306	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 306	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor - South, 1st Floor - North	Inspected	
Instance on Basement - Annex	Inspected	
Lighting		
Instance on 1st Floor - South, 1st Floor - North	Inspected	
Instance on Basement - Annex	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor - South, 1st Floor - North	Does not exist	
Instance on Basement - Annex	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor - South, 1st Floor - North	Does not exist	
Instance on Basement - Annex	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - South, 1st Floor - North	Does not exist	
Instance on Basement - Annex	Does not exist	

trical Inspection		X(
Question	Response	
MULTIPURPOSE ROOM		
Lighting		
Lighting Fixture - LED		
Instance on 1st Floor - South, 1st Floor - North	Inspected	
Instance on Basement - Annex	Inspected	
Pendant Mounted		
Instance on 1st Floor - South, 1st Floor - North	Does not exist	
Instance on Basement - Annex	Does not exist	
Surface Mounted		
Instance on 1st Floor - South, 1st Floor - North	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Basement - Annex	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	7	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted		
Instance on 1st Floor - South, 1st Floor - North	Does not exist	
Instance on Basement - Annex	Does not exist	
Local Sound System		
Instance on 1st Floor - South 1st Floor - North	Does not exist	

Instance on 1st Floor - South, 1st Floor - North	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Basement - Annex	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALL	AST DEFECTIVE
Deficiency Quantity	7	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted		
Instance on 1st Floor - South, 1st Floor - North	Does not exist	
Instance on Basement - Annex	Does not exist	
Local Sound System		
Instance on 1st Floor - South, 1st Floor - North	Does not exist	
Instance on Basement - Annex	Inspected	
Instance Condition	5- Poor	
Installation Year	1965	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATION	ONAL
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 1st Floor - South, 1st Floor - North	Does not exist	
Instance on Basement - Annex	Does not exist	
Theater Lighting System		
Instance on 1st Floor - South, 1st Floor - North	Does not exist	
Instance on Basement - Annex	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Partners Version 2.0 (P)	Page 6 of 12	Print Date: 8/8/2024

Electrical Inspection	X060

_		
Question	Response	
TOILET ROOM - STAFF		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Does not exist	
Manual Pull Station	Inspected	
Condition	3- Fair	

### **Building Condition Assessment Survey 2023-2024**

Electrical Inspection X060

	710
Response	
No deficiencies recorded	
Inspected	
3- Fair	
No deficiencies recorded	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Inspected	
*	
No deficiencies recorded	
Inspected	
Electrical Room	
2- Between Good and Fair	
1	
EACH	
Silent Knight	
Transmitter	
2014	
Documented	
3- Fair	
No deficiencies recorded	
Does not exist	
Inspected	
Electrical Room	
3- Fair	
1	
EACH	
ACME	
N/A	
1965	
Documented	
BEYOND USEFUL LIFE	
Electrical Room	
113,000	
S.F.	
REPLACE	
PRIORITY 1	
LEVEL 2	
No violations recorded	
Inspected	
Inspected	
3- Fair	
No deficiencies recorded	
	No deficiencies recorded  Inspected 3 - Fair No deficiencies recorded Inspected 3 - Fair No deficiencies recorded Does not exist Inspected 3 - Fair No deficiencies recorded Inspected Inspected Inspected Electrical Room 2 - Between Good and Fair 1 EACH Silent Knight Transmitter 2014 Documented No deficiencies recorded Inspected Betwien Room 3 - Fair No deficiencies recorded Does not exist Inspected Electrical Room 3 - Fair 1 EACH ACME N/A 1965 Documented BEYOND USEFUL LIFE Electrical Room 113,000 S.F. REPLACE PRIORITY 1 LEVEL 2 No violations recorded Inspected

#### **Building Condition Assessment Survey 2023-2024**

trical Inspection	Pagnanga
Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Electronic)	4.0
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Mircom
Model	Series 1000
EquipmentId	Fire Alarm Control Panel
Installation Year	1997
Source of Installation Year	Documented  NAME ADDRESS OF A STATE OF A STA
Deficiency Deficiency Quantity	PANEL DEFECTIVE
	1 EACH
Quantity Uom Potential Action	EACH REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	
	1 EACH
Instance Quantity Uom	
Manufacturer	Siemens
Model	PAD-3 BPS
EquipmentId	2014
Installation Year Source of Installation Year	Documented
Deficiency	No deficiencies recorded
	Does not exist
Fire Alarm Control Panel (Standard)  Remote Annunciator	Does not exist  Does not exist
Sprinkler Flow/Air Pressure Switch	Does not exist  Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inaccessible
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
E ID: (C t/ L T	T 1

**Fused Disconnect Switch Type** 

Deficiency

Condition

Inspected

PANEL BOARD BEYOND USEFUL LIFE

3- Fair

#### **Building Condition Assessment Survey 2023-2024**

Question	Response
PANEL BOARD	- Coponit
Fused Disconnect Switch Type	
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Inspected
Fused Knife Switch Type Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement Room B13
Deficiency Quantity	
	1 FACIL
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2
Violations	No violations recorded
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Main Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 125
	1965
Installation Year Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Office
Deficiency Quantity	113,000 S.F.
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

No violations recorded

Inspected

Violations

SECURITY

rical Inspection	Dosnonso	
uestion	Response	
SECURITY		
IPDVS/CCTV System	Does not exist	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Basement - Mechanical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista - 128B	
Installation Year	2003	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	3- Fair	
	No deficiencies recorded	
Deficiency		
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Lexington	
EquipmentId	Main Service Switch	
Capacity/Size Quantity	2000	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Fuse Size	
Installation Year	1965	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
	and the second s	

Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH

### **Building Condition Assessment Survey 2023-2024**

Electrical Inspection X060

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Manufacturer	Lexington
EquipmentId	Switchgear
Capacity/Size Quantity	1000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	4
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist