Mechanical Inspection	X060

Asset:	P.S. 333 - BRC	ONX, 888 REV. J.A. POLITE	AVENUE, BRO	NX, NY, 10459			
Inspection Id	Inspection Type				Time In		Last Edited
3094	4 MECHANICAL				2024-02-08 07:1	7AM	2024-03-16 12:42PM
sset Data							
Question				Answer			
Have any Syst	tems/Major Building	g Components been upgraded?		Systems:	Student Fixtures - Urinals	s (~80%)	
				Years:	2022		
				Systems:	Terminal Unit Thermostar	tic Traps	; Climate Control
				Years:	System - Electric System 2019		
				Systems:	F&T/Steam Drip Traps		
				Years:	2018		
				Systems:	DX Split Systems for Au	litorium:	Sumn Pumps: Gas
				Systems.	Meter Room Vent; CO/Ga		
				Years:	2014		
				Systems:	MDF Room - Dedicated A	A/C Equi	pment (DX Split
					System)		
				Years:	2013		
Are there fuel				Yes			
	above ground tanks			2			
	acity of all above gro			15,000			
	below ground tanks acity of all below gro			0			
_	ter main service entr	_		3			
	ooms Locations				Building: Basement - North	MER B	oiler Room
WIENES Tun 100	Soms Eccations				al Area; Fan Room above A		
					khead Fan Rooms, Penthou		
			Douin Dui	Kiicaa i ali 1000iiis, i ciitiioa	isc - I all	rtoom, rank	
					ilding Addition: Basement		Room, Tank
	-	g or Defective CO Detectors?		Room. Bu No			Room, rank
Are there any	Painted/Obstructed	Sprinkler Heads?		Room. Bu No No	ilding Addition: Basement		Room, Tank
Are there any l	Painted/Obstructed Emergency Stop Sv			Room. Bu No	ilding Addition: Basement		Noon, Tank
Are there any Are there any I	Painted/Obstructed Emergency Stop Sv	Sprinkler Heads? vitches with Missing Hammers?		Room. Bu No No No compo	ilding Addition: Basement nents	MER	
Are there any Are there any Are there any Are there any Are there are Are the Are there are Are the Are the Are the Are there are Are the Ar	Painted/Obstructed Emergency Stop Sv ition iority	Sprinkler Heads? vitches with Missing Hammers? Condition	Component Affected	Room. Bu No No No compo	nents Person(s) Person(s)	MER	oto
Are there any large there any large there any large triority Conditions. Exist Pri Last Year? Care	Painted/Obstructed Emergency Stop Sv ition itiority ategory	Sprinkler Heads? vitches with Missing Hammers?	Component Affected	Room. Bu No No No compo	ilding Addition: Basement nents	MER	
Are there any Are there are the Are th	Painted/Obstructed Emergency Stop Sv ition itiority ategory	Sprinkler Heads? vitches with Missing Hammers? Condition	-	Room. Bu No No No compo	nents Person(s) Person(s)	MER	oto
Are there any Are there are the Ar	Painted/Obstructed Emergency Stop Sv ition itiority ategory	Sprinkler Heads? vitches with Missing Hammers? Condition	-	Room. Bu No No No compo	nents Person(s) Person(s)	MER	oto
Are there any Are there are the	Painted/Obstructed Emergency Stop Sv ition itiority ategory	Sprinkler Heads? vitches with Missing Hammers? Condition	-	Room. Bu No No No compo	nents Person(s) Person(s)	MER	oto
Are there any Are there are the Ar	Painted/Obstructed Emergency Stop Sv ition iority ntegory recorded	Sprinkler Heads? vitches with Missing Hammers? Condition	-	Room. Bu No No No compo	nents Person(s) Person(s)	MER	oto
Are there any Are there are Are there any Are there any Are there are the Are there are the Are there are the Are there are the	Painted/Obstructed Emergency Stop Sv ition iority ntegory recorded	Sprinkler Heads? vitches with Missing Hammers? Condition	-	Room. Bu No No No compo	nents Person(s) Person(s) Notified Title	MER	oto
Are there any Are there are the Are there are the Are there are the Are	Painted/Obstructed Emergency Stop Sv ition ition riority ntegory recorded DITIONING Vater System	Sprinkler Heads? vitches with Missing Hammers? Condition Description	Affected	Room. Bu No No No compo	nents Person(s) Person(s) Notified Title	MER	oto
Are there any Are there are the Are Condense Are there are the Are there are the Are there are the A	Painted/Obstructed Emergency Stop Sv ition ition riority ntegory recorded DITIONING Vater System	Sprinkler Heads? vitches with Missing Hammers? Condition	Affected	Room. Bu No No No compo Location Description Response Inspected Does not of	nents Person(s) Person(s) Notified Title	MER	oto
Are there any Are there are Are there are Are there are Are there are Are the Are there are Are the Are	Painted/Obstructed Emergency Stop Sv ition riority ategory recorded DITIONING Vater System er Water Distributio Coil in Ductwork	Sprinkler Heads? vitches with Missing Hammers? Condition Description	Affected	Room. Bu No No No compo Location Description Response Inspected Does not of	nents Person(s) Person(s) Notified Title exist exist exist	MER	oto
Are there any Are there are Are there are Are there are Are there are Are the Are there are Are the Are	Painted/Obstructed Emergency Stop Sv ition riority ategory recorded DITIONING Vater System er Water Distributio Coil in Ductwork Tower	Sprinkler Heads? vitches with Missing Hammers? Condition Description	Affected	Room. Bu No No No compo Location Description Response Inspected Does not of Does not of	nents Person(s) Person(s) Notified Title exist exist exist	MER	oto
Are there any Are there are Are the Ar	Painted/Obstructed Emergency Stop Sv ition riority ategory recorded DITIONING Vater System er Water Distributio Coil in Ductwork Tower System	Sprinkler Heads? vitches with Missing Hammers? Condition Description	Affected	Room. Bu No No No No compo Location Description Response Inspected Does not of Does not of Inspected Inspected Inspected Inspected	Person(s) Person(s) Notified Title	MER	oto
Are there any Are there are Are the Are th	Painted/Obstructed Emergency Stop Sv ition iority ntegory recorded DITIONING Vater System er Water Distributio Coil in Ductwork Tower System Unit	Sprinkler Heads? vitches with Missing Hammers? Condition Description	Affected	Room. Bu No No No No compo Location Description Response Inspected Does not of Does not of Inspected Inspected Inspected Inspected	nents Person(s) Person(s) Notified Title exist exist exist	MER	oto
Are there any Are there are Are there are Are the	Painted/Obstructed Emergency Stop Sv ition iority ntegory recorded DITIONING Vater System er Water Distributio Coil in Ductwork Tower System Unit	Sprinkler Heads? vitches with Missing Hammers? Condition Description	Affected	Room. Bu No No No No composite Location Description Response Inspected Does not of Does not of Does not of Inspected Inspected Location	Person(s) Person(s) Notified Title	MER	oto
Are there any Are there are Are Condition respection Question Mechanical AIR COND Chilled W Condenses Cooling C Cooling T DX Split S Indoor U Condit	Painted/Obstructed Emergency Stop Sv ition riority ategory recorded DITIONING Vater System er Water Distributio Coil in Ductwork Tower System Unit tion Deficiency r Unit	Sprinkler Heads? vitches with Missing Hammers? Condition Description	Affected	Room. Bu No No No No composite Location Description Response Inspected Does not of Does not of Does not of Inspected Inspected Inspected 2- Between	nents Person(s) Person(s) Notified Title exist exist exist exist exist exist exist	MER	oto
Are there any Are there are Are the Are Condition To a section	Painted/Obstructed Emergency Stop Sv ition riority ategory recorded DITIONING Vater System er Water Distributio Coil in Ductwork Tower System Unit tion Deficiency r Unit	Sprinkler Heads? vitches with Missing Hammers? Condition Description	Affected	Room. Bu No No No No composite Location Description Response Inspected Does not of Does not of Does not of Inspected Inspected 1. September 1. Se	nents Person(s) Person(s) Notified Title exist exist exist exist exist exist exist	MER	oto
Are there any Are there are Are the Ar	Painted/Obstructed Emergency Stop Sv ition riority ategory recorded DITIONING Vater System er Water Distributio Coil in Ductwork Tower System Unit tion Deficiency r Unit	Sprinkler Heads? vitches with Missing Hammers? Condition Description	Affected	Room. Bu No No No No composite Location Description Response Inspected Does not of Does not of Inspected Inspected 2- Betwee No deficie Inspected 2- Betwee 2- Betwee 2- Betwee Property of the property of	Person(s) Person(s) Notified Title exist	MER	oto
Are there any Are there are Are the Ar	Painted/Obstructed Emergency Stop Sv ition ition itiority ategory recorded DITIONING Vater System er Water Distributio Coil in Ductwork Tower System Unit tion Deficiency r Unit tion Deficiency	Sprinkler Heads? vitches with Missing Hammers? Condition Description	Affected	Room. Bu No No No No composite Location Description Response Inspected Does not of Does not of Inspected Inspected 2- Betwee No deficie Inspected 2- Betwee 2- Betwee 2- Betwee Property of the property of	Person(s) Person(s) Notified Title exist	MER	oto
Are there any Are there are Are the Are Condition To Are Condition To Are Cooling Cooling To DX Split Solid Indoor Undoor Condition Co	Painted/Obstructed Emergency Stop Sv ition ition itiority ategory recorded DITIONING Vater System er Water Distributio Coil in Ductwork Tower System Unit tion Deficiency r Unit tion Deficiency	Sprinkler Heads? vitches with Missing Hammers? Condition Description	Affected	Room. Bu No No No No composite Location Description Response Inspected Does not of Does not of Does not of Inspected Inspected 2- Betwee No deficie Location Locat	Person(s) Person(s) Notified Title Exist	MER	oto
Are there any Are there are Are the Are Condition To a section	Painted/Obstructed Emergency Stop Sv ition riority ategory recorded DITIONING Vater System er Water Distributio Coil in Ductwork Tower System Unit tion Deficiency r Unit tion Deficiency er I / Rooftop Unit I Terminal A/C	Sprinkler Heads? vitches with Missing Hammers? Condition Description on: Piping, Pumps and Auxiliarion	Affected	Room. Bu No No No No composite Location Description Response Inspected Does not of Does not of Inspected Inspected 2- Betwee No deficie Inspected 2- Betwee No deficie Does not of	Person(s) Person(s) Notified Title Exist	MER	oto
Are there any Are there are Are the Are Condition To Are the A	Painted/Obstructed Emergency Stop Sv ition riority ategory recorded DITIONING Vater System er Water Distributio Coil in Ductwork Tower System Unit tion Deficiency r Unit tion Deficiency er 1/Rooftop Unit 1 Terminal A/C unt Leak Detection	Sprinkler Heads? vitches with Missing Hammers? Condition Description on: Piping, Pumps and Auxiliarion	Affected	Room. Bu No No No No composite Location Description Response Inspected Does not of Does not of Inspected Inspected 2- Betwee No deficie Inspected 2- Betwee No deficie Does not of	Person(s) Person(s) Notified Title Exist	MER	oto

Mechanical Inspection	X060

uestion	Response
AIR CONDITIONING	
Refrigerant Piping	
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
Hybrid System	Does not exist
Electric System	Inspected
Instance	Throughout (Heat Timer System)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
COMPACTOR	Does not exist
CONVEYING	Does not exist
OOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Inspected
Supply Pump	Does not exist
Roof Tank	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Penthouse - Tank Room
Deficiency Quantity	1
Quantity Uom	EACH NO A CITYON
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Original Building: Basement - Storage Room; Building Addition:
Instance Condition	Basement - Water Meter Room 4- Between Fair and Poor
Instance Quantity	3 EACH
Instance Quantity Uom	
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Original Building: Basement - Storage Room; Building Addition: Basement - Water Meter Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

Mechanical Inspection X06	60
---------------------------	----

uestion	Response
DOMESTIC WATER SYSTEM	
Domestic Cold Water System	
Water Service	
Deficiency	WATER MAIN: DEFECTIVE VALVE
Deficiency Location/Instance	Original Building: Basement - Storage Room; Building Addition: Basement - Water Meter Room
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	Rheem / Ruud
Manufacturer	N/A
EquipmentId Capacity/Size Quantity	512
Capacity/Size Quantity Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2010
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
	Inspected
Sump Pump Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

Mechanical Inspection	X060
Question	Response

Question	Response
FIXTURES	
Staff And Other	
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	5th Floor Staff Toilet Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action Purpose of Action	PRIORITY 3 LEVEL 2
Violations	No violations recorded
	Inspected
Urinal Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	Inspected
Student Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Lavatory/Sink Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	Does not exist
Locker Room Shower	Inspected
Sink And Fountain Combo Unit Condition	3- Fair
	No deficiencies recorded
Deficiency	
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Inspected 1- Good
Condition	No deficiencies recorded
Deficiency C. P. P. C.	Does not exist
Gas Pressure Booster CO/Gas Leak Detection	Inspected
Instance	Basement - Boiler Room, Gas Meter Room, Outside Gas Meter
instance	Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2014
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded

Mechanical Inspection		X060
Question	Response	

Question	Response
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
•	
Deficiency Location/Instance Deficiency Quantity	Building Addition: Basement M ER 20
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Pumping System	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Building Addition: Basement M ER
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Does not exist
HEATING PLANT	Inspected
Instance on Basement	Inspected
Is there a water meter on the boiler make-up water piping?	Yes
Observed Operational?	No
Burner Manufacturer	Iron Fireman
Burner Model	AG0-2-15-RK
Burner Type	Oil
Heating Plant Oil Number	2
Boiler Auxiliaries	
Instance on Basement	Inspected
Boiler Auxiliary Piping	
Instance on Basement	Inspected

uestion	Response	
HEATING PLANT	•	
Boiler Auxiliaries		
Boiler Auxiliary Piping		
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater Treatment(Automatic)		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Flue Exhaust		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping	The deficiences recorded	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	DEFECTIVE/LEAKS	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	10	
Quantity Uom	L.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Safety Valve		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler System		
Instance on Basement	Inspected	
Coal-fired Boiler		
Instance on Basement	Does not exist	
Hot Water Boiler		
Instance on Basement	Does not exist	
Modular Boiler		
Instance on Basement	Does not exist	
Steam Boiler		
Instance on Basement	Inspected	
Instance on Basement	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Condition Instance Quantity	6,877	
-		

Building Condition Assessment Survey 2023-2024

uestion	Response	
HEATING PLANT		
Boiler System		
Steam Boiler		
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	Burnham	
EquipmentId	2907-01	
Capacity/Size Quantity	8857	
Capacity/Size UOM	MBH Gross	
Source of Capacity/Size	Documented	
Installation Year	2001	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	6,877	
Instance Quantity Uom	MBH NET	
	No	
Cast Iron Boiler? Manufacturer	A. L. Eastmond & Sons Inc.	
Manufacturer EquipmentId	2907-02	
Capacity/Size Quantity	8857	
Capacity/Size Quantity Capacity/Size UOM	MBH Gross	
Source of Capacity/Size	Documented	
Installation Year	2001	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Fuel System	To deficiences recorded	
Instance on Basement	Inspected	
Boiler Fresh Air Louver/Damper	Inspected	
Instance on Basement	Lucusosto d	
	Inspected 3- Fair	
Instance Condition		
Type	Automatic	
Deficiency	No deficiencies recorded	
Burner/Burner Control Panel		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fuel Oil Storage/Supply System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Trains And Vent At The Boiler		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Enclosed IDF Room	Inspected	
Instance on Original Building - Room 353	Inaccessible	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas System		

Instance on 1st Floor

Inspected

Building Condition Assessment Survey 2023-2024

anical Inspection	Dogwows	X
uestion	Response	
KITCHEN		
Gas System Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Grease Trap Instance on 1st Floor	Turnes de J	
	Inspected 3- Fair	
Instance Condition	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Hood	Lucusotod	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork	*	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System		
Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 1st Floor	Does not exist	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Original Building - Room 551	Inspected	
Dedicated A/C Equipment		
Instance on Original Building - Room 551	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Does not exist	
Sprinkler Head	Inspected	
Sprinkier Head		
Condition	3- Fair	
	3- Fair No deficiencies recorded	
Condition		

No deficiencies recorded

Does not exist

Does not exist

Does not exist

Inspected

Yes

Deficiency

Is the building Mechanically ventilated?

Standpipe System

SWIMMING POOL

Water Gong

Building Condition Assessment Survey 2023-2024

Mechanical Inspection X060

uestion	Response
VENTILATION	
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	No
Deficiency	No deficiencies recorded
Supply Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-5
Deficiency	No deficiencies recorded
Unit Ventilator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded