Asset:	P.S. 63 - BRON	X. 1260 FRANKLIN A	VENUE, BRONX, NY,	. 10456		
Inspection		A, 1200 FRANKLINA	VERVE, DROMA, IVI,	, 10430	Time In	Last Edited
	060 ELECTRICAL				2024-02-08 09:17AN	
sset Data	000 ELECTRICAL				2024-02-08 09.17AN	1 2024-04-17 03.4711
Question				Answer		
	lystems/Major Ruilding	Components been upgrade	A?	Systems:	IPDVS/CCTV System	
Trave arry 5	ystems/wajor building	components been upgrade	ou.	Years:	2024	
				Systems:	Multipurpose Rooms (LED L	ighting)
				Years:	2022	<i>C O</i> ,
				Systems:	Security Lights	
				Years:	2021	
				Systems:	Fire Alarm System, Public Ad Sound System	dress System, Local
				Years:	2020	
				Systems:	Auxiliary Signal/Bell System, Lighting (Battery Pack), Most Packs), Intrusion Alarm Syste	Exit Lights (Battery
				Years:	Remote Annunciator) 2018	,
				Systems:	Interior Lighting (Except Libr Recessed Fluorescent Lighting	
				Years:	2014	<i>9)</i>
				Systems:	Most Molded Case Circuit Br	eaker Panel Boards
				Years:	2012, 2005, 1995	
				Systems:	Multipurpose Room (Fluoresc	cent Lighting)
				Years:	2012	
				Systems:	Telephone System, LAN	
				Years:	2011	
				Systems:	Recessed Fluorescent Lighting	g
				Years:	2008	
				Systems:		
				Years: Systems:	2006 Intrusion Alarm System	
				Years:	1996	
					Emergency Lights/Exit Panel,	Fused Disconnect
				Systems.	Switch Type Panel Boards	r used Disconnect
				Years:	1992	
Type of Sea	rvice			Below Gr	ound	
	active Whiteboard (IWB			Yes		
	tration In Electrical Roc			No		
	TED INTERCOMS	IN FIRE RESCUE AR	EAS	,	D	
Question Are there	any Life Rescue Assist	ance Areas. Fire Rescue Ar	reas, and/or Holding Room		Response No	
your buil	ding?		. To the state of			
Priority Con	Priority	Condition	Component	Location	Person(s) Person(s)	Photo
Last Year?	Category	Description Description	Affected	Description	Notified Title	Image
No condition	on recorded					
Inspection				Da		
Question				Response	:	
Electrical					• .	
	FIC FIELD			Does not		
AUDITORIUM			Inspected			
	Instance on 2nd Floor	•		Inspected		
House	Lighting					
	Instance on 2nd Floor	•		Inspected		

Electrical Inspection	X063
	_

action	Domana	
estion	Response	
UDITORIUM		
House Lighting	N.	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Local Sound System		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2020	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 2nd Floor	Does not exist	
Theater Lighting System		
Instance on 2nd Floor	Inspected	
Dimming System		
Instance on 2nd Floor	Does not exist	
Theater Lighting		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	26	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
AFETERIA	Inspected	
Instance on 1st Floor	Inspected	

Building Condition Assessment Survey 2023-2024

ricui inspection		AUU
uestion	Response	
CAFETERIA		
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		-
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	-
Deficiency Quantity	5	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2020	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Inspected	

Electrical Inspection	A003

нсш інгресион		Λ00
Question	Response	
COMPUTER LAB		
Instance on Room 402	Inspected	
Power Panel?	Yes	
Lighting		
Instance on Room 402	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 402	Inspected	
Pendant Mounted		
Instance on Room 402	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 402	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 402	Does not exist	
Lighting Fixture - HID	DOG HOLOKOV	
Instance on Room 402	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Room 402	Does not exist	
	Does not exist	
Lighting Fixture - LED Instance on Room 402	Does not exist	
	Does not exist	
Raceway With Receptacles Instance on Room 402	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 306/308	Inspected	
	A	
Lighting		
Lighting Instance on Room 306/308	Inspected	

Electrical Inspection	A003

*		
Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Room 306/308	Inspected	
Pendant Mounted		
Instance on Room 306/308	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 306/308	Does not exist	
Recessed Mounted		
Instance on Room 306/308	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 306/308	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 306/308	Does not exist	
Lighting Fixture - LED		
Instance on Room 306/308	Does not exist	
Raceway With Receptacles		
Instance on Room 306/308	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 306/308	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor - North, 1st Floor - South	Inspected	
Lighting	тырессей	
Instance on 1st Floor - North, 1st Floor - South	Inspected	
Lighting Fixture - Fluorescent	шроссо	
Instance on 1st Floor - North, 1st Floor - South	Inspected	
Pendant Mounted	тырессей	
Instance on 1st Floor - North, 1st Floor - South	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	100 deficiences recorded	
Instance on 1st Floor - North, 1st Floor - South	Does not exist	
Recessed Mounted	Does not exist	
Instance on 1st Floor - North, 1st Floor - South	Does not exist	
	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on 1st Floor - North, 1st Floor - South	Does not exist	
Lighting Fixture - Incandescent	D	
Instance on 1st Floor - North, 1st Floor - South	Does not exist	
Lighting Fixture - LED	Y 1	
Instance on 1st Floor - North, 1st Floor - South	Inspected	
Pendant Mounted	Turner 1	
Instance on 1st Floor - North, 1st Floor - South	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor - North, 1st Floor - South	Does not exist	
Recessed Mounted		

Building Condition Assessment Survey 2023-2024

iricai mspeciion		1005
Question	Response	
MULTIPURPOSE ROOM		
Lighting		
Lighting Fixture - LED		
Recessed Mounted		
Instance on 1st Floor - North, 1st Floor - South	Does not exist	
Local Sound System		
Instance on 1st Floor - North, 1st Floor - South	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2020	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor - North, 1st Floor - South	Does not exist	
Theater Lighting System		
Instance on 1st Floor - North, 1st Floor - South	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - Incandescent Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected Inspected	
Lighting Fixture - Fluorescent Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
	2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	

Building Condition Assessment Survey 2023-2024

исан Інѕресион	X
uestion	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Condition	3- Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35665493L
	35643237P
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	1- Good
Deficiency	PULL STATION COVER IS MISSING
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	INSTALL COVER
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fan Shutdown Control	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected

Building Condition Assessment Survey 2023-2024

	1100
Response	
1- Good	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
Inspected	
Does not exist	
Inspected	
Main Entrance Lobby	
1- Good	
1	
EACH	
Mircom	
FX - 2000	
Fire Alarm Control Panel	
2020	
No deficiencies recorded	
-	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
1- Good	
No deficiencies recorded	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Inspected	
Inspected Inspected	
	1- Good No deficiencies recorded Inspected 1- Good No deficiencies recorded Inspected 1- Good No deficiencies recorded Does not exist Inspected 1- Good No deficiencies recorded Does not exist Inspected Main Entrance Lobby 1- Good 1 EACH Mircom FX - 2000 Fire Alarm Control Panel 2020 Documented No deficiencies recorded Does not exist Inspected Does not exist Inspected Toes not exist Inspected Does not exist Inspected Does not exist Inspected Toes not exist Inspected 1- Good No deficiencies recorded Does not exist Inspected 1- Good No deficiencies recorded Does not exist Inspected 1- Good No deficiencies recorded Inspected I- Good No deficiencies recorded

Building Condition Assessment Survey 2023-2024

AUU
Response
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
Does not exist
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
PANEL BOARD BEYOND USEFUL LIFE
Penthouse Mechanical Room, Auditorium Mechanical Room
2
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No violations recorded
PANEL BOARD DOOR LOCK IS MISSING
Penthouse Mechanical Room, Auditorium Mechanical Room
2
EACH
MAINTENANCE
PRIORITY 2
LEVEL 2
No violations recorded
Inspected
3- Fair
PANEL BOARD BEYOND USEFUL LIFE
Electrical Room
1
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No violations recorded
Inspected
2- Between Good and Fair
PANEL BOARD COVER IS MISSING
Corridor near Auditorium
2
EACH MAINTENANCE
MAINTENANCE
PRIORITY 2
LEVEL 2
No violations recorded
PANEL BOARD DOOR LOCK IS MISSING Boiler Room

Building Condition Assessment Survey 2023-2024

estion	Response
ANEL BOARD	
Molded Case Circuit Breaker Type	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridor near Auditorium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
UBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 205
	1- Good
Instance Condition	
Instance Quantity	1 FACH
Instance Quantity Uom	EACH
Model	Bogen DST1
Installation Year	2020
Source of Installation Year	Documented
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Basement
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
ECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2024
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 110
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
	Inspected
Infrared Sensor	
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Deficiency Remote Annunciator	No deficiencies recorded Inspected

Building Condition Assessment Survey 2023-2024

Question	Response
SECURITY	
Intrusion Alarm System	
Remote Annunciator	
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Roof by Exit 3, Stair A/B
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	N/A
EquipmentId	Ser SW
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1960
Source of Installation Year	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	4
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	N/A
EquipmentId	N/A
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1960
	Inspector Estimate
Source of Installation Year	1
Source of Installation Year Deficiency	FUSED DISCONNECT NOT OPERATIONAL
Source of Installation Year Deficiency Deficiency Quantity	FUSED DISCONNECT NOT OPERATIONAL 1

Building Condition Assessment Survey 2023-2024

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist